

Ms. Mary Logan Remedial Project Manager USEPA, Region 5 77 W. Jackson Boulevard Chicago, Illinois 60604-3590 April 10, 2008 (1530)

RE: Remedial Investigation/Feasibility Study (RI/FS) Work Plan – Revision 1
Wisconsin Public Service Corporation's Former Manitowoc Manufactured Gas Plant (MGP) Site
CERCLA Docket No.: V-W-06-C-847

Dear Ms. Logan:

This letter contains responses to United States Environmental Protection Agency's (USEPA) written comments received February 11, 2008 regarding RI/FS Work Plan Revision 0 dated June 5, 2007 for the Manitowoc Former MGP. For ease of review, USEPA comments are summarized followed by our response to comment. The substance of these comment responses have been incorporated in RI/FS Work Plan Revision 1 enclosed herewith (clean copy, as requested). Revisions necessary to address USEPA comments on the Completion Report, received June 4, 2007 with responses dated July 25, 2007, have also been incorporated in Revision 1. Further, more details are provided in Revision 1 than were contained in Revision 0 related to evaluation of potential soil vapor intrusion (Section 6.5).

#### General Comments

1. Integration with Multi-Site Field Sampling Plan (FSP) Comments: In a letter dated December 20, 2007, EPA submitted comments on the FSP. This site-specific work plan refers to the FSP. Any applicable comments on the FSP apply to this work plan, as well.

The comment is acknowledged. The SSWP references the Multi-Site FSP Revision 3 submitted on February 20, 2008.

2. Use of Screening Tools (e.g., TarGOST): The work plan proposes that TarGOST may be used as a screening tool for the sediment characterization. Has any consideration been given to using this approach for some of the upland soils? For example, could this be used to evaluate residuals below the stabilized soils or in the vicinity of MW-12, MW-13 or MW-14? Alternatively, are there any screening tools for BTEX that might be useful?

The use of screening tools has been evaluated (i.e., TarGOST, Darts) for the sediment and upland soils at the Manitowoc site, and it has been concluded that these screening tools will not be used. For the upland soils, collection of soil samples instead of indirect screening methods is preferred, because tar source areas are generally believed to have been previously excavated or addressed through insitu soil stabilization (ISS) measures. Investigating potential remaining source areas beneath areas of ISS, for example, first requires drilling through the stabilized monolith with a conventional drill rig, and it will be more efficient to collect a soil sample beneath the monolith with this same rig than to mobilize a second rig to use indirect screening tools. For the sediment, TarGOST will not be used because the source areas are generally defined based on previously collected data and additional sediment cores will be collected

for direct assessment of the presence/absence of tar. Accordingly, discussion of TarGOST and Darts has been removed from Section 6.7.5.1 of the SSWP.

- 3. Potential Site-Specific Considerations for the Conceptual Site Model and RI/FS Planning: the following site-specific considerations should be evaluated to better understand the site-specific CSM. Additionally, as appropriate, RI sampling may be needed to address these concerns, and the FS may need to consider the concerns in the development of remedies.
  - a. Groundwater/Surface Water Interactions: There are some reasons to believe that there may be groundwater/surface water interactions that may affect sediment quality. The Completion Report identified a number of upland sample locations below the water table with visually stained soils, LNAPL or DNAPL. It is not clear whether these potential sources may be moving towards the surface water. Additionally, historical sediment sample showed extremely high levels of BTEX in some samples near the shore. It is imperative to understand whether there may be contaminated groundwater and/or NAPL that is discharging to surface water and affecting either the sediment or the water quality, or both. Without this understanding, attempts at remediation may be less successful.

As revised in Section 6.6.2, the proposed piezometer installations in the sand unit below the ISS material along the river (one to three piezometers at locations SB100, SB101 and SB102), and shallow well MW22 located on Wisconsin Central Railroad property, are intended to monitor the quality of the groundwater discharging to sediment and surface water. In addition, Section 6.7.5.2 includes discussion of evaluating potential residual upwelling (see response to Part 3c).

b. Turning Basin Boat Traffic: An effort should be made to determine the impact that turning basin boat traffic may have on the fate and transport of contaminants and sediments in the site vicinity. While the work plan proposes to evaluate general flow velocity into and out of the turning basin, there are no proposals to evaluate localized velocity, prop wash, or other boat traffic influences that may be important to sediment stability and/or water quality. It is important to consider this in the RI and the results may influence remedy assumptions in the FS.

Section 6.7.4 has been revised to include discussion of a qualitative assessment of water quality within the turning basin to provide information regarding the influences boat traffic on sediment stability and water quality. Also, Section 6.7.4 and Table 4 have been revised to include field-measured turbidity and total suspended solids in the lab during the surface water sampling activities.

c. Residual Upwelling: During previous work, upwelling of coal tar residuals has been observed in the river. Please plan to evaluate this during the RI. If the upwelling occurs only in areas where (presumptively) sediment will be removed, it may be less important to understand the mechanisms at work. However, if this is occurring in areas where other remedial alternatives may be considered (e.g., capping or MNR), it may be more important to understand the mechanisms (possibly gas ebullition?), to better understand potential risks, and design and evaluate alternatives.



Ms. Mary Logan, USEPA April 10, 2008 Page 3

> Section 6.7.5.2 has been revised to include observation and documentation of locations where sheen has been observed on the surface water. In addition, sediment cores will be collected and examined for potential coal tar and gas bubbles. As discussed with USEPA, gas ebullition is the likely cause.

4. Surface Water Sampling: The work plan proposes an approach to broadly understand potential surface water impacts from the site. While this is important, we may also need to consider a second phase that is more focused on localized impacts above and/or immediately downgradient of the contaminated sediments. This information may be important in evaluating remedial alternatives (e.g., existing conditions vs. potential dredging resuspension). Please provide flexibility in the work plan for the Step I sediment sample results to be used to refine or expand the surface water sampling. In addition, the surface water sampling should be conducted during warmer weather, as more volatiles and semi-volatiles would be released in warmer water temperatures. If possible, the appropriate surface water sampling time should coincide with one of the groundwater sampling rounds in 2008 when river water temperature would be conducive to cause a release to surface water

Section 6.7.4 has been revised to clarify the data quality objectives (DOOs) and provide flexibility for a second surface water sampling event based on the results of the initial surface water sampling event, groundwater sampling, and/or warm weather conditions.

5. Navigation Dredging: Since it is likely that remediation dredging will be evaluated as an alternative at the site, the RI and FS should consider the dredging in the navigation channel done by the US Army Corps of Engineers. The RI should summarize historic channel dredging, and to the extent possible, discuss the influence of this dredging on the fate and transport of site contaminants. The FS should consider future potential navigation dredging and the possible effects on site remedies.

Section 3.6.6 has been included to summarize historic channel dredging events and includes discussion of contaminant fate and transport and considerations for future remedial options with respect to maintaining operational channel depths.

6. Wisconsin Central Railroad Property: The site-specific Completion Report summarizes available data from the Wisconsin Central Railroad property. Based on the existing work, section 7.2 of the Completion Report recommends additional surface and subsurface characterization of the Wisconsin Central Railroad property. Further, figure 2 of this draft work plan indicates that the site boundary needs to be determined to the west. However, soil sampling on the Wisconsin Central Railroad property has not been proposed in this draft as a data need or as sample locations. Please address.

New Section 6.4.2.3 has been added to include collection of soil samples during installation of well MW22. Also, Section 3.6.1.2 provides a brief summary of the past sampling results on the property performed by WPSC (predecessor company Wisconsin Fuel & Light) and other sampling that was performed by Wisconsin Central associated with leaking aboveground and underground storage tank sites. The tank site information was obtained from the WDNR web site of Geographic Information System (GIS) registry for closed sites, and Bureau of Remediation and Redevelopment Tracking System (BRRTS) sites; this information is provided in Appendix B3.



7. Subsurface Sampling: The work plan proposes that subsurface sampling generally extends to 20 feet below ground surface. It would be useful to check depths and contaminant locations of previous subsurface samples, and base the new proposed depths on that historic information to try to bound the vertical extent of contamination. The approach to subsurface sampling should, of course, be linked to the work on characterizing potential continuing sources.

The intent is to bound the vertical extent of contamination as described in Section 6.4.3, which states "Also, soil samples will be collected to define the vertical extent of contamination from both above and below contaminated layers, as needed, from each boring." Section 6.4.2.2 (Winter Property) has been revised to be consistent with Section 6.4.1 (On-Property Locations) to include "Soil borings will be advanced approximately 20 feet bgs, or until a minimum of 4 consecutive feet of soil that exhibits no MGP impacts (by visual observation and field PID screening) is encountered, unless refusal occurs at a shallower depth." Also, these sections have been revised to include the use of historic sampling information as a basis for proposed boring depths.

8. Groundwater Monitoring for VOCs: EPA is aware that the site-specific groundwater monitoring program evolved over time under WDNR oversight, to represent site-related contaminants. However, it appears that there may be upgradient or "background" VOCs in the vicinity. Please evaluate whether it would be useful to conduct a full VOC scan for some rounds, because the presence of other contaminants (even if not site related) may affect the cost and effectiveness of certain groundwater remedies.

A full VOC scan is being conducted on the treatment system influent sample collected semi-annually which, along with prior full VOC scans on the individual monitoring wells (sampling event in May 2005), provides sufficient information to evaluate the cost and effectiveness of groundwater remedies. A summary of analytical data from the treatment system sampling through August 2006, and the May 18, 2005 groundwater laboratory analytical report, are included in Appendix G.

- 9. Field Documentation: Generally, EPA cannot mandate the format in which information is documented or submitted. However, it has been our experience that it is generally easier for our state agency counterparts to review information if it is provided on forms or in formats that are familiar. To the extent possible, please follow WDNR formats to document RI work and/or results. This might include:
  - a. The WDNR Well Information Form http://dnr.wi.gov/org/water/dwg/gw/forms/4400\_89.pdf
  - b. There also may be RI field and documentation activities associated with Chs. NR 700, NR 105, NR 140, and NR 141.

We acknowledge these forms are available. It is desired to maintain consistency in the Integrys Unitary Program and, as such, the field forms included in the Multi-Site FSP will be used. These forms address the elements of the referenced WDNR forms.



#### II. Specific Comments

10. Section 2.4, Previous Response Actions, Excavation and Disposal, Page 7: Were the excavations done in 2004 or in 1994?

The excavations were done in 1994. Section 2.4 has been revised accordingly.

11. Section 3.1, Site Topography and Drainage, Page 8: Inclusion of a topographic map at the scale of figure 3 or Figure 4 would facilitate an understanding of this section.

Site topography information has been added to Figure 4 and Section 3.1 has been revised accordingly.

12. Page 13, first paragraph: While the area to the north and east may be zoned business, there are residential properties directly adjacent to the site. For example, the first parcel north of the WPS parking lot is 422 s. 10<sup>th</sup> Street, is a residence. Please discuss this in the land use observations

Section 3.4 has been revised to include this discussion.

13. Section 3.6.2.1, Groundwater Monitoring, page 17: Please provide a table with well depths and screen lengths for the existing wells.

Section 3.6.2.1 has been revised to include a table of existing well information, including well depths, screen lengths, and date of installation.

14. Section 3.6.2.1 and 3.6.2.2, Page 18 and Figure 11: The text mentions the drawdown effects of extraction well PW-1 and Figure 11 shows a cone of depression at the extraction well. It appears that the cone of depression is based entirely on the water level measured at the extraction well. Water levels at extraction wells should not be used directly due to well inefficiencies and losses. The water level measured in an extraction wells may be much lower than water levels in the aquifer material just outside of the well bore. There appear to be no water level measurement points outside the extraction well and near the extraction well. Using water levels at extraction wells can bias the interpretation of capture; the capture zone suggested by Figure 11 may be interpreted to be much larger than it actually is and the assumed groundwater gradient control may not be being achieved. A piezometer should be installed adjacent to the extraction well to confirm the achievement of hydraulic control.

We acknowledge that the water level at the extraction well should not be used to interpret the capture zone of the extraction well. An existing piezometer (MW12D) is present adjacent to the extraction well which is screened at the same interval (20 to 35 ft bgs) as the extraction well. The water level at MW12D will be used for future capture zone interpretation in lieu of the water level at the extraction well. The groundwater quality and elevation at proposed water table well MW22 (downgradient from the extraction well and off-property) will assist with determining the adequacy of the capture zone of the extraction well. If groundwater extraction is determined to be part of the final remedy for the site, we acknowledge that additional monitoring wells may be needed to more precisely determine the capture zone of the extraction well and confirm achievement of hydraulic control.



15. Page 19, last paragraph: The reference to a 2003 surface water sample with a detection of possible creosote oil components was collected by a WDNR Marine Warden and resulted in the issuance of a Wis. Stats 292.11, "Responsible Party" letter requiring WPS to investigate the degree and extent of the contamination and at a minimum, conduct an Interim Action according the requirements of NR 708.11 Wis. Adm. Code. The erection of the signage was a result of the coal tar release to the environment and not in response to the DHFS report.

The comment is acknowledged. Section 3.6.3 has been revised accordingly.

16. Page 20, bullet: Please add a bullet specifying that other contaminants were found as well (e.g., sediment sample SB-22 (collected at 0-2 feet) contained benzene at 32,000 mg/kg, benzo(a)pyrene at 330 mg/kg, and total BTEX at 112,000 mg/kg).

Section 3.6.4 has been revised accordingly.

17. Page 25 Groundwater COPCs: Given that new areas and new depths are being investigated as part of the RI, please add cyanide (OIA-1677) to the COPC lists for one round minimum to confirm prior findings and assess the new areas.

Section 3.7 has been revised to add cyanide (OIA-1677) to the groundwater COPC list for one round minimum.

18. Page 29, Section 4.2.4: Please remove the final sentence. Section 3.7 does not discuss risk management tools, it discusses COPCs. Further, decisions about risk management should be deferred until later in the process.

Section 4.2.4 has been revised to remove this sentence.

19. Page 30, second paragraph and page 33, Section 4.3.4: Please leave flexibility in the work plan to consider the inclusion of a residential land use scenario as part of the site-specific CSM and/or risk assessment after the data is obtained. Parts of the contaminated property are municipally owned with no restricted access. The property is bordered by residential property to the north.

Sections 4.3 and 4.3.4 and Figure 12 have been revised to include the possibility of a residential land use scenario as part of the site-specific CSM and future risk assessment.

20. Page 32 second paragraph: The future land use scenario of recreational use should probably include more than the Winter Property. The potential future exposure scenarios for any property not under ownership of WPSC, particularly along the waterfront should be further considered in the RI report

Section 4.3.3 has been revised to include the possibility of future recreational land use for properties not under ownership of WPSC, including City property and Wisconsin Central Railroad property along the waterfront.

21. Page 34, birds (upland and Aquatic): The "qualitative habitat assessment" (appendix E) conducted



in January should be confirmed at a time of year when the full quality of the habitat on and off-site can be observed and evaluated to confirm or expand the findings. This can be done concurrently with the RI work.

Sections 4.1 and 4.4 have been revised to include discussion of confirming the habitat assessment for ecological receptors during a time of year when the full quality of the habitat on and off-site can be observed.

22. Page 37, section 5.1, Task 1: please ensure that this list includes the most recent versions of the multi-site documents.

The comment is acknowledged. Section 5.1 has been revised to include the most recent versions of the multi-site documents.

23. Section 6.3.3, Sampling Methods and Abandonment, Page 44: Are the "hydraulic-push" sampling techniques mentioned here equivalent to the "direct-push technology" mentioned in the Multi-Site FSP? It is stated that samples will be "selected as described in Section 4 of the Multi-Site FSP; this reference is not obvious; provide a more specific reference to the Multi-Site FSP or include the rationale for selecting samples in the Site Specific Work Plan.

The hydraulic-push sampling techniques are equivalent to direct-push technology. For consistency, Section 6.3.3 has been revised to include the use of the term "direct-push" in lieu of "hydraulic-push." The sentence "Samples will be selected as described in Section 4 of the Multi-Site FSP" is not necessary and will be deleted. Rationale for selecting samples is included in the next sentence: "One discrete sample of surface soil (0 to 2 feet depth interval) will be collected from each location for analysis of the parameters and associated methods listed on Table 4."

24. Section 6.4.2.1, City Property, Page 45: It is stated that soil borings will be performed to assess "...the potential for remaining source in the sand unit below the ISS material." How is this potential being evaluated, if no soil samples are being collected? If only groundwater samples are being collected, then at most the potential for dissolution and leaching from any source material is being evaluated. Is the purpose of these soil borings to evaluate the potential of dissolution and leaching from any source material present into the groundwater, or is it to evaluate the potential presence of source material? Also, see general comment 2 above on the use of screening tools.

The purpose of the soil borings is to evaluate the potential presence of remaining source material, which would include observation for coal tar product (DNAPL) or residuals in soils during logging of the soil boring. In addition to observation and the collection of the proposed groundwater grab sample, Section 6.4.2.1 has been revised to include possible collection of soil samples if field observation and/or screening indicate the presence of MGP impacts at any of these borings. Soil samples would be collected for additional confirmation of remaining source.

25. Section 6.4.3, Sampling Methods and Abandonment, Page 46: Are the "hydraulic-push" sampling techniques mentioned here equivalent to the "direct-push technology" mentioned in the Multi-Site FSP?



As noted in the response to Comment 23, the hydraulic-push sampling techniques are equivalent to direct-push technology. Section 6.4.3 has been revised to include the use of the term "direct-push" in lieu of "hydraulic-push."

26. Page 47, Section 6.5: The nearby groundwater results should also be considered in evaluating the potential for soil vapor intrusion.

Section 6.5 has been revised to include the consideration of the nearby groundwater results in evaluating the potential for vapor intrusion.

27. Section 6.6.1, Existing Well Evaluation, Page 47: How old are the existing wells? Clarify that depending on the results of the evaluation, wells may be redeveloped, rehabilitated, or replaced (consistent with SAS-08-05 of the Multi-Site FSP).

As noted in the response to Comment 13, Section 3.6.2.1 has been revised to include an existing well information table which includes well depth, screen length, and date of well installation. Also, Section 6.6.1 has been revised to include discussion that depending on the results of the existing well evaluation, the wells may be redeveloped, rehabilitated, or replaced.

28. Section 6.6.2. Monitoring Well/Piezometer Installation: It is stated on page 48, that drilling and well construction methods will be completed in accord with the methods in Section 4 of Multi-Site FSP. But the Multi-Site FSP is written generally and refers back to the Site Specific Work Plan. The Well Installation SOP in the Multi-site FSP mentions "commonly used well construction materials", "In general ...", and "typically ...". Somewhere specific details of well construction for this site should be provided. The wells will be constructed of what, of what diameters, with what screen slot size, with what size and amount of filter pack? Because the Multi-Site FSP is written somewhat generally, specific details need to be included in this site specific document for all the proposed piezometers and water table wells.

Section 6.6.2 has been revised to include specific details on the proposed well construction.

29. Section 6.6.2.1, Bedrock, Page 49: If the piezometers are to be drilled using sonic rotary methods, then why would "wireline rotary drilling methods" be used to obtain bedrock cores?

Wireline rotary drilling methods will allow collection of competent bedrock cores for field inspection and logging of the rock quality designation (RQD). The sonic method uses vibration to advance the drill stem, which breaks up the cores. Once the competent bedrock cores are collected, the hole will be overdrilled using sonic drilling to provide a large enough diameter for installation of the piezometer. Section 6.6.2.1 has been revised to include this clarification.

30. Section 6.6.2.2, City Property, Page 49: Clarify the rationale for deciding the number of permanent piezometers to be installed. Exactly what field observations and/or mobile laboratory data would support installing the second and third piezometers?

Section 6.6.2.2 has been revised to clarify the rationale.



31. Section 6.6.4, Water Level Measurements, Page 50: It is stated that water level measurements will be completed in accord with the methods in Section 4 of Multi-Site FSP. But the Multi-Site FSP is written generally and the applicable SOP includes two methods (electronic water level indicator and chalked steel tape) and refers back to the Site Specific Work Plan. The Multi-Site FSP states that water levels in wells containing tar will be measured with a weighted standard measuring tape (presumably chalked). What is the measuring method for other wells?

Water levels in wells without product will be measured with an electronic water level indicator as indicated in Multi-Site FSP, Appendix A, SOP No. SAS-08-01. The well(s) with DNAPL product (i.e., MW14) will first use an electronic water level indicator for water level measurement followed by a clear, bottom-filling bailer to measure product thickness (SOP No. SAS-08-01). Section 6.6.4 has been revised to include this information.

32. Section 6.6.5, Sampling Schedule and Parameters: The work plan is proposing 1 year of quarterly sampling followed by annual sampling. While this is acceptable for planning purposes, if monitored natural attenuation ends up being considered as a remedial option for groundwater, more than one year of quarterly data likely will be needed to demonstrate a clear trend of decreasing contaminant concentrations.

The comment is acknowledged. Sections 6.6.5 and 6.6.8 have been revised to include this discussion.

33. Page 52, section 6.6.7: If it is determined that a well requires abandonment, please confer with the agencies regarding the abandonment and the need to construct a replacement well in that location.

Section 6.6.7 has been revised to include this step in the process for well abandonment.

34. Page 56: section 6.7.4: Please clarify the DOOs for the surface water samples. At this time, only one surface water sample will be taken above the known impacted area. If the intent of the surface water sampling is to determine if the impacted sediments are contaminating surface water, then a much higher percentage of samples should be collected above the impacted areas. In addition, the surface water sampling should be conducted during seasonal conditions conducive to releases (e.g., warmer water temperatures).

As discussed in the response to Comment 4, Section 6.7.4 has been revised to clarify the data quality objectives (DQOs) and provide flexibility for a second surface water sampling event based on the results of the initial surface water sampling event, groundwater sampling, and/or warm weather conditions.

35. Page 57, first paragraph, section 6.7.4: Please discuss the basis for the proposed velocity measurements at "0.6 times the total water column depth." Is there any reason to believe that the water velocities may differ at different depth strata so significantly that the data would affect the interpretation of the results?

Section 6.7.4 has been expanded to evaluate water velocity at up to two intervals within the water column depending on water depth, consistent with SOP SAS-09-02 in the latest version of the Multi-Site FSP.



Ms. Mary Logan, USEPA April 10, 2008 Page 10

The minimum and maximum velocity at each depth and each location will be recorded on field logs to evaluate the differences in water velocities with depth and for use in the FS.

36. Page 59, section 6.7.5.1: Please evaluate whether the proposed distribution of sample quantities and PAH range is best. For example, are 5 samples above 1000 ppm likely to be needed? Should there be some samples below 10 ppm that may not be reference locations? Also, will the samples be screened for BTEX to ensure that the toxicity is related to PAHs, and if so, how might we account for BTEX toxicity in the SLERA?

Initial PAH sample results may be used with an average TOC concentration (from previous analytical results) to evaluate whether the PAH concentrations summarized above provide an appropriate range of predicated toxicity using the USEPA's equilibrium partitioning sediment benchmark (ESB) approach. The distribution may be adjusted based on site-specific conditions.

BTEX and other COPCs will be analyzed to assess confounding effects. COPC concentrations will be compared to the screening levels presented in the Multi-Site RAF. If necessary, the samples selected for toxicity testing may be adjusted to include elevated BTEX concentrations.

37. Page 60, third full paragraph, section 6.7.5.1: Please provide more detail about how and when a determination to conduct a benthic community structure assessment will be made. If done, it should be conducted at an appropriate season. Finally, how will the potential effects of boat turning and/or navigation dredging be distinguished from contaminants?

The discussion on the benthic community structure assessment was moved from Section 6.7.5.1 to 6.7.5.2. Section 6.7.5.2 has been expanded to include decision criteria for performing the benthic community structure assessment. The approach and locations will be reviewed with USEPA prior to performing the assessment in an effort to distinguish the potentially confounding effects of boat traffic and/or dredging versus COPC concentrations in sediment.

38. Page 62: The section on sediment source area delineation calls for a screening assessment to characterize the presence or absence of tar and the total PAHs. The section is fairly vague about what will be done – it states that TarGOST may be used, or other methods such as poling or coring. Prior to the work, additional detail about how this delineation will be conducted should be provided to the Agencies.

The potential use of TarGOST to evaluate source areas in sediment has been removed. Source areas will be delineated as part of Step II sediment sampling using previously collected data and results of Step I to focus the initial sediment sampling locations as described in Section 6.7.5.2.

39. Page 64, Section 6.7.5.2, first paragraph: Prior to the work, additional detail about the specific method to obtain sediment cores should be provided to the Agencies.

The specific drilling methods will be identified to USEPA prior to contracting as described in Section 6.7.5.2, the second paragraph. The drilling method selected will consider core recovery, core disturbance, contractor availability, and contractor costs.



40. Page 65, first paragraph: Please rephrase the statement "... the core location will not be considered in the FS." All cores that are analyzed must be reported in the RI and should be "considered" (acknowledged) in the FS. Perhaps a better phrasing would be "Data from the cores and the site-specific risk values will be used in the FS to establish areas for which remedial alternatives will be developed."

The text has been revised as suggested.

41. Page 65 – 66, Sampling Transects: This section acknowledges that the location of transects may be adjusted based on findings in Step I. Please plan to discuss this with the Agencies after Step I information is available. Additionally, there are some inconsistencies between the introductory paragraph and the bullets (e.g., is TS2-1 500 or 600 feet upstream; is TS2-9 500 or 700 feet downstream?). Finally, we should begin a dialogue about how data will be extrapolated between data points because this may influence decisions about more samples in certain areas, spacing of transects, or other characterization approaches.

The initial sediment transects/locations will be reviewed with USEPA prior to initiating Step II sampling. Section 6.7.5.2, the first paragraph under "Sampling Transects" has been modified to include discussions with USEPA prior to initiating Step II sampling. Initial sediment transects and locations may be adjusted based on the findings of Step I.

42. Page, 70 investigative derived waste: prior to collecting samples for disposal purposed WPS/NRT should contact the receiving landfill and obtain the list of required samples and analyses protocol.

Section 6.8 has been clarified to include contact with the landfill to verify the required analysis prior to sending waste characterization samples to the laboratory.

- 43. Table 4: Please consider adding the following parameters to be analyzed:
  - a. Surface water TSS and or turbidity should be listed in note 8 as a field parameter.
  - b. Sediment It might be useful in developing remedies to include some measures of bearing strength, in-situ porosity, or bulk density.
- 43.a. Surface water samples will be analyzed for total suspended solids (TSS) in the analytical laboratory and turbidity will be measured in the field during surface water sampling activities.
- 43.b. Field measurement of fine-grained sediment shear strength was added to Table 4. Bulk density and porosity can/will be back-calculated using specific gravity and moisture content test results, and the assumption that the sediments are saturated.



Ms. Mary Logan, USEPA April 10, 2008 Page 12

Please do not hesitate to contact Mr. Brian Bartoszek (Integrys Business Support, LLC) at 920-433-2643 if you have any questions regarding this letter or the enclosed Work Plan Revision 1. Per our earlier discussion, we are available to have a conference call regarding the revisions made to these documents in order to expedite finalization of these documents.

We look forward to your review and approval.

Sincerely,

NATURAL RESOURCE TECHNOLOGY, INC.

Julie A. Zimdars, PE Senior Engineer

Richard H. Weber, PE Managing Engineer

Encl.: RI/FS Work Plan, Revision 1 (3 hard copies, plus 2 CD's)

cc: Mr. Brian Bartoszek, IBS (w/ 1 CD)

> Ms. Annette Weissbach, WDNR (w/ 1 hard copy) Mr. Mark Thimke, Foley & Lardner (letter only)

[P:\1500\1530\Reports\Site Specific Work Plan\SSWP Rev1\1530\_RI\_FS\_Response\_to\_USEPA\_Comments\_080410.doc]



# Remedial Investigation / Feasibility Study Site Specific Work Plan

Manitowoc Former Manufactured Gas Plant Site Manitowoc, Wisconsin WIN 000509949

Revision 1 April 10, 2008

Project No: 1530



# REMEDIAL INVESTIGATION/FEASIBILITY STUDY SITE-SPECIFIC WORK PLAN

# FORMER MANITOWOC MANUFACTURED GAS PLANT SITE MANITOWOC, WISCONSIN WIN000509949

Project No: 1530

Prepared For:

Integrys Business Support, LLC 700 N. Adams Street Green Bay, WI 54307

Prepared By:

Natural Resource Technology, Inc. 23713 W. Paul Road, Suite D Pewaukee, WI 53072

> Revision 1 April 10, 2008

Julie A. Zimdars, PE

Senior Engineer

Richard H. Weber, PE Managing Engineer

# **TABLE OF CONTENTS**

1	INITO	ODLICTI	ON	1
•	1.1		e:	
	1.2	•	ves	
	1.3	•	ves	
_	-	•		
2			ROUND AND SETTING	
	2.1		escription and Current Conditions	
	2.2		story	
	2.3		us Investigation Summary	
	2.4		us Response Actions	
3	SUM		OF CURRENT SITE CHARACTERISTICS	
	3.1		pography and Drainage	
	3.2	Geolog	y and Hydrogeology	9
		3.2.1	Regional Setting	9
		3.2.2	Local Summary	10
	3.3	Climate	e	11
	3.4	Popula	tion and Land Use	13
	3.5	Cultura	al and Natural Resource Features	13
	3.6	Previou	us Investigation Findings & Current Site Status	14
		3.6.1	Soil Quality and Potential Source Areas	14
		3.6.2	Groundwater Quality	17
		3.6.3	Surface Water Sampling	21
		3.6.4	Sediment Sampling	21
		3.6.5	Sediment Quality	23
		3.6.6	Manitowoc River USACE Dredging History	24
	3.7	Contar	minants of Potential Concern (COPCs)	25
4	SITE	-SPECIF	IC CONCEPTUAL SITE MODEL SUMMARY	30
	4.1	Site Re	econnaissance	30
	4.2	Media	of Potential Concern	31
		4.2.1	Surface Soil	31
		4.2.2	Subsurface Soil	32
		4.2.3	Soil Vapor (pending subsurface soil quality)	32
		4.2.4	Groundwater	32
		4.2.5	Sediment	32
		4.2.6	Surface Water	32
	4.3	Potent	ial Exposure Pathways - Human Health	33
		4.3.1	Industrial/Commercial Land Use Scenario - Worker	33
		4.3.2	Construction Worker	
		4.3.3	Recreational Land Use Scenario - Visitor/Trespasser	35
		4.3.4	Residential Land Use Scenario	

	4.4	Potent	ial Exposure Pathways – Ecological Receptors	.36
		4.4.1	Mammals (Upland and Aquatic)	.37
		4.4.2	Birds (Upland and Aquatic)	.37
		4.4.3	Fish	.38
		4.4.4	Benthic Invertebrates (Aquatic Ecological Receptor)	.38
	4.5	Data N	eeds	.39
5	PRO.	JECT SC	OPING AND PLANNING ACTIVITIES	.40
	5.1	Project	Scoping (Task 1)	.40
	5.2	Approa	ach	41
	5.3	Project	Management Communications	.41
	5.4	Purpos	e and Data Quality Objectives Review	42
	5.5	Prelimi	nary Objectives for Remedial Action	42
	5.6	Prelimi	nary Remedial Action Alternatives	.42
	5.7	Comm	unity Relation (Task 2)	43
6	SITE	CHARA	CTERIZATION AND ASSESSMENT ACTIVITIES	.44
	6.1	Mobiliz	zation Planning	45
		6.1.1	Pre-Mobilization	45
		6.1.2	Daily Planning	45
		6.1.3	Demobilization	45
	6.2	Site S	urveying and Map Development	46
	6.3	Surfac	e Soil Sampling	46
		6.3.1	On-Property Locations	46
		6.3.2	Off-Property Locations (Winter Property)	46
		6.3.3	Sampling Methods and Abandonment	47
	6.4	Subsu	rface Soil Exploration and Sampling	. 47
		6.4.1	On-property Locations	47
		6.4.2	Off-Property Locations	48
		6.4.3	Sampling Methods and Abandonment	49
	6.5	Potent	ial Soil Vapor Intrusion Evaluation	50
		6.5.1	Soil Vapor Sampling Locations	51
		6.5.2	Sampling Methods and Abandonment	52
6.6 Groundwater Evaluation				53
		6.6.1	Existing Well Evaluation	53
		6.6.2	Monitoring Well/Piezometer Installation	53
		6.6.3	Groundwater Monitoring Well Development	56
		6.6.4	Groundwater Level Measurements	56
		6.6.5	Sampling Schedule and Parameters	57
		6.6.6	Aquifer Characterization	59
		6.6.7	Groundwater Monitoring Well Abandonment	59
		6.6.8	On-Going System Operation, Maintenance and Monitoring and Future Groundwater Monitoring	59
	6.7	Manito	owoc River Assessment	60
		6.7.1	Site Morphology	60
		6.7.2	Bathymetric Survey, Side-Scan Sonar, and Sub-Bottom Profiling	
		6.7.3	Sediment Poling	62

	6.8 6.9 6.10	6.7.5 Disposa Record	Surface Water Sampling			
	6.11	Data Ev	valuation and Tabulation for Risk Assessment81			
7	REME	EDIAL IN	VESTIGATION REPORT82			
8	FEAS		STUDY SCOPE OF WORK83			
	8.1		oment and Screening of Alternatives83			
		8.1.1	Development of Remedial Action Objectives83			
		8.1.2	Identify Areas or Volumes of Media84			
		8.1.3	Identify, Screen, and Document Remedial Technologies84			
			Assemble and Document Alternatives84			
	8.2		d Analysis of Alternatives85			
		8.2.1	Compare Alternatives against Each Other and Document the Comparison of Alternatives86			
		8.2.2	Alternatives Analysis for Institutional Controls86			
	8.3	FS Rep	ort87			
9	SCH	EDULE	89			
10	REFE	RENCES	90			
		EC				
	<u>GUR</u>	<u>E9</u>				
Fig	jure 1		Site Location Map (1530-A02)			
Fig	ure 2		Current Site Layout and Vicinity (1530-72-B09C)			
Fig	jure 3		Current Property Owner and Zoning Information (1530-72-B10C)			
Fig	gure 4		Former MGP Structure Locations (1530-72-B11C-01)			
Fig	gure 5	i	Historical Site Layout and Vicinity (1530-72-804-01)			
Fig	gure 6	i	Previous Upland Investigation Sampling Locations (1530-72-B12)			
Fig	jure 7	•	Previous Response Actions (1530-72-B13)			
Figure 8		i	Former Gas Holder Soil Data (1530-72-B05)			
Figure 9		1	MW14 Area Soil Data and Product in Soil Matrix (1530-72-B02)			
Figure 10		0	Wisconsin Central Property Soil Data (1530-72-B03)			
Fig	gure 1	1	Water Table Elevation Contours, November 28, 2005 (1530-72-B14)			
_	gure 1		Site-Specific Conceptual Site Model			
	gure 1		Proposed Soil Exploration and Sampling Locations (1530-72-B06-01)			
•	gure 1		Proposed Soil Vapor Sampling Locations (1530-72-B15C)			
-	gure 1		Proposed Well/Piezometer Locations (1530-72-B08-01)			
Fig	gure 1	6	Preliminary Schedule			

#### **TABLES**

Table 1	Groundwater Analytical Results - PVOCs and Cyanide
Table 2	Groundwater Analytical Results - PAHs
Table 3	Groundwater Elevation Summary
Table 4	Sampling and Analysis Plan Summary

#### **APPENDICES**

Appendix A: Historical Structures Maps

Appendix A1: Sanborn Maps

Appendix A2: Historical Plant Drawings

Appendix B: EDR and Other Site Vicinity Information

Appendix B1: EDR Radius Map and Report

Appendix B2: EDR Report Excerpts for Sites B6, B9 and C12

Appendix B3: Former Holmes Oil Information from WDNR BRRTS and GIS Registry Sites

Appendix C: WWES In-situ Stabilization of Coal Impacted Soils Drawings (Sheets C1

through C4, S1 and S2)

Appendix D: ISS Verification Sample Locations

Appendix E: Site Reconnaissance Field Notes, Observations and Photo Log (January

5, 2007)

Appendix F: Site-Specific Modifications to Multi-Site Documents

Appendix F1: Site-Specific Quality Assurance Project Plan

Appendix F2: Site-Specific Health and Safety Plan

Appendix F3: Site-Specific Conceptual Site Model and Risk Assessment Framework

Appendix F4: Site-Specific Field Sampling Plan

Appendix G: Additional Analytical Data

Appendix G1: May 2005 Groundwater Laboratory Analytical Report

Appendix G2: Treatment System Analytical Summary Tables

## **SHEETS**

Sheet 1	Previous Sediment Poling Positions and Sampling Locations
Sheet 2	Step I Proposed Sediment and Surface Water Sampling Locations
Sheet 3	Step II Proposed Sediment and Parent Material Sampling Locations

# **ACRONYMS**

AOC Administrative Order On Consent

ARARs Applicable or Relevant and Appropriate Requirements

bgs Below Ground Surface

BERA Baseline Ecological Risk Assessment

BIRA Baseline Risk Assessment

BTEX Benzene, Toluene, Ethylbenzene, Xylene

BTX Benzene, Toluene, and Xylene

CBSQG Consensus Based Sediment Quality Guidelines

CERCLA Comprehensive Environmental Response, Compensation, and Liability

("Superfund") Act

Commerce Wisconsin Department of Commerce
COPCs Contaminants of Potential Concern
CSM Generalized Conceptual Site Model
DGPS Differential Global Position System

DHFS Wisconsin Department of Health and Family Services

DLs Detection Limits

DNAPL Dense Non-Aqueous Phase Liquid

DQOs Data Quality Objectives

EDI Engineering & Science, Inc
EDR Environmental Data Research Inc.

ERAGS Ecological Risk Assessment Guidance For Superfund

ERP Environmental Response Program
ES NR 140 Enforcement Standard

FEMA Federal Emergency Management Administration

FSP Multi Site Field Sampling Plan
GIS Geographic Information System
GLNPO Great Lakes National Program Office
HASP Multi Site Health and Safety Plan

IC Institutional Control

ISS In-Situ Solidification/Stabilization
LAST Leaking Aboveground Storage Tank

LIF Laser-Induced Fluorescence
LNAPL Light Non-Aqueous Phase Liquid
LUST Leaking Underground Storage Tank

mg/kg Milligrams Per Kilogram
MGP Manufactured Gas Plant

MNA Monitored Natural Attenuation

MSL Mean Sea Level

NAPL Non-Aqueous Phase Liquid NCP National Contingency Plan

NRT Natural Resource Technology, Inc.

OSR Off-site Rule

O&M Operation and Maintenance

OM&M Operation, Maintenance and Monitoring
PAHs Polynuclear Aromatic Hydrocarbons
PAL NR 140 Preventive Action Limit

PCBs Polychlorinated Biphenyls

POTW Publicly Owned Treatment Works

PQLs Project Quantitation Limits

PVOCs Petroleum Volatile Organic Compounds
QA/QC Quality Assurance/Quality Control

QAPP Multi Site Quality Assurance Project Plan RAF Multi Site Risk Assessment Framework

RAO Remedial Action Objective
RI Remedial Investigation

RI/FS Remedial Investigation and Feasibility Study

RLs Reporting Limits
ROD Record of Decision

RQD Rock Quality Designation

SARA Superfund Amendments and Reauthorization Act

SIM Selected Ion Monitoring

SLERA Screening Level Ecological Risk Assessment

SSLs Soil Screening Levels

SOP Standard Operating Procedure

SOW Statement of Work
SSWP Site Specific Work Plan

SVOC Semi Volatile Organic Compounds

TBC To Be Considered

TEC Threshold Effect Concentration

TOC Total Organic Carbon UCL Upper Confidence Limit

USACE United States Army Corps of Engineers

USEPA United States Environmental Protection Agency

USFWS US Fish and Wildlife Service
USGS United States Geological Survey
UST Underground Storage Tank
UTM Universal Transverse Mercator
VOCs Volatile Organic Compounds
WAC Wisconsin Administrative Code
WAD Weak Acid Dissociable Cyanide

WDNR Wisconsin Department of Natural Resources

WF&L Wisconsin Fuel & Light Co.

WPSC Wisconsin Public Service Corporation

WWES WW Engineering & Science

# 1 INTRODUCTION

#### 1.1 Purpose

This Site-Specific Work Plan (SSWP) describes the procedures to be followed and tasks necessary to complete the Remedial Investigation and Feasibility Study (RI/FS) at the former Manitowoc Manufactured Gas Plant (MGP) facility (Figure 1), in accordance with the Administrative Order on Consent (AOC) and Statement of Work (SOW), CERCLA Docket No. V-W-06-C-847, dated May 5, 2006. The AOC and SOW addresses six of Wisconsin Public Service Corporation's (WPSC) former MGPs. Under the AOC/SOW, a generic approach to addressing the six sites is to be developed (the Multi-Site approach), which, in turn, may be modified to account for site-specific differences that may exist at a particular location.

As discussed in this SSWP and the Manitowoc Completion Report (December 2006, Natural Resource Technology, Inc. [NRT]), substantial RI and response actions were previously performed prior to WPSC's transferring the Site from the Wisconsin Department of Natural Resources (WDNR) to the United States Environmental Protection Agency (USEPA). This SSWP builds upon previous data and information, as well as reports prepared by WPSC. This SSWP was prepared in accordance with applicable federal regulations, including Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA, or "Superfund") as amended by Superfund Amendments and Reauthorization Act (SARA) and the National Contingency Plan (NCP).

The SSWP includes elements of the FS, as defined in the SOW that will be fully developed pending approval of the Multi-Site FS support documents. Although the Multi-Site support documents are not yet approved, and USEPA has not yet finished review of the Completion Report, WPSC developed this SSWP to maintain progress with respect to the former Manitowoc MGP facility. If necessary, modifications will be provided in revisions or separate documents, as appropriate.

# 1.2 Objectives

This SSWP identifies the procedures to be used for evaluating the nature and extent of MGP residuals in soil, groundwater, sediment, and surface water for use in human health and ecological risk assessments and feasibility studies. The risk assessments will determine if the Site presents a risk to human health and/or the environment. The SSWP also sets forth the process to be used to develop and evaluate remedial alternatives.

#### 1.3 Scope

The SSWP is organized as follows:

Section 2	Site Background and Setting
Section 3	Summary of Site Characteristics
Section 4	Site-Specific Conceptual Site Model Summary
Section 5	Project Scoping and Planning Activities
Section 6	Site Characterization and Assessment Activities
Section 7	Remedial Investigation Report
Section 8	Feasibility Study Scope of Work
Section 9	Schedule
Section 10	References

## 2 SITE BACKGROUND AND SETTING

For the purposes of this document, the following definitions will be used herein:

- Facility Refers to the former WPSC MGP structures and related areas (Figures 3 and 4);
- On-property Refers to the specific parcel currently owned by WPSC located at 402 North Tenth Street, Manitowoc (Figures 2 and 3); and
- Site Refers to areas where contamination related to the former MGP has been discovered through site investigation activities completed to-date and near-by areas necessary for implementation of the response action. These areas include the facility and on-property as well as portions of City Property, Chicago Street and North Eleventh Street right-of-ways, privately owned and WPSC-owned land south of Chicago Street and privately owned land west of North Eleventh Street, and an adjacent portion of the Manitowoc River containing contaminated sediments related to the former MGP. The approximate extent of the upland portion of the Site is shown on Figures 2 and 3.

# 2.1 Site Description and Current Conditions

The former Manitowoc MGP facility is located at 402 North Tenth Street, Manitowoc, Manitowoc County, Wisconsin (Figure 1). The current WPSC property (referred to as on-property) is bounded on the northwest by City-owned property and the Manitowoc River, on the north by additional WPSC-owned parcels (not included as "on-property"), on the east by North Tenth Street, on the south by Chicago Street, and on the west by North Eleventh Street (Figure 2). The property encompasses approximately 1.1 acres as shown on the property owner and zoning map (Figure 3). A multi-tenant office building occupies much of the property, which was formerly used by Wisconsin Fuel & Light Company (WF&L). Areas north, east and west of the building are covered by asphalt pavement, whereas the south side area is mostly grass. Currently, Manitowoc Food Service leases the top floor of the building for office space. The bottom floor of the building is used mainly for WPSC vehicle storage and also contains the groundwater treatment system equipment. The former MGP structures were located mostly on-property, with the addition of a former gas holder located off-property to the south (Figure 4).

The City owns property between the subject property's north property line and the river (triangular-shape property shown on Figure 3). The property located west of the subject property on the west side of Eleventh

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 April 10, 2008 Section 2 – Site Background and Setting Page 4 of 91

Street (along the river) is owned by Canadian National Railroad (formerly Wisconsin Central Railroad Ltd). To be consistent with past reports, the property will continue to be referred to as the Wisconsin Central Railroad's property. Braun Building Center Inc. is located south of Wisconsin Central Railroad's property. Braun Building appears to use Wisconsin Central Railroad's property to store lumber for their pre-fabricated building operations. The properties located south of the subject property, on the south side of Chicago Street, are owned by Tom Kitzerow Enterprises LLC (parcel on the west), 306 North Tenth Street Building LLC (parcels in middle) and Winter (parcel on the east). WPSC owns a small parcel along the south side of Chicago Street, adjacent to the Winter Property. The building on the Winter Property, where an MGP gas holder was located, is an attorney's office.

The Manitowoc River is approximately 400 feet across adjacent to the former MGP facility and is utilized as a turning basin for large cargo ships. A sheet pile wall exists adjacent to the City Property and steep banks exist on both the north and west ends of the wall. There is no obvious location to easily access the river and only a limited distance out into the river is possible for wading. At a distance of approximately 60 feet from the shoreline, water depths are known to be more than 21 feet, the project depth within the U.S. Army Corps of Engineers (USACE) navigation channel. It is difficult to accurately estimate the size of the Site within the Manitowoc River based on the historic results; therefore, data from the work outlined herein will be used to establish the size of the Site within the river. Property owner information and zoning is shown on Figure 3.

The responsible party, Site location and identification information is summarized below.

Responsible Party: Wisconsin Public Service Corporation

Contact: Mr. Brian Bartoszek (920.433,2643) 700 North Adams Street, P.O. Box 19002

Green Bay, WI 54307 9002

Site Location: T19N, R24E, Section 19

402 North Tenth Street Manitowoc, Wisconsin Manitowoc County

USEPA ID (WDNR BRRTS #) WIN000509949

(02-36-000219)

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 April 10, 2008 Section 2 – Site Background and Setting Page 5 of 91

The majority of the upland portion of the Site is covered with pavement and buildings with a slope toward the Manitowoc River. Nineteen monitoring wells and piezometers and one pumping well are located on or near the Site. The monitoring wells are located on property currently owned by WPSC, property owned by others, City Property adjacent to the river, and City right-of-way of streets to the west and south (Figure 2).

#### 2.2 Site History

Sanborn maps obtained for development of historical maps for this SSWP were from 1883 through 1966 and showed the presence of numerous former MGP related structures from the early 1900's to the 1950's (Appendix A1). Also, a 1963 historical plant drawing indicated some former MGP related structures (Appendix A2). These maps were used as source maps to update the historical map for the facility. These structures are shown on Figure 4 and include:

- Retort building with condenser and purifier;
- Water gas plant building;
- Purifying boxes; and
- Two gas holders with capacities of 100,000 cubic feet (on-property) and 300,000 cubic feet (off-property to south in location of present Winter building).

Background research for this Work Plan was supplied by Environmental Data Research Inc. (EDR). The EDR radius map and report are provided in Appendix B1. The report indicates that several aboveground storage tanks were present on the west side of North Eleventh Street on property previously owned by Shell Oil, Sinclair Refining Co., and Standard Oil (approximate locations shown on Figure 5). This property is currently owned by Canadian National/Wisconsin Central. Two leaking underground storage tanks (LUSTs) and one leaking above ground storage tank (LAST) were documented in the EDR report as the Holmes Oil site (Appendix B2); however, Canadian National/Wisconsin Central is listed as the responsible party. The investigation was closed with deed restrictions by the Wisconsin Department of Commerce (Commerce) in September of 2005.

Additional near-by impacted sites documented in the EDR report include a LUST site located south of the property at 308 North Tenth Street, and an Environmental Response Program (ERP) site also south of the

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 April 10, 2008 Section 2 – Site Background and Setting Page 6 of 91

property at the corner of North Eleventh and Buffalo Street (Appendix B2). Metz Baking Company was the responsible party for the LUST site which was closed by WDNR in August of 1996. That property is currently owned by 306 North Tenth Street Building LLC. Soo Line and Canadian National Railroads were the responsible parties for the ERP site which had reported polynuclear aromatic hydrocarbon (PAH) and volatile organic compound (VOC) impacts. This site was conditionally closed by WDNR with deed restrictions in July of 2006, and is currently owned by Canadian National/Wisconsin Central.

#### 2.3 Previous Investigation Summary

The Completion Report (December 2006, NRT) contains a full bibliography of the reports and summaries issued for the Site. Site investigation and remediation activities were previously undertaken since the late-1980s through the present. Investigations completed prior to the soil remediation activities in 1993 and 1994 focused on identifying source areas and groundwater assessment. Investigations included soil borings and groundwater sampling from monitoring wells and piezometers. WDNR supervised remediation activities that were performed in 1993 and 1994, as discussed in Section 2.4.

Additional investigation work occurred between 1995 and 1997 for the upland portion of the Site and between 2000 and 2003 for the Manitowoc River. All upland sampling locations are shown on Figure 6 and all sediment poling and sampling locations in the Manitowoc River on shown on Sheet 1. Supplemental Site investigation activities focused on the Manitowoc River, the Wisconsin Central Railroad Property, and the MGP product discovered at groundwater monitoring well MW14 located near the southwest corner of the on-property building. Groundwater remediation and monitoring is on-going and groundwater monitoring reports have been prepared on an annual basis, the last one dated October 31, 2006 (October 2006, NRT). The current conditions of the Site are summarized in Section 3.6.

# 2.4 Previous Response Actions

A number of response actions were previously performed at the Site (see Completion Report, December 2006, NRT). These previous response actions are illustrated on Figure 7 and include:

■ Excavation for Sheet Pile Retaining Wall Reconstruction. As part of implementing in-situ solidification/stabilization (ISS), the anchor system for the existing sheet pile wall was replaced. These activities included removal and segregation of the top 2 feet of overburden

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 2 – Site Background and Setting
Page 7 of 91

soil and removal of 3,051 cubic yards (4,271 tons) of contaminated soil and disposal at Ridgeview Landfill in Whitelaw, Wisconsin in June and July 1993. Drawings of the retaining wall (Sheets S1 and S2, Appendix C) indicate that the wall is constructed of sheets that are approximately 36-feet in length. The top of the wall is at approximately 585 feet and extends down to approximately 549 feet, which is near the till and/or bedrock surface as shown in the cross-sections (Sheets C3 and C4, Appendix C).

- In-situ stabilization and solidification (ISS). Approximately 13,772 cubic yards of soil was treated by ISS in 1993 and 1994 on the north, west and south sides of the on-property building, the majority of the ISS area being located on City-owned land or right-of-way. Soils were treated to reported depths of 32 to 40 feet below ground surface, ending in native sand material. As part of this activity, 4,093 cubic yards of overburden soils were required to be landfilled. This material expanded above ground during the ISS process.
- Surface Soil Removal. The top four feet of soil was excavated on the north side of the onproperty building in 1994 (most likely). No documentation of this surface soil excavation was found in the 1995 Interim Closure Report with exception of a report figure showing this 4-foot excavation, and therefore the disposition of the soil is unknown. From this 1995 map, NRT estimates that the surface area of the 4-foot excavation is 17,575 square feet, with an estimated volume of 2,600 cubic yards (3,640 tons).
- Excavation and Disposal. Soils were excavated in January 1994 in the following areas: 1) a small area located west of the storm sewer; and 2) a larger area located west and south of the on-property building and east of the storm sewer. The majority of the soils were excavated in the right-of-way of North Eleventh Street and Chicago Street. Approximately 1,410 cubic yards (1,975 tons) of coal tar impacted soils were removed and disposed at Ridgeview Landfill. The final depth of the excavation was based on the depth to groundwater, ranging from 10 feet to 12 feet below ground surface.
- Backfilling and Surface Restoration. The excavation performed west and south of the onproperty building, and presumably the surface soil excavation performed north of the building, were backfilled with clean imported fill. Following this, asphalt or concrete pavement was restored in all areas that were disturbed, including ISS and excavation.
- Groundwater Remediation. A single groundwater extraction well (PW-1) and pre-treatment system (filtration followed by granular activated carbon) were installed in 1997 to address residual product and MGP residuals outside of the stabilized area (e.g., well MW14 area). The well is located in the North Eleventh Street right-of-way. The system discharges to the City of Manitowoc wastewater treatment plant at flow rates ranging from 4 to 18 gallons per minute (gpm).

# 3 SUMMARY OF CURRENT SITE CHARACTERISTICS

## 3.1 Site Topography and Drainage

The Site is located along the southern bank of the Manitowoc River and contains topographic features related to the floodplains and bluffs of the river (Figures 3 and 4). River stage is approximately 580 feet above mean sea level (MSL) at the Site. The banks of the river in the vicinity of the Site are steep woody slopes and/or sheet pile walls. Areas within the 100 year floodplain defined by the Federal Emergency Management Agency (FEMA) are located adjacent to the river banks (Figure 3), including:

- A portion of the triangular shaped City parking lot located along the river and a portion of the property located south of the City lot;
- The northern end of North Eleventh Street approximately 60 feet south of the sheet pile wall; and
- The private road west of North Eleventh Street located on Wisconsin Central Railroad Property between the river and the storage buildings on Braun Building Property.

Generally, the floodplain is flat with a mild slope toward the Manitowoc River. Ground surface elevation of the floodplain is approximately 590 feet above sea level.

Slopes from the bluff down to the floodplain are found northeast of the parking lot between the on-property building and the fence on top of the bluff, and from the intersection of North Tenth and Chicago Streets down to the river along Chicago and North Eleventh Streets (Figure 4). On-property, the ground slopes steeply from the top of the bluff down to the northeast corner of the parking lot. Off-property, Chicago Street and North Eleventh Street slopes moderately from the top of the bluff down to the river along the southern and western edges of the property. The on-property building that borders the parking lot on the east and south sides was constructed along the edge of the bluff so the basement floor is at the same elevation as the parking lot (100 year floodplain), and the first floor is at the same elevation as the top of the bluff.

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1

April 10, 2008

Section 3 – Summary of Current Site Characteristics Page 9 of 91

The remainder of the Site, including the eastern portion on-property and within Chicago Street and the Winter Property is located on top of the bluff. The bluff is generally flat with ground surface elevations of approximately 600 feet above sea level.

Surface water from the floodplain areas slopes off the bluff described above and flows over land into the river. Curb-side storm inlets collect runoff from paved surfaces, roads, and grass areas located on top of the bluff. Storm water from the bluff enters the 12-inch storm sewer in Chicago Street which flows west into a 15-inch storm sewer located in North Eleventh Street. From there, the water flows north towards the river and discharges from a storm sewer pipe that passes through the sheet pile wall. There are no wetlands present in the vicinity of the Site as further documented in Appendix E.

## 3.2 Geology and Hydrogeology

The information provided below is based on previous investigations, and it includes results from soil borings, test pits, groundwater monitoring wells, etc. This summary is an overview for purposes of providing reference information in this SSWP. Details are set forth in the Completion Report (December 2006, NRT) and other previously referenced Site documents.

#### 3.2.1 Regional Setting

Manitowoc is located on the western shore of Lake Michigan and lies within the Wisconsin-Lake Michigan basin. The Wisconsin-Lake Michigan basin is a 3,600 square mile drainage area that lies along eastern Wisconsin and borders the western shore of Lake Michigan (Skinner and Borman, 1973). The near-surface geology of the Manitowoc area is characterized by poorly permeable glacial lake deposits of sand, silt, and clay that range up to 150 feet thick. Stratified sand and gravel alluvial deposits also occur along the Manitowoc River.

Silurian dolomite bedrock underlies the glacial soils around Manitowoc, and is present at depths between 50 and 200 feet below ground surface (bgs). In the Manitowoc area, the Silurian bedrock is the top of a sequence of layered sedimentary rocks dating from the Cambrian to the Silurian which overlie crystalline pre-Cambrian rocks. Regionally, this sequence of sedimentary rocks slopes to the southeast.

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 3 – Summary of Current Site Characteristics
Page 10 of 91

The Wisconsin-Lake Michigan basin contains three main aquifers, the unlithified sand and gravel aquifer, the Niagara dolomite aquifer, and the Cambrian sandstone aquifer. The sand and gravel glacial alluvium in the basin is a significant source of water. These deposits may be inter-layered with or covered by less permeable overburden. Thick accumulations of sand and gravel have produced as much as 1,200 gpm inland; while, collector (Ranney) wells in Manitowoc that induce recharge from Lake Michigan have produced as much as 5,500 gpm (Skinner and Borman, 1973). Generally, groundwater flow in the sand and gravel is toward rivers and streams that eventually discharge into Lake Michigan. Recharge is local from precipitation and surface water bodies.

The Niagara aquifer underlies the sand and gravel aquifer and is the most widely used source of groundwater. Water moves through cracks, crevices, and fractures within the dolomite bedrock. The distribution of those openings is not uniform throughout the formation and therefore well yields from this formation are not predictable. Most wells produce at least 10 gpm and some high capacity wells have produced up to 1,200 gpm (Skinner and Borman, 1973). Many parts of the Niagara aquifer are artesian, due in part to the glacial clay till overburden present in most locations. Generally, groundwater flow in the Niagara is toward Lake Michigan. Recharge to the Niagara is local, and paths of movement are short.

The Cambrian sandstone aquifer underlies the entire Wisconsin-Lake Michigan basin and includes Ordovician and Cambrian units between the Maquoketa shale and Pre-Cambrian rocks. Where present, the Maquoketa shale is a regional aquatard that isolates the Niagara and Cambrian sandstone aquifers. The sandstone aquifer is most extensively used in the southern portions of the basin including the Milwaukee area. Yields from this aquifer vary with the thickness of the sandstone penetrated, with as much as 1,500 gpm being produced in a well near Milwaukee (Skinner and Borman, 1973). Generally, groundwater flow in the sandstone is toward Lake Michigan. Most recharge to the sandstone is by lateral movement of water from west of the basin, although a small amount of water moves down through the Maquoketa shale.

#### 3.2.2 Local Summary

Soil stratigraphy at the former Manitowoc MGP Site consists of three to 10 feet of miscellaneous sand, silt and clay fill material overlying glacial deposits of sand with varying amounts of gravel, silt and clay. The glacial deposits along the western portion of the property generally consist of sand and silt, while the

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 April 10, 2008

Section 3 – Summary of Current Site Characteristics Page 11 of 91

deposits on the eastern portion of the property consist mostly of sand and gravel. Unlithified materials extend to at least 40 feet bgs, and bedrock is estimated to be approximately 50 feet bgs depending on surface elevation.

None of the Site soil borings or wells penetrated into bedrock. The top of bedrock and/or pieces of bedrock have been noted on a few of the boring logs in the Completion Report (December 2006, NRT). Cross-sections of the ISS area (Sheets C3 and C4 of Appendix C) show the bedrock surface is flat and located approximately 40 feet bgs adjacent to the river.

Depth to groundwater measurements across the Site are variable (between five and 22 feet bgs) due to changes in topography discussed above. Groundwater measurements indicate that shallow groundwater horizontal gradients are relatively flat (around 0.003 ft/ft) and flow is generally north towards the Manitowoc River (Figure 11). The Manitowoc River is a gaining stream near Lake Michigan that receives groundwater and surface water from the Manitowoc area and discharges into the lake. Shallow groundwater from the central and western portions of the Site currently are captured within the cone of depression created when groundwater pumping well (PW-1) is active.

Currently there are no nested wells with piezometers for the evaluation of groundwater vertical gradients. Additionally, there are no wells monitoring groundwater in the bedrock to determine local bedrock flow.

#### 3.3 Climate

The climate in the vicinity of Manitowoc is typically continental with some modification by Lake Michigan. The moderating effect of Lake Michigan is well illustrated by the fact that the growing season of 140 to 150 days along the east-central coastal area is of the same duration as in the southwestern Wisconsin valleys. The average date of last spring freeze is early May and the first autumn freezes occur in mid-October along the Lake Michigan coastline. Most of the streams and lakes in the area are ice-

covered from late November to late March, and snow covers the ground for much of the same period. Flooding is most frequent and serious during April.<sup>1</sup>

Historic temperature and precipitation data for Manitowoc is summarized in the table below<sup>2</sup>. Average monthly temperatures range from about 18°F in January to about 70°F in July. The high and low monthly averages range by approximately  $\pm 10^{\circ}$ F from the monthly mean. Almost 60 percent of the total annual rainfall generally occurs between May and October. Over 90 percent of the total annual snowfall occurs between December and March. Overall, the mean average temperature for the area is approximately 45°F and over 30 total inches of precipitation (both rainfall and snow accumulation) is received.

	Monthly Temperature Ranges (°F)			Monthly Averages (in.)	
Month	High	Low	Mean	Precipitation	Snowfall
January	26.5	10.8	18.7	1.83	6.3
February	30.4	15.3	22.9	1.24	5.4
March	39.9	24.4	32.2	1.94	4
April	52.1	34.1	43.1	2.85	0.5
May	64.9	44.3	54.6	2.79	0
June	74.6	53.6	64.1	3.26	0
July	79.6	60.1	69.9	3.44	0
August	77.6	59.3	68.5	3.73	0
September	69.8	51.6	60.7	3.1	0
October	57.4	40.8	49.1	2.25	0
November	43.5	29.2	36.4	2.3	1.5
December	31.3	16.7	24	1.76	4.3
Annual Precipitation Totals				30.49	22

1530-SSWP Rev-1

NATURAL

RESOURCE

TECHNOLOGY

<sup>&</sup>lt;sup>1</sup> Climactic information from Wisconsin State Climatology Office website, http://www.aos.wisc.edu/%7Esco/state.html

<sup>&</sup>lt;sup>2</sup> Historic data from the Midwestern Regional Climate Center (MRCC) website, http://mcc.sws.uiuc.edu/climate\_midwest/mwclimate\_data\_summaries.htm#

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 3 – Summary of Current Site Characteristics
Page 13 of 91

#### 3.4 Population and Land Use

The population of the City of Manitowoc is approximately 35,000 people, based on the 2005 U.S. census and current projection for 2010. The City of Manitowoc does not track land use outside of property zoning permits. The land around the former MGP facility has been zoned for business, commercial and industrial use (Figure 3). It is important to note that single and multi-family dwellings may be located within the business zones, but not the commercial or industrial zones. According to the Zoning Map for Manitowoc, portions of the Site are located within the business and industrial zones. The on-property former MGP structures and the land to the north and east is Zoned B-3 "Business (General)". It is known that a residence exists on the first parcel north of the WPSC parking lot. The off-property land to the south and west where the 300,000 cubic foot gas holder was located (Winter Property) and the Wisconsin Central Railroad Property are Zoned I-2 "Industrial (Heavy)". This zoning information was obtained through the City of Manitowoc interactive Geographic Information System (GIS) website<sup>3</sup>.

The City of Manitowoc receives municipal water from intake pipes located 2-miles off-shore in Lake Michigan. The City also maintains an underground "Ranney Well", known as Collector C located just south of Silver Creek Park. Patented by the Ranney Corporation, these wells utilize horizontal shafts, like the spokes of a wheel, to increase collection capacities. Collector C was constructed and put into service in 1944. The Ranney Well is a standby well located approximately 3 miles south of the Site and by design induces recharge from Lake Michigan to supply the well. Site conditions have not affected the municipal water supply because the City uses Lake Michigan water either directly or indirectly to meet demands.

#### 3.5 Cultural and Natural Resource Features

An inquiry was made by WPSC to the United States Fish and Wildlife Service (USFWS) regarding potential endangered or threatened species or critical habitat present in the vicinity of the Site. USFWS

1530-SSWP Rev-1

NATURAL
RESOURCE
TECHNOLOGY

<sup>&</sup>lt;sup>3</sup> The City of Manitowoc Zoning Map was accessed using the city GIS website, http://webmap.manitowoc.org/website/PASystem/gisportal.htm

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 3 – Summary of Current Site Characteristics
Page 14 of 91

indicated that a threatened fish species (Greater Redhorse) was identified as being located in this section and within the Manitowoc River. During preparations for sediment investigation and remediation, the local fisheries biologist will be contacted for further information. The spawning period for this fish species is between May and June.

A similar review of the state Historic Preservation database indicates the presence of Site MN-0331. This site is described as a campsite/village where a copper knife was found on or near the former MGP. As such, further archaeological survey work may be required to determine if the Site has any integrity. However, the severity of soil disturbance documented at the Site over the last 50 years suggests that the Site does not have any integrity; and therefore, additional survey work will likely not be required. If it is determined that additional archaeological work is required, it must be conducted in unfrozen conditions.

## 3.6 Previous Investigation Findings & Current Site Status

This section summarizes the current Site status including the extent and magnitude of MGP residuals.

#### 3.6.1 Soil Quality and Potential Source Areas

The Completion Report (December 2006, NRT) identified remaining potential upland areas of concern related to soil quality including:

- On-property areas including the former 100,000 cubic foot gas holder and the source area located at the southwest corner of the building near the former condenser (MW14 area) (Figure 4);
- Wisconsin Central Railroad property located to the west of the former MGP facility; and
- Off-property gas holder located to the south of the former MGP facility on the Winter Property.

Residual benzene and naphthalene concentrations in soil in these three areas are shown on Figures 8 through 10. Other potential source areas that require further investigation have been identified on-property including the former retort building and purifier, the former water gas plant building, and the purifier boxes. These areas will be included with the discussions of the on-property potential source areas below.

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 3 – Summary of Current Site Characteristics
Page 15 of 91

#### 3.6.1.1 On-Property Potential Source Areas

The remaining on-property potential source areas include the former MGP structures (Figure 6). These structures have limited soil boring information and require further investigation to assess if response actions are warranted to manage the potential risk to human health and the environment as summarized below:

On-property Gas Holder – One soil boring (SB3) was previously performed on the south side of the current building inside the former gas holder. The boring identified coal tar impacts at the base of the holder at a depth of 16 to 17 feet bgs in this location. Concentrations of benzene and naphthalene in soil at this depth interval were identified to be 32 mg/kg and 730 mg/kg, respectively, as shown on Figure 8. The bottom of the holder was identified at 17 feet bgs.

<u>Retorts</u> – One soil boring (SB15) was previously performed on the north side of the current building on the north end of the retorts area. The boring identified coal tar impacts (approximately 0.3 feet in thickness) just above the suspected retort foundation at 10 feet bgs as shown on Figure 9. The boring ended with refusal at 10 feet bgs and no soil samples were collected.

Condenser – One soil boring (SB58) was previously performed on the south side of the current building in the former condenser location to a depth of 35 feet bgs. A soil sample was collected from 13 to 15 feet bgs which indicated a non-detectable benzene concentration and 3,200 mg/kg of naphthalene as shown on Figure 9. As indicated in past reports documenting the previous ISS and excavation activities, a tank was identified 3 to 6 feet bgs in the former condenser area. An electromagnetic survey indicated a metal anomaly in this same area, likely near boring SB58. As documented, the western half of the tank was encapsulated by ISS. No documentation was found to indicate the tank or tank contents, suspected to be coal tar product, was removed. This tank may be cause of the product found at MW14.

<u>Purifier</u> – One soil boring (SB4) was performed on the south side of the current building in the area of the former purifier to a depth of 21.5 feet bgs. A soil sample was collected from 7.5 to 9 feet bgs which indicated a non-detectable benzene concentration and 0.5 mg/kg of naphthalene as shown on Figures 8 and 9. No evidence of purifier waste was indicated in the boring log.

<u>Water Gas Plant Building</u> – No soil borings have been completed within the footprint of the former water gas plant.

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 3 – Summary of Current Site Characteristics
Page 16 of 91

<u>Purifier Boxes</u> – One soil boring (SB2) was performed on the south side of the current building in the area of the former purifier boxes to a depth of 21.5 feet bgs. A soil sample was collected from 20 to 21.5 feet bgs which indicated non-detectable concentrations of benzene and naphthalene as shown on Figure 8. No evidence of purifier waste was indicated in the boring log.

#### 3.6.1.2 Wisconsin Central Railroad Property

No former MGP structures are known to have been present on Wisconsin Central Railroad Property. However, due to suspected off-site migration of coal tar contamination onto this property, several borings and wells were completed in 1995 including wells MW15T and MW16T and borings SB95-1, SB95-2, SB95-3, SB95-4, and SB95-6 (Figure 6). Residual benzene and naphthalene concentrations in soil on this property are shown on Figure 10. Only one soil sample from SB95-3 collected at 3 to 5 feet bgs indicated PAH and carbazole impacts, including 19 mg/kg naphthalene. The boring logs for all SB95 borings indicated the presence of coal and/or cinders in the shallow soils, which may be the cause of the detectable PAH concentrations at SB95-3 since no coal tar odors were noted.

As mentioned previously, two LUST sites and one LAST site existed in the locations of Sinclair Refining Co., Shell Oil Co., and Standard Oil Co. (all collectively known as Former Holmes Oil). Although the site was closed in September 2005, residual soil and groundwater petroleum impacts exist in the approximate areas shown on Figure 5. Information on the residual soil and groundwater concentrations from this site are included Appendix B3. Residual naphthalene concentrations in shallow soil range from non-detectable to 16.8 mg/kg near Eleventh Street. A residual petroleum impacted groundwater plume also exists. Groundwater flow beneath this site appears to have been influenced by the start-up of the pumping well PW-1 in November 1997 (refer to flow maps in Appendix B3). The November 1997 flow map for the Holmes site indicates groundwater flow to the west. Subsequent flow maps (January 1998 and April 2004) indicate a substantial flow to the northeast toward the pumping well. Further investigation of this property will include groundwater quality assessment, with subsurface soil sampling in an attempt to determine the source of the prior PAH concentrations.

#### 3.6.1.3 Winter Property

The off-property gas holder was located on the Winter Property (Figure 6). Two wells and one soil boring have been completed on the property including MW01, MW06 and SB1. Residual benzene and

naphthalene concentrations in soil on this property are shown on Figure 8. No soil samples were collected from MW01 or MW06 and one soil sample was collected from SB1 at 7 to 7.5 feet bgs located at the base of the holder. Concentrations of benzene and naphthalene in soil at this depth interval were identified to be 9 mg/kg and 1,700 mg/kg, respectively. The bottom of the holder was identified at 7.8 feet bgs. Further investigation of the surface and subsurface soils are needed to assess if response actions are warranted to manage the potential risk to human health and the environment.

#### 3.6.2 Groundwater Quality

The Completion Report (December 2006, NRT) identified remaining potential upland areas of concern related to groundwater quality including:

- Shallow groundwater quality assessment to the west (Wisconsin Central Railroad Property);
- Supplemental bedrock investigation; and
- Continued groundwater monitoring.

Also, we have identified as an additional area of concern, the groundwater quality beneath the solidified soils. The ISS remediation was designed to treat subsurface MGP contamination to a depth of 32 feet along the river as shown on Figure 7. The base of the ISS did not extend to bedrock, but rather ended in native sand materials above a possible glacial till layer (refer to sheets C3 and C4, Appendix C). Thirteen verification sample locations were performed through the area of the proposed 32-foot depth ISS material as shown in Appendix D (VS-1 through VS-8 and VS-12 through VS-16). Multiple borings were performed in some locations. Based on the sixteen boring logs (VS-2, VS-3 and VS-4 location logs not available), the actual ISS depth in the area along the river typically ranged from 30 to 32 feet, with two logs indicating ISS depths of 25 feet and 28 feet. Investigation of the groundwater quality of the sand unit below the ISS material will be performed to determine the extent of groundwater contamination near the river (downgradient direction).

#### 3.6.2.1 Groundwater Monitoring

Groundwater monitoring began in 1988, when five of the Site monitoring wells were installed (MW01 through MW05). Wells were added in 1991 (MW06), 1994 (MW07 through MW14), 1995 (MW15T

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 3 – Summary of Current Site Characteristics
Page 18 of 91

through MW18T), and 1997 (MW12D, MW19T through MW21T). Currently, there are nineteen wells and piezometers on or near the Site, as three wells were abandoned (MW03, MW04 and MW11) (Figure 2).

Wells screen lengths range from 3 to 15 feet, with screened intervals at varying depths. The table below lists the wells that serve as water table wells and those that serve as piezometers, in addition to date constructed, well depth based on the well construction log, well depth based on 2007 measurement, and screen length. Only one well nest (MW12/12D) exists for estimating vertical gradient; however, this well nest is located within 10 feet of the pumping well. As noted from the table, wells MW01, MW06 and MW19T have more than one foot of discrepancy between the well construction log depth and the 2007 measured depth. These depth discrepancies will be evaluated during the RI work.

		<b>Well Construction Log</b>	Estimated Well Depth	
	Construction	Well Depth (from	from 2007 Measurement	Screen
Well ID	Date	ground surface, ft)	(from ground surface, ft)	Length (ft)
Water Tak	ole Wells			
MW06	9/30/1991	31	29.4	10
MW07	8/31/1994	11	12.0 *	5
80WM	9/2/1994	11	12.1 *	5
MW09	9/1/1994	11	12.5 *	5
MW 12	9/6/1994	14	14.6 *	5
MW13	9/6/1994	13	15.0 *	5
MW 14	9/7/1994	18	nm	5
MW15T	5/15/1995	20	nm	15
MW16T	5/16/1995	17 <i>.</i> 5	nm	15
MW17T	5/17/1995	24.5	24.0	15
MW18T	5/17/1995	27	26.5	15
Piezomete	ers			
MW01	8/23/1988	24	21.3	3
MW02	8/23/1988	24	24.8 *	3
MW05	8/23/1988	29.5	29.4	3
MW10	9/1/1994	15	15.8 *	5
MW12D	4/2/1997	35	34.9	15
MW19T	4/1/1997	40	28.3	15
MW20T	3/31/1997	40	39.0	15
MW21T	4/2/1997	39.8	39.1	15
Extraction				
PW-1	10/22/1997	35	nm	15

nm - not measured

Currently, groundwater samples are collected and analyzed for petroleum volatile organic compounds (PVOCs) and PAHs on an annual basis, typically in May. Cyanide analysis was discontinued in 2004, as allowed by WDNR, because of detections below the Wisconsin Administrative Code (WAC) NR 140 Preventive Action Limit (PAL). A discussion of contaminants of potential concern (COPCs) and a brief summary of the various compounds that have been analyzed over time are discussed in Section 3.7. Groundwater sampling results from April 2000 through May 2006 are summarized on Tables 1 and 2 for PVOCs/cyanide and PAHs, respectively.

<sup>\* =</sup> Appears the ground surface was raised after well construction

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 3 – Summary of Current Site Characteristics
Page 20 of 91

Groundwater elevation is measured in all wells semi-annually to evaluate groundwater flow (typically in May and November) (Table 3). Groundwater elevation contours constructed prior to remediation suggest groundwater beneath the Site flowed toward the river and the horizontal gradient was relatively flat, ranging from 0.003 ft/ft in August 1988 to 0.0007 ft/ft in October 1991.

Groundwater elevations measured since 2001 suggest groundwater flow at the Site is currently influenced by the ISS soils and the drawdown effects of the extraction well (PW-1), which extracts groundwater at a rate of approximately 10 gpm and creates a localized cone of depression. Groundwater flow in the northern portion of the Site, on either side of the ISS soils, is toward the Manitowoc River, while flow in the central and western portions of the Site is generally toward PW-1. Figure 11 illustrates the current Site groundwater flow from the November 28, 2005 water level measurements.

#### 3.6.2.2 Groundwater Remediation System

A groundwater gradient control system, consisting of a pumping well (PW-1) located at the western boundary of the Eleventh Street right-of-way, a bag filter and a granular activated carbon adsorption pretreatment system, was installed at the Site in October 1997. Start-up of this system occurred in November 1997 and has been operating since that time. The system has been operating, for the most part, at approximately 10 gpm or higher since July 2001. The flow rate gradually decreased after about September 2005, likely due to a measured increase of pressure in the carbon vessels that may be a result of iron bacteria. However, groundwater gradient control was maintained based on the November 28, 2005 water levels and sewer discharge criteria are still being met.

Well MW14 (installed near boring SB53) contains Dense Non-Aqueous Phase Liquid (DNAPL) free product. A small amount of free product (less than one-half gallon) continues to be bailed from MW14 during the semi-annual monitoring visits. Collected free product is temporarily stored in a labeled 55-gallon drum located inside the building near the groundwater pretreatment system, until it is eventually disposed at a suitably licensed disposal facility.

1530-SSWP Rev-1

# 3.6.3 Surface Water Sampling

WDNR collected surface water samples in 1989 and 2003 from an area along the Manitowoc River where an oil sheen appeared to be rising from below the surface of the water near the former MGP. The 1989 sample indicated results for benzene, toluene and, xylene (BTX) as well as ethyl-benzene, naphthalene, cyanide (total and amenable), and oil & grease below their reported detection limits. The 2003 sample indicated a detection of possible creosote oil components from the oil sheen observance area. Two other samples collected in 2003 from 100 yards upstream and 100 yards downstream of the oil sheen observance area did not indicate the presence of petroleum compounds.

NRT and WPSC recorded oil sheen observations from five different locations along the Manitowoc River adjacent to, upstream and downstream of the former MGP from November 2003 to July 2004. Oil sheen was often observed on the river immediately adjacent to the Site. Exceptions were over the winter months during ice cover and during periodic site visits a few other times of the year. It was concluded that the possibility remains that the river oil sheen observations adjacent to the former MGP were related to coal tar residuals in the sediments documented in the NRT (October 2003b) Phase I Sediment Sampling Report.

In November 2004, WDNR sent WPSC a Public Health Consultation letter to address the presence of oil sheens in the vicinity of the former MGP. WDNR compared the NRT Phase I sediment sampling results to some of the WDNR Consensus-Based Sediment Quality Guidelines (CBSQG) (December 2003). Based on that comparison, a Wisconsin Statute 292.11 "Responsible Party" letter was issued stating that some kind of interim action needed to take place in accordance with the requirements of NR 708.11 W.A.C. because the hydrocarbon sheen is a potential health hazard, and that hazard will continue as long as the contaminant mass remains. As a result of the potential coal tar release to the environment, an institutional control (IC) was placed by WPSC in 2005 in the form of 10 warning signs along the railing above the sheet pile wall between the former MGP and the Manitowoc River.

#### 3.6.4 Sediment Sampling

The locations and analytical results for PAHs, BTX, polychlorinated biphenyls (PCBs), and cyanide of previously collected Manitowoc River sediment data are summarized on Sheet 1.

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 3 – Summary of Current Site Characteristics
Page 22 of 91

In September 1990, the WDNR collected four petite Ponar® grab samples from the Manitowoc River adjacent to the former MGP. The sediment surface samples were collected adjacent to the sheet piling, and 20 feet, 50 feet, and 120 feet from shore; however, the exact sample locations within the river are not known. Samples collected from 20 feet (M2) and 50 feet (M1) from shore indicated the presence of benzene, toluene, ethylbenzene and xylenes (BTEX) compounds and PCB-1254.

WW Engineering & Science (WWES) performed sediment sampling in 1991 using an offshore drill rig (for borings SB21 through SB35, SB41, and SB42) and a Wildco sediment corer (for locations SD01 through SD06). Core samples collected from the drill rig ranged in depth from 4-14 feet below sediment surface, while the Wildco sediment corer penetrated 30 inches or less. Samples SB21 through SB35 were analyzed for PAHs, oil & grease, VOCs, total and amenable cyanide, and metals (lead, selenium, sulfate, and zinc). Samples SB41 and SB42 were analyzed for additional parameters related to leachate analysis.

The following observations were noted during review of the WWES analysis results:

- Total PAHs ranged from below the detection limit to 10,860 mg/kg in core samples;
- The sample locations with sediment PAHs above 450 mg/kg were generally near shore, adjacent to the former MGP;
- Benzene concentrations ranged from below the detection limit to 32,000 mg/kg in core samples; levels of BTEX and benzo(a)pyrene were also detected;
- Lead, zinc, total cyanide and oil & grease were also detected in core samples;
- Where encountered, MGP residuals were generally reported in the upper 6 feet of sediments; and
- Impacted soils were found below soft sediment in the river near the former MGP.

During June 2000, USEPA's Great Lakes National Program Office (GLNPO) and the U.S. Army Corps of Engineers (USACE) collected vibrocores and Ponar® grab samples for a screening level sediment survey on the Manitowoc River. Several of the sampling stations were in the vicinity of the former MGP. Eleven vibrocores were extended to approximately 50 inches below river bottom, while 12 Ponar® grab samples were from the top 6 to 8 inches of sediment. GLNPO screened for PAHs, oil & grease, pesticides, PCBs, VOCs, total organic carbon (TOC), total cyanide, ammonia, and metals (arsenic, cadmium, chromium, copper, lead, mercury, nickel, silver, and zinc). Laboratory toxicity tests (using

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 3 – Summary of Current Site Characteristics
Page 23 of 91

Hyallela azteca and Chironomus tentans) were also conducted on grab samples. Based upon the sediment survey, GLNPO had the following conclusions:

- PAH concentrations in the sediments in the vicinity of the former MGP are elevated and potentially present an ecological and/or human health risk;
- PAHs and oil & grease are the primary contaminants of concern identified in the sediments;
- Metals and PCBs are not present in the sediments at levels that present a major ecological and/or human heath risk; and
- Historical data along with the results of the June 2000 assessment indicate a potential ongoing source of contamination to the sediments of the turning basin, potentially from contaminated soil/groundwater related to the former MGP.

In May 2003, NRT conducted a sediment investigation of the Manitowoc River sediments using Ponar® grab samples and soft sediment poling observations. Poling was performed on seven transects across the river and two transects parallel to shore, at 43 locations. A petite Ponar® was used to sample the upper 4 to 6 inches of the river bottom in some poling locations. Grab samples were taken in areas where odor and/or sheen were noted during poling, and in areas to aid in delineating the extent of surficial sediment impacts. Grab samples were analyzed for BTEX, PAHs, metals (including arsenic, cadmium, chromium, copper, lead, mercury, silver, and zinc), total cyanide, PCBs, ammonia, and total organic carbon.

Grab samples confirmed BTEX and PAH impacts. Soft sediment thicknesses along the 2003 poling transects ranged from 2 inches to 7 feet 10 inches. The approximate extent of MGP impacts (coal tar or sheen) based on poling data extend from the upstream edge of the former MGP to approximately 280 feet downstream of Eleventh Street, and approximately 130 feet out from shore (Sheet 1).

## 3.6.5 Sediment Quality

The Completion Report (December 2006, NRT) identified remaining potential areas of concern related to sediment quality including:

■ Refinement is needed on the current aerial extent of contamination and definition is needed on the profile of the contaminated sediments; and

■ Further characterization may involve a risk assessment to be performed in accordance with the RI/FS work planning process.

Also, we have identified as an additional area of concern, the quality of unlithified soils that lie beneath the soft sediments of the Manitowoc River near the former MGP. Further review of the WWES boring logs and cross-sections in the river sediments indicate that elevated levels of BTEX and PAHs were found in sandy material that required 50 or more blows per foot for collection. Therefore, investigation of the river sediments will include the parent material beneath the soft river sediments.

## 3.6.6 Manitowoc River USACE Dredging History

The USACE maintains the Manitowoc river channel from the harbor entrance upstream to the Burger Boat Company at USACE river station 191+56. This is upstream of the former MGP site, which is at approximately USACE river station 156+50. The USACE maintains a project depth of 21 feet in the vicinity of the former MGP, and this project depth extends from the harbor river mouth upstream to river station 185+00. Upstream of this location, the USACE project depth was 12 feet, but the Water Resources Development Act of 2007 authorized a change in project depth from 12 feet to 18 feet. The entire channel is generally surveyed bi-annually by the USACE and dredging of the river is performed as needed (if USACE funds are available) to maintain the project depth.

Dredging events that have occurred in the Manitowoc River are summarized in the Annual Dredging Report/Contract Dredging Report for the Manitowoc River supplied by the USACE. Review of this report indicates that the latest dredging effort within the channel was performed in June-July 2007 and was mostly upstream of station 178+00 (upstream of the MGP site), and a limited area in the harbor. The report also indicates that the river channel in the vicinity of the former MGP was most recently dredged in 1995 and 1991. The dredging report does not fully describe which portions of the channel were dredged during events prior to 1991. At this time, we are unaware of further dredging events planned for the Manitowoc River, but it is presumed the USACE will dredge upstream of station 185+00 as soon as funds are available.

Dredged material from the river channel has been reportedly placed within the Manitowoc Confined Dredging Disposal Area (CDF) since 1976. With dredged material placed in the CDF, it is assumed that there is little or no potential for release, re-suspension, or re-deposition of probable contaminants within

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 3 – Summary of Current Site Characteristics
Page 25 of 91

the CDF to the Manitowoc harbor or other portions of the river. Prior to 1976, it is unknown how much material was dredged from the vicinity of the former MGP or how dredged materials were handled.

It is assumed that the river channel in the vicinity of the former MGP will require periodic maintenance dredging by the USACE in the future. Potential site remedies to be evaluated during the FS will consider the present operational depth of the channel.

# 3.7 Contaminants of Potential Concern (COPCs)

Based on the Generalized Conceptual Site Model (CSM) and the Multi-Site Risk Assessment Framework (RAF), the general COPCs are considered to be PAHs, PVOCs, phenols (2,4-dimethylphenol, 2-methylphenol, 4-methylphenol, and phenol), and inorganics (aluminum, antimony, arsenic, barium, cadmium, chromium, copper, cyanide, iron, lead, manganese, mercury, nickel, selenium, silver, vanadium, and zinc).

The following table summarizes Site COPCs for each media to be evaluated. A site-specific summary of the sampling and analysis plan, presented generically in the Multi-Site Quality Assurance Project Plan (QAPP) and Multi-Site Field Sampling Plan (FSP) is provided on Table 4. Table 4 also includes analytical data needs to support the FS.

Media	COPCs
Soil	PVOCs, PAHs, cyanide, lead and vanadium
Groundwater	PVOCs, PAHs; and aluminum, iron, manganese, and vanadium (metals - minimum one round) and available cyanide (minimum one round)
Soil Vapor (if determined necessary)	BTEX and Naphthalene
Sediment	PVOCs, PAHs, phenols, cyanide, aluminum, antimony, barium, copper, iron, lead, manganese, nickel, selenium, silver, vanadium, and zinc
Surface Water	PVOCs, PAHs, phenols, cyanide, aluminum, antimony, arsenic, barium, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel, selenium, silver, vanadium, and zinc

Environmental samples were collected as part of the Site Investigation by EDI Engineering & Science (EDI) in 1988; during additional investigation, remedial planning, documentation and post-remedial groundwater monitoring by WWES/ Earth Tech in 1991 through 1994; during post-remedial groundwater monitoring and/or sediment sampling by Horizon Environmental (1998-2001), GLNPO (2000), and NRT (2002-present). A summary of previous sample media and chemical analytes follows:

Phase of Work/Report	Soil	Groundwater	Sediment
	VOCs, base/neutrals (B/N),		
	metals*, total and amenable	VOCs, B/N, metals*,	
EDI 1988 SI	cyanide (T+A Cn)	T+A Cn, sulfate	N/A
	VOCs, PAHs, lead (Pb),		
	selenium (Se), Zinc (Zn),	VOCs, B/N, Pb, Se,	VOCs, PAHs, Pb,
	T+A Cn, sulfate, grease &	Zn, T+A Cn, sulfate,	Se, Zn, T+A Cn,
WWES 1991 SI	oil	grease & oil	sulfate, grease & oil
	VOCs, Semi-volatile		
	organic compounds		VOCs, SVOCs,
WWES 1993 Pilot Test	(SVOCs), metals*, T+A		metals*, T+A Cn,
Report	Cn, sulfate	N/A	sulfate
WWES April 1993			
Sampling, Work Plan for	VOCs, PAHs, metals*,		
ISS	T+A Cn	N/A	N/A
WWES September 1993	VOCs, SVOCs, metals*	N/A	N/A

1530-SSWP Rev-1

Phase of Work/Report	Soil	Groundwater	Sediment
Characterization			
Sampling			
WWES 1994 Shallow		VOCs, SVOCs,	
Soils Excavation Interim	VOCs, SVOCs, metals*,	metals*, T+A Cn,	
Closure	T+A Cn, sulfate	sulfate	N/A
Earth Tech 1995 Interim		VOCs, B/N, metals*,	
Closure Report	N/A	T+A Cn, sulfate	N/A
Horizon May 1995			
Subsurface Investigation		PVOCs, SVOCs,	
of Adjacent Properties	PVOCs, SVOCs, T+A Cn	T+A Cn, Sulfate, Zn	N/A
Horizon June 1996			
Subsurface Investigation	PVOCs, SVOCs, T+A Cn	N/A	N/A
Horizon 1998-2001			
Annual Groundwater		PVOCs, SVOCs,	
Monitoring	N/A	T+A Cn	N/A
			VOCs, PAHs,
		1	PCBs, Pesticides,
GLNPO 2000 Survey of			metals*, T Cn,
Sediment Contamination			ammonia, Oil &
on the Manitowoc River	N/A	N/A	grease
		PVOCs, PAHs, T+A	
NRT 2002-2003		Cn, weak-acid	BTEX, PAH, PCBs,
Groundwater Monitoring		dissociable (WAD)	metals*, T Cn,
and Sediment Sampling	N/A	Cn	ammonia
NRT 2004 Groundwater		PVOCs, PAHs,	
Monitoring	N/A	Available Cn	N/A
NRT 2005-present			
Groundwater Monitoring	N/A	PVOCs and PAHs	N/A

<sup>\*</sup> Metals analyzed during the 1988 investigation included antimony, arsenic, beryllium, cadmium, chromium, copper, lead, mercury, nickel, selenium, silver, thallium and zinc. Analyses of antimony, beryllium and thallium were eliminated during subsequent investigations, which also included barium. Metals analyzed during the GLNPO 2000 investigation included arsenic, cadmium, chromium, copper, lead, mercury, nickel, silver, and zinc. Metals analyzed during the NRT 2003 investigation include arsenic, cadmium, chromium, copper, lead, mercury, silver, and zinc.

As noted above, early investigations through 1991 included analysis of soil and groundwater samples for VOCs, base/neutral semi-volatile organic compounds (base/neutral SVOCs) or PAHs, total and amenable cyanide, metals, sulfate and grease and oil. Grease and oil was eliminated following review of the 1991 data, as it was observed that soils and groundwater impacted with grease and oil were also impacted by PAHs or base/neutral SVOCs and VOCs, and the analysis was not necessary. Sulfate is not considered a COPC based on the Multi-Site RAF. The full list of SVOCs was performed during several soil and

groundwater sampling events from 1993 through 2001. This list includes the acid extractable SVOCs (i.e. phenols).

Soil COPCs – PVOC and PAH compounds are elevated in soil and are considered COPCs. Continued cyanide (total) sampling in soil is recommended to characterize the former MGP structures, particularly the former purifier areas. Also, continued sampling for lead in soil is recommended due to a past lead concentration of 490 mg/kg at SB1 inside the former 300,000 cubic foot gas holder. Concentrations of other metals are below the EPA Soil Screening Levels (SSLs) for ingestion-dermal or inhalation pathways (commercial/industrial scenario). The maximum arsenic concentration (3 mg/kg) is just above the SSL, but within typical background levels. Vanadium is included on the COPCs list as it was never analyzed in soil at the Site. Although aluminum, iron and manganese were also never analyzed, no EPA SSLs exist for these compounds for human health risk assessment. As indicated in Section 4, ecological risk assessment for soils is not necessary. The phenol compounds listed in the Multi-Site RAF were not previously detected in soil at the Site, and therefore they are not included on the COPCs list.

Groundwater COPCs - Current groundwater analytes at the Site include PVOCs and PAHs and are considered COPCs. Groundwater samples through 1995 and also in May 2005 (refer to Appendix G1 for results) were analyzed for the full list of VOCs. Carbon tetrachloride, trichloroethene and methylene chloride have historically exceeded the WAC NR 140 Enforcement Standard (ESs) in isolated occurrences. As these compounds are not typical MGP-related constituents, sampling of PVOCs only began in 1995. Groundwater analyses of metals were discontinued in 1995 as concentrations in 1994 were not above the NR 140 ES, with the exception of lead at MW12 (lead was also present in the equipment blank). Zinc concentrations were above the NR 140 ES at wells MW01 and MW02 in 1991, but is likely related to the wells being constructed of galvanized steel. Groundwater samples continued to be submitted for analysis of total and amenable cyanide through 2002. Beginning in 2002, weak-acid dissociable cyanide was also analyzed. In 2004, sampling of cyanide was transitioned to available cyanide only by OIA-1677 method based on WDNR correspondence. The resulting concentrations were below NR 140 PAL and with WDNR's concurrence; cyanide sampling was discontinued at the Site thereafter. Because of new depths and areas being investigated, available cyanide will be included in the COPCs list for a minimum of one round. Since the phenol compounds listed in the Multi-Site RAF were detected below the NR 140 ES, they are not included on the COPCs list. Since aluminum, iron,

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 3 – Summary of Current Site Characteristics
Page 29 of 91

manganese, and vanadium were never analyzed in groundwater at the Site, they are included in the COPCs list for a minimum of one round of groundwater sampling. Based on the initial results of these compounds in groundwater, they will be discontinued if concentrations are below screening values presented in the Multi-Site RAF.

<u>Soil Vapor COPCs</u> (if determined necessary) – BTEX and naphthalene compounds are elevated in both soil and groundwater at the Site, and are therefore considered COPCs for soil vapor. These compounds are volatile or semi-volatile and are the primary constituents of concern with respect to soil vapor.

<u>Sediment COPCs</u> – PVOCs, PAHs and cyanide are considered COPCs for sediment. Since phenols were never analyzed in sediment at the Site, they are included in the COPCs list. At locations previously analyzed, arsenic, cadmium, and chromium were all detected below ecological screening levels and have been removed from the COPCs list. At locations previously analyzed, mercury was detected at or below ecological screening levels and also has been removed from the COPCs list. The remaining metals from the Multi-Site RAF will be included in the COPCs list.

<u>Surface Water COPCs</u> – Due to the limited data collected to date on surface water, the complete COPCs list, as presented in the Multi-Site RAF, will be analyzed for surface water.

1530-SSWP Rev-1

# 4 SITE-SPECIFIC CONCEPTUAL SITE MODEL SUMMARY

A Site-Specific Conceptual Site Model (CSM) was developed for the Manitowoc Former MGP Site (Figure 12). The Site-Specific CSM is based on the Generalized CSM. It is refined to reflect: (1) site-specific conditions observed during the Site reconnaissance (discussed below) and (2) information summarized in the Completion Report (December 2006, NRT). The Site-Specific CSM provides the framework to identify data needs to characterize the Site and evaluate potential human health and ecological risks.

The Site-Specific CSM and risk assessment approach will be reviewed on an iterative basis to refine the media of concern and individual pathways as more data are generated to ensure the RI report considers the newly collected data. Similarly, as remedial actions are performed, the CSM will be revised.

## 4.1 Site Reconnaissance

The Site reconnaissance field notes are provided in Appendix E and include select photographs and the completed habitat assessment checklist from the Ecological Risk Assessment Guidance for Superfund (ERAGS) (USEPA 1997). The site reconnaissance was completed prior to submittal of Revision 1 of the RAF, which includes the use of an additional habitat assessment form.

The Site reconnaissance was performed on January 5, 2007 by NRT and Exponent (formerly Menzie-Cura and Associates, the risk assessors) staff as part of the RI work plan development. The primary purpose of the Site reconnaissance was to verify which exposure pathways may be complete for both human health and ecological receptors. A qualitative habitat assessment was performed as a beginning step of the screening level ecological risk assessment to assess if sufficient ecological habitat is present in the upland portions of the Site. The qualitative habitat assessment will be confirmed during the warmer weather, concurrently with the RI field activities, when the full quality of the habitat can be evaluated. Refinement to the site-specific CSM will be made as appropriate. The observations from the Site reconnaissance are incorporated in the assessment of potential exposure pathways set forth in the following sections.

1530-SSWP Rev-1

Page 31 of 91

#### 4.2 Media of Potential Concern

The Generalized CSM considered the following media as media of potential concern:

- Soil (Surface and subsurface soil)
- Surface Water
- Groundwater
- Sediment

These media will also be considered media of potential concern, as described in the following sections. In addition, soil vapor may also be considered a media of potential concern; however, this will be determined following further characterization of the potential source areas under the on- and off-property buildings. These media will be evaluated as part of the risk assessment activities to assess if response actions, including risk management tools, are warranted to manage the potential risk to human health and the environment at the Manitowoc Site.

The risk assessment evaluation of these media will be based on previously collected RI data and data to be collected as described in Section 6. The previously collected data will be assessed for the adequacy of the data as part of the RI Report. The assessment will consider the age and quality control of the data, detection limits, the likelihood that the data is still representative of conditions, and may include comparison with newly collected RI data.

#### 4.2.1 Surface Soil

Surface soil is considered a media of potential concern on-property and off-property at the Winter Property due to the presence of former MGP structures requiring further characterization as described in Section 3.6.1.1 and 3.6.1.3, respectively. Previously performed response actions (Section 2.4) included ISS and excavation of shallow soils over an area located both on-property and on City-owned land and right-of-way (North Eleventh Street). However, surface soils located on-property south of the building and portions of the Winter Property are considered a potential exposure pathway.

WPSC Manitowoc Former MGP Site Site-Specific Work Plan

Revision 1

April 10, 2008

Section 4 – Site-Specific Conceptual Site Model Summary

Page 32 of 91

4.2.2 Subsurface Soil

Subsurface soil is considered a media of potential concern as MGP residuals were detected in subsurface

soil during previous investigations. Subsurface soil requires further investigation in the potential source

areas (former MGP structures) as described in Section 6.4 to assess potential human health risks.

4.2.3 Soil Vapor (pending subsurface soil quality)

Soil vapor, relating to vapor intrusion into buildings, may be considered a media of potential concern for

buildings on the Site. Recommendations on whether soil vapor sampling is warranted are discussed in

Section 6.5.

4.2.4 Groundwater

Groundwater is considered a media of potential concern as MGP residuals were detected in groundwater

samples during previous investigations and on-going annual groundwater monitoring events. Additional

groundwater data are needed to define the vertical and horizontal extent of the plume and associated

environmental risk, as described in Section 6.6.

4.2.5 Sediment

Sediment in the Manitowoc River will be evaluated as a media of potential concern. Previously

performed investigations detected MGP residuals in sediment samples collected from the river. Further

investigations are needed as described in Section 6.7 to assess both human health and ecological risks.

4.2.6 Surface Water

Surface water in the Manitowoc River will be evaluated as a media of potential concern. Oil sheens have

been observed on the river adjacent to the Site that may potentially be related to MGP coal tar residuals.

Further investigations are needed as described in Section 6.7 to assess both human health and ecological

risks.

1530-SSWP Rev-1

# 4.3 Potential Exposure Pathways – Human Health

This section evaluates the potential exposure pathways for human health receptors as presented in the Generalized CSM. A site-specific evaluation of the Generalized CSM exposure pathways has been considered to develop the former Manitowoc MGP CSM. This evaluation considers both current Site land use as well as potential future Site land use conditions.

These exposure pathways will be evaluated as part of the risk assessment activities to assess if response actions, including risk management tools, are warranted to manage the potential risk to human health at the Manitowoc Site. It is understood that without proving unrestricted use and unlimited access is protective of human health for current and future land uses, risk management tools will be required to prevent residential land use of the Site. The methods that will be used to evaluate potentially complete exposure pathways are included in the Multi-Site RAF.

Ingestion of groundwater is not expected under any current or future land uses because there is a public water supply, and therefore this media pathway was dropped from the Generalized CSM. Groundwater ingestion will not be quantitatively evaluated. State and federal drinking water standards will be used to qualitatively evaluate groundwater ingestion. This evaluation will be documented in the Baseline Risk Assessment (BIRA).

#### 4.3.1 Industrial/Commercial Land Use Scenario - Worker

The Generalized CSM considered the exposure route to the industrial/commercial worker was through incidental ingestion, dermal contact, and inhalation of soils (as a result of soil disturbance). Two main properties exist within known contaminated areas (not previously remediated) that each contain a building for commercial use, asphalt parking area and grass/landscape areas. Based on the current land use, industrial/commercial workers could be exposed to MGP residuals if present near the surface in the limited grass/landscape areas or if the soil under the asphalt would be exposed. The most likely workers coming in contact with the Site on a regular basis would be maintenance personnel for each property, consistent with the Generalized CSM. Exposure to these personnel is expected to be minimal due to the paved areas and established grass areas. Dermal exposure and ingestion of groundwater is not expected

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site Site-Specific Work Plan

Revision 1 April 10, 2008

Section 4 – Site-Specific Conceptual Site Model Summary

Page 34 of 91

due to the depth to groundwater (ranging from 5 to 22 feet bgs – below depths encountered for landscaping activities) and public water supply.

An additional worker exposure scenario for this Site, not included in the Generalized CSM, may include potential inhalation of vapors as a result of vapor intrusion. Both buildings were constructed over former MGP structures. Subsurface soils beneath or immediately adjacent to the buildings will be investigated to evaluate if conditions indicate that soil vapor intrusion is potentially an issue. The basement floor of the on-property building is exposed along the north side. A basement likely does not exist for the Winter Building due to the shallow depth to the base of the gas holder (approximately 7 feet).

In summary, the commercial/industrial worker scenario will be assessed using existing Site data of sufficient quality (as discussed in Section 4.2) and proposed additional data to evaluate potential risks under the following exposures:

- Incidental ingestion of soil (surface and subsurface);
- Dermal contact with soil (surface and subsurface) as a result of soil disturbance;
- Inhalation of vapors and dusts as a result of surface soil disturbance; and
- Soil vapor (if warranted as described in Section 6.5).

#### 4.3.2 Construction Worker

The Generalized CSM considered the exposure route to the construction worker was through incidental ingestion, dermal contact, and inhalation of soils (as a result of soil disturbance) and groundwater via dermal contact and inhalation.

Consistent with the Generalized CSM, there is the potential that construction workers may be exposed to surface and subsurface soils and groundwater if portions of the Site are redeveloped or if subsurface utility work occurs. Using previously collected data of sufficient quality (as discussed in Section 4.2) and proposed data, the potential risks associated with construction worker exposure to soils and groundwater will be evaluated, including:

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 4 – Site-Specific Conceptual Site Model Summary
Page 35 of 91

- Incidental ingestion of soil (surface and subsurface);
- Dermal contact with surface/subsurface soil and groundwater associated with excavation activities; and
- Inhalation of vapors and dusts derived from surface/subsurface soil and groundwater with excavation activities.

## 4.3.3 Recreational Land Use Scenario – Visitor/Trespasser

The Generalized CSM considered the exposure route to the recreational visitor/trespasser was through incidental ingestion and dermal contact with surface soil, incidental ingestion and dermal contact with surface water and sediment. Under current land use conditions, there is the potential that visitors/ trespassers may be exposed to surface water and sediment via wading into the river. The river is wide (approximately 400 feet across) with an elevated concrete platform (atop the sheet pile wall) and a metal railing present throughout most of the river bank adjacent to the City Property. There is no obvious location to easily access the Manitowoc River. During the Site reconnaissance, Exponent waded into the Manitowoc River by traversing a steep embankment down to the shoreline. Exponent noted there was only a limited distance out into the river that was possible for wading. Water depths were approximately two to three feet deep within five feet of the shore and the river bottom drops abruptly from this point. Water depths are known to be more than 21 feet at a distance of approximately 60 feet from the shoreline.

Under a future land use scenario, recreational use of the Winter Property, in addition to the waterfront area on the City Property and Wisconsin Central Railroad property, will be evaluated. The exposure routes considered for the recreational land use scenario at the Manitowoc Site are consistent with the Generalized CSM. Using proposed surface soil, sediment, and surface water data, the potential risks associated with recreational land use exposures will be evaluated as follows:

- Incidental ingestion of surface soil, surface water, and sediment; and
- Dermal contact with surface soil, surface water, and sediment.

Human health screening levels for surface water and sediment will be tailored to the Site-Specific characteristics of the Manitowoc River and will be developed as part of the Risk Assessment.

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 4 – Site-Specific Conceptual Site Model Summary
Page 36 of 91

#### 4.3.4 Residential Land Use Scenario

The Generalized CSM considered the residential land use exposure route to be through surface incidental ingestion, dermal contact, and inhalation of surface soil, subsurface soil, and groundwater.

Although there is no indication that future use of this Site will be residential, the Site-Specific CSM will include flexibility for evaluating a residential land use scenario within the BlRA, particularly on the Cityowned property. It is WPSC's intention to use risk management tools or to maintain the WPSC property under ownership. As appropriate, Site property that is not WPSC-owned may also require risk management tools to control future residential development, which will be documented in the BlRA.

# 4.4 Potential Exposure Pathways – Ecological Receptors

This section evaluates the potential exposure pathways for ecological receptors as presented in the Generalized CSM. A site-specific evaluation of the Generalized CSM exposure pathways has been considered to develop the Manitowoc CSM. As discussed in Section 5.4 of the Generalized CSM, all of the potential ecological receptors are considered applicable for evaluation in the Screening Level Ecological Risk Assessment (SLERA). The results of the qualitative habitat assessment conducted in January 2007 for the Manitowoc Site were used to identify the ecological receptors to be evaluated in the SLERA, which include fish and benthic invertebrates as further discussed below.

The results of the habitat assessment (Section 2.3.1 of the RAF), performed during the site reconnaissance, are used to refine the Manitowoc CSM. Field notes and photos from the habitat assessment are included in Appendix E. As described in Section 4.1, the habitat quality assessment will be confirmed as part of the RI field work. The site-specific CSM will be refined, as appropriate.

Wetlands are not present at the Site based on site observations and review of the Wisconsin wetland inventory map for the area. The methods that will be used to evaluate the potential exposures to these ecological receptors are included in the Multi-Site RAF.

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1

April 10, 2008

Section 4 – Site-Specific Conceptual Site Model Summary Page 37 of 91

## 4.4.1 Mammals (Upland and Aquatic)

The Generalized CSM considered carnivorous, piscivorous, insectivorous, omnivorous, and herbivorous mammals as an ecological receptor that may be exposed to COPCs through incidental ingestion and dermal exposure of soil, sediment, and/or surface water and ingestion of plant and prey items.

Based on the Site reconnaissance and the habitat assessment (refer to Appendix E), the Site does not provide sufficient habitat for mammals in the upland areas. The Site is primarily asphalt parking areas, buildings and paved streets. There are no natural terrestrial ecological communities present at the Site that would afford habitat for small mammals beyond those normally found in any city environment. For example, there are no forest lands at the Site or grasslands that would provide high quality habitat for a range of small mammal species or other wildlife. No evidence of wildlife usage was observed during the Site reconnaissance.

Based on the Site reconnaissance and the habitat assessment (refer to Appendix E), the Manitowoc River does not provide sufficient habitat for mammals in the aquatic environment. The shoreline of the river consists of a sheet pile wall and steep embankments which limits burrowing of aquatic mammals such as muskrats and beavers. This area of the river is deep due to its use as a turning basin and aquatic vegetation is not present.

For the above mentioned reasons related to insufficient habitat, potential risk to mammals in the upland and aquatic areas will not be further evaluated.

## 4.4.2 Birds (Upland and Aquatic)

The Generalized CSM considered carnivorous, piscivorous, insectivorous, omnivorous, and sediment-probing birds as an ecological receptor that may be exposed to COPCs through incidental ingestion and dermal exposure of soil, sediment, and/or surface water and ingestion of plant and prey items.

Geese and seagulls were observed using the area of the river near the property during the Site reconnaissance visit. Most other avian species had migrated south for the winter at the time the habitat assessment was conducted. However, based on the observations made during the habitat assessment, little habitat exists in the area for birds. Sediment probing birds would unlikely be using the Site as the

NATURAL RESOURCE TECHNOLOGY

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 4 – Site-Specific Conceptual Site Model Summary
Page 38 of 91

water depths are generally too deep. Mudflat areas are not present adjacent to the river and the water depth is approximately two feet adjacent to the shorelines and then drops off quickly to depths greater than 10 feet deep. Piscivorous and insectivorous bird species may forage in the Manitowoc River near the Site, but this would be expected to be limited in nature as there are not nesting sites available for these bird species at the Site. Consistent with the lack of sufficient habitat provided at the Site for mammals, bird habitat is considered insufficient in the upland and aquatic areas and will not be further evaluated.

#### 4.4.3 Fish

The Generalized CSM considered fish as an ecological receptor that may be exposed to COPCs through incidental ingestion and dermal exposure of sediment and/or ingestion of food.

A variety of fish species may be present in the Manitowoc River portion of the Site. Fish will be considered an ecological receptor because habitat at the site does exist. As described in Section 6.1.2.1 of the RAF, a qualitative biological survey of fish habitat will be performed during surface water and sediment investigation. The qualitative habitat survey will identify the types of fish habitat that exists (e.g., spawning grounds, foraging areas, etc.), if present, over the investigation area. Also, the habitat survey will evaluate whether sufficient habitat is available for the potential threatened fish species discussed in Section 3.5. Together with the concentrations of COPCs in surface water and sediment, the spatial distribution, the habitat information, and the ability of the detected COPCs to bioaccumulate or biomagnify in fish tissue, the need to further evaluate potential risks to fish as part of the ecological risk assessment will be determined.

## 4.4.4 Benthic Invertebrates (Aquatic Ecological Receptor)

The Generalized CSM considered benthic invertebrates as an ecological receptor that may be exposed to COPCs in sediment and surface water.

MGP residuals were detected in sediment samples collected in the Manitowoc River. Many of the detected concentrations are above ecological screening levels, indicating that the sediment media requires further evaluation to assess if sediment poses an ecological concern. As discussed in Section 5.4.4 of the RAF, benthic invertebrates form the base of many food chains and spend most or all of their life-cycle burrowed or feeding just at the interface between surface water and sediment.

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 4 – Site-Specific Conceptual Site Model Summary
Page 39 of 91

Based on observations from the Site reconnaissance, the river provides habitat for benthic invertebrates as benthic invertebrates were observed in the river (Appendix E). Therefore, the potential risks to benthic invertebrates associated with sediment and surface water exposures from the Manitowoc River will be evaluated as part of the ecological risk assessment.

#### 4.5 Data Needs

As described in the Completion Report (December 2006, NRT) and previous sections of this SSWP, the media that require further assessment and/or were not fully addressed by previous work with respect to public health, welfare or the environment include the following:

- On-property and off-property (Winter) surface soil sampling will be performed to assess current conditions in remaining potential source areas and provide additional data for assessment of alternatives and pathways;
- On-property and off-property (Winter) subsurface soil sampling will be performed to assess current conditions in remaining potential source areas, evaluate the potential for vapor intrusion, and provide additional data for assessment of alternatives and pathways;
- Groundwater well installation and sampling will be performed to define the lateral and vertical extent of MGP residuals in groundwater and evaluate concentrations trends;
- Surface water sampling will be performed to assess the distribution of COPCs and the potential risk to human health and the aquatic environment; and
- Sediment sampling will be performed to assess the distribution of COPCs and the potential risk to human health and the aquatic environment. In addition, geotechnical parameters will be collected to support and FS.

1530-SSWP Rev-1

NATURAL
RESOURCE
TECHNOLOGY

# 5 PROJECT SCOPING AND PLANNING ACTIVITIES

# 5.1 Project Scoping (Task 1)

As defined in the SOW, attached to the AOC, the scope of this project includes:

- Task 1: Project Scoping and RI/FS Planning Documents;
- Task 2: Community Relations;
- Task 3: Site Characterization;
- Task 4: Remedial Investigation Report (including human health and ecological risk assessments);
- Task 5: Treatability Studies (if needed);
- Task 6: Development and Screening of Alternatives (Technical Memoranda);
- Task 7: Detailed Analysis of Alternatives (FS Report); and
- Task 8: Progress Reports.

Task 1, Project Scoping and RI/FS Documents included the use of Multi-Site documents which set forth general approaches and concepts with the intent of streamlining preparation of work plans and minimizing review times for future deliverables. In addition, the Multi-Site documents provide a consistent approach to investigating and assessing WPSC's sites. Multi-Site documents include:

- Multi-Site Health and Safety Plan (HASP) Revision 2 (August 2, 2007);
- Multi-Site Quality Assurance Project Plan (QAPP) Revision 2 (September 24, 2007);
- Generalized Conceptual Site Model (CSM) Revision 0 (August 5, 2007);
- Multi-Site Risk Assessment Framework (RAF) Revision 0 (September 5, 2007);
- Multi-Site Field Sampling Plan (FSP) Revision 3 (February 20, 2008); and
- Multi-Site Feasibility Study (FS) Support Documents (to be prepared).

WPSC Manitowoc Former MGP Site Site-Specific Work Plan

Revision 1

April 10, 2008

Section 5 - Project Scoping and Planning Activities

Page 41 of 91

These Multi-Site documents are intended to set forth the general approaches and concepts for performing

RI/FS activities. Site-specific information relevant to these documents is included in Appendix F.

Previously collected data and observations were compiled in the Manitowoc Completion Report

(December 2006, NRT), submitted to USEPA on December 5, 2006. The conclusions of the Completion

Report and Site reconnaissance were used as the basis for developing this SSWP.

5.2 Approach

Previously performed Site activities have generated a significant amount of existing data for

characterizing Site conditions. The activities proposed in this SSWP will focus on the supplementing

previously collected data to refine migration and exposure pathways identified through the CSM and Site

reconnaissance.

Sampling activities will also be completed to gather data that can be used to support human health and

ecological risk assessments and feasibility study evaluations. A dynamic work plan approach has been

developed to collect the data necessary to satisfy the Data Quality Objectives (DQOs) and address

concerns regarding specific pathways.

Representatives from USEPA, USEPA's technical support team, WPSC and WPSC's consultants will

participate in technical meetings to mutually resolve problems, as necessary.

5.3 Project Management Communications

Appendix F4 includes the lines of communication that will be used during field activities with the contact

information. Additional team members may be added throughout the project duration.

It is anticipated at a minimum, during field activities that require rapid decision-making a weekly meeting

will be used to provide a schedule update and to discuss problems that have occurred and resolutions that

have been implemented. The frequency of these meetings may be increased depending on the specific

activity being performed.

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 5 – Project Scoping and Planning Activities
Page 42 of 91

These meetings will include the Field Team Leader, NRT Project Manager, WPSC Project Coordinator and USEPA Remedial Project Manager.

# 5.4 Purpose and Data Quality Objectives Review

DQOs for the Former Manitowoc MGP Site are consistent with the DQOs presented in the Multi-Site QAPP. As discussed in Section 1, data will be collected during the RI activities to satisfy the following site-specific objectives:

- Evaluate the nature and extent of MGP residuals in the Manitowoc River sediment and surface water;
- Evaluate the presence of MGP residuals in surface soils and evaluate the presence of MGP residuals in subsurface soil at the Site;
- Assess soil conditions beneath or immediately adjacent to the buildings for an indication of the potential for vapor intrusion;
- Evaluate the nature and extent of MGP residuals in groundwater at the Site and assess the characteristics of the residual plume;
- Support development and evaluation of potential remedial alternatives (feasibility studies), if response actions are necessary; and
- Collect data to support a baseline risk assessment for human health and the environment and evaluate the potential risk for human health and ecological receptors.

# 5.5 Preliminary Objectives for Remedial Action

The objectives for remedial action will be developed as part of the FS tasks described in Section 8.1.1. In general, the remedial action objective is to protect public health, welfare and/or the environment from site contaminants that may pose a risk and if a risk is present, reduce the risk.

# 5.6 Preliminary Remedial Action Alternatives

The remedial action alternatives will be developed as part of the FS tasks described in Section 8.2 and will include site-specific evaluation of Applicable or Relevant and Appropriate Requirements (ARARs) and To Be Considered (TBC) requirements.

1530-SSWP Rev-1 NATURAL RESOURCE

TECHNOLOGY

Previous remedial action alternatives were evaluated prior to selecting the response actions discussed in Section 2.4. These response actions may be reviewed and updated to reflect current Site conditions. In general, the following responses (but not limited to) may be appropriate to address MGP residuals:

#### **■** Groundwater

- Containment
- Active remediation
- Monitored natural attenuation
- Institutional controls

#### ■ Soil

- Removal and disposal
- In-situ treatment
- Capping/containment
- Institutional controls

#### ■ Soil Vapor (if determined necessary)

- Engineering or institutional controls on building
- Source removal and disposal

#### **■** Sediment

- Dredge/excavate and disposal
- In-situ treatment
- Capping
- Monitored natural recovery

# 5.7 Community Relation (Task 2)

WPSC is prepared to provide community relation support if requested by USEPA.

1530-SSWP Rev-1

# 6 SITE CHARACTERIZATION AND ASSESSMENT ACTIVITIES

The scope of supplemental RI Site characterization and assessment activities addressed by this SSWP includes:

- Supplemental Site-wide survey work;
- Surface soil sampling;
- Subsurface soil sampling;
- Additional groundwater monitoring well installation;
- Groundwater sampling;
- Surface water sampling; and
- Sediment assessment.

Sampling locations, frequencies, analytical parameters, and methods to be used are presented. Work preparation, mobilization, site-specific dynamic sampling and analysis techniques, investigative waste management, record keeping, sample analysis and validation, and data evaluation processes are also discussed.

The planned field activities will be completed in accordance with the methods and techniques described in the Multi-Site QAPP, FSP, and HASP. These general methods and techniques are not repeated herein. Site-specific information relevant to these Multi-Site documents are discussed below and details are included in Appendix F.

# 6.1 Mobilization Planning

#### 6.1.1 Pre-Mobilization

Field mobilization activities will be completed in accordance with Section 3 of the Multi Site FSP and include:

- Making arrangements for Site access;
- Review shipping calendar;
- Utility notification/and location through Wisconsin Diggers Hotline and, if need be, a private contractor. The City of Manitowoc representatives may need to be contacted directly for locating storm and sanitary sewers and water main lines; and
- Establishing a communication structure for field to office personnel and for WPSC and USEPA/WDNR so that they are also kept aware of the status of field activities.

## 6.1.2 Daily Planning

Daily planning will occur as described in the Multi-Site FSP and HASP including but not limited to:

- Daily progress tracking;
- Problem identification and resolution;
- Communications from field to office managers, WPSC and USEPA, as appropriate to insure decision points and objectives for the work are fulfilled; and
- Safety meetings, particularly with respect to the sediment and surface water sampling work on the Manitowoc River, due to the inherent danger of working in the river environment.

#### 6.1.3 Demobilization

Generally, demobilization planning will occur during the pre-mobilization planning, as NRT staff and outside contractors plan for the field activities. Any issues regarding final Site status will be identified during the planning process (e.g. ensuring that landscaping issues are addressed, etc.).

# 6.2 Site Surveying and Map Development

Numerous surveying efforts have been completed over the years to locate sampling locations and notable features. Generally, the survey datum used was NAD83 (state plane coordinates) or the Wisconsin County Coordinate System datum for Manitowoc County. A new survey will be completed in accordance with the survey methods in Section 7 of the Multi-Site FSP. This will ensure that all Site features are accurately located and that conversion of the survey points to the Universal Transverse Mercator (UTM) projection, which is required by USEPA, is consistent.

Updated survey work and mapping will include:

- Establishing additional location survey information, if needed, such that drawings and maps can be updated to show current Site features, particularly on properties not owned by WPSC (e.g., Winter and Wisconsin Central Railroad Properties); and
- Establishing new survey control points so that future Site activities (e.g. sediment sampling locations, soil boring locations, additional wells, etc.) can be accurately located and tied to a common datum as work progresses.

# 6.3 Surface Soil Sampling

## 6.3.1 On-Property Locations

Surface soil samples from the 0 to 2 feet depth interval will be collected on-property to assess current conditions in the former MGP structure locations and provide additional data for the FS. Discrete surface soil samples are proposed to be collected from four borings (SB106, SB108, SB111 and SB113) inside the current building footprint to assess soil conditions and potential vapor intrusion (discussed further in Section 6.5), and five borings (SB114 through SB118) on the south side of the building located in grass areas as shown on Figure 13. Access to locations inside the current building, appear to be feasible due to overhead garage doors, pending further review of access constraints.

# **6.3.2 Off-Property Locations (Winter Property)**

Surface soil samples from the 0 to 2 feet depth interval will be collected off-property (on the Winter Property) to assess current conditions in the former 300,000 cubic foot gas holder location and provide

1530-SSWP Rev-1

RESOURCE
TECHNOLOGY

additional data for the FS. Discrete surface soil samples are proposed to be collected from three borings (SB119 through SB121) outside the former gas holder and two borings (SB122 and SB124) inside the former gas holder, all currently located in grass areas as shown on Figure 13. No surface soil samples are proposed to be collected inside the building footprint due to the difficulty in obtaining these samples. Surface soil samples to be collected exterior to the building but within the former gas holder footprint are expected to be representative of soil conditions within the entire gas holder based on the physical layout of the structure, building and proposed locations (Figure 13).

#### 6.3.3 Sampling Methods and Abandonment

Surface soil samples will be collected using direct-push sampling techniques, which are described in Section 4 of the Multi-Site FSP. One discrete sample of surface soil (0 to 2 feet depth interval) will be collected from each location for analysis of the parameters and associated methods listed on Table 4. Cyanide will be analyzed in a fixed-based laboratory. Other parameters will be analyzed in either an on-site mobile laboratory or a fixed-based laboratory, which may depend on whether the soil sampling is performed congruent with the sediment sampling. Most boring locations will also be used for subsurface soil sample collection and following completion, the soil borings will be abandoned in accordance with the methods described in Section 4 of the Multi-Site FSP.

# 6.4 Subsurface Soil Exploration and Sampling

#### 6.4.1 On-property Locations

A test pit exploration (TP101) will be performed on-property in the former condenser area in the vicinity of SB58 to determine whether the suspected coal tar underground storage tank (UST) remains in this area (Figure 13). Specifically, the UST was found during both the ISS and excavation activities at approximately 3 to 6 feet bgs. The eastern half of the UST was reportedly encapsulated by ISS. If found, the tank and tank contents will be removed (if possible) and disposed in accordance with applicable regulations. If the UST is required to be left in-place, the tank contents (if any) will be removed and disposed accordingly, and the tank will be abandoned in-place and filled with inert materials in accordance with applicable regulations. No subsurface soil samples are anticipated for collection from the test pit.

1530-SSWP Rev-1

Subsurface soil samples will be collected on-property to assess current conditions in the former MGP structure locations and provide additional data for the FS. Subsurface samples are proposed to be collected from three soil borings (SB103 through SB105) performed on the north side of the current building, eight soil borings (SB106 through SB113) inside the current building footprint, and five borings (SB114 through SB118) on the south side of the current building as shown on Figure 13. Access to locations inside the current building appears feasible due to overhead garage doors, pending further review of access constraints. Historic sampling information will be used as a basis for proposed boring depths. Generally, soil borings will be advanced approximately 20 feet bgs, or until a minimum of 4 consecutive feet of soil that exhibits no MGP impacts (by visual observation and field PID screening) is encountered, unless refusal occurs at a shallower depth.

#### 6.4.2 Off-Property Locations

Subsurface soil exploration is planned off-property on: 1) City Property; 2) the Winter Property; and 3) Wisconsin Central Railroad Property.

#### 6.4.2.1 City Property

Soil borings (SB100, SB101 and SB102) will be performed for exploration purposes on City Property/ right-of-way adjacent to the river to assess groundwater quality and the potential for remaining source in the sand unit below the ISS material. Soil samples may be collected of the sand unit below the ISS material from these borings if field observation and/or screening indicate the presence of MGP impacts. Also, groundwater grab samples will be collected from these locations, as described in Section 6.6.2.2 (Groundwater Evaluation, City Property), to determine the location(s) for installation of a piezometer. Refer to Section 6.6.2.2 for further details regarding methods for performing these borings and selection of location(s) for piezometer installation.

#### 6.4.2.2 Winter Property

Subsurface soil samples will be collected on the Winter Property to assess current conditions in the former 300,000 cubic foot gas holder area and provide additional data for the FS. Subsurface samples are proposed to be collected from three soil borings (SB119 through SB121) located outside the former gas

1530-SSWP Rev-1

Natural
RESOURCE
TECHNOLOGY

holder and three borings (SB122 through SB124) inside the former gas holder as shown on Figure 13. If soil conditions inside the holder appear consistent, subsurface samples may not be collected at all three boring locations. No subsurface soil samples are proposed to be collected inside the building footprint due to the difficulty in obtaining these samples. Subsurface soil samples to be collected exterior to the building, but within the former gas holder footprint, are expected to be representative of soil conditions within the entire gas holder based on the physical layout of the structure, building and proposed locations (Figure 13). Historic sampling information will be used as a basis for proposed boring depths. Generally, soil borings will be advanced approximately 20 feet bgs, or until a minimum of 4 consecutive feet of soil that exhibits no MGP-impacts (by visual observation and field PID screening) is encountered, unless refusal occurs at a shallower depth.

#### 6.4.2.3 Wisconsin Central Railroad Property

Soil samples will be collected during installation of monitoring well MW22 adjacent to the river to assess the soil quality off-property to the west and in an attempt to determine the source of the PAH concentrations previously detected in soil (refer to Section 3.6.1.2). Field observation of the fill materials (e.g., presence of coal or cinders) and type of odor (e.g., petroleum, coal tar, or none) will be key to this determination.

### 6.4.3 Sampling Methods and Abandonment

Subsurface soil samples will be collected using direct-push sampling techniques, as described in Section 4 of the Multi-Site FSP. It is anticipated that one to three subsurface soil samples will be collected from each boring location for analysis of the parameters and associated methods listed on Table 4. Cyanide will be analyzed in a fixed-based laboratory. Other parameters will be analyzed in either an on-site mobile laboratory or a fixed-based laboratory, which may depend on whether the soil sampling is performed congruent with the sediment sampling.

During drilling, soil samples will be collected for field screening to document subsurface conditions and if necessary identify samples for laboratory analysis. Field screening will occur in accordance with the methods and screening techniques identified in the Multi-Site FSP. Visual observations (tar staining) and odors will also be logged and used to identify samples for laboratory analysis. Also, soil samples will be

1530-SSWP Rev-1 NATURAL

collected to define the vertical extent of contamination from both above and below contaminated layers, as needed, from each boring. If observations or field screening results suggest that the soil is contaminated by a potentially unrelated source, pending any access agreements, at minimum benzene and PAHs will be analyzed for consideration in interpreting future groundwater data. The soil samples will be collected and analyzed in accordance with the methods described in the Multi-Site QAPP and Multi-Site FSP.

Following completion, the soil borings will be abandoned in accordance with the methods described in Section 4 of the Multi-Site FSP.

# 6.5 Potential Soil Vapor Intrusion Evaluation

Based on the subsurface conditions, the need to further consider the potential for soil vapor intrusion will be evaluated. The following data will be considered:

- Concentrations of COPCs in soil below or anticipated to be below the building floor both near the surface and at depth;
- Presence/absence of coal tar-contaminated soil layers (depth and thickness) below or anticipated to be below the building floor and assessment of the extent and connectedness of the layers;
- Fill material soil type (i.e. fine grained or coarse grained) and quality of any overburden material above coal tar-contaminated soils, if encountered.; and
- Chemical concentrations in samples from groundwater monitoring wells in proximity to the buildings.

Based on the data evaluation, the need for soil vapor sampling will be determined and the decision will be reviewed with USEPA. In general, soil vapor samples will be proposed if available data indicate the potential presence of MGP residuals near or beneath an existing building. If sampling is determined necessary, the soil boring results will be used to determine the soil vapor probe locations and sample depths as outlined in the following sections. Prior to soil vapor probe installation, the sampling locations and depths, along with justification for any proposed deviations, will be reviewed with USEPA. The data evaluation process for the vapor intrusion assessment is provided in Section 1.2 of Appendix F3.

1530-SSWP Rev-1

## 6.5.1 Soil Vapor Sampling Locations

Potential remaining source areas will be characterized prior to initiating any soil vapor sampling. External soil vapor sampling is generally preferred to sub-slab sampling since it is less intrusive to building occupants; however, soil vapor sample locations for vapor intrusion pathway assessment will be based primarily on the locations of the remaining source material and the measured chemical concentrations in groundwater samples from existing wells near each building.

Building construction will also be considered when selecting soil vapor sampling locations; therefore, an attempt will be made to gather construction drawings for the buildings prior to initiating soil vapor sampling in order to have additional information on floor slab and foundation construction. The drawings will be reviewed and the buildings will be inspected to identify potential preferential pathways (i.e. utility corridors, floor drains, sumps, other penetrations) that may exist below the floor slabs or foundations. An assessment will be made as to whether additional vapor sampling locations are warranted within any identified permeable backfill zone. The assessment will consider the permeability of the backfill relative to native soil, depth of utilities, and anticipated distribution of permeable backfill.

#### 6.5.1.1 On-Property Locations

For the on-property building, if source material remains in the subsurface both inside and outside of the building footprint at similar depth, magnitude and concentration, soil vapor sampling probes will be located exterior to the building within approximately 10 feet of the building edge. Exterior proposed locations SV101 through SV106 are shown on Figure 14. If source material substantially remains inside the building footprint only, soil vapor sample locations will be located interior to the building. Interior locations would be near proposed borings SB106 through SB113 (Figure 14). Soil vapor samples will be collected above the water table at two different depths at each location, including approximately 3 and 6 feet below the lowest floor elevation. Depending on the depth at which groundwater is encountered, sample depths may require adjustment such that soil vapor samples are collected from the unsaturated zone. In the case of interior soil vapor probe installation, a sub-slab soil vapor sample will be collected at each location, in addition to the samples collected at approximately 3 and 6 feet below the lowest floor elevation.

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 6 – Site Characterization and Assessment Activities
Page 52 of 91

#### 6.5.1.2 Off-Property Locations (Winter Property)

For the off-property building (Winter property), because of the physical layout of the gas holder structure and building, any source material present within the holder is expected to remain in the subsurface at similar depth, magnitude and concentration both inside and outside of the building footprint. For this reason, soil vapor sampling probes will be located exterior to the building within approximately 10 feet of the building edge. Proposed locations SV107 through SV109 are shown on Figure 14. Soil vapor samples will be collected above the gas holder base (anticipated to be at 7.5 feet bgs) at two different depths at each location, including approximately 3 and 6 feet below the lowest floor elevation. Depending on the depth at which groundwater is encountered, sample depths may require adjustment such that soil vapor samples are collected from the unsaturated zone.

#### 6.5.2 Sampling Methods and Abandonment

Soil vapor probes are proposed to be installed as semi-permanent probes with flushmount covers such that they can be sampled more than one time in order to assess data validity and temporal/seasonal effects. The probes will be installed in accordance with Multi-Site FSP, Appendix A, SOP No. SAS-11-03 using direct-push techniques. The probe will consist of ¼-inch diameter stainless tubing connected to a ¼-inch diameter, 0.5-ft long stainless steel screen with proper filter pack and bentonite grout seal. For the collection of samples at two different depths at each location, probes will be nested within the same borehole with bentonite placed between the screens/filter packs.

During soil vapor probe installation, samples of the subsurface soil will be collected for grain size analysis, bulk density, specific gravity of soil solids, and moisture content for use in the soil vapor risk assessment.

Active soil vapor sampling will be performed which involves extracting a volume of soil vapor and analyzing the resulting vapor sample. Samples will be collected in 1-L or smaller Summa canisters supplied and certified by the laboratory to ensure cleanliness. Samples will be collected according to the procedures and methods described in the Multi-Site FSP, Appendix A, SOP Nos. SAS-11-04 (probe sampling) and SAS-11-01 (sub-slab sampling) including proper purge volume, sample collection, flow rate and vacuum requirements. Leak detection testing will be conducted using the direct method as described in the above SOPs, including the use of a helium tracer gas and field screening to detect

1530-SSWP Rev-1

presence of helium in the soil vapor samples. Parameters and methods of analysis for the vapor samples are listed in Table 4. Also, samples will be analyzed for oxygen, carbon dioxide, and methane for vertical profiling to assess bioattenuation. Samples will be analyzed in a fixed-based laboratory as described in Section 6 of the Multi-Site FSP. Probes will be abandoned when no further sampling is deemed necessary.

# 6.6 Groundwater Evaluation

# 6.6.1 Existing Well Evaluation

The integrity of existing monitoring wells will be assessed by observing whether the surface seal is cracked, well covers are missing, etc. The Well Condition Field Form will be completed anytime a well is sampled or the water elevation is measured as part of continued groundwater monitoring. Also, the field measurements of total well depth will be compared to the monitoring well logs annually to detect any potential issues with a well. Depending on the results of the well evaluation, a well or wells may be redeveloped, rehabilitated or replaced (consistent with SAS-08-05 of the Multi-Site FSP).

# 6.6.2 Monitoring Well/Piezometer Installation

Monitoring wells and piezometers are proposed at locations shown on Figure 15 to address the following specific areas of the Site:

- 1. Three bedrock piezometers located on-property (PZ7B) and within City right-of-way (PZ18TB and PZ23B) to compliment data for proposed wells in the sand unit and define vertical extent;
- 2. Three groundwater water grab samples from soil borings SB100, SB101, and SB102 adjacent to the Manitowoc River with conversion of one to three locations to permanent piezometers, to evaluate groundwater quality within the sand unit, below the ISS material, discharging to sediment and surface water; and
- 3. One water table well (MW22) on the Wisconsin Central Railroad Property to monitor groundwater quality off-property to the west and downgradient of the MW14 residual source area and MW-12, and discharging to sediment and surface water.

Details for the installation, decision-making, and sampling of the proposed wells are provided below.

#### 6.6.2.1 Bedrock

The three proposed bedrock piezometers will be located as follows (proposed wells in bold):

- MW7/PZ7B, located on-property to the east/southeast of the ISS treatment area;
- MW18T/**PZ18TB**, located in City right-of-way to the south/southeast of the known source area; and
- **PZ23B**, located on City right-of-way Property, within the ISS area and downgradient of the known source area.

As discussed in Section 3, groundwater flow within the dolomite is likely toward Lake Michigan (east), or perhaps very locally toward the river (northwest).

The bedrock surface is expected to be encountered between 50 to 60 feet below ground surface (anticipated elevation of 535 to 545 feet), based on previous borings which apparently "tagged" the surface of the bedrock and also based on well logs of former industrial wells in the area. If drilling continues to 90 feet bgs without encountering bedrock but rather a thick glacial till layer is present exhibiting no evidence of MGP-impacts, the piezometers will be screened within the most permeable interval (based on visual observation) encountered in the till.

The piezometers are anticipated to be drilled approximately 10 feet into competent bedrock. Piezometer screens will have a 5-foot length, with the screen base set at least 10 feet below the top of bedrock. The piezometers are proposed to be drilled by sonic methods, in addition to wireline rotary drilling to collect bedrock core samples. Cores are not able to be obtained using sonic methods. Drilling and well construction activities will be completed in accordance with the methods described in Section 4 of the Multi-Site FSP. Piezometers will be constructed of 2-inch diameter polyvinyl chloride (PVC) material with a 0.01 inch screen slot size. The filter pack will extend two feet above the top of screen and 0.5 feet below the bottom of the screen. A fine sand filter pack seal will then be placed to 2-feet above the filter pack sand.

During drilling, soil samples will be collected to log lithology, determine existence of coal tar contamination, and for field screening to document subsurface conditions and if necessary identify samples for laboratory analysis. Once bedrock is encountered, wireline rotary drilling methods will be

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 6 – Site Characterization and Assessment Activities
Page 55 of 91

used to obtain bedrock cores for field inspection and logging of the rock quality designation (RQD) as specified in the additional SOP included in Appendix F4. Once the competent bedrock cores are collected, the hole will be overdrilled using the sonic method to provide a large enough diameter for installation of the piezometer.

The proposed piezometers were not located in known source areas due to avoid "dragdown" of the MGP contaminants during drilling. If contamination is encountered during drilling in the unlithified zone, sonic drilling allows a larger diameter temporary casing to be set into a confining layer (such as the till) while drilling proceeds into the bedrock. The temporary casing is then removed during the grouting operation.

#### 6.6.2.2 City Property

Three soil borings (SB100, SB101 and SB102) will be performed on the City Property/right-of-way adjacent to the river to collect groundwater grab samples. The purpose of the proposed groundwater sampling at all three locations is to assess groundwater quality and the potential for remaining source in the sand unit below the ISS material. The groundwater grab samples will be collected in the sand unit just above the till layer (if present) with a temporary screen. The grab samples will be analyzed with an onsite mobile laboratory for PVOCs and PAHs to aid in determining the permanent piezometer location(s). At minimum, a piezometer will be installed at one of the three locations (i.e., for the scenario of low to non-detectable concentrations at all three locations). A second and possibly third piezometer will be installed at the two remaining locations based on field observations and/or mobile laboratory data that indicate multiple locations of MGP impacts, or the need to define the lateral extent of groundwater impacts discovered at any of the locations. The grab samples indicating elevated concentrations above the WAC NR 140 ES will be preferred locations. The need to define the eastern and western lateral extent of groundwater impacts at this depth (if appropriate) will also be considered. Piezometer(s) will be screened in the sand unit just above the till layer (if present) with a 5-foot screen. Piezometers will be labeled starting with PZ23, as appropriate for the location. Piezometers will be constructed of 2-inch diameter polyvinyl chloride (PVC) material with a 0.01 inch screen slot size. The filter pack will extend two feet above the top of screen and 0.5 feet below the bottom of the screen. A fine sand filter pack seal will then be placed to 2-feet above the filter pack sand.

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 6 – Site Characterization and Assessment Activities
Page 56 of 91

Because of their location within the ISS treated material, sonic drilling will be used to install the soil borings. The sonic method will advance through the "hardened" ISS material, providing an indication of drill cutting material; however, no high quality cores of the ISS material will be collected.

#### 6.6.2.3 Wisconsin Central Railroad Property

The proposed water table well (MW22) will provide better definition of the lateral extent of MGP residuals in shallow groundwater to the west. Well MW22 will be screened as a water table well with a 10-foot screen. The well will be constructed of 2-inch diameter polyvinyl chloride (PVC) material with a 0.01 inch screen slot size. The filter pack will extend two feet above the top of screen and 0.5 feet below the bottom of the screen. A fine sand filter pack seal will then be placed to 2-feet above the filter pack sand. The monitoring well is proposed to be drilled by sonic methods. Drilling and well construction activities will be completed in accordance with the methods described in Section 4 of the Multi-Site FSP.

# 6.6.3 Groundwater Monitoring Well Development

The new monitoring wells and piezometers will be developed in accordance with the methods described in Section 4 of the Multi-Site FSP following installation. Development will continue until the field parameters (pH, temperature, conductivity, etc.) stabilize and at least 10 well volumes of water have been removed from the well (based on the generally sandy subsurface conditions). Further, an additional volume of water equal to the amount added will be removed from the well should it have been necessary to introduce liquids into the well to assist with drilling and/or well construction. Purge water from well development and well sampling activities is anticipated to be sampled and disposed of through the permit that is in place with the City of Manitowoc waste water treatment plant.

# 6.6.4 Groundwater Level Measurements

Groundwater levels will be measured to assess the elevation and direction of groundwater flow whenever the monitoring wells and piezometers are sampled, or as needed to assess flow conditions. Water level measurements will be collected from all the monitoring wells and piezometers regardless of whether or not a particular location is being sampled. Water levels in wells without product will be measured with an electronic water level indicator as indicated in Multi-Site FSP, Appendix A, SOP No. SAS-08-01. The

1530-SSWP Rev-1 NATURAL RESOURCE

RESOURCE TECHNOLOGY well(s) with DNAPL product (i.e. MW-14) will first use an electronic water level indicator for water level measurement followed by a clear, bottom-filling bailer to measure product thickness (SOP No. SAS-08-01). Observations and measurements regarding the presence of MGP-residuals within a well will be recorded on the appropriate forms on which the water level measurements will be recorded.

## 6.6.5 Sampling Schedule and Parameters

Continued groundwater sampling will be completed for the following reasons.

- To detect changes in environmental conditions (e.g., hydrogeologic, chemical, or other changes) that may result in an increased risk or exposure potential;
- To identify any potentially toxic and/or mobile transformation products;
- To assess plume stability and groundwater concentration trends;
- To verify no unacceptable impact to downgradient receptors; and
- To detect new releases of contaminants to the environment that could impact potential remedial action alternatives (e.g., Monitored Natural Attenuation (MNA), institutional controls, etc.).

Groundwater monitoring will be initiated on a quarterly basis following the new monitoring well/piezometer installations such that enough data is collected from the new wells and piezometers before beginning the RI Report. Wells were sampled for the full list of VOCs in May 2005; results of this sampling are provided in Appendix G1. As indicated previously, PVOCs will be sampled in future rounds. The table below indicates which wells and parameters will be sampled during each quarter with notes on the rationale for the well sampling.

1530-SSWP Rev-1

	1 <sup>st</sup> Qtr	2 <sup>nd</sup> Qtr	3 <sup>rd</sup> Qtr	4 <sup>th</sup> Qtr
Existing Wells				
MW1, MW2,	PVOCs, PAHs,	PVOCs, PAHs,		
MW5, MW7,	metals, cyanide	Note 1 - metals, cyanide		
MW8, MW10,				
MW12, MW12D,				
MW13,				
MW17T,MW18T,				
MW19T, MW20T,				
MW21T				
MW6	Water Level only			
MW9	PVOCs, PAHs,		Note 2	
	metals, cyanide			
MW14	Water/Product Level only			
MW15T,MW16T	Water Level		Note 3	
	only			
Staff Gauge	Water Level only			
PW1	Water Level only			
Proposed Wells	•			
MW22	PVOCs, PAHs,		PVOCs, PAI	Hs,
	metals, cyanide	·	Note 1 - metals, o	cyanide
PZ7B, PZ18TB,	PVOCs, PAHs,		PVOCs, PAI	Hs,
PZ23B	metals, cyanide		Note 1 - metals, o	cyanide
New Piezometers	PVOCs, PAHs,		PVOCs, PAJ	Hs,
Along River	metals, cyanide		Note 1 - metals,	cyanide

#### Notes:

- (1) If concentrations from first quarterly round for metals (aluminum, iron, manganese and vanadium) and available cyanide (OIA-1677) are below screening levels, these parameters will be discontinued from further analysis.
- (2) If concentrations from first quarterly round indicate MW7 and MW9 have similar groundwater quality, MW9 (located only 40 ft from MW7) will be discontinued from further sampling. Water level only to be measured at MW9.
- (3) If groundwater concentrations at MW22 (on Wisconsin Central Railroad property) are above screening levels during the first quarterly round, wells MW15T and MW16T will be sampled in the subsequent rounds to define the western extent of contamination.

Following quarterly RI sampling for one year, the groundwater monitoring schedule will revert back to annual sampling. If monitored natural attenuation is considered as a remedial option for groundwater, more than one year of quarterly data may be needed. The RI Report will be prepared after two quarterly rounds of groundwater data is collected, with later data added as a supplement. The estimated schedule for the well installations and quarterly sampling is shown on Figure 16. Groundwater samples will be collected for analysis of the parameters and associated methods listed on Table 4. Samples will be

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 6 – Site Characterization and Assessment Activities
Page 59 of 91

analyzed in a fixed-based laboratory as described in the Multi-Site QAPP and FSP. Groundwater sampling will be completed using bailer sampling methods (as previously performed) described in Section 4 of the Multi-Site FSP, to maintain consistency with previous sampling data. Additionally, USEPA sample identification protocol and sampling forms will be used to ensure that samples are tracked accordingly, and that the laboratory analytical data is provided in a manner consistent with the USEPA database requirements. Field parameters will also be recorded including pH, temperature, dissolved oxygen, oxidation/reduction potential, and conductivity.

## 6.6.6 Aquifer Characterization

Single well aquifer tests will be completed to characterize hydraulic conductivity at the new monitoring well locations only if the drilling observations indicate that the formation is different from the majority of the wells previously installed. Therefore, if the subsurface materials encountered at each well location(s) are comprised primarily of fine to medium grained sand, no testing will be done. No aquifer tests will be performed at the bedrock piezometers. If appropriate, single well tests will be completed in accordance with the methods described in Section 4 of the Multi-Site FSP.

## 6.6.7 Groundwater Monitoring Well Abandonment

If it is determined that any of the wells or piezometers in the monitoring network require abandonment, the agencies will be conferred with to determine the need for a well replacement in that location. These activities will be completed in accordance with the methods described in Section 4 of the Multi-Site FSP. At this time, no well abandonment activities are planned.

# 6.6.8 On-Going System Operation, Maintenance and Monitoring and Future Groundwater Monitoring

System operation, maintenance and monitoring (OM&M) and site groundwater monitoring (as described above) will continue during RI/FS work, including influent/effluent sampling on a semi-annual basis and between carbon unit samples on a bimonthly basis (to evaluate when the carbon units require change-out) as indicated in the table below. Prior treatment system analytical results are provided in Appendix G2. Routine operation and maintenance of the system will continue to be conducted on a weekly basis

1530-SSWP Rev-1

including completing the operations log and changing filter bags as needed. Annual reports of the system OM&M and site groundwater monitoring will be completed.

Treatment System Sampling				
Influent	VOCs, PAHs - Semi-annually in May and November			
Intermediate (Between Carbon)	BTEX – Bimonthly			
Effluent	VOCs, SVOCs, pH - Semi-annually in May and November			

After completing the fourth quarter of groundwater sampling, monitoring will revert back to annual sampling with potential modifications to the groundwater monitoring well network and parameter list. The revised groundwater monitoring schedule will be maintained for the time period between which the RI Report is submitted to the time the RI Report is approved.

The RI Report will provide a plan for continued groundwater monitoring between the timeframe of performing the RI and remedial action. If monitored natural attenuation is considered as a remedial option for groundwater, more than one year of quarterly data may be needed. Identification of and the need for continuing site activities will be discussed with USEPA representatives following completion of the RI work and report.

#### 6.7 Manitowoc River Assessment

## 6.7.1 Site Morphology

A benchmark (585.33 feet above MSL) is located on the sheet pile wall (Figure 2) at the interface of the Manitowoc River. The depth to river water level will be recorded during each groundwater monitoring event to assess the interaction of the river with groundwater.

Measurements will be obtained in the field to calculate flow velocities and discharge of the river as water enters the turning basin, as water passes through the turning basin, and as water exits the turning basin (Sheet 2). Those sampling locations will correspond with the surface water sampling transects identified in Section 6.7.4. Information available from the United States Geological Survey (USGS) gauging station 04085427 located on the Manitowoc River approximately five miles upstream of the Site will be used in

1530-SSWP Rev-1

conjunction with field data to assess trends in flow volumes and discharge velocities. This gauging station can only provide relative flow information in the vicinity of the Site due to the separation distance between the gauging station and Site, and other inputs to flow from point and non-point sources. In addition, current and historical river bathymetry measurements collected by the USACE will be obtained and compared to each other to identify areas of erosion and deposition within the river channel. The turning basin is actively being used by commercial ships.

#### 6.7.2 Bathymetric Survey, Side-Scan Sonar, and Sub-Bottom Profiling

Prior to collecting any sediment samples, river bathymetry and stratigraphy will be evaluated using single-beam or multi-beam sonar, side-scan sonar and sub-bottom profiling. A subcontractor will be used to perform the bathymetric survey, side-scan sonar and sub-bottom profiling. The subcontractor will be identified to USEPA prior to initiating field activities in accordance with the AOC/SOW and the subcontractor's SOPs will be submitted to USEPA for review and approval.

Results of the bathymetric survey, side-scan sonar and sub-bottom profiling will be presented in the RI Report.

#### 6.7.2.1 Bathymetric Survey

Prior to collecting any sediment samples, river bathymetry will be evaluated using single-beam or multi-beam sonar. The results from the sonar survey will provide a comprehensive assessment of the river geometry and water depths which will be used to establish a baseline condition, measure river flow velocities and hydrologic characteristics, and provide data for use in the FS. The data collected will also be used with stream flow measurements (velocity measurements, staff gauge measurements, and historic stream flow data from USGS gauging station 04085427) to calculate flow velocities and discharge for this segment of the river, as discussed in Section 6.7.4.

The bathymetry transects will be spaced appropriately to cover the river from bank to bank and extend a distance of approximately 1,200 river feet downstream, corresponding to a portion of the river that widens just downstream of the Wisconsin Central Railroad bridge, and extend a distance of approximately 1,200 river feet upstream which is beyond the upstream end of the turning basin (Sheet 2). Additional bathymetric transects may be added in the field at the direction of the RI Leader.

1530-SSWP Rev-1

Natural Resource Technology

WPSC Manitowoc Former MGP Site Site-Specific Work Plan

> Revision 1 April 10, 2008

Section 6 - Site Characterization and Assessment Activities

Page 62 of 91

6.7.2.2 Side-Scan Sonar

Following the bathymetric survey, a side-scan sonar survey will be performed. The results from the side-scan sonar will provide a three-dimensional picture of the bottom of the river at a resolution fine enough to identify debris (e.g., bricks and wood timbers). Results will be used to determine areas where the river bottom is irregular and to assist in identifying debris or other man-made materials present on the river bed, which may be used to refine sediment coring locations. In addition, the side-scan sonar may provide information on the location of the underwater utilities that may need to be considered during the FS.

The side-scan sonar will cover the same area of the river as the bathymetric survey (Sheet 2). Additional side-scan sonar transects may be added in the field at the direction of the RI Leader.

6.7.2.3 Sub-Bottom Profiling

Sub-bottom profiling will be used to further identify the lateral extent of sediment types identified by the cores/borings and provide a high-resolution image of the subsurface stratigraphy. The data will provide information regarding the vertical extent of the soft sediment transition to hard sediment horizon in the subsurface. The sub-bottom profiles will be completed moving parallel to the shoreline.

The sub-bottom profile survey will be conducted concurrently with the side-scan sonar survey.

Therefore, the same survey line spacing will be implemented for sub-bottom profiling as described above for side-scan sonar.

The sub-bottom profile data will be processed and interpreted to graphically represent the sediment horizon. Longitudinal profiles will be generated and incorporated in the project database with the bathymetric and side-scan sonar datasets. These data will be used to assist in identifying the lateral and vertical requirements for sediment sampling and assist in remedial design.

6.7.3 Sediment Poling

Sediment poling using an aluminum pole, as described in Section 4 of the Multi-Site FSP will be used to measure the river water depth (i.e. depth to river bottom) and thickness of soft sediment. The elevation of the river will be surveyed from a known benchmark, and this will serve as the reference for both the depth

1530-SSWP Rev-1 NATURAL

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 6 – Site Characterization and Assessment Activities
Page 63 of 91

measurements for later conversion to elevations. These results will be correlated with the results of the bathymetric survey, side-scan sonar survey, and sub-bottom profiling. It will also be used to assist with identifying sediment sampling locations. In addition, sediment poling results will be used to refine volume estimates for use in the FS. Sediment poling will be conducted at every sediment and surface water sampling location along the transects illustrated on Sheets 2 and 3. Poling locations will be determined using a differential global position system (DGPS) unit that is accurate to ±1 meter in accordance with the methods described in Section 7 of the Multi-Site FSP.

The results of the sediment poling locations will be compared to the results of the bathymetric survey, sub-bottom profiling, and the NRT 2003 poling data. Discrepancies, if present, may be confirmed with additional sediment poling. However, the minimum distance between poling transects will be 100-feet, unless otherwise determined by the RI or Field Team Leader, based on field conditions. Based on previous sediment poling and analytical results, the sediment poling density may be increased adjacent to the former MGP facility to evaluate the volume of soft sediment present in areas that may be identified with elevated concentrations of MGP-residuals.

The thickness of soft sediment will be recorded on field forms as discussed in Section 4 of the FSP. If sediment is observed on the tip of the pole, the observations (e.g., presence of clay, sand, evidence of tar) will be recorded. If debris is present on the surface of the sediment, there is typically a distinguishable sound when the aluminum pole hits debris, rather than soft sediment. If debris is suspected, additional poling may be performed in the immediate vicinity (5-foot radius or less) to evaluate the differences in the top of soft sediment. The presence of debris will also be noted on the field forms.

#### 6.7.4 Surface Water Sampling

One, and possibly two, surface water sampling events within the Manitowoc River will be performed. The first surface water sampling event will assess the surface water quality in the proximity of the former MGP. The first sampling event is targeted to be performed during warmer weather when volatiles and semi-volatiles would be expected to be released and if possible, during the Step I sediment sampling event (Section 6.7.5) and/or concurrent with a groundwater monitoring event. Surface water samples from the river will be collected with the pump and tubing method as discussed in Section 4 of the Multi-Site FSP.

1530-SSWP Rev-1

Three transects will be established for the first surface water sampling event. There will be three sampling locations on each transect; at one-quarter, at one-half, and at three-quarters of the distance across the river. One discrete sub-sample will be collected from each transect location, at 0.8 times the total water column depth at a particular location; totaling 9 water sub-samples to be collected from the river. Surface water sampling locations will fall on transects that will also be used for the bulk chemistry portion of the investigation. Each transect sub-sample location will be identified by the suffix A, B, or C, as samples are collected from the east bank toward the west bank of the river. The three transects will extended perpendicular from the shore to the opposite shore and will be established in the following areas (Sheet 2):

- Transect TSW-1, located upstream of the former MGP property and just upstream of the turning basin (potential ambient sample locations);
- Transect TSW-2, located on the southern end of the sheet pile wall and centered on the area of MGP impacted sediments; and
- Transect TSW-3, located at the downstream end of the turning basin just north of the Wisconsin Central Railroad bridge (potential ambient sample locations).

A second surface water sampling event may be performed, pending the analytical results of the first sampling event. If COPCs are detected above the screening levels provided in the Multi-Site RAF, additional sampling may be performed to assess surface water quality in localized areas above and downstream of affected sediment to evaluate if affected sediments are impacting surface water quality. The surface water sampling locations for the second sampling event, if performed, will be selected based on field conditions (i.e., COPC concentrations, presence of MGP-residuals in sediment, etc.). Sample locations and rationale will be reviewed with USEPA prior to performing the second surface water sampling event.

A peristaltic pump and flow-through cell will be used to collect the surface water samples and determine field characteristics, including pH, temperature, dissolved oxygen, oxidation/reduction potential, conductivity, and turbidity. Sediment poling with an aluminum pole as described in Section 4 of the Multi-Site FSP will be used to measure the total water column depth and estimate soft-sediment thickness at each location. Based on the historic sediment sampling results, surface water samples will be analyzed for the full list of COPCs and total suspended solids (Table 4) in accordance with the Multi-Site QAPP.

1530-SSWP Rev-1

River velocity measurements will be made concurrent with the surface water sampling. The river velocity measurements will be collected as described in Section 4 of the Multi-Site FSP at each surface water subsample location (Sheet 2). A velocity meter attached to a ridged steel rod will be used to record river velocity from the sampling boat. After the sampling location has been poled to verify depth to top of sediment, the velocity meter will be lowered to into the water column. For water depths of 2.5 feet or less, a velocity measurement will be made at 0.6 times the total water column depth. The velocity measurements at locations where the water column is greater than 2.5 feet will be recorded at 0.2 and 0.8 times the total water column depth. At each depth, the velocity meter will be rotated around until the maximum velocity is recorded on the display. The minimum and maximum velocity at each depth and each location will be recorded on field logs to evaluate the differences in water velocities with depth and for use in the FS.

A qualitative assessment of water quality within the turning basin will be performed to provide information regarding the influences that boat traffic has on sediment stability and water quality. This assessment pertains to large lake freighters/barges, not small recreational craft. Anecdotal information to date suggests that some large boats come close to the former MGP when they turn around in the basin. The City of Manitowoc harbor master will be contacted for their views in this assessment, and also to obtain information about the types, frequency, and scheduling of the large boat traffic. During RI activities, field personnel will visually observe the water clarity immediately before, during, and for a short period after a boat's trafficking within the turning basin to characterize the changes in water clarity as a result of the boat. A goal is to assess up to five large boats. The qualitative assessment will be performed from land rather than from a boat due to safety concerns of being in the turning basin with large boats.

Sampling and measurement locations will be recorded using a DGPS unit that is accurate to  $\pm 1$  meter in accordance with the methods described in Section 7 of the Multi-Site FSP.

## 6.7.5 River Sediment Sampling

Sediment sampling will be conducted in two steps. Step I sampling will be conducted to collect samples to be subject to toxicity testing and to calculate a site-specific risk value based on results of ecological risk and human health risk assessments. Step II sampling will identify zones of risk based on sediment

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 April 10, 2008 Section 6 – Site Characterization and Assessment Activities Page 66 of 91

concentration and the nature of soft sediments and consolidated parent materials that exceed the calculated site-specific risk value and source (i.e., tar) areas. Representative sediment samples for geotechnical and waste disposal characterization will also be collected in Step II. The sampling events will employ different sampling techniques and will have separate analytical parameters, based on the results of Step I, it is anticipated Step II COPCs will be refined.

The investigation will include surface water samples, soft sediment samples, and parent material samples (consolidated soils that underlie the soft sediment). Surface water and soft sediment samples will be collected upstream, adjacent to, and downstream of the former MGP facility as discussed in Section 6.7.4 and shown on Sheets 2 and 3. Prior investigations suggest that MGP-impacted parent material is limited to portions of the river adjacent to the former MGP facility; as such, sampling of the parent material will be limited to the area in and around the MGP-impacted sediments illustrated on Sheet 3. Table 4 of the Work Plan provides the analytical summary with analytical methods, quantity of samples, container type, sample volume, preservation, and holding times from sample date.

Horizontal control will utilize a DGPS and the boat will be properly anchored to maintain position as described in Section 7 of the Multi-Site FSP. Locations will be recorded as latitude/longitude and later converted to the Wisconsin State Plane - North datum. Vertical control will be established relative to the benchmark established on Site (NAVD88).

#### 6.7.5.1 Step I Sediment Sampling

#### **Ecological Risk Assessment**

A minimum of 23 samples soft sediment samples (Sheet 2) will be collected adjacent to the former MGP facility to provide samples with a range of PAH concentrations (see table below) to support the SLERA. The intent is not to limit the SLERA to the near-surface biologically active zone, but rather to evaluate risk correlations to different ranges of PAH concentrations regardless of depth. Samples will be collected generally within the areas previously characterized, with a goal of obtaining several samples in each of four total PAH concentration ranges described below. It is very likely that more than 23 samples will be necessary to obtain the required number of samples in each of the PAH concentration ranges. Since the exact number of samples and concentration distribution will be determined in the field, these additional

1530-SSWP Rev-1 NATURAL RESOURCE

TECHNOLOGY

sample locations (beyond the minimum 23) have not been plotted on Sheet 2. The samples will be collected in and around the area of MGP-impacted sediments illustrated on Sheet 2 and the final locations will be recorded using a DGPS unit as described in Section 7 of the Multi-Site FSP.

A Ponar® grab sampler will be used as described in Section 4 of the Multi-Site FSP to collect soft sediment samples at select locations within the areas previously characterized. The depth to the top of soft sediment and the thickness of soft sediment measured by poling techniques will be recorded prior to using the Ponar® grab sampler. Sufficient sediment volume will be collected (estimated to require three to five grabs) and homogenized in a stainless steel bowl to allow for chemical analysis (mobile laboratory or fixed-based laboratory), physical analysis, and sediment toxicity testing. Samples for PVOCs will not be homogenized to minimize volatilization. Each of these sub-samples will be collected using a stainless steel spoon. If the surficial sediment samples do not provide the range of PAH concentrations required, samples of the subsurface soft sediment (e.g., 0 to 2 feet) may be collected using direct push or vibrocore methods described in Section 4 of the Multi-Site FSP.

All samples will be initially analyzed using an on-site mobile laboratory to identify samples with concentrations representing a range of total PAH concentrations. Optimally, the samples will be evenly distributed in the following ranges:

Sample Quantity	Total PAHs (ppm)		
3	Ambient Reference Locations		
5	10-90		
10	100-900		
5	1,000 +		

Initial PAH sample results may be used with an average TOC concentration (from previous analytical results) to evaluate whether the PAH concentrations summarized above provide an appropriate range of predicted toxicity using the USEPA's equilibrium partitioning sediment benchmark (ESB) approach.

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 6 – Site Characterization and Assessment Activities
Page 68 of 91

Reference (ambient) locations will be selected from areas:

- A reasonable distance(s) upstream of the former MGP site;
- Where soft sediment has a similar texture to impacted soft sediment; and
- Where soft sediment has a similar depositional environment to impacted soft sediment.

Sediment samples with total PAH concentrations that are not within these ranges listed above, or samples with total PAH concentrations in a range that has already met the optimum sample quantity, will be handled as investigative waste material and a new sample location will be evaluated. All sediment samples will be stored on ice during the mobile laboratory analysis.

Total PAH concentrations within these ranges will be distributed to the extent possible in order to evaluate a broad range of sediment toxicity; however, the distribution may be modified based on field encountered conditions (i.e., range of concentrations) and initial estimates of expected toxicity using the ESB approach. Based on the predicted toxicity and the site-specific concentrations detected, the above distribution may be modified. For example, if the ambient reference locations are greater than 10 ppm total PAHs, the distribution or sample quantity may be shifted. The concentrations of the selected samples for toxicity testing will be reviewed with USEPA prior to performing toxicity testing.

Samples will be further analyzed for COPCs (as identified in Section 3.7), ammonia, and sulfide as described in the Multi-Site QAPP and in accordance with the methods listed in Table 4 to evaluate potential confounding effects. COPCs will be compared to the screening levels of the Multi-Site RAF to evaluate the need for additional assessment. If necessary, the samples selected for toxicity testing may be adjusted to include elevated BTEX concentrations. Sediment samples will also be analyzed for black carbon (aka "soot" carbon), based on the procedural definition of soot as the remaining carbon after muffle furnace drying and acid treatment of sediments to remove other forms of carbon (Gustaffson *et al.* 1997, Accardi-Dey and Gschwend, 2003). The ecological risk assessment analytical data package will be fully data validatable.

A portion of each of the 23 samples selected for further analysis will also be sent to a toxicity laboratory for testing using a modified version of the procedures described by EPA/600/R-99/064 Methods for Measuring the Toxicity and Bioaccumulation of Sediment-Associated Contaminants with Freshwater

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site Site-Specific Work Plan

> Revision 1 April 10, 2008

Section 6 – Site Characterization and Assessment Activities

Page 69 of 91

Invertebrates, Second Edition; Method 100.4. The test endpoints will be a 28-day survival and growth (weight and length) test using Hyalella azteca (amphipod) to evaluate the toxicity of whole sediments. Each set of whole sediment toxicity tests will be conducted with an uncontaminated control sediment and

a minimum of 8 replications of each sediment sample.

Human Health Risk Assessment

Human Health screening levels have not been established in the RAF and will be developed (based on site-specific conditions) for the Manitowoc Site and presented in the Risk Assessment section of the RI report. Based on preliminary review of potential exposure assessments, the human health receptors are not anticipated to drive screening level decisions. Ecological screening levels are generally lower than the human health screening levels and will be assumed as the basis for defining risk zones within this

SSWP.

A minimum of 3 samples will be collected for the human health risk assessment. Soft sediment samples will be collected adjacent to and slightly downstream of the former MGP facility, generally within the areas previously investigated based upon areas where there is a high probability of direct contact to MGP residuals in the sediments due to recreational activities (i.e., wading or swimming in river, fishing, etc). Based on field reconnaissance, there is no evidence (i.e. pathways to the river) to indicate that people are wading in the river. As previously discussed, the river drops off abruptly approximately 5-feet from the shore, the river is known to be over 20 feet deep in places within 50 feet of shore, and the sheet pile wall and railing prevents people from wading into the water along much of the shore line adjacent to the former MGP facility.

The depth to the top of soft sediment and the thickness of soft sediment will be recorded on field logs prior to sample collection. Samples will be collected from 0 to 2 feet below the top of sediment (the assumed depth to which a person would sink to, wading across the river) in locations that meet the following criteria:

Areas in which MGP residuals (tar and sheen) have been observed;

Areas with shallow water depths;

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 April 10, 2008 Section 6 – Site Characterization and Assessment Activities Page 70 of 91

- Areas of the river accessible from land (i.e., boat dock areas);
- Areas of the river in which site conditions indicate people may access the river; and
- An Ogeechee<sup>TM</sup> open barrel corer or other drive-push sampler will be manually pushed or driven to 2 feet below mudline as described in Section 4 of the Multi-Site FSP. The sediment will be homogenized over the entire core length in a stainless steel bowl using a stainless steel spoon. The sediment will be analyzed in the mobile laboratory for the parameters identified in Table 4.

Samples will be analyzed as described in the Multi-Site QAPP and in accordance with the methods listed in Table 4. Samples for PVOCs will not be homogenized to minimize volatilization. The analytical data package will be fully data validatable.

If the analytical results indicate the interval concentration is greater than the screening value presented in the Step I of the Multi-Site RAF or if field observations during the RI activities indicate an access point to the river, additional borings may be collected. However, the analytical results generated as part of the ecological risk assessment will also be used to assess potential human health risk.

#### Site Specific Risk and COCs

The results of Step I sampling will be used to calculate a site-specific risk value based on ecological risk and human health risk assessments, and to assist delineation of the source area of sediment contamination. This information will be used to reduce the list of COPCs into a list of COCs and assist in sample location for Step II. The COC list will be developed from COPCs that cause risk to human health or the environment at such levels that a response action will be considered.

#### 6.7.5.2 Step II Sediment Sampling

Sediment coring will be conducted to further characterize sediment concentrations and the nature of soft sediment and parent material exceeding the calculated site-specific risk value (delineate risk zones) and further refine grossly affected sediment areas. Characterization will include definition of degree and extent of contaminated sediment, evaluation of geotechnical properties of sediment, and analytical testing for waste disposal. All sampling activities will be cleared with Digger's Hotline to mark submerged utility structures, cables, and pipelines, if any.

1530-SSWP Rev-1 NATURAL RESOURCE

TECHNOLOGY

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 April 10, 2008

Section 6 - Site Characterization and Assessment Activities

Page 71 of 91

Sediment and parent material samples will be collected as described below using a spud barge and vibrocore, hollow-stem auger drill rig, sonic drill rig, or direct push sampling unit as described in Section 4 of the Multi-Site FSP. The specific drilling methods will be identified to USEPA prior to contracting. The drilling method selected will consider core recovery, core disturbance, contractor availability, and contractor costs. The subcontractor will be identified to USEPA prior to initiating field activities in accordance with the AOC/SOW and the qualifications will be submitted to USEPA for review and approval. If applicable, subcontractor SOPs may also be submitted at this time.

Sampling locations will be recorded using a DGPS unit as described in Section 7 of the Multi-Site FSP.

Sediment cores will be continuously sampled, visually characterized, logged and sub-sampled in accordance with Section 4 of the Multi-Site FSP. The sediment core will be subdivided into the following intervals:

- 0 to 6 inches below mudline (river bottom)
- 6 to 18 inches below mudline
- 18 to 30 inches below mudline
- 30 to 42 inches below mudline
- 42 to 54 inches below mudline, etc.

The 0 to 6 inch below mudline interval will be collected to assess the current concentrations the benthic community is exposed to. The core will be subdivided in one-foot intervals to the bottom of the core. If the last interval is less than 4 inches in thickness, it will be added to the previous interval or analyzed as a separate interval. Each interval will be homogenized in a stainless steel bowl using a stainless steel spoon. Upon completion of sediment borings, non-dedicated sampling equipment will be decontaminated as described in Section 8 of the Multi-Site FSP.

Samples will be analyzed to further characterize sediment concentrations of the chemicals of concern (COCs) identified in the risk assessments (Step I). The list of COCs will be reviewed with USEPA prior to initiation of Step II. Table 4 provides the analytical summary of the full list of COPCs from which the COCs will be determined. The analytical data packages will be fully validated by an independent third party data validator.

1530-SSWP Rev-1

NATURAL
RESOURCE

Cores which exhibit visible or olfactory evidence of tar or significant sheen in all intervals may not be analyzed, as these cores will be considered affected by MGP residuals, and thus require evaluation during the FS. Each interval in cores without visual or olfactory evidence of tar or significant sheen will be analyzed for COCs to characterize concentrations in sediment. Additional cores may be advanced between sampling locations and transects to refine the area considered in the FS. Data from cores and the site-specific risk values will be used in the FS to establish areas for which remedial alternatives will be developed.

#### Sampling Transects

Step II sampling will occur along nine sampling transects labeled TS2-1 through TS2-9 (Sheet 3). Initial sediment transects and locations may be adjusted based on the findings of Step I. The initial sediment transects/locations will be reviewed with USEPA prior to initiating Step II sampling.

The proposed initial locations of the transects are based on relative location to MGP impacted sediments as observed from previously performed investigations. Sediment sampling will be bounded approximately 700 river feet at the channel center upstream and approximately 900 river feet at the channel center downstream of the MGP property by transects TS2-1 and TS2-9 respectively. Transects TS2-4, TS2-5, and TS2-6 are located approximately one quarter, one half, and three quarters of the length of the source area. Location of the sediment sampling transects relative to source area has been summarized below:

- TS2-1: Upstream limit of sampling (approximately 700 river feet at the channel center upstream), provides narrow channel velocity measurements, and potential ambient measurements of soft sediment and surface water.
- TS2-2: Fills data gap between upstream limit and upstream edge of source area transects (TS2-1 and TS2-3), provides soft sediment samples.
- TS2-3: Upstream edge of source area, provides soft sediment and parent material samples.
- TS2-4: Upstream portion of source area (approximately ¼ length of source area), provides source area soft sediment and parent material samples, potential waste characterization samples.

- TS2-5: Central portion of source area (approximately ½ length of source area), provides turning basin channel velocity measurements, source area soft sediment, parent material, and surface water samples.
- TS2-6: Downstream portion of source area (approximately ¾ length of source area), provides source area soft sediment and parent material samples, potential waste characterization samples.
- TS2-7: Downstream edge of source area provides soft sediment and parent material samples.
- TS2-8: Fills data gap between downstream limit and downstream edge of source area transects (TS2-7 and TS2-9), soft sediment samples.
- TS2-9: Downstream limit of sampling (approximately 900 river feet at the channel center downstream), provides downstream channel velocity measurements, and potential ambient measurements of soft sediment and surface water.

MGP-impacted sediments identified in previous investigations are located between the USACE navigation channel and the shore of the former MGP facility (Sheet 3). Therefore, sediment sampling locations are more dense between the USACE navigation channel and the east shore along each transect (i.e., sediment sampling is weighted towards the bench sediments near the former MGP facility).

Sampling along each transect will start from the east shore moving towards the west shore. A minimum spacing of 50 feet will be maintained between sampling locations starting on the east side of the river (east bench). Wherever possible, more than one sampling location will be placed within the east bench river sediments. After collection of the east bench samples, one channel sample will be collected 100 feet from the last east bench sample along the transect. On most transects, one sample will also be collected from the west bench sediments to evaluate the other side of the channel. All transects except TS2-4, TS2-5, and TS2-6 include samples collected from the west bench and the navigation channel. Initial transect sediment samples are summarized on Sheet 3.

Additional sediment transects or sampling locations may be added on an iterative approach to refine the area/volume of sediment above the site-specific risk values, background "ambient" concentrations, or other screening values (i.e., PEC, etc.) from the Multi-Site RAF used to define the zones of acceptable versus unacceptable risk. The approach to extrapolating (i.e., kriging, inverse distance weighting, straight interpolation, etc.) between these data points will be discussed with USEPA as part of the RI Report scoping meeting.

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site Site-Specific Work Plan

Revision 1 April 10, 2008

 $Section \ 6-Site \ Characterization \ and \ Assessment \ Activities$ 

Page 74 of 91

Soft Sediment Samples

The soft sediment samples will be collected along transects (Sheet 3) discussed above using a vibrocore

sampler or equivalent to refusal (i.e., top of consolidated parent material) as described in Section 4 of the

Multi-Site FSP. The vibrocore sampler is electrically powered to advance a core tube with a dedicated

liner up to 20 feet into soft sediment. After selecting the subcontractor, the operating procedure may be

modified. The number and location of the soft sediment samples may be adjusted in response to Step I

source area delineation.

Historical data has shown that core recoveries are as low as 60 percent; however, technology for

collecting core samples has advanced to the point where 90 percent recovery should be expected for most

sample types. To prevent precluding any emergent technologies, a performance-based specification will

be written in the request for proposal to potential sampling subcontractors. The specifications that will be

required include:

Ability to attain and maintain station position: use of spuds is preferred over anchoring;

Station location: less than 3 feet (approximately 1 meter) (x, y) using DGPS in latitude/longitude degrees, minutes, and seconds and later converted to Wisconsin State Plane

- North datum:

■ Depth measurement with water level correction: less than 0.1 feet (approximately 3

centimeters (cm)) (z) referenced to NAVD88; water elevation to be surveyed at least once per

day (i.e., mid-day) for determining core sample elevation;

Coring equipment: vibrocore or equivalent;

Recovery/penetration: greater than 90 percent (this is a goal, not a minimum requirement);

Ability to document rate of penetration; and

■ Ability to collect core samples down to parent material (potentially 1 to 10 feet).

Parent Material Samples

Previous investigations identified MGP impacts and coal tar in the consolidated (between 5 to 50+ blows

per foot) sand, silt, and clay parent material. These impacts were documented within 50 feet of shore

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 6 – Site Characterization and Assessment Activities

Page 75 of 91

along the east bank of the river from the north end of the sheet pile wall approximately 400 feet downstream (within the area of observed coal tar impacted sediment on Sheet 3). Impacts in the parent material were documented at depths from 0 to 13 feet below river bottom.

Samples of the parent material will be collected along transects (Sheet 3) discussed above with either hollow stem auger or sonic drilling rigs as described in Section 4 of the Multi-Site FSP. Collection of parent material samples will be limited to transects that are inside or adjacent-to the area of observed coal tar impacted sediment (Sheet 3). Parent material cores will be continuously sampled and advanced approximately 20 feet below river bottom, or until 4 consecutive feet of un-impacted material is encountered (determined by field the geologist visually and using Photo ionization detector (PID)). Cores will be subdivided into 2-foot sections, instead of 1-foot sections, for analysis of COCs. The number and location of parent material cores may be adjusted in response to Step I source area delineation.

#### Additional Elements for Evaluating Ecological Risk

A benthic community structure assessment may be performed if elevated concentrations of PAHs are widely detected in the surface sediment (0-6 inches below mudline). Ideally, the benthic community assessment would be performed at locations selected for toxicity testing. If toxicity testing samples are collected below the biologically active zone (BAZ), the benthic community assessment would not provide meaningful data.

If field conditions indicate otherwise, benthic community structure assessments may be performed concurrently with warm weather surface water sampling activities, to evaluate:

- The abundance and diversity of bottom-dwelling species;
- Evaluate the overall ecological integrity of the river; and
- Assist with defining background or "ambient" conditions.

Prior to performing a benthic community assessment, the RI Leader, Project Manager, Project Coordinator, and Remedial Project Manager will discuss appropriate assessment locations and approach

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 April 10, 2008 Section 6 – Site Characterization and Assessment Activities Page 76 of 91

to distinguish the potentially confounding effects of boat traffic and/or dredging versus COPC concentrations in sediment.

If benthic community structure assessment is performed, a field biologist will assess the benthic community structure, as described in Section 4 of the Multi-Site FSP using sediment samples collected from a grab sampler. The benthic community structure assessment samples will be co-located along sediment and surface water transects and, if possible, next to toxicity testing sample locations. Benthic community assessment locations may be adjusted in the field.

Grab samples will be collected from a reference location, considered as the background or "ambient" location (as described in Section 6.7.5.2), two mid-point transects, and the downstream-most transect within a range of observed total PAH concentration, similar to the distribution to select toxicity samples. Up to three sample locations may be located on each transect based on the total PAH concentration, whether a toxicity testing sample was collected at the location, or the presence of soft sediment identified in the sediment poling (Section 6.7.3). Four replicate samples will be collected from each sample location.

The sediment will be collected from the top of the mudline to six inches below the mudline, generally considered the BAZ for burrowing and feeding in freshwater benthic organisms. Multiple grab samples may be necessary to collect a representative sample of sediment. Field logs will note locations where soft sediment was collected using DGPS as described in Section 7 of the Multi-Site FSP.

#### **Evaluating Residual Upwelling**

As discussed in the Manitowoc Completion Report, surface water samples were collected by WDNR in an attempt to evaluate the presence of MGP residuals in sheens observed on the surface water adjacent to the former MGP. Thereafter, between November 2003 and July 2004, the presence of oil sheens was periodically documented at five different locations along the Manitowoc River. Based on these observations, it appears the oil sheens may be related to the presence of MGP-residuals within the sediment.

1530-SSWP Rev-1 NATURAL RESOURCE

TECHNOLOGY

Page 77 of 91

To assist with evaluating the occurrence of sheens from upwelling caused by gas ebullition, up to ten clear plastic cores will be collected in areas where sheens have been previously observed and where sediment is not grossly affected with MGP residuals (based on visual observations made during Step II Sediment Sampling). It is anticipated that areas with grossly impacted sediment are more likely to be removed and therefore understanding the mechanisms of residual upwelling in these areas is not as relevant. Areas with less affected sediment will be evaluated for a larger range of remedial actions and the mechanisms of residual upwelling will need to be considered to understand potential risks and appropriately design and evaluate remedial alternatives.

The cores will be qualitatively inspected for visual evidence of coal tar, gas bubbles, and sheen within the sediment matrix. Observations will be recorded on the field logs. The cores will be brought back to NRT's warehouse to further observe over time the cores through the clear tubes for potential changes in the presence/absence of sheen as well as gas bubbles.

# Step II Sediment Sample Summary

In summary, 32 COC transect sampling locations are proposed for Step II. These may be modified based on results obtained in Step I and from near real-time results obtained in the field during Step II. Each sampling location could have an average of 5 soft sediment samples submitted for analysis (160 soft sediment COC analyses). Eight of those locations are proposed to include parent material sampling which may have 10 samples per boring submitted for analysis (80 parent material COC analyses). To address Quality Assurance/Quality Control (QA/QC), blind duplicate and matrix spike/matrix spike duplicate (MS/MSD) samples will be collected as described in Section 3.0 of the QAPP.

#### 6.7.5.3 Geotechnical and Waste (WDNR Chapter 347) Sampling

In addition to the cores for analytical testing, approximately 20% of the cores (approximately 7 core locations) will include sample volume for analysis of geotechnical parameters for use in the FS. These parameters include: Atterberg Limits, grain-size, specific gravity, organic content by loss-on-ignition, and moisture content. Field measurements to estimate shear strength may be collected using a pocket penetrometer and/or a torvane (using a large vane for soft soils) as described in Section 4 of the Multi-Site FSP.

1530-SSWP Rev-1

Geotechnical samples will be collected from distinct layers of soft sediment and parent material and may be discrete intervals, or composite samples, depending on the conditions observed. Three core samples will be collected at the same location as the NR 347 samples (Sheet 3) discussed below. The geotechnical samples will be collected from 7 different core locations as summarized below:

- Four core locations will only analyze soft sediment (1 sample each core location);
- Three core locations will analyze soft sediment and parent material (approximately 3 samples per core location);
- The three core locations that analyze both soft sediment and parent material will be collected from the same core locations and the same layers as the NR 347 samples described below; and
- At least 3 samples will be collected from each distinct unit near the source area (e.g. soft sediment, parent material sand, parent material silt and clay).

The final number of geotechnical samples collected may change based on the number of distinct units identified during investigation.

Because dredging of MGP-impacted sediment will likely be included as a remedial alternative to be evaluated in the FS, analytical samples will be collected pursuant to WDNR Chapter 347 "Sediment Sampling and Analysis, Monitoring Protocol and Disposal Criteria for Dredging Projects" (NR 347).

The degree and extent of sediment contamination will be defined through the two step investigation discussed above. In accordance with the substantive requirements of NR 347, three sediment core locations are proposed within and downstream-of the MGP-impacted sediments for the collection of representative waste characterization samples. Two sampling locations will be located within the MGP-impacted sediments identified on Sheet 3, and one sampling location will be located immediately downstream of the MGP-impacted sediments (Sheet 3). Summary of NR 347 sampling:

- Samples will be collected from each distinct layer observed in the material to be dredged;
- If a distinct layer is encountered in more than one boring (very possible), aliquots of that layer from each boring may be composited as described in Multi-Site FSP, Appendix A, SOP No. SAS-06-01 for a representative sample;
- If distinct layers are not present in a boring, the core will be divided into 2-foot segments and each segment will be treated as a distinct layer;

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 6 – Site Characterization and Assessment Activities
Page 79 of 91

- Where MGP-impacts have been observed beneath the soft sediment, sampling will extend into the parent material beneath;
- Each distinct layer of the soft sediment and parent material will be submitted for the suggested base parameter analyses for Great Lakes waterways (Summarized in Table 4); and
- Each core will extend 2 feet past the deepest observed MGP-impacts in either soft sediment or parent material (i.e. maximum potential dredging depth plus 2-feet). This material may be submitted for analysis to establish residual contaminant levels and physical parameters of residual materials.

A composite sample will also be prepared for waste characterization by collecting and combining the entire core from the three NR 347 borings. The composite sample will be sent to a fixed-based laboratory under chain-of-custody procedures. The sample will be analyzed for Protocol B parameters to identify potential disposal options.

In summary, one sample from each distinct layer within the MGP-impacted material (approximately 4 samples) will be submitted for NR 347 analysis, at least three samples from each distinct layer will be submitted for geotechnical parameters (approximately 12 samples), and one composite will be collected for waste characterization. In addition, each 2-foot sample below the proposed project depth (three samples) may also be submitted for NR 347 and geotechnical analysis.

# 6.8 Disposal of Investigation-Derived Waste

Investigative wastes will continue to be containerized during Site investigation activities prior to disposal off-site. NRT will ensure that both facilities listed below meet the requirements of the "Off-Site Rule (OSR)" (September 1993, USEPA) for the disposal of investigation-derived waste prior to undertaking any disposal activities. If either of these facilities does not meet the OSR requirements, USEPA will be informed and appropriate facilities will be identified.

During the soil remediation activities, solid wastes were disposed through Waste Management's Ridgeview Landfill. Therefore, soils and sediment wastes generated during well/boring installation and river sampling activities may be disposed at this facility based on the historic use of this Site for solid waste disposal purposes. Because the soil data from the site was collected in the 1990's, the landfill will likely require that new samples be collected. A composite sample of soil and a composite sample of sediment will be prepared for waste characterization by collecting representative soil and sediment in the

WPSC Manitowoc Former MGP Site Site-Specific Work Plan

Revision 1 April 10, 2008

Section 6 – Site Characterization and Assessment Activities

Page 80 of 91

project area. The composite sample will be sent to a fixed-based analytical laboratory for Protocol B

analysis parameters.

Groundwater wastes have been disposed through the City of Manitowoc publicly owned treatment works

(POTW). Therefore, groundwater and surface water wastes are anticipated to be disposed through this

POTW. All disposal activities will be completed in accordance with applicable state and federal

regulations and the methods described in Section 9 of the Multi-Site FSP.

Representative samples for disposal purposes will be obtained and provided as required by the disposal

authority through which the wastes will be managed and disposed. The landfill will be contacted prior to

sending waste characterization samples to the laboratory to verify the required analysis.

6.9 Record Keeping

Details of field and laboratory records and data management and storage are provided in the Multi-Site

QAPP and FSP.

6.10 Sample Analysis and Validation

The on-site mobile, fixed-based, toxicity and geotechnical laboratories will be coordinated and contracted

following USEPA written approval of this SSWP. The selected laboratories will be identified to USEPA

prior to initiating field activities in accordance with the AOC/SOW and the laboratories SOPs, if not

previously submitted or if revised since submittal, will be provided to USEPA for review and approval.

Table 4 summarizes the proposed Sampling and Analysis Plan for the Manitowoc Former MGP and

includes samples to satisfy QA/QC requirements in accordance with Section 2 of the Multi-Site QAPP.

As described above, the dynamic work plan approach will be used and additional samples (including

QA/QC samples) may be collected.

Laboratory procedures, field measurements and sample results will be verified and/or validated as

discussed in the Multi-Site QAPP (Section 4).

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 6 – Site Characterization and Assessment Activities
Page 81 of 91

6.11 Data Evaluation and Tabulation for Risk Assessment

Verified and/or validated data will be entered into NRT's database and tabulated for use as described in the Multi-Site QAPP. Details of the procedures for assessing the precision, accuracy, representativeness, completeness and comparability of field data and analytical laboratory data are described in Section 4 of the Multi-Site QAPP.

The data will be evaluated to assess if the DQOs identified in the Multi-Site QAPP have been met.

Analytical results will be organized in a logical manner such as by sample location number, sample type or sample area. Analytical tables will indicate the unique sample identification number corresponding to the sample/location/well name, sampling date and time, sample depth, detection limits, analytical results (following the units of measurement presented in the Multi-Site QAPP Table 9) and validation qualifiers, if appropriate. Data may be presented in summary tables, graphs, and as plan view and/or cross-sectional views with COPC concentrations, as determined necessary.

Data sets may be created for each medium and may include summary statistics (detection frequency, arithmetic mean concentration, maximum detected concentration, standard deviation, and 95% upper confidence limit of the mean (UCL).

1530-SSWP Rev-I

# 7 REMEDIAL INVESTIGATION REPORT

An RI Report will be prepared at the conclusion of the investigation activities. This report will include the following information and documentation, as appropriate, in accordance with Task 4 of the SOW attached to the Settlement Agreement:

- A description of the field procedures and methods used during the RI;
- A discussion of the nature and rationale for any significant variances from the scope of work described in this RI/FS SSWP;
- The data obtained during the RI and previously collected data considered to be of useable quality. This will include analytical data, field measurements, etc. To the extent practicable, RI and previously collected data will be presented in figures and tabular formats;
- The results of an assessment to evaluate if the RI acceptance/performance criteria, as specified in the Multi-Site QAPP, were met;
- The methods and rationales used in evaluating RI and previously collected data;
- Conclusions regarding extent and nature of MGP residuals in the various media being investigated;
- A revised Site-Specific CSM with a discussion of environmental fate and transport of COPCs;
- Baseline Risk Assessment Report, as discussed in the Multi-Site RAF;
- Discussion of anticipated future land use and reuse assessment; and
- Supporting materials for RI data. These will include boring logs, monitoring well construction diagrams, groundwater sampling logs, laboratory analytical reports, and similar information.

# 8 FEASIBILITY STUDY SCOPE OF WORK

This section identifies the approach to the FS for the Manitowoc Former MGP Site. The FS will be completed in accordance with the guidelines presented in "Guidance for Conducting Remedial Investigations and Feasibility Studies under CERCLA" (USEPA, 1988). Additional guidance may be identified as part of future discussions with USEPA during scoping meetings to prepare the Multi-Site FS Memorandum and Documents included in the SOW.

Multi-Site FS Documents to be prepared include:

- Preliminary Remedial Technology Screening (SOW Task 1.2.2.1);
- Preliminary List of Possible ARARs (SOW Task 1.2.2.2); and
- Preliminary Permitting/Equivalency Requirements (SOW Task 1.2.2.3).

# 8.1 Development and Screening of Alternatives

Task 6 of the SOW requires a range of site-specific remedial alternatives be developed and screened for evaluation in the FS. The site-specific remedial alternatives will build on the Multi-Site FS Documents. A Site-Specific Alternatives Screening Technical Memorandum will be prepared to summarize the site-specific alternative array analysis. The memorandum will document the methods, the rationale and the results of the alternatives screening process and will include the following elements:

## 8.1.1 Development of Remedial Action Objectives

Remedial action objectives will be developed based on the results of the human health and ecological risk assessments. Prior to developing these objectives, the contaminants and media of concern, potential pathways, and contaminant level or ranges that are protective of human health and environment will be specified. The remedial response objectives that may be developed will focus on eliminating or minimizing substantial risks to human health and the environment.

1530-SSWP Rev-1

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 April 10, 2008 Section 8 – Feasibility Study Scope of Work Page 84 of 91

# 8.1.2 Identify Areas or Volumes of Media

The areas and/or volumes of media in which response actions may apply will be delineated and will consider the requirements for protectiveness as identified in the RAO. These areas and/or volumes of media addressed will form the foundation for developing and screening remedial technologies.

### 8.1.3 Identify, Screen, and Document Remedial Technologies

Applicable technologies will be identified and evaluated to eliminate technologies that cannot be implemented at the Site. This screening will be accomplished by evaluating alternatives on the basis of effectiveness, implementability, and cost as described below.

- Effectiveness Evaluation The effectiveness evaluation will consider the capability of each remedial alternative to protect human health and the environment. Each alternative will be evaluated as to the protection it would provide and the reductions in toxicity, mobility or volume of COPCs it would achieve.
- Implementability Evaluation The implementability evaluation will be used to measure both the technical and administrative feasibility of constructing, operating and maintaining a remedial action alternative. In addition, the availability of the technologies involved in a remedial alternative will be considered. Innovative technologies will be considered throughout the screening process if there is a reasonable belief that they offer potential for better treatment performance or implementability, few or lesser adverse impacts than other available approaches, or lower costs than demonstrated technologies.
- Cost Evaluation The cost evaluation will include estimates of capital costs, annual operation and maintenance (O&M) cost, and present worth analyses. These conceptual cost estimates are order-of-magnitude estimates, and will be prepared based on preliminary conceptual engineering for major construction components and unit costs of capital investment and general O&M costs available from USEPA guidance documents or past experience with similar systems/projects.

#### 8.1.4 Assemble and Document Alternatives

A draft remedial alternatives screening memorandum for the FS will be prepared that will document the preliminary FS work tasks described above and will address each affected media or operable unit. A draft memorandum will be submitted to USEPA for review and comment, summarizing the results of the preliminary screening. The list of potential remedial alternatives developed above will initially undergo preliminary screening to reduce the number of technologies and alternatives for future analysis while

1530-SSWP Rev-1

NATURAL

RESOURCE

TECHNOLOGY

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 8 – Feasibility Study Scope of Work
Page 85 of 91

preserving a range of options, if necessary. In addition, the ARARs associated with each of the assembled alternatives will be summarized.

# 8.2 Detailed Analysis of Alternatives

Task 7 of the SOW requires a detailed analysis of remedial alternatives be presented to USEPA for use in selecting the Site remedy. This analysis will use the Multi-Site FS documents as the framework.

The remedial alternatives that pass the initial screening will be further evaluated. The detailed evaluation will include an analysis of each remedial option against nine evaluation criteria as set forth in 40 C.F.R. § 300.430(e)(9)(iii). These nine criteria include:

- Overall Protection of Human Health and the Environment Assess whether each remedial alternative meets the remedial action objective that it is protective of human health and the environment. The overall assessment of protection is based on several factors assessed under the evaluation criteria, including long-term effectiveness and permanence, short-term effectiveness, and compliance with ARARs.
- Compliance with ARARs Evaluate how each alternative complies with applicable or relevant and appropriate requirements (ARARs) (Federal and State).
- Long-Term Effectiveness and Permanence Assesses the remedial action in terms of the risk remaining at the Site after the response objectives have been met. The assessment focuses on evaluating the extent and effectiveness of the controls that may be required to manage the risk posed by treatment residuals and/or untreated wastes and is based on the magnitude of remaining risk and the adequacy, suitability, and long-term reliability of management controls to provide continued protection from residuals.
- Reduction of Toxicity, Mobility and Volume through Treatment Addresses the preference for selecting remedial actions that include treatment technologies to permanently and significantly reduce toxicity, mobility or volume of contaminants. Factors to be considered include treatment processes selected, the volume of material to be treated/destroyed, the degree of reduction in toxicity, mobility or volume, and the type/quantity of treatment residuals.
- Short-Term Effectiveness Assesses the effects of the alternative during the construction and implementation phase until the remedial actions have been completed and protection is achieved. The assessment considers the effects on the community and on-site workers during the remedial action, environmental impacts during implementation, and the amount of time until protection is achieved.

- Implementability Addresses the technical and administrative feasibility of implementing an alternative and availability of services and materials to implement the remedy. Technical feasibility considers construction, operation, reliability, flexibility for future remedial action (if necessary), and the ability to monitor performance. Administrative feasibility considers coordination with agency groups, permitting, and approvals.
- Cost Addresses the capital costs, annual operation and maintenance (O&M) costs, and present worth analysis. Capital costs include direct (equipment, labor and materials) and indirect (engineering, financial and other services required to complete remedial actions) costs. Annual O&M costs are post-construction costs to ensure the on-going performance of the remedial action. Remedial action cost estimates will be compared using present worth analysis to reflect future expenses in present-day dollars.
- **Agency Acceptance** Compares the technical and administrative issues and concerns of each alternative presented. Agencies may include USEPA, WDNR, and the State Department of Health.
- Community Acceptance Addresses the community's concerns into the evaluation of remedial alternatives. It is anticipated the focus on community concerns will be on short-term impacts during remedial action and potential reuse scenarios. Community acceptance may be re-evaluated as necessary during public comment on the FS.

# 8.2.1 Compare Alternatives against Each Other and Document the Comparison of Alternatives

After the remedial alternatives have been assessed against the evaluation criteria, a comparative analysis will be performed. This analysis will compare all of the remedial alternatives against each other for each criterion. USEPA will identify and select the preferred alternative.

## 8.2.2 Alternatives Analysis for Institutional Controls

Alternatives that rely on institutional controls will be evaluated using the following criteria:

- Overall Protection of Human Health and the Environment Includes specific institutional control components that will ensure the alternative will remain protective and describes how theses specific control will meet remedial action objectives.
- Compliance with ARARs Evaluates how each institutional control complies with applicable or relevant and appropriate Federal and State requirements.
- **Long-Term Effectiveness** Assesses the adequacy and reliability of institutional controls and how long the institutional control must remain in place.

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 April 10, 2008 Section 8 – Feasibility Study Scope of Work Page 87 of 91

- **Short-Term Effectiveness** Assesses the amount of time it will take to impose an institutional control.
- Implementability Includes research and documentation that the proper entities (e.g., potentially responsible parties, state, local government entities, local landowners, conservation organizations) are willing to enter into any necessary agreement or restrict covenant with the proper entities and/or that laws governing the restriction exist or allow implementation of the institutional control.
- Cost Includes the cost to implement, maintain, monitor and enforce the institutional control.
- State and Community Acceptance Addresses the community's concerns into the use of institutional controls. Community acceptance may be re-evaluated as necessary during public comment on the FS.

# 8.3 FS Report

A Draft FS Report will be prepared to summarize the activities performed and to present the results and associated conclusions for the tasks performed. The report will include a summary of the initial screening study process and present the detailed analysis of remedial alternatives considered as basis for developing a Record of Decision (ROD).

It is anticipated, the FS Report will contain the following sections:

- Introduction and Site Background;
- Development of Remedial Action Objectives and General Response Actions;
- Identification and Screening of Remedial Technologies;
- Development and Initial Screening of Remedial Alternatives;
- Detailed Analysis of Alternatives;
- Comparative Analysis of Alternatives; and
- Summary.

WPSC Manitowoc Former MGP Site
Site-Specific Work Plan
Revision 1
April 10, 2008
Section 8 – Feasibility Study Scope of Work
Page 88 of 91

The feasible technology options for Site remediation, if warranted, will be identified for each general response action, and the results of the remedial technologies screening will be described. Remedial alternatives will be developed by combining the technologies identified in the previous screening process. The results of the initial screening of remedial alternatives, with respect to effectiveness, implementability and cost will be described. Final screening against the nine comparative criteria and the comparison of remedial alternatives will be presented with a final recommended remedial alternative. A description of the key requirements for alternative implementation and estimated time frame for construction of the final recommended alternative will also be presented in the summary and conclusions section of the report.

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision I April 10, 2008 Section 9 – Schedule Page 89 of 91

# 9 SCHEDULE

Figure 16 presents a preliminary project schedule showing the overall progress of the work for the major tasks to be performed in support of the Manitowoc Former MGP RI/FS. Although not included on the schedule, soil vapor sampling and a second round of surface water sampling may be performed pending initial RI results. Due to the seasonally-dependent sampling events, the overall schedule is dependent on USEPA approvals.

The preliminary schedule assumes:

- At least four rounds of groundwater from the proposed groundwater monitoring wells and piezometers are collected,
- Treatability testing is not required and if a treatability study is deemed necessary during the RI, the schedule will be modified when the scope of work is identified; and
- Contractor availability during the time periods needed.

Following approval of the SSWP, a more detailed or revised schedule may be submitted to USEPA with the first monthly progress report, at least 15 days following approval of the SSWP.


## 10 REFERENCES

- 1973 Skinner E.L., and Borman, R.G., Water Resources of Wisconsin-Lake Michigan Basin. U.S. Geological Survey. Hydrologic Investigations Atlas HA-432.
- 1988 October, United States Environmental Protection Agency, Guidance for Conducting Remedial Investigations and Feasibility Studies under CERCLA. Office of Emergency and Remedial Response, OSWER Directive No. 9355.3 01.
- 1993 June, WW Engineering and Science Drawings, Wisconsin Fuel & Light Company Manitowoc, Wisconsin: In Situ Stabilization/Solidification of Coal Tar Impacted Soils: Contract No. 2. Project Number 22574/63595
- 1993 September 22, United States Environmental Protection Agency, "Off-Site Rule". Regulatory citation is 40 CFR 300.440. http://www.epa.gov/epaoswer/hazwaste/id/offsite/offsite.htm.
- 1997 June 5, United States Environmental Protection Agency, Ecological Risk Assessment Guidance for Superfund: Process for Designing and Conducting Ecological Risk Assessments - Interim Final. Environmental Response Team, EPA 540-R-97-006.
- 2003 December, Wisconsin Department of Natural Resources, Consensus-Based Sediment Quality Guidelines, Recommendations for Use & Application, Interim Guidance.
- November, Wisconsin Department of Natural Resources, Letter to Wisconsin Public Service Corporation, Public Health Consultation, Former Manufactured Gas Plant, 402 North 10th Street, Manitowoc, WI, BRRTS #02-36-000219.
- 2006 May 5, United States Environmental Protection Agency and Wisconsin Public Service Corporation, Settlement Agreement and Administrative Order on Consent for the conduct of Remedial Investigations and Feasibility Studies at six WPSC MGP Sites in Green Bay, Manitowoc, Marinette, Oshkosh, Stevens Point and Two Rivers, Wisconsin. U.S. EPA Region 5, CERCLA Docket No. V-W-06-C-847.
- 2006 October 31, Natural Resource Technology, Inc., Operation, Maintenance and Monitoring Status Report, Reporting Period September 1, 2005 to August 31, 2006, Former Wisconsin Fuel & Light Manufacturing Gas Plant, 402 North Tenth Street, Manitowoc, Wisconsin, USEPA ID# WIN000509949.
- 2006 December 4, Natural Resource Technology, Inc., Completion Report, Former Manufactured Gas Plant, Manitowoc, Wisconsin, USEPA# WIN000509949.
- 2007 August, Generalized Conceptual Site Model, prepared for Integrys.

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 April 10, 2008 Section 10 – References Page 91 of 91

2007	September, Exponent, Multi-Site Risk Assessment Framework Revision 0, Former Manufactured Gas Plant Sites.
2007	September Multi-Site Quality Assurance Project Plan Revision 2, prepared for Integrys.
2007	August Multi-Site Health and Safety Plan, prepared for Integrys.
2008	February, Multi-Site Field Sampling Plan Revision 3, prepared for Integrys.

# **FIGURES**



SOURCE: EARTHVISIONS U.S. TERRAIN SERIES, © EARTHVISIONS, INC. 603-433-8500. USGS 7.5 MINUTE QUADRANGLE, MANITOWOC. DATED 1954. PHOTOREVISED 1973.



DRAWN BY: RLH 7/1/02





Natural Resource Technology

# SITE LOCATION

FORMER MANUFACTURED GAS PLANT WISCONSIN PUBLIC SERVICE CORPORATION MANITOWOC, WISCONSIN

APP'D BY: JTB DATE: 7/1/02


FIGURE NO.


PROJECT NO.


1530


DRAWING NO.


1530-12-A01




















SOURCE NOTES:
THIS DRAWING WAS DEVELOPED FROM A DRAWING BY
HORIZON ENVIRONMENTAL, PROJECT NUMBER: WFL-0110,
DATED: APRIL 2001.
CARBON ABSORPTION PRETREATMENT LOCATION DEVELOPED
FROM A DRAWING BY HORIZON ENVIRONMENTAL, PROJECT
MILIBERS, WEL-012, DATED DECEMBER 1007.

CARBUN ABSORPTION PREIREATMENT LUCATION DEVELOPE FROM A DRAWING BY HORIZON ENVIRONMENTAL, PROJECT NUMBER: WFL-0107, DATED DECEMBER 1997. ALL LOCATIONS ARE APPROXIMATE. WELL POSITIONS SURVEYED BY WPSC SEPTEMBER 2003. REMEDIATION AREA TAKEN FROM EARTH TECH DRAWING DATED MARCH 1995. SURVEY COORDINATES FOR MW-15T. MW-18T AND SG-1

DATED MARCH 1993.

SURVEY COORDINATES FOR MW-15T, MW-16T AND SG-1
WERE PROVIDED BY WPSC, MAY 25, 2005.

BORING LOCATIONS SB1 THROUGH SB4 TAKEN FROM A
DRAWING BY WW ENGINEERING AND SCIENCE, INC., PROJECT
NUMBER: 22159, DATED DECEMBER 1991.

BORING LOCATIONS SB5 THROUGH SB58 TAKEN FROM A
DRAWING BY WW ENGINEERING AND SCIENCE, INC., PROJECT
NUMBER: 22319, DATED OCTOBER 1993.

NUMBER: 22319, DATED OCTOBER 1993. BORING LOCATIONS SB95-1 THROUGH SB95-6 TAKEN FROM A DRAWING BY HORIZON ENVIRONMENTAL, PROJECT NUMBER: WFL-0101, DATED AUGUST 1995.

A DRAWING BY HORIZON ENVIRONMENTAL, PROJECT NUMBER: WFL-0101, DATED AUGUST 1995.

BORING LOCATIONS SB-96-1 THROUGH SB-96-12 TAKEN FROM A DRAWING BY HORIZON ENVIRONMENTAL, PROJECT NUMBER: WFL-0101, FIGURE 2, DATED DECEMBER 1996. PROPERTY BOUNDARY 2001 TAKEN FROM A DRAWING BY SCHINDEL SURVEYING LLC, JOB NAME: WPSMAN1, DATED SEPTEMBER 3, 2001.

SCHINDEL SUPVETING LLC, JOB NAME: WPSMANT, DATED SEPTEMBER 3, 2001.
PROPERTY BOUNDARY 2002 AND RIVER BANK TAKEN FROM A DRAWING FROM BAY LAKES REGIONAL PLANNING COMMISSION, GREEN BAY, WI, DATED OCTOBER 30, 2002.
RIGHT OF WAYS AND CURBS APPROXIMATED FROM A DRAWING FROM BAY LAKES REGIONAL PLANNING COMMISSION, GREEN BAY, WI, DATED OCTOBER 30, 2002.

# FORMER GAS HOLDER SOIL DATA SITE SPECIFIC WORK PLAN FORMER WISCONSIN FUEL AND LIGHT COMPANY MGP SITE WISCONSIN PUBLIC SERVICE CORPORATION MANITOWOC, WISCONSIN

NATURAL

RESOURCE

ECHNOLOGY

PROJECT NO.

1530/7.2

FIGURE NO.

8

06/01/07

D BY: RHW DAT NO: 1530-72-

DRAWING NO REFERENCE:

APPROVED BY:

01/11/06

JAZ


₩.:


CHECKED


DATE: DATE: DATE:


BZ X

DRAWN









### **GENERAL NOTES:**

- 1. This site-specific Conceptual Site Model was developed based on the Generalized Conceptual Site Model Revision 0 and observations made during the January 5, 2007 site reconnaissance.
- 2. Exposure assumptions are presented in the Multi-Site Risk Assessment Framework Revision 0, dated September 5,2007.
- 3. Groundwater ingestion is not expected under current or future land use because there is a public water supply. Groundwater will not be quantitatively
- 4. Birds (aquatic and upland) and mammals (aquatic and upland) are not considered to be receptors at the site due to insufficient habitat.
- 5. Refer to Section 4 of the report for additional discussion on the site specific CSM.

### FOOTNOTES:

### Known Historic

- 1A. MGP residuals were released to surface and subsurface soil during MGP operations which ceased in the 1950s.
- 1B. NAPL was released from the MGP plant, ceasing operations in the 1950s.

- 2A. Records not complete to determine whether NAPL directly discharged to surface water (i.e. via historic trench).
- 2B. Surface soil erosion adjacent to river has been controlled with ISS and/or capping with asphalt.
- 2C. Subsurface soil erosion of river banks has been controlled with sheet pile wall installation and vegetated sloped banks.

### **Known**

- 3A. NAPL currently observed at MW14 and surrounding subsurface soils to be further investigated for the presence of a coal tar UST.
- 3B NAPL exists and COPCs in subsurface soil may be soluble in groundwater.
- 3C. Ongoing groundwater monitoring indicates elevated COPCs. Public water supply limits exposure to human receptors for ingestion (see General Note 3 above). Groundwater characterization for additional COPCs is necessary to assess worker exposure risk.

### Potential Current/Future

- 4A. Surface soil near former MGP structure areas will be characterized to assess worker exposure risk and possible future recreational land use, and to assess potential migration to subsurface soil and groundwater.
- 4B. Subsurface soil near former MGP structures will be characterized to assess worker exposure risk and the potential for on-going source to groundwater.
- 4C. Groundwater adjacent to the river will be characterized to assess the potential for on-going source (remaining below or adjacent to the ISS) to the sediment and surface water.
- 4D. Sediment will be characterized to assess potential risk for recreational use and ecological exposure risk.
- 4E. Surface water will be characterized to assess potential risk for recreational use and ecological exposure risk.

### PATHWAY LEGEND:

- ▲ Pathway potentially complete and warrants further evaluation within the Baseline Risk Assessment.
- Pathway incomplete or considered insignificant under current land use condition, but potentially complete under future land use scenario.
- $^{\circ}$  Pathway not complete or considered insignificant; No further evaluation is recommended.
- NA Not Applicable
  - Inhalation exposure route may warrant further evaluation related to potential vapor intrusion into buildings based on subsurface soil conditions.

BENTHIC

**INVERTEBRATES** 

NA

NA

NA

NA

NA

NA

NA


NA


 $\blacksquare$ 


### PATHWAY STATUS:



PROJECT No.		SITE SPECIFIC CONCEPTUAL SITE	Drawn	Date
1530		MODEL FOR	By: JTB	04/02/2008
	NATURAL	MANITOWOC FORMER MGP SITE	Checked	JAZ
Figure	Resource Technology		Approved	JAZ
12		Wisconsin Public Service Corporation		







Wisconsin Public Service Corporation

WIN 000509949 3008 1009 2009 4009 ID Task Name Duration Start Finish 2 Project Planning 387 days Tue 6/5/07 Wed 6/25/08 3 Submit Site Specific Work Plan Revision 0 to USEPA 0 days Tue 6/5/07 Tue 6/5/07 Receive USEPA Comments on Draft SSWP Revision 0 and Partial Approval 0 days Mon 2/11/08 Mon 2/11/08 Submit Site Specific Work Plan Revision 1 to USEPA Thu 4/10/08 Thu 4/10/08 0 days 6 USEPA Approves SSWP Revision 1 Fri 5/9/08 Fri 5/9/08 0 days Contract/Schedule RI Field Activities 45 days Mon 5/12/08 Wed 6/25/08 8 340 days Thu 6/18/09 Q ... Soil Boring Installation/Sampling 10 days Mon 7/14/08 Wed 7/23/08 10 Install and Develop Groundwater Monitoring Wells 9 days Thu 7/24/08 Fri 8/1/08 11 Quarterly Groundwater Sampling Event 319 days Mon 8/4/08 Thu 6/18/09  $\Diamond$  $\Diamond$ 12 Quarterly Groundwater Sampling Event 1 Mon 8/4/08 Mon 8/4/08 13 Quarterly Groundwater Sampling Event 2 1 day Mon 11/3/08 Mon 11/3/08 14 Quarterly Groundwater Sampling Event 3 1 day Mon 2/2/09 Mon 2/2/09 15 Quarterly Groundwater Sampling Event 4 Mon 5/4/09 Mon 5/4/09 Quarterly Groundwater Fixed Based Laboratory Analysis 318 days Tue 8/5/08 Thu 6/18/09 17 Quarterly Groundwater Fixed Based Laboratory Analysis 1 Tue 8/5/08 Thu 9/18/08 45 days 18 Data Validation 60 days Fri 9/19/08 Mon 11/17/08 11/17 19 Quarterly Groundwater Fixed Based Laboratory Analysis 2 45 days Tue 11/4/08 Thu 12/18/08 \_12/18 20 Data Validation Fri 12/19/08 Mon 2/16/09 60 days 21 Quarterly Groundwater Fixed Based Laboratory Analysis 3 45 days Tue 2/3/09 Thu 3/19/09 22 Quarterly Groundwater Fixed Based Laboratory Analysis 4 6/18 45 days Tue 5/5/09 Thu 6/18/09 23 24 Field Activities - River 471 days \$at 8/2/08 Sun 11/15/09 25 Pre-Approved Bathymetric, Side-Scan, Sub-Bottom Sonar Surveys 5 days Sat 8/2/08 Wed 8/6/08 Step I Sediment/Surface Water Sampling 26 157 days Sun 9/21/08 Tue 2/24/09 27 9/27 9/28 Identify Sediment Samples for Toxicity testing and COPCs 7 days Sun 9/21/08 Sat 9/27/08 28 Surface Water Sampling Sun 9/28/08 1 day Sun 9/28/08 29 Toxicity Testing Sun 11/2/08 35 days Mon 9/29/08 11/2 30 Tue 11/11/08 Additional Laboratory Analysis 45 days Sun 9/28/08 j<sub>1</sub>11/11 31 Sediment Sample Validation 45 days Wed 11/12/08 Fri 12/26/08 32 Development of Dose Response and Site Specific Risk Values 60 days Sat 12/27/08 Tue 2/24/09 \_2/24\_\_ 33 Step If Sediment Sampling 126 days Mon 7/13/09 Sun 11/15/09 34 Sediment Sampling for COCs 21 days Mon 7/13/09 Sun 8/2/09 35 Additional Laboratory Analysis 45 days Mon 8/3/09 Wed 9/16/09 36 Sediment Sample Validation Thu 9/17/09 Sun 11/15/09 11/15 37 38 medial Investigation Reporting 255 days Mon 11/16/09 Wed 7/28/10 39 Baseline Risk Assessment (included in RI Report) Thu 1/14/10 40 Current and Future Land Reuse Assessment (included in RI Report) 60 days Mon 11/16/09 Thu 1/14/10 41 Submit RI Report Revision 0 to USEPA 0 days Mon 3/15/10 Mon 3/15/10 42 Receive USEPA Comments on RI Report Revision 0 Fri 5/14/10 0 days 43 Submit RI Report Revision 1 to USEPA 0 days Mon 6/28/10 Mon 8/28/10 44 USEPA Approves RI Report Revision 1 0 days Wed 7/28/10 Wed 7/28/10 45 46 Feasibility Study Reporting 304 days Fri 5/14/10 Mon 3/14/11 47 Submit Development and Screening of Alternatives to USEPA Fri 5/14/10 Fri 5/14/10 0 davs 48 Receive USEPA comments on Development and Screening of Alternatives 0 days 49 Sumbit FS Report Revision 0 to USEPA 0 days Mon 9/13/10 Mon 9/13/10 50 Receive USEPA Comments on FS Report Revision 0 0 days Fri 11/12/10 Fri 11/12/10 51 Submit FS Report Revision 1 to USEPA 45 days Tue 12/28/10 Thu 2/10/11 52 USEPA Approves FS Report Revision 1 1 day Mon 3/14/11 Mon 3/14/11 53 54 roject Management Reporting 1217 days Tue 4/15/08 Mon 8/15/11 55 Monthly Progress Reports 1217 days Tue 4/15/08 Mon 8/15/11 56 Monthly Progress Reports 0 davs Tue 4/15/08 Tue 4/15/08 57 Monthly Progress Reports 2 0 days Thu 5/15/08 Thu 5/15/08 58 Monthly Progress Reports 3 0 days Sun 6/15/08 Sun 6/15/08 59 Monthly Progress Reports 4 0 days Tue 7/15/08 Tue 7/15/08 60 Monthly Progress Reports 5 Fri 8/15/08 0 days Fri 8/15/08 0 days Mon 9/15/08 Mon 9/15/08 61 Monthly Progress Reports 6 62 Monthly Progress Reports 7 0 days Wed 10/15/08 Wed 10/15/08 63 Monthly Progress Reports 8 0 days Sat 11/15/08 Sat 11/15/08 Task Milestone Rolled Up Task Rolled Up Progress External Tasks Group By Summary Project: 1530 Manitowoc RI FS schedule rev1 080410 Progress Rolled Up Milestone Project Summary 1. This preliminary schedule is dependent on USEPA-approval and weather conditions to completed field investigations. Schedule modifications will be in accordance with the AOC/SOW (CERCLA Docket No. V-W-06-847). Page 1

ID Task	Name	Duration	Start	Finish	2Q07 3Q Apr May Jun Ju	207	4Q07	1Q08 Dec Jan Fe	2Q08	3Q08	4Q08	1Q09 v Dec Jan Feb N	2Q09	3Q09	4Q09	1Q10	2Q10	3Q10	4Q10 Sep Oct Nov	1Q11 Dec Jan Feb M
64 Task	Monthly Progress Reports 9			Mon 12/15/08	Apr May Jun Ju	ul Aug Se	ep Oct Nov	Dec   Jan   Fe	b   Mar   Apr   Ma :	y Jun Jul Aug	Sep Oct Nov	v   Dec   Jan   Feb   N	far Apr May	Jun Jul Aug	Sep Oct   Nov	Dec Jan Feb N	ar Apr∣May Ju	n Jul Aug	Sep Oct Nov	Dec Jan Feb M
55	Monthly Progress Reports 10	0 days	Thu 1/15/09					:				<b>♦</b> 1/15								
6	Monthly Progress Reports 11	0 days	Sun 2/15/09	Sun 2/15/09								<b>▲</b> 2/1	5	•						
57	Monthly Progress Reports 12	0 days	Sun 3/15/09	Sun 3/15/09							:	: <b>V</b>	<b>▲</b> 3/15	:						
88	Monthly Progress Reports 13	0 days	Wed 4/15/09	Wed 4/15/09	:		i					`	<b>4/15</b>							
9	Monthly Progress Reports 14	0 days	Fri 5/15/09	Fri 5/15/09	1		:	:	1				<b>▲</b> 51	15			1		:	
o o	Monthly Progress Reports 15	0 days	Mon 6/15/09	Mon 6/15/09			1						<b>*</b>	<b>▲</b> 6/15					:	:
4	Monthly Progress Reports 16	0 days	Wed 7/15/09	Wed 7/15/09					: :					7/15	*				:	
2	Monthly Progress Reports 17	0 days	Sat 8/15/09	Sat 8/15/09										<b>▲</b> 8/	15					
73	Monthly Progress Reports 18	0 days	Tue 9/15/09	Tue 9/15/09									:		<b>4</b> 9/15					
74	Monthly Progress Reports 19	0 days	Thu 10/15/09	Thu 10/15/09									:		▲ 10/15				1	:
75	Monthly Progress Reports 20	0 days	Sun 11/15/09	Sun 11/15/09							:				<b>→</b> 1	1/15	į	i		
76	Monthly Progress Reports 21	0 days	Tue 12/15/09	Tue 12/15/09	:				1		:		1		•	<b>12/15</b>	1		:	
7	Monthly Progress Reports 22	0 days	Frì 1/15/10	Fri 1/15/10				:	i i	•	:		:			<b>▲</b> 1/15		:	1	
78	Monthly Progress Reports 23	0 days	Mon 2/15/10	Mon 2/15/10										:		<b>▲</b> 2 <i>i</i>	15			
79	Monthly Progress Reports 24	0 days	Mon 3/15/10	Mon 3/15/10				:			:					- I	15 <b>♦</b> 3/15			į.
80	Monthly Progress Reports 25	0 days	Thu 4/15/10	Thu 4/15/10			\$										<b>4/15</b>	:		
81	Monthly Progress Reports 26	0 days	Sat 5/15/10	Sat 5/15/10													<b>5/15</b>			
32	Monthly Progress Reports 27	0 days	Tue 6/15/10	Tue 6/15/10			:		<u> </u>								· ·	6/15	:	
33	Monthly Progress Reports 28	0 days	Thu 7/15/10	Thu 7/15/10				1			ł				4		`	<b>4</b> 7/15	:	
34	Monthly Progress Reports 29	0 days	Sun 8/15/10	Sun 8/15/10							:		:				1		¥15	
35	Monthly Progress Reports 30	0 days	Wed 9/15/10	Wed 9/15/10					i i									· ·	9/15	
36	Monthly Progress Reports 31	0 days	Fri 10/15/10	Fri 10/15/10											i				<b>10/15</b>	
37	Monthly Progress Reports 32	0 days	Mon 11/15/10	Mon 11/15/10			:						i i						•	11/15
88	Monthly Progress Reports 33	0 days	Wed 12/15/10	Wed 12/15/10										:						<b>12/15</b>
89	Monthly Progress Reports 34	0 days	Sat 1/15/11	Sat 1/15/11				:			:		\$					i		<b>4</b> 1/15
90	Monthly Progress Reports 35	0 days	Tue 2/15/11	Tue 2/15/11										:	1					<b>♦</b> 2
01	Monthly Progress Reports 36	0 days	Tue 3/15/11	Tue 3/15/11										:				:	:	
02	Monthly Progress Reports 37	0 days	Fri 4/15/11	Fri 4/15/11									:		:			:		:
93	Monthly Progress Reports 38	0 days	Sun 5/15/11	Sun 5/15/11									:		1		:	:	:	
94	Monthly Progress Reports 39	0 days	Wed 6/15/11	Wed 6/15/11				:									:			
5	Monthly Progress Reports 40	0 days	Fri 7/15/11	Fri 7/15/11										:			:	:		
96	Monthly Progress Reports 41	0 days	Mon 8/15/11	Mon 8/15/11								1			:					

Rolled Up Task Rolled Up Progress Milestone External Tasks Group By Summary Project: 1530 Manitowoc RI FS schedule rev1 080410 Date: 4/10/08 Rolled Up Milestone Project Summary Progress Summary

# **TABLES**

Table 1 - Groundwater Monitoring Well Analytical Results - PVOCs and Cyanide Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin USEPA ID# WIN000509949

			Petr	oleum Volati	le Organic C	ompounds (¡	ıg/L)		Cyanide	s (mg/L) (field	d filtered)
Sample Date	Sample Location	Benzene	Ethylbenzene	Trimethylbenzene**	Methyl-tert-butyl-ether	Toluene	Xylenes, total	Total BTEXs	Cyanide, total	Cyanide, weak acid dissociable	Cyanide, OIA-1677
			Wisco	nsin Ground	water Quality	/ Standards	(NR 140)				
Preventive Action Lim		<u>0.5</u>	<u>140</u>	<u>96</u>	<u>12</u>	<u>200</u>	<u>1,000</u>	ns	ns	<u>0.04</u>	<u>0.04</u>
Enforcement Standard	d (ES)	<u>5</u>	<u>700</u>	<u>480</u>	<u>60</u>	<u>1,000</u>	<u>10,000</u>	ns	ns	0.2	<u>0.2</u>
MW-1	04/11/2000 03/27/2001	 <1.0	 <1.0	 <1.0	 <5.0	 <1.0	 <3.0	 nd	 <0.005		
	06/05/2002 05/15/2003	<0.45 	<0.82	<0.92	<0.43	<0.68	<0.77	nd 	0.021 A 	<0.0022 	
	05/24/2004 05/18/2005	<0.14 <0.41	<0.40 <0.54	<0.40 <0.97	<0.36 <0.61	<0.36 <0.67	<0.74 <1.8	nd nd			<0.0050 
	05/30/2006 05/16/2007	0.21 Q <u>4.7</u>	<0.40 1.3 Q	<0.40 3.74 Q	<0.36 <0.36	<0.36 7.0	<0.74 7.2	0.21 20.2			
MW-2	04/11/2000 03/27/2001 06/05/2002	<u>4.6</u> <u>1.4</u> 0.63 Q	5.5 40 18	<1.0 2.8 1.6 Q	<50 <5.0 <0.43	3.3 1.4 0.85 Q	<3.0 3.6 1.6 Q	13.40 46.40 21.08	0.18 0.17 0.043 A	  0.010	  
	05/15/2003 05/24/2004 05/18/2005	0.79 Q 0.64 <0.41	19 40 38	1.1 Q 1.9 4.4	<0.58 <0.36 <0.61	2.9 3.2 0.94 Q	5.2 7.3 2.6 Q	27.89 51.14 41.54	0.14 	0.011  	0.020
Dup (QC-2)	05/18/2005 05/30/2006	<0.41 <u>1.0</u> 2.3	37 7.8	4.3 5.3	<0.61 <0.36	0.94 Q <0.36	2.4 Q 3.3 Q	40.34 12.10	  	 	  
MW-5	05/16/2007 04/11/2000 03/27/2001	<u>2.3</u>  	4.8  	1.2 Q  	0.40 Q 	<0.36 	2.0 Q 	9.1  			
Dup (Duplicate -1)	06/05/2002 05/15/2003 05/15/2003	<0.45 <0.30 <0.30	<0.82 <0.60 <0.60	<0.92 <0.66 <0.66	<0.43 <0.58 <0.58	<0.68 <0.58 <0.58	<0.77 <1.2 <1.2	nd nd nd	0.047 A 0.0019 Q 0.0032 Q	<0.0022 0.0022 Q 0.0024 Q	
	05/24/2004 05/18/2005 05/30/2006 05/16/2007	<0.14 <0.41 0.44 Q <0.14	<0.40 <0.54 <0.40 <0.40	<0.40 <0.97 <0.40 <0.40	<0.36 <0.61 <0.36 <0.36	<0.36 <0.67 <0.36 <0.36	<0.74 <1.8 <0.74 <0.74	nd nd 0.44 nd	  	  	<0.0050   
Dup (051607017)	05/16/2007	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd			
MW-6	04/11/2000 03/27/2001	<1.0 <1.0	<1.0 4.1	<1.0 <1.0	<50 <5.0	<1.0 <1.0	<3.0 9.9	nd 14	0.066 0.095		
	10/25/2001 06/05/2002 05/15/2003	<1.0 <0.45 <0.30	<1.0 <0.82 <0.60	<1.0 <0.92 <0.66	<5.0 <0.43 <0.58	<1.0 <0.68 <0.58	<3.0 <0.77 <1.2	nd nd nd	0.21 A 0.19	0.0099 0.017	
Dup (Duplicate -2)	05/15/2003	<0.30	<0.60	<0.66	<0.58	<0.58	<1.2	nd (al anly	0.18	0.014	
AA) 47 - 7	05/24/2004	.4.0	.4.0	.4.0			oled - water lev		0.000		
MW-7	04/11/2000 03/27/2001	<1.0 <1.0	<1.0 <1.0	<1.0 <1.0	<50 <5.0	<1.0 <1.0	<3.0 <3.0	nd nd	0.008 0.18		
	06/05/2002 05/15/2003 05/24/2004	<0.45 <0.30	<0.82 <0.60	<0.92 <0.66	<0.43 <0.58 Well no	<0.68 <0.58	<0.77 <1.2 oled - water lev	nd nd vel only	0.47 0.35	0.028 0.032	 
MW-8	04/11/2000	_1 n	<i>-</i> 1 0	<b>~10</b>		· ·		· ·	0.47		
IVIVV-8	03/27/2001	<1.0 <1.0	<1.0 <1.0	<1.0 <1.0	<50 <5.0	<1.0 <1.0	<3.0 <3.0	nd nd	0.47 0.35		
Dup (QC2)	06/05/2002 06/05/2002	<0.45 <0.45	<0.82 <0.82	<0.92 <0.92	<0.43 <0.43	<0.68 <0.68	<0.77 <0.77	nd nd	1.8 1.3	<u>0.073</u> 0.015	
	05/15/2003 05/24/2004	<0.30 <0.14	<0.60 <0.40	<0.66 <0.40	<0.58 <0.36	<0.58 <0.36	<1.2 <0.74	nd nd	1.2 	<u>0.090</u> 	 0.011
	05/18/2005 05/30/2006	<0.41 <0.14	<0.54 <0.40	<0.97 <0.40	<0.61 <0.36	<0.67 <0.36	<1.8 <0.74	nd nd			
	05/16/2007	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd			



Table 1 - Groundwater Monitoring Well Analytical Results - PVOCs and Cyanide Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin USEPA ID# WIN000509949

			Petr	oleum Volati	le Organic C	ompounds (μ	ıg/L)		Cyanide	s (mg/L) (field	d filtered)
Sample Date	Sample Location	Benzene	Ethylbenzene	Trimethylbenzene**	Methyl-tert-butyl-ether	Toluene	Xylenes, total	Total BTEXs	Cyanide, total	Cyanide, weak acid dissociable	Cyanide, OIA-1677
			Wisco	nsin Ground	water Quality	y Standards (	(NR 140)			•	
Preventive Action Lim		<u>0.5</u>	<u>140</u>	<u>96</u>	<u>12</u>	<u>200</u>	<u>1,000</u>	ns	ns	<u>0.04</u>	<u>0.04</u>
Enforcement Standard	d (ES)	<u>5</u>	<u>700</u>	<u>480</u>	<u>60</u>	<u>1,000</u>	<u>10,000</u>	ns	ns	<u>0.2</u>	<u>0.2</u>
MW-9	04/11/2000	<u>3.1</u>	<1.0	<1.0	<50	<1.0	<3.0	3.1	0.42		
	03/27/2001	<u>8.8</u>	<1.0	<1.0	<5.0	<1.0	<3.0	8.8	0.18		
- (00.0)	06/05/2002	<u>0.94 Q</u>	<0.82	<0.92	<0.43	<0.68	<0.77	0.9	0.33 A	0.029	
Dup (QC-1)	06/05/2002	<u>0.90 Q</u>	<0.82	<0.92	<0.43	<0.68	<0.77	0.9	0.21	0.018	
	05/15/2003 05/24/2004	<u>1.3</u> 0.30 Q	<0.60 <0.40	<0.66 <0.40	<0.58 <0.36	<0.58 <0.36	<1.2 <0.74	1.3 nd	0.18	0.0091	0.018
	05/18/2005	<0.41	<0.40	<0.40	<0.61	<0.36	<1.8	nd			0.016
	05/30/2006	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd			
	05/16/2007	<0.14	<0.40	0.65 Q	<0.36	<0.36	<0.74	nd			
MW-10	04/11/2000	<1.0	<1.0	9	<50	<1.0	<3.0	nd	0.15		
11111	03/27/2001	<1.0	<1.0	<1.0	<5.0	<1.0	<3.0	nd	0.11		
	06/05/2002	< 0.45	< 0.82	< 0.92	4.6	<0.68	<0.77	nd	0.28	0.010	
	05/15/2003	< 0.30	< 0.60	13	3.2	<0.58	<1.2	nd	0.30	0.014	
	05/24/2004	<0.14	<0.40	3.8	3.0	<0.36	<0.74	nd			0.015
	05/18/2005	<0.41	<0.54	7.5	1.3 Q	<0.67	<1.8	nd			
	05/30/2006	<0.14	<0.40	1.3 Q	1.5	<0.36	<0.74	nd 0.40			
	05/16/2007	<0.14	<0.40	17	0.84	<0.36	0.49 Q	0.49			
MW-11	04/11/2000	<1.0	<1.0	<1.0	<50	<1.0	<3.0	nd	0.11		
	03/27/2001	<1.0 <0.45	<1.0	<1.0	<5.0	<1.0 <0.68	<3.0 <0.77	nd	0.14 0.15 A	0.026	
	06/05/2002 05/15/2003	<0.45	<0.82 <0.60	<0.92 <0.66	<0.43 <0.58	<0.58	<1.2	nd nd	0.15 A 0.14	0.026	
	05/24/2004	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd		0.010	<0.0050
Dup (QC-1)	05/24/2004	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd			<0.0050
,	05/18/2005		·····	·····	Well no	longer sample	ed - will be ab	andoned	4		A
	05/30/2006					Aban	doned				
MW-12	04/11/2000	<1.0	<1.0	<1.0	<50	<1.0	<3.0	nd	0.8		
	03/27/2001	<1.0	<1.0	<1.0	<5.0	<1.0	<3.0	nd	1.4		
	06/05/2002	<0.45	<0.82	<0.92	<0.43	<0.68	<0.77	nd	0.73	0.016	
	05/15/2003							red with aspha	alt)	T	T 0 045
	05/24/2004 05/18/2005	<0.14 <0.41	<0.40 <0.54	<0.40 <0.97	<0.36 <0.61	<0.36 <0.67	<0.74 <1.8	nd nd			0.015
	05/30/2006	<b>\0.41</b>	<b>\0.54</b>					to stormwater	runoff	1	I =
	6/20/2006	<0.14	< 0.40	<0.40	<0.36	<0.36	<0.74	nd			
	5/16/2007	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd			
MW-12D	04/11/2000	<1.0	<1.0	<1.0	<50	<1.0	<3.0	nd	0.039		
	03/27/2001	<1.0	<1.0	<1.0	<5.0	<1.0	<3.0	nd	0.036		
	06/05/2002	<0.45	<0.82	<0.92	<0.43	<0.68	<0.77	nd	0.11 A	<0.011 N,C	
	05/15/2003	<0.30	<0.60	<0.66	<0.58	<0.58	<1.2	nd	0.021	0.0041Q	
Dun (00.0)	05/24/2004	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd			<0.0050
Dup (QC-2)	05/24/2004 05/18/2005	<0.14 <u>2.3</u>	<0.40 <0.54	<0.40 <0.97	<0.36 <0.61	<0.36 <0.67	<0.74 <1.8	nd 2.3			<0.0050
Dup (QC-1)	05/18/2005	5.3	<0.54	<0.97	<0.61	<0.67	<1.8	5.3			
200 (40 1)	05/30/2006	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd			
	05/16/2007	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd			
Dup (051607006)	05/16/2007	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd			
MW-13	04/11/2000	1,800	5,800	720	<50	<u>470</u>	3,800	11,870	0.36		
	03/27/2001	1,500	3,300	760	<5.0	100	2,700	7,600	0.34		
	06/05/2002	<u>2,600</u>	4,800	<u>790</u>	<8.6	<u>1,800</u>	<u>4,300</u>	13,500	0.21 A	<0.0022	
	05/15/2003	300 240	<u>200</u>	<u>129</u>	<1.2	21	670	1,191	0.61	<u>0.051</u>	0.0070
	05/24/2004	210 270	29 670	94 128 O	< 0.36	6.3	400	645			0.0073
	05/18/2005 05/30/2006	<u>270</u> 330 K	<u>670</u> 640 K	<u>138 Q</u> 240 K	<12 <7.2 K	17 Q 29 K	530 650 K	1,487 1,649			
Dup (QC01)	05/30/2006	330 K	650 K	241 K	<7.2 K	29 K	660 K	1,669			



Table 1 - Groundwater Monitoring Well Analytical Results - PVOCs and Cyanide Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

			Petr	oleum Volati	le Organic C	ompounds (µ	ug/L)		Cyanide	s (mg/L) (field	d filtered)
Sample Date	Sample Location	Benzene	Ethylbenzene	Trimethylbenzene**	Methyl-tert-butyl-ether	Toluene	Xylenes, total	Total BTEXs	Cyanide, total	Cyanide, weak acid dissociable	Cyanide, OIA-1677
				nsin Ground	water Quality		`				
Preventive Action Lim		<u>0.5</u>	<u>140</u> <b>700</b>	<u>96</u> <b>480</b>	<u>12</u> <b>60</b>	<u>200</u>	<u>1,000</u>	ns	ns	<u>0.04</u>	<u>0.04</u>
Enforcement Standard	·	<u>5</u>				<u>1,000</u>	<u>10,000</u>	ns	ns	0.2	<u>0.2</u>
MW-14	04/11/2000	<u>310</u>	<u>600</u>	<u>950</u>	<500	4,000	<u>4,100</u>	9,010	0.11		
	03/27/2001 06/05/2002 05/15/2003 05/24/2004 05/18/2005 05/30/2006 05/16/2007	410	810	1,110	<5.0 Not sar	4,200 npled due to p	4.200 product being	9,620 present	0.054		L
MW-17T	04/11/2000	<1.0	<1.0	<1.0	<50	<1.0	<3.0	nd	<0.005		
	03/27/2001	<1.0	<1.0	<1.0	<5.0	<1.0	<3.0	nd	0.054		
	06/05/2002	<0.45	<0.82	<0.92	<0.43	<0.68	<0.77	nd	0.0029 Q	<0.0022	
	05/15/2003 05/24/2004	<0.30 <0.14	<0.60 <0.40	<0.66 <0.40	<0.58 <0.36	<0.58 <0.36	<1.2 <0.74	nd nd	0.0060	0.0019	<0.0050
	05/18/2005	<0.14	<0.54	<0.40	<0.61	<0.67	<1.8	nd			
	05/30/2006	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd			
	05/16/2007	<0.14	<0.40	<0.40	<0.36	<0.36	<0.74	nd			
MW-18T	04/11/2000 03/27/2001 06/05/2002 05/15/2003 05/24/2004 05/18/2005 05/30/2006 05/16/2007	<1.0 <1.0 <0.45 <0.30 <0.14 <0.41 <0.14 <0.14	<1.0 <1.0 <0.82 <0.60 <0.40 <0.54 <0.40	<1.0 <1.0 <0.92 <0.66 <0.40 <0.97 <0.40 <0.40	<50 <5.0 <0.43 <0.58 <0.36 <0.61 <0.36 <0.36	<1.0 <1.0 <0.68 <0.58 <0.36 <0.67 <0.36 <0.36	<3.0 <3.0 <0.77 <1.2 <0.74 <1.8 <0.74 <0.74	nd nd nd nd nd nd nd	<0.005 <0.005 <0.0021 0.0058   	 -0.0022 0.0037 Q   	   <0.0050  
MW-19T	04/11/2000 03/27/2001 06/05/2002 05/15/2003 05/24/2004 05/18/2005 05/30/2006 05/16/2007	<1.0 <1.0 2.4 <0.30 1.1 <0.41 0.17 Q 0.31 Q	<1.0 1.7 <0.82 <0.60 <0.40 <0.54 <0.40 <0.40	<1.0 <1.0 <0.92 <0.66 <0.40 <0.97 <0.40 <0.40	<50 <5.0 <0.43 <0.58 <0.36 <0.61 <0.36 <0.36	<1.0 <1.0 <0.68 <0.58 <0.36 <0.67 <0.36 <0.36	<3.0 <3.0 0.94 Q <1.2 0.76 Q <1.8 <0.74 <0.74	nd nd 3.3 nd 1.9 nd 0.17	0.037 0.043 0.029 A 0.035   	  0.0053 Q 0.0046 Q   	   <0.0050  
MW-20T	04/11/2000 03/27/2001 06/05/2002 05/15/2003 05/25/2004 05/18/2005 05/30/2006	<1.0 <1.0 <0.45 <0.30 <0.14 <0.41 0.22 Q	<1.0 <1.0 <0.82 <0.60 <0.40 <0.54 <0.40	<1.0 <1.0 <0.92 <0.66 <0.40 <0.97 <0.40	<50 <5.0 <0.43 <0.58 <0.36 <0.61 0.88 Q	<1.0 <1.0 <0.68 <0.58 <0.36 <0.67 <0.36	<3.0 <3.0 <0.77 <1.2 <0.74 <1.8 <0.74	nd nd nd nd nd nd	0.040 0.061 0.063 A 0.051  	 -0.0022 0.0046 Q  	   <0.0050 
Dup (QC02)	05/30/2006	0.23 Q	<0.40	<0.40	0.85 Q	<0.36	<0.74	0.23			
Dup (051607010)	05/16/2007 05/16/2007	0.19 Q 0.19 Q	<0.40 <0.40	<0.40 <0.40	0.80 Q 0.86 Q	<0.36 <0.36	<0.74 <0.74	0.19 0.19			
MW-21T	04/11/2000 03/27/2001 06/05/2002 05/15/2003 05/24/2004 05/18/2005 05/30/2006	<1.0 <1.0 <0.45 0.31 Q <0.14 <0.41 <0.14	<1.0 <1.0 <0.82 <0.60 <0.40 <0.54 <0.40	<1.0 <1.0 <0.92 <0.66 <0.40 <0.97 <0.40	<50 <5.0 1.9 1.6 Q <0.36 <0.61 <0.36	<1.0 <1.0 <0.68 <0.58 <0.36 <0.67 <0.36	<3.0 <3.0 <0.77 <1.2 <0.74 <1.8 <0.74	nd nd 1.9 0.3 nd nd	0.061 0.075 0.18 0.37  	 <0.0022 0.026  	   <0.0050 
	05/16/2007	0.19 Q	<0.40	<0.40	1.8	<0.36	<0.74	0.19			
					LITD/AA	S-7/1/02][JTB/F	A D. 07/001/ 11/0/	/ 00/0470 040/	1411 07/057/114	0/0.10.00/0077	11.10/0.10.0/071

[JTB/AAS-7/1/02][JTB/PAR-07/03][JKY/ -06/04][HMS/JAH-07/05][HMS/RJG-06/06][HMS/RJG 6/07]



Table 1 - Groundwater Monitoring Well Analytical Results - PVOCs and Cyanide Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

			Petr	oleum Volati	le Organic C	ompounds (µ	ıg/L)		Cyanide	s (mg/L) (field	d filtered)
Sample Date	Sample Location	Benzene	Ethylbenzene	Trimethylbenzene**	Methyl-tert-butyl-ether	Toluene	Xylenes, total	Total BTEXs	Cyanide, total	Cyanide, weak acid dissociable	Cyanide, OIA-1677
			Wisco	nsin Ground	water Quality	/ Standards (	NR 140)				
Preventive Action Lim	it (PAL)	<u>0.5</u>	<u>140</u>	<u>96</u>	<u>12</u>	<u>200</u>	1,000	ns	ns	<u>0.04</u>	<u>0.04</u>
Enforcement Standard	d (ES)	<u>5</u>	<u>700</u>	<u>480</u>	<u>60</u>	1,000	10,000	ns	ns	0.2	0.2

### Notes:

- 1) Pre-2002 data from Horizon Environmental reports.
- 2) Concentrations that attain or exceed an NR 140 PAL are italicized/underlined.
- 3) Concentrations that attain or exceed an NR 140 ES are <u>underlined/bold.</u>
- 4) Wells PW-1 and MW-12 were buried by asphalt and well MW-1 was dry during the 5/15/03 sampling event.
- **PVOCs:** Petroleum volatile organic compounds.
  - ns: Standard has not been established.
  - --: Analysis was not performed.
- Dup (QC-1): Field duplicate sample.
  - \*\*: Standard is for 1,2,4-trimethylbenzene and 1,3,5-trimethylbenzene combined.
  - μg/L: Micrograms per liter.
  - mg/L: Milligrams per liter.
    - A: Laboratory note Analyte detected in method blank. N = Spiked sample recovery not within control limits.
    - C: Laboratory note Elevated levels due to matrix effects.
    - Q: Laboratory note The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ).
    - D: Laboratory note Analyte value from diluted analysis
    - \*: In May 2004, cyanide was analyzed using method OIA-1677.
    - **K**: Detection limit may be elevated due to the presence of an unrequested analyte.



Table 2 - Groundwater Monitoring Well Analytical Results - PAHs Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin USEPA ID# WIN000509949

									POLYN	UCLEAR AR	OMATIC HYD	ROCARBON	NS (μg/L)							
Sample Location	Sample Date	1-Methyl-naphthalene	2-Methyl-naphthalene	Acenaphthene	Acenaphthylene	Anthracene	Benz(a) anthracene	Benzo(a)pyrene	Benzo(b) fluoranthene	Benzo(g,h,i) perylene	Benzo(k) fluoranthene	Chrysene	Dibenz(a,h) anthracene	Fluoranthene	Fluorene	Indeno(1,2,3-cd) pyrene	Naphthalene	Phenanthrene	Pyrene	Total PAHs
								Wisconsii	n Groundwat	er Quality St	andards (NR	140)								
Preventive Actio	n Limit (PAL)	ns	ns	ns	ns	<u>600</u>	ns	<u>0.02</u>	<u>0.02</u>	ns	ns	<u>0.02</u>	ns	<u>80</u>	<u>80</u>	ns	<u>8</u>	ns	<u>50</u>	ns
Enforcement Sta	andard (ES)	ns	ns	ns	ns	<u>3,000</u>	ns	<u>0.2</u>	<u>0.2</u>	ns	ns	<u>0.2</u>	ns	<u>400</u>	<u>400</u>	ns	<u>40</u>	ns	<u>250</u>	ns
MW-1	04/11/2000 03/27/2001 06/05/2002 05/15/2003	  <0.54 	 <5.0 <0.56	 <5.0 2.7 	 <5.0 0.48 Q 	 <5.0 <8.0 C	 2.4 29 C 	 <u>3</u> <u>46 C</u> 	 <u>5.8</u> <u>55 C</u> 	 <5.0 40 C	 <5.0 43 C 	 <5.0 <u>48 C</u> 	 <2.0 11 Q,C	 7.7 <u>100 C</u> 	 <5.0 4.5	 2.3 34 	 <5.0 <0.54	 <5.0 53 C	 6.0 <u>86 C</u> 	 27 553 
	11/19/2003 02/25/2004 05/24/2004 05/18/2005 05/30/2006 05/16/2007	<00.36 <0.34 <0.34 <0.80 <1.0 0.95	<0.34 <0.32 <0.32 <0.90 <1.1 1.5	<0.36 0.99 Q <0.34 <0.78 <0.82 <0.16	<0.38 0.43 Q <0.36 <0.77 <0.81 0.27 Q	0.70 Q 4.0 0.58 Q 0.75 Q 2.4 Q 0.77	5.2 13 D 3.7 4.4 11 2.2	8.2 19 D 5.3 10 18 4.9	8.6 16 D 5.0 11 20 Z 6.2 Z	6.9 14 D 4.3 9.8 & 16 5.3	6.5 17 D 4.4 10 & 18 Z 4.3 Z	6.6 19 D 4.5 8.9 & 17 4.2	2.0 4.3 1.3 2.1 Q& 3.5 Q 1.2 Q	14 D 45 D 8.1 13 32 7.4	<0.34 1.6 <0.32 <0.87 <0.91 0.25 Q	6.1 12 Q, D 3.9 7.8 & 13 4.5	<0.48 2.3 <0.45 <0.89 <1.2 1.7	4.6 21 D 3.0 4.7 9.2 2.6	9.1 32 D 6.0 9.5 23.0 5.5	79 222 50 92 183 54
MW-2  Dup (QC-2)	04/11/2000 03/27/2001 06/05/2002 05/15/2003 02/25/2004 05/24/2004 05/18/2005 05/18/2005 05/30/2006	 14 D 9.2 D* 11 D 10 D 11 D 7.2	<1.0 8.6 0.035 Q 0.023 Q* 0.025 Q 0.019 Q <0.45 <0.48 <0.46	1.7 <5.0 5.4 D 3.8 D* 4.9 D 4.8 D 4.2 2.9 5.6	1.8 <5.0 4.0 D 2.3 D* 2.8 Q, D 2.8 D 2.7 2.0 3.5	<1.0 <5.0 0.067 0.055 Q* 0.040 Q 0.42 <0.35 0.39 Q 0.70 Q	<1.0 <2.0 0.15 0.12 0.083 1.5 D 1.1 Q 1.5 2.4	<1.0 <2.0 0.17 0.14 0.10 1.4 D 1.2 1.5 2.4 Q	<1.0 <2.0 <u>0.16</u> <u>0.14</u> <u>0.10</u> <b>1.1 D</b> <b>1.1 Q</b> <b>1.2 Q</b> <b>2.2 Z</b>	<1.0 <5.0 0.12 0.11 0.091 0.86 Q, D 0.94 Q& 0.88 Q 1.4 Q	<1.0 <5.0 0.11 0.10 0.090 1.1 Q, D 1.1 Q& 1.4 2.1 QZ	<1.0 <5.0 <u>0.12</u> <u>0.12</u> <u>0.088</u> <u>1.4 D</u> <u>1.1 &amp;</u> <u>1.9</u> <u>2.3 Q</u>	<1.0 <2.0 0.046 Q 0.033 Q 0.024 Q 0.28 <0.44 & <0.47 <0.77	<1.0 <5.0 0.28 0.23 * 0.17 3.3 D 2.3 3.4 5.5	<1.0 <5.0 0.94 Q,D 0.65 Q*D 0.81 Q, D 0.87 Q, D 0.52 Q 0.47 Q 0.77 Q	<1.0 <2.0 0.12 0.100 0.079 0.76 Q, D 0.77 Q& 0.68 Q 1.30 Q	<1.0 <5.0 0.18 0.19 I* 0.20 0.19 0.71 Q 0.54 Q <0.50	<1.0 <5.0 0.21 0.13 * 0.13 1.4 D 0.74 Q 1.20 Q 1.6	<5.0 <5.0 0.25 0.22 * 0.17 2.7 D 2.0 3.7 4.4	3.5 8.6 26 18 21 35 31 31
MW-5	05/16/2007 04/11/2000 03/27/2001 06/05/2002	2.8 D   <0.40	<0.056   <0.42	1.7   <0.27	1.0   <0.34	0.18 Q   <0.30	0.66   1.7	0.74   2.1	0.67 Z   2.5	0.50   1.9	0.61 Z   1.6	0.60   1.8	0.15 Q   0.56 Q	1.5   4.1	0.32   <0.32	0.49   1.6	0.12 Q   <0.40	0.58   1.5	1.2   3.1 3.6 D*	14   22
Dup (Duplicate -1)  Dup (051607017)	05/15/2003 05/15/2003 02/25/2004 05/24/2004 05/18/2005 05/30/2006 05/16/2007 05/16/2007	0.033 Q* <0.072 <0.17 <0.017 <8.5 <5.1 <5.1 <0.20	0.035 Q* <0.068 <0.16 0.017 Q <9.6 <5.6 <5.6 <0.22	0.20 * <0.072 <0.17 0.068 <8.2 <4.1 <4.1 0.50 Q	0.053 Q* <0.076 <0.18 0.022 Q <8.2 <4.1 <4.1 0.48 Q	0.26 * <0.080 <0.19 0.11 <7.5 6.7 Q 8.6 Q 2.3	1.1 D 0.20 1.0 0.62 D 25 Q 29 17 Q 8.8 QD	1.5 D 0.26 1.6 0.89 D 58 56 45 20 D	2.3 D 0.39 1.6 1.2 D 110 99 Z 60 Z 31 ZD	1.5 D 0.27 1.4 0.83 D 75 & 62 46 21 D	1.9 D 0.30 1.6 0.95 D 98 & 73 Z 56 Z 22 ZD	2.3 D 0.40 1.6 1.1 D 110 & 84 58 24 D	0.49 <0.064 0.39 Q 0.23 18 Q& 12 Q 10 Q 4.8	5.1 D* 1.1 3.0 2.2 D <u>190</u> <u>160</u> <u>96</u> 43 D	0.24 * <0.068 <0.16 0.075 <9.2 <4.5 <4.5 0.69	1.1 Q,D 0.23 Q 1.2 0.72 D 60 & 51 & 38 19 D	0.072 Q*I 0.48 0.28 Q 0.030 Q <9.5 <6.2 <6.2 <0.25	2.8 D* 0.57 0.87 0.92 D 48 40 28 12 D	3.6 D* 0.69 2.1 1.6 D <u>120</u> <u>110</u> <u>66</u> 30 D	25 4.9 17 12 912 783 529 240



Page 1 of 7

Table 2 - Groundwater Monitoring Well Analytical Results - PAHs Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin USEPA ID# WIN000509949

									POLYN	UCLEAR AR	OMATIC HYD	ROCARBON	IS (μg/L)							
Sample Location	Sample Date	1-Methyl-naphthalene	2-Methyl-naphthalene	Acenaphthene	Acenaphthylene	Anthracene	Benz(a) anthracene	Benzo(a)pyrene	Benzo(b) fluoranthene	Benzo(g,h,i) perylene	Benzo(k) fluoranthene	Chrysene	Dibenz(a,h) anthracene	Fluoranthene	Fluorene	Indeno(1,2,3-cd) pyrene	Naphthalene	Phenanthrene	Pyrene	Total PAHs
								Wisconsii	n Groundwat	er Quality St	andards (NR	140)								
Preventive Actio	n Limit (PAL)	ns	ns	ns	ns	<u>600</u>	ns	0.02	<u>0.02</u>	ns	ns	0.02	ns	<u>80</u>	<u>80</u>	ns	<u>8</u>	ns	<u>50</u>	ns
Enforcement Sta	andard (ES)	ns	ns	ns	ns	3,000	ns	0.2	0.2	ns	ns	0.2	ns	<u>400</u>	400	ns	<u>40</u>	ns	<u>250</u>	ns
MW-6  Dup (Duplicate -2)  MW-7	04/11/2000 03/27/2001 06/05/2002 05/15/2003 05/15/2003 02/25/2004 05/24/2004 04/11/2000 03/27/2001 06/05/2002 05/15/2003 02/25/2004 05/24/2004	 <0.027 <0.018 0.022 Q 0.018 Q  <0.027 <0.018 *	<1.0 <5.0 <0.028 <0.017 <0.017 0.026 Q <1.0 <5.0 <0.028 <0.017 * 0.022 Q	<1.0 <5.0 <0.018 <0.018 <0.017 <1.0 <5.0 <0.018 <0.018 * 0.037 Q	<1.0 <5.0 0.040 Q 0.043 Q 0.038 Q 0.067 <1.0 <5.0 0.30 0.11 * 0.24	<1.0 <5.0 <0.020 <0.020 <0.019 <1.0 <5.0 0.13 0.13 * 0.26	<1.0 <2.0 0.032 Q 0.016 Q 0.023 Q <1.0 <2.0 0.39 0.22 1.5 D	<1.0 <2.0 <u>0.032 Q</u> <u>0.041 Q</u> 0.019 Q <u>0.026 Q</u> <1.0 <2.0 <u>0.53 D</u> <u>0.44</u> 3.0 D	<1.0 <2.0 <b>0.41</b> <b>0.67 D</b> <b>4.7 D</b>	<1.0 <5.0 0.047 Q 0.032 Q 0.018 Q 0.021 Q Well no longe <1.0 <5.0 0.43 0.54 D 3.4 D Well no longe	<1.0 <5.0 0.32 0.44 3.3 D	<1.0 <5.0 <b>0.31</b> <b>0.54 D</b> <b>4.2 D</b>	<1.0 <2.0 0.14 0.12 0.65 Q, D	<1.0 <5.0 0.069 Q 0.058 0.033 Q 0.045 <1.0 <5.0 0.40 0.87 D* 9.2 D	<1.0 <5.0 <0.021 <0.017 <0.017 <0.016 <1.0 <5.0 <0.021 <0.017 * 0.059	<1.0 <2.0 0.020 Q 0.027 Q <0.021 <0.020 <1.0 <2.0 0.36 0.43 2.8 D	<1.0 <5.0 <0.027 0.051 Q 0.15 0.090 <1.0 <5.0 0.029 Q 0.026 Q*I 0.097	<1.0 <5.0 0.033 Q 0.029 Q 0.017 Q 0.029 Q <1.0 <5.0 0.097 0.20 * 2.0 D	<5.0 <5.0 0.059 Q 0.056 0.032 Q 0.040 Q <5.0 <5.0 <5.0 0.53 D 0.69 D* 6.0 D	nd nd 0.4 0.5 0.4 0.5 nd nd 4.4 5.4 41
MW-8 Dup (QC2)	04/11/2000 03/27/2001 06/05/2002 06/05/2002 05/15/2003 02/25/2004 05/24/2004 05/18/2005 05/30/2006 05/16/2007	 <0.67 <0.54 <0.18 *  <0.34 <0.80 <0.41 0.023 Q	<1.0 <5.0 <0.70 <0.56 <0.17 *  <0.32 <0.91 <0.46 0.044	<1.0 <5.0 <0.45 <0.36 <0.18 *  <0.34 <0.78 <0.33 0.042	<1.0 <5.0 1.0 Q 1.0 Q 0.61 *  1.0 Q 2.0 Q 1.6 1.0 D	<1.0 <5.0 1.0 Q 1.0 Q 0.43 Q*  0.68 Q 1.8 Q 1.6 0.66 QD	<1.0 <2.0 3.7 4.9 1.5  2.3 5.5 4.4 2.5 D	<1.0 <2.0 4.0 5.3 2.0  2.8 7.8 5.2 4.0 D	<1.0 <2.0 3.0 4.1 1.6  2.3 6.2 4.6 Z 3.0 DZ	<1.0 <5.0 2.5 3.8 1.5  2.0 5.6 & 3.4 2.7 D	<1.0 <5.0 2.5 3.3 1.4  1.8 6.6 & 3.6 Z 3.2 DZ	<1.0 <5.0 2.7 3.7 1.4  2.0 6.3 & 3.9 2.7 D	<1.0 <2.0 0.73 Q 0.97 Q 0.34 Q  0.56 Q 1.2 Q& 0.81 Q 0.56 QD	<1.0 <5.0 7.0 9.8 2.7 *  4.4 13 9.5 5.4 D	<1.0 <5.0 <0.53 <0.42 <0.17 *  <0.32 <0.87 <0.37 0.081	<1.0 <2.0 2.4 3.1 1.3  1.8 4.5 & 2.9 & 2.4 D	<1.0 <5.0 <0.67 4.9 <0.24 *  <0.45 <0.89 <0.50 0.071	<1.0 <5.0 2.0 2.8 0.70 *  1.2 3.7 2.8 1.2 D	<5.0 <5.0 5.9 8.4 2.6 *  3.9 12 8.0 4.8 D	nd nd 38 57 18  27 76 52 34



Page 2 of 7

Table 2 - Groundwater Monitoring Well Analytical Results - PAHs Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin USEPA ID# WIN000509949

									POLYN	UCLEAR AR	OMATIC HYD	ROCARBON	NS (μg/L)							
Sample Location	Sample Date	1-Methyl-naphthalene	2-Methyl-naphthalene	Acenaphthene	Acenaphthylene	Anthracene	Benz(a) anthracene	Benzo(a)pyrene	Benzo(b) fluoranthene	Benzo(g,h,i) perylene	Benzo(k) fluoranthene	Chrysene	Dibenz(a,h) anthracene	Fluoranthene	Fluorene	Indeno(1,2,3-cd) pyrene	Naphthalene	Phenanthrene	Pyrene	Total PAHs
								Wisconsi	n Groundwat	er Quality St	andards (NR	140)								
Preventive Action	on Limit (PAL)	ns	ns	ns	ns	<u>600</u>	ns	<u>0.02</u>	<u>0.02</u>	ns	ns	<u>0.02</u>	ns	<u>80</u>	<u>80</u>	ns	<u>8</u>	ns	<u>50</u>	ns
Enforcement St	andard (ES)	ns	ns	ns	ns	<u>3,000</u>	ns	<u>0.2</u>	<u>0.2</u>	ns	ns	<u>0.2</u>	ns	<u>400</u>	<u>400</u>	ns	<u>40</u>	ns	<u>250</u>	ns
MW-9  Dup (QC-1)  MW-10  Dup (QC-1)	04/11/2000 03/27/2001 06/05/2002 06/05/2002 05/15/2003 02/25/2004 05/24/2004 05/18/2005 05/30/2006 05/16/2007 04/11/2000 03/27/2001 06/05/2002 05/15/2003 02/25/2004 05/24/2004 05/18/2005 05/30/2006 05/16/2007	0.039 Q <0.34 <1.8 * <0.091 0.11 <0.16 <0.20 0.14 Q <0.090 0.28Q* 0.14 0.071 0.21 0.45 Q 0.17 Q 0.82 D	<1.0 <5.0 <0.028 <0.35 <1.7 * <0.086 0.046 Q <0.18 <0.22 <0.11 <1.0 <5.0 <0.093 <0.085 * 0.17 0.072 0.040 Q <0.23 <0.058 0.13	<1.0 <5.0 0.14 <0.23 <1.8 * <0.091 0.19 <0.16 <0.16 0.20 Q <1.0 <5.0 0.85 0.85 * 0.55 Q, D 0.40 0.77 D 0.66 0.81 0.63 D	<1.0 <5.0 0.21 <0.29 <1.9 * <0.096 0.29 0.19 Q 0.18 Q 0.26 Q <1.0 <5.0 0.38 0.38 * 0.43 0.13 0.29 0.7 0.38 0.17 D	<1.0 <5.0 0.22 0.38 Q 2.2 Q* <0.10 0.38 0.29 Q 0.28 Q 0.29 Q <1.0 <5.0 0.29 0.32 * 0.29 0.080 0.26 0.49 Q 0.30 0.17	<1.0 <2.0 0.87 D 1.8 10 0.21 1.5 D 0.94 1.3 0.42 Q <1.0 <2.0 0.42 0.65 0.93 D 0.13 0.71 D 1.2 0.67 0.33	<1.0 <2.0 0.96 D 2.1 12 0.4 2.6 D 1.9 2.9 0.78 <1.0 <2.0 0.43 0.80 1.4 D 0.17 1.2 D 2.0 1.1 0.58 D	<1.0 <2.0 0.97 D 2.2 12 0.72 3.4 D 2.5 4.6 Z 1.1 Z <1.0 <2.0 0.32 0.83 1.7 D 0.17 1.4 D 2.3 1.2 Z 0.71 DZ	<1.0 <5.0 0.75 D 1.6 9.5 0.54 2.6 D 2.2 & 3.3 0.9 <1.0 <5.0 0.34 0.68 1.4 D 0.16 1.2 D 2.1 & 1.0 0.64 D	<1.0 <5.0 0.60 D 1.4 11 0.48 2.6 D 2.0 & 3.1 Z 0.92 Z <1.0 <5.0 0.23 0.64 1.3 D 0.16 1.3 D 2.0 & 1.0 Z 0.60 DZ	<1.0 <5.0  0.75 D  1.6  13  0.59  2.9 D  1.9 &  3.4  0.79  <1.0 <5.0  0.27  0.73  1.5 D  0.17 Q  1.4 D  2.1 &  1.0  0.51 D	<1.0 <2.0 0.31 0.51 Q 2.4 Q 0.098 Q 0.66 Q, D 0.45 Q& 0.63 Q 0.20 Q <1.0 <2.0 0.095 Q 0.18 Q 0.33 0.039 Q 0.31 0.39 Q& 0.20 Q	<1.0 <5.0 2.1 D 3.8 29 * 1.3 5.5 D 3.1 5.6 1.8 <1.0 <5.0 1.0 1.3 * 3.1 D 0.41 2.8 D 3.8 2.1 1.0 D	<1.0 <5.0 0.041 Q <0.26 <1.7 * <0.086 0.086 <0.17 <0.18 0.14 Q <1.0 <5.0 0.64 0.47 * 0.43 0.35 0.37 0.31 Q 0.34 0.16	<1.0 <2.0 0.65 D 1.4 7.7 0.45 2.2 D 1.7 & 2.6 0.79 <1.0 <2.0 0.28 0.56 1.1 D 0.14 0.96 D 1.6 & 0.79 0.54 D	<1.0 <5.0 0.12 <0.34 <2.4 * <0.12 0.35 <0.18 0.38 Q 0.25 Q <1.0 <5.0 0.090 Q 0.28 Q*I 0.39 0.17 0.47 0.25 Q 0.087 Q 0.087 Q 0.13	<1.0 <5.0 0.41 0.90 10 * 0.25 Q 1.0 D 0.58 0.91 0.66 <1.0 <5.0 0.16 Q 0.33 * 0.75 D 0.14 0.57 D 0.84 0.37 0.24	<5.0 <5.0 1.8 D 3.2 23 * 0.94 4.1 D 2.4 3.8 1.4 <5.0 <5.0 1.0 1.4 * 2.4 D 0.33 2.2 D 3.2 1.7 0.77 D	nd nd 11 21 142 6.0 31 20 33 11 nd nd 6.8 11 18 3.3 16 24 13 8.3
MW-11  Dup (QC-2)	04/11/2000 03/27/2001 06/05/2002 05/15/2003 02/25/2004 02/25/2004	 0.25 0.28 * 0.047 Q 0.042 Q	<1.0 <5.0 <0.028 0.026 Q* 0.035 Q 0.036 Q	<1.0 <5.0 0.16 0.35 * 0.096 0.097	<1.0 <5.0 0.32 0.25 * 0.23 0.21	<1.0 <5.0 0.11 0.13 * 0.069 0.12	<1.0 <2.0 0.18 0.39 0.10 0.77 D	<1.0 <2.0 <b>0.20</b> <b>0.53 D</b> <u>0.14</u> <b>1.2 D</b>	<1.0 <2.0 <u>0.16</u> <u>0.64 D</u> <u>0.15</u> 1.1 D	<1.0 <5.0 0.16 0.52 D 0.14 1.0 D	<1.0 <5.0 0.12 0.49 0.12 1.1 D	<1.0 <5.0 <u>0.15</u> <b>0.49</b> <u>0.13</u> Q	<1.0 <2.0 0.047 Q 0.14 0.035 Q 0.030	<1.0 <5.0 0.39 0.89 D* 0.30 2.4 D	<1.0 <5.0 0.050 Q 0.12 * 0.10 0.10	<1.0 <2.0 0.13 0.46 0.11 0.85 D	<1.0 <5.0 0.048 Q 0.046 Q*I 0.087 0.097	<1.0 <5.0 0.090 0.17 * 0.11 0.64 D	<5.0 <5.0 0.45 0.80 D* 0.26 1.7 D	nd nd 3.0 6.7 2.3
Dup (QC-1)	05/24/2004 05/24/2004 05/18/2005 05/30/2006	0.10 0.073	0.019 Q <0.016*	0.23 0.18 *	0.27 0.20 *	0.14 0.13 *	0.26 0.29	0.42 0.45	0.46 D 0.48 D	0.45 0.45 /ell no longer	0.35 0.41 sampled - will Abandoned	0.40 0.43	0.12 0.11 ed	0.72 D 0.85 D*	0.15 0.12	0.38 0.39	0.033 Q 0.064 Q	0.15 0.16 *	0.64 Q 0.68 D*	5 5

NATURAL RESOURCE TECHNOLOG

Table 2 - Groundwater Monitoring Well Analytical Results - PAHs Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin USEPA ID# WIN000509949

									POLYN	UCLEAR AR	OMATIC HYD	ROCARBON	NS (μg/L)							
Sample Location	Sample Date	1-Methyl-naphthalene	2-Methyl-naphthalene	Acenaphthene	Acenaphthylene	Anthracene	Benz(a) anthracene	Benzo(a)pyrene	Benzo(b) fluoranthene	Benzo(g,h,i) perylene	Benzo(k) fluoranthene	Chrysene	Dibenz(a,h) anthracene	Fluoranthene	Fluorene	Indeno(1,2,3-cd) pyrene	Naphthalene	Phenanthrene	Pyrene	Total PAHs
								Wisconsii	n Groundwat	er Quality St	andards (NR	140)								
Preventive Action	n Limit (PAL)	ns	ns	ns	ns	<u>600</u>	ns	<u>0.02</u>	<u>0.02</u>	ns	ns	<u>0.02</u>	ns	<u>80</u>	<u>80</u>	ns	<u>8</u>	ns	<u>50</u>	ns
Enforcement Sta	andard (ES)	ns	ns	ns	ns	<u>3,000</u>	ns	<u>0.2</u>	<u>0.2</u>	ns	ns	<u>0.2</u>	ns	<u>400</u>	<u>400</u>	ns	<u>40</u>	ns	<u>250</u>	ns
MW-12	04/11/2000 03/27/2001 06/05/2002 05/15/2003	  <0.027	<1.0 <5.0 <0.028	<1.0 <5.0 <0.018	<1.0 <5.0 0.025 Q	<1.0 <5.0 0.053 Q	<1.0 <2.0 0.61 C	<1.0 <2.0 <b>0.65 C</b>			<1.0 <5.0 0.48			<1.0 <5.0 1.0 D	<1.0 <5.0 <0.021	<1.0 <2.0 0.49 C	<1.0 <5.0 0.056 Q	<1.0 <5.0 0.23	<5.0 <5.0 1.1 D	nd nd 6.8
	02/25/2004 05/24/2004	<0.34	<0.32	<0.34	<0.36	<0.38	2.7		/ell was not ac <u>6.2</u>	ccessible for s	sampling (und	er water from <u>4.7</u>	surface runof	f) 7.7	<0.32	4.6	<0.45	1.6	5.8	50
	05/18/2005	<0.80	<0.91	<0.78	<0.77	<0.71	4.5	<u>5.2</u> 9.5	<u>0.2</u> <u>11</u>	11 &	10 &	8.9 &	2.2 Q&	13	<0.32	8.3 &	<0.43	2.5 Q	10	91
	05/30/2006									tain a represe	entative samp	e due to storr	mwater runoff							
	6/20/2006 5/16/2007	<0.81 <0.20	<0.90 <0.22	<0.65 <0.16	<0.65	1.8 Q 0.47 Q	5.6 3.1	<u>13</u> 7.4	<u>16 Z</u> 9.4 Z	20 5.0 D	13 Z 6.6 Z	<u>12</u> 5.7	3.9 Q	19 9.0	<0.72 <0.18	15 7.9	<0.99 <0.25	3.4 1.7	15 6.8	138 65
MM 40D					0.22 Q								1.8							
MW-12D	04/11/2000 03/27/2001		<1.0 <5.0	<1.0 <5.0	<1.0 <5.0	<1.0 <5.0	<1.0 <2.0	<1.0 <2.0	<1.0 <2.0	<1.0 <5.0	<1.0 <5.0	<1.0 <5.0	<1.0 <2.0	<1.0 <5.0	<1.0 <5.0	<1.0 <2.0	<1.0 <5.0	<1.0 <5.0	<5.0 <5.0	nd nd
	06/05/2002	<0.16	<0.17	<0.11	<0.14	<0.12	0.67	0.76	0.96	0.61	0.63	0.68	0.16 Q	1.9	<0.13	0.59	<0.16	0.55	1.5	9.0
	05/15/2003	<0.018 *	<0.017 *	<0.018 *	0.059 Q*	0.051 Q*	0.52 D	<u>0.92 D</u>	1.2 D	0.93 D	1.1 D	<u>1.1 D</u>	0.28	1.6 D*	<0.017 *	0.73 D	0.065 Q*I	0.34 *	1.2 D*	10
	02/25/2004			•	Ţ			,	Well was not	accessible fo	r sampling (int	erior of flush	mount frozen)		_	_	·	_	•	
	05/24/2004	<0.34	< 0.32	<0.34	<0.36	<0.38	0.95	<u>2.2</u>	<u>2.9</u>	2.6	2.1	<u>2.0</u>	0.64 Q	3.2	<0.32	2.2	<0.45	0.67 Q	2.5	22
Dup (QC-2)	05/24/2004	<0.017	<0.016*	<0.017*	0.034 Q *	0.049 Q *	0.46	0.90 D	1.1 D	1.0 D	0.92 D	0.85 D	0.28	1.5 D *	<0.016	0.85 D	0.045 Q	0.26 *	1.0 D *	9.0
Dup (QC-1)	05/18/2005 05/18/2005	0.10 Q <0.10	<0.091 <0.11	<0.078 <0.097	0.11 Q 0.12 Q	<0.071 <0.088	0.45 0.51	0.84 0.94	<u>1.2</u> 1.2	1.0 & 1.0	0.88 & 1.1	0.8 <u>&amp;</u> 0.93	0.22 Q& 0.21 Q	1.1 1.1	<0.087 <0.11	0.80 & 0.81	0.5 <0.11	0.21 Q 0.25 Q	0.80 0.97	8.9 9.1
Dup (QO 1)	05/30/2006	<0.010	<0.011	<0.0082	0.016 Q	0.014 Q	0.086	<u>0.94</u> <u>0.19</u>	0.24 Z	0.24	0.20 Z	<u>0.16</u>	0.047 Q	0.21	<0.0091	0.18	0.024 Q	0.041	0.18	1.8
	05/16/2007	0.025 Q	0.014 Q	0.014 Q	0.036	0.024 Q	0.095	0.27	0.34 Z	0.32	0.24 Z	<u>0.17</u>	0.059 Q	0.23	<0.0091	0.26	0.17	0.046	0.18	2.5
Dup (051607006)	05/16/2007	0.11	0.012 Q	0.016 Q	0.047	<0.012	0.020 Q	<u>0.049 Q</u>	<u>0.074 Z</u>	0.068	0.053 QZ	<u>0.039</u>	<0.019	0.055	<0.0091	0.058 Q	0.077	0.017 Q	0.042 Q	0.74
MW-13	04/11/2000		90	29	3.8	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	2.0	<1.0	<u>2,000</u>	<1.0	<5.0	2,125
	03/27/2001 06/05/2002	 <430 D	210 <450 D	72 <290 D	<5.0 2.9	<5.0 0.88 Q	<2.0 2.4	<2.0	<2.0	<5.0 2.9	<5.0 2.6	<5.0 2.5	<2.0 0.63 Q	<5.0 6.6	<5.0 5.3	<2.0 2.5	3,700 3,800 C	<5.0 3.7	<5.0 5.8	3,982 3,846
	05/05/2002	30 D*	0.77 Q*	18 D*	1.2 *	0.88 Q 1.2 Q*	2.4 4.4	<u>3.4</u> <u>6.2</u>	<u>4.1</u> 6.0	5.7	5.0	<u>2.5</u> 5.1	1.4	12 D*	2.1 *	4.5	1.6 *	3.7 4.3 *	9.7 *	3,0 <del>4</del> 6 119
	02/25/2004										ole for samplin									
	05/24/2004	55 D	24 D	17 Q, D	2.0	<0.38	1.4	<u>2.7</u>	<u>2.7</u>	2.7	1.9	<u>1.8</u>	0.72 Q	3.3	2.3	2.3	140 D	1.5	2.7	264
	05/18/2005	190 D	66 QD	51 QD	4.5 Q	<1.8	<2.0	<1.8	<1.8	<2.1 &	<1.9 &	<1.6 &	<2.2 &	2.0 Q	3.5 Q	<1.7 &	920 D	<2.0	<1.6	1,237
Dun (0001)																				213
Dup (QC01)																			<29 0.62 D	1,241 9.5
Dup (QC01)	05/18/2005 05/30/2006 05/30/2006 05/16/2007	190 D 99 220 0.49 D	66 QD 22 100 0.16	51 QD 37 61 1.80 D	4.5 Q 4.0 Q <16 0.25	<1.8 <4.7 <23 0.091	<2.0 <6.4 <31 0.35	<1.8 <7.5 <37 <u>0.69 D</u>	<1.8 <6.4Z <31 Z <u>0.69 DZ</u>	<2.1 & <7.9 <39 0.69 D	<1.9 & <7.9Z <39 Z 0.64 DZ	<1.6 & <7.7 <38 <u>0.48 D</u>	<2.2 & <7.7 <38 0.17	2.0 Q <6.3 <31 0.84 D	3.5 Q <3.7 <18 0.066	<1.7 & <7.7 <38 0.59 D	920 D 51 860 0.62 D	<2.0 <4.6 <23 0.22	<5.9 <29	

Table 2 - Groundwater Monitoring Well Analytical Results - PAHs Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin USEPA ID# WIN000509949

									POLYN	UCLEAR AR	OMATIC HYD	DROCARBON	IS (µg/L)			_	_			
Sample Location	Sample Date	1-Methyl-naphthalene	2-Methyl-naphthalene	Acenaphthene	Acenaphthylene	Anthracene	Benz(a) anthracene	Benzo(a)pyrene	Benzo(b) fluoranthene	Benzo(g,h,i) perylene	Benzo(k) fluoranthene	Chrysene	Dibenz(a,h) anthracene	Fluoranthene	Fluorene	Indeno(1,2,3-cd) pyrene	Naphthalene	Phenanthrene	Pyrene	Total PAHs
								Wisconsi	n Groundwat	er Quality St	andards (NR	140)								
Preventive Acti	on Limit (PAL)	ns	ns	ns	ns	<u>600</u>	ns	<u>0.02</u>	<u>0.02</u>	ns	ns	<u>0.02</u>	ns	<u>80</u>	<u>80</u>	ns	<u>8</u>	ns	<u>50</u>	ns
Enforcement S	tandard (ES)	ns	ns	ns	ns	3,000	ns	0.2	0.2	ns	ns	0.2	ns	<u>400</u>	<u>400</u>	ns	<u>40</u>	ns	<u>250</u>	ns
MW-14	04/11/2000 03/27/2001	 	140,000 140,000	3,300 3,300	36,000 45,000	13,000 13,000	9,500 10,000	8,600 8,400	6,700 8,300	4,500 3,300	7,700 <4,800	8,800 7,400	1,200 1,100	27,000 28,000	18,000 15,000	4,000 3,800	<u>540,000</u> <u>510,000</u>	45,000 50,000	23,000 24,000	896,300 870,600
	05/15/2003 02/25/2004 05/24/2004 05/18/2005 05/30/2006 05/16/2007																			
MW-17T	04/11/2000 03/27/2001 06/05/2002 05/15/2003 02/25/2004 05/24/2004 05/18/2005 05/30/2006 05/16/2007	 0.041 Q <0.020 * 0.021 Q <0.017 <0.02 0.012 Q <0.010	<1.0 <5.0 0.045 Q <0.019 * 0.037 Q <0.016 <0.023 0.017 QB <0.011	<1.0 <5.0 <0.018 <0.020 * <0.017 <0.017 <0.019 <0.0082 <0.0082	<1.0 <5.0 <0.023 <0.021 * 0.036 Q <0.018 <0.019 <0.0081	<1.0 <5.0 <0.020 0.022 * 0.053 Q <0.019 <0.018 <0.012 <0.012	<1.0 <2.0 <0.019 <0.013 0.39 <0.011 <0.020 <0.016 <0.016	<1.0 <2.0 <0.012 <0.016 <b>0.70 D</b> <0.013 <b>0.030 Q</b> <0.018 <0.018	<1.0 <2.0 <0.014 <0.015 <b>1.0 D</b> <0.012 <b>0.032 Q</b> 0.019 QZ <0.016 Z	<1.0 <5.0 <0.015 <0.018 0.90 D <0.015 0.031 Q& <0.019 <0.019	<1.0 <5.0 <0.013 <0.021 0.70 D <0.018 0.030 Q& <0.019Z <0.019 Z	<1.0 <5.0 <0.018 <0.016 <b>0.73 D</b> <0.013 <b>0.026 Q&amp;</b> <0.019 <0.019	<1.0 <2.0 <0.017 <0.018 0.21 <0.015 <0.022 & <0.019	<1.0 <5.0 <0.028 <0.015 * 1.2 D <0.012 0.037 Q 0.025 Q 0.020 Q	<1.0 <5.0 <0.021 <0.019 * 0.022 Q <0.016 <0.022 <0.0091	<1.0 <2.0 <0.014 <0.024 0.73 D <0.020 0.024 Q& <0.019	<1.0 <5.0 0.49 <0.027 * 0.56 D <0.023 0.046 Q 0.013 QB <0.012	<1.0 <5.0 <0.019 <0.018 * 0.28 <0.015 <0.02 0.014 Q <0.011	<5.0 <5.0 <0.020 <0.019 * 0.88 D <0.016 0.033 Q 0.020 Q 0.016 Q	nd nd 0.6 nd 8.4 nd 0.29 0.12 0.04
MW-18T	04/11/2000 03/27/2001 06/05/2002 05/15/2003 02/25/2004 05/24/2004 05/18/2005	 <0.027 <0.018 <0.017 <0.017 <0.02	<1.0 <5.0 <0.028 <0.017 <0.016 <0.016 <0.023	<1.0 <5.0 <0.018 <0.018 <0.017 <0.017	<1.0 <5.0 <0.023 <0.019 <0.018 <0.018 <0.019	<1.0 <5.0 <0.020 <0.020 <0.019 <0.019 <0.018	<1.0 <2.0 <0.019 <0.012 <0.011 <0.011	<1.0 <2.0 <0.012 <0.014 <0.013 <0.013 0.019 Q	<1.0 <2.0 <0.014 <0.013 <0.012 <0.012 0.022 Q	<1.0 <5.0 <0.015 <0.016 <0.015 <0.015 <0.021 &	<1.0 <5.0 <0.013 <0.019 <0.018 <0.018 <0.019 &	<1.0 <5.0 <0.018 <0.014 <0.013 <0.013 0.019 Q&	<1.0 <2.0 <0.017 <0.016 <0.015 <0.015 <0.022 &	<1.0 <5.0 <0.028 <0.013 <0.012 0.013 Q 0.030 Q	<1.0 <5.0 <0.021 <0.017 <0.016 <0.016 <0.022	<1.0 <2.0 <0.014 <0.021 <0.020 <0.020 <0.017 &	<1.0 <5.0 0.12 0.100 0.028 Q <0.023 <0.022	<1.0 <5.0 <0.019 <0.016 <0.015 <0.015 <0.02	<5.0 <5.0 <0.020 <0.017 <0.016 <0.016 0.025 Q	nd nd 0.1 0.1 0.03 0.01

Table 2 - Groundwater Monitoring Well Analytical Results - PAHs Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin USEPA ID# WIN000509949

									POLYN	UCLEAR AR	OMATIC HYD	ROCARBON	NS (μg/L)							
Sample Location	Sample Date	1-Methyl-naphthalene	2-Methyl-naphthalene	Acenaphthene	Acenaphthylene	Anthracene	Benz(a) anthracene	Benzo(a)pyrene	Benzo(b) fluoranthene	Benzo(g,h,i) perylene	Benzo(k) fluoranthene	Chrysene	Dibenz(a,h) anthracene	Fluoranthene	Fluorene	Indeno(1,2,3-cd) pyrene	Naphthalene	Phenanthrene	Pyrene	Total PAHs
								Wisconsi	n Groundwat	er Quality St	andards (NR	140)								
Preventive Actio	n Limit (PAL)	ns	ns	ns	ns	<u>600</u>	ns	<u>0.02</u>	<u>0.02</u>	ns	ns	<u>0.02</u>	ns	<u>80</u>	<u>80</u>	ns	<u>8</u>	ns	<u>50</u>	ns
Enforcement Sta	andard (ES)	ns	ns	ns	ns	3,000	ns	<u>0.2</u>	<u>0.2</u>	ns	ns	<u>0.2</u>	ns	<u>400</u>	<u>400</u>	ns	<u>40</u>	ns	<u>250</u>	ns
MW-19T	04/11/2000 03/27/2001 06/05/2002 05/15/2003 02/25/2004 05/24/2004 05/18/2005 05/30/2006 05/16/2007 04/11/2000 03/27/2001 06/05/2002 05/15/2003	 <0.16 <0.018 * <0.017 0.019 Q <0.02 0.018 Q <0.010   <0.027 0.053 Q	<1.0 <5.0 <0.17 <0.017 * 0.016 Q 0.026 Q <0.023 0.020 QB 0.014 Q <1.0 <5.0 <0.028 0.035 Q	<1.0 <5.0 <0.11 <0.018 * <0.017 <0.019 <0.0082 <0.0082 <1.0 <5.0 <0.018 <0.018	<1.0 <5.0 0.30 Q 0.031 Q* <0.018 0.068 0.040 Q 0.029 0.016 Q <1.0 <5.0 <0.023 <0.019	<1.0 <5.0 0.19 Q 0.022 Q* <0.019 0.093 0.026 Q 0.017 Q <0.012 <1.0 <5.0 <0.020 <0.020	<1.0 <2.0 0.86 0.092 0.023 Q 0.66 D 0.10 0.054 0.019 Q <1.0 <2.0 0.022 Q <0.012	<1.0 <2.0 <b>1.2</b> <u>0.16</u> <u>0.043 Q</u> <b>1.5 D</b> <u>0.17</u> <u>0.098</u> <u>0.039 Q</u> <1.0 <2.0 <u>0.031 Q</u> 0.018 Q	<1.0 <2.0 <b>1.1</b> 0.17 0.059 <b>2.1 D</b> <b>0.21</b> 0.12 Z 0.038 QZ <1.0 <2.0 0.033 Q 0.025 Q	<1.0 <5.0 0.92 0.15 0.054 1.8 D 0.20 & 0.11 0.042 Q <1.0 <5.0 0.029 Q 0.023 Q	<1.0 <5.0 0.71 0.12 0.044 Q 1.4 D 0.16 & 0.088 Z <u>0.033 QZ</u> <1.0 <5.0 0.024 Q <0.019	<1.0 <5.0 <b>0.69</b> <u>0.12</u> <u>0.044 Q</u> <b>1.5 D</b> <u>0.14 &amp;</u> <u>0.075</u> <u>0.028 Q</u> <1.0 <5.0 <u>0.025 Q</u> <u>0.020 Q</u>	<1.0 <2.0 0.29 Q 0.038 Q <0.015 0.42 0.041 Q& 0.023 Q <0.019 <1.0 <2.0 <0.017 <0.016	<1.0 <5.0 1.7 0.19 * 0.070 2.2 D 0.24 0.13 0.056 <1.0 <5.0 0.061 Q 0.032 Q	<1.0 <5.0 <0.13 <0.017 * <0.016 0.024 Q <0.022 <0.0091 <0.0091 <1.0 <5.0 <0.021 <0.017	<1.0 <2.0 0.91 0.13 0.043 Q 1.5 D 0.16 & 0.086 0.029 Q <1.0 <2.0 0.026 Q <0.021	<1.0 <5.0 0.44 0.032 Q*I 0.12 0.045 Q 0.069 Q 0.25 B 0.034 Q <1.0 <5.0 <0.027 0.33	<1.0 <5.0 0.44 0.060 * 0.020 Q 0.54 D 0.075 0.039 0.024 Q <1.0 <5.0 0.027 Q 0.018 Q	<5.0 <5.0 1.4 0.18 * 0.053 Q 1.7 D 0.2 0.11 0.046 Q <5.0 <5.0 <0.063 Q 0.028 Q	nd nd 11 1.5 0.6 16 1.8 1.3 0.4 nd nd 0.3 0.6
Dup (QC02) Dup (051607010	02/25/2004 05/24/2004 05/18/2005 05/30/2006 05/30/2006 05/16/2007 05/16/2007	0.020 Q <0.017 <0.020 <0.010 0.017 Q <0.010 <0.010	0.030 Q <0.016 <0.023 0.015 QB 0.018 QB <0.011 <0.011	<0.017 <0.017 <0.019 <0.0082 <0.0082 <0.0082 <0.0082	0.042 Q 0.019 Q <0.019 <0.0081 0.014 Q <0.0081 0.0086 Q	<0.019 <0.019 <0.018 <0.012 <0.012 <0.012 <0.012	0.039 0.078 <0.020 0.032 Q 0.028 Q <0.016 0.020 Q	0.046 0.12 0.027 Q 0.055 Q 0.052 Q <0.018 0.038 Q *	0.048 0.14 0.035 Q 0.053 Z 0.054 Z 0.023 QZ 0.048 QZ*	0.040 Q 0.12 0.029 Q 0.051 Q 0.049 Q <0.019 0.038 Q*	0.037 Q 0.10 0.027 Q 0.041 QZ 0.037 QZ 0.020 QZ 0.038 QZ	0.049 0.11 0.029 Q 0.044 Q 0.044 Q 0.019 Q 0.040 Q	<0.015 0.031 <0.022 <0.019 <0.019 <0.019 <0.019	0.10 0.21 0.046 Q 0.084 0.087 0.037 Q 0.071 *	<0.016 <0.016 <0.022 <0.0091 0.016 Q <0.0091 <0.0091	0.032 Q 0.10 0.022 Q 0.037 Q 0.035 Q <0.019 0.036 Q *	0.096 <0.023 0.039 Q <0.012 0.064 B <0.012 <0.012	0.065 0.078 0.023 Q 0.032 Q 0.043 0.021 Q 0.038 Q	0.079 0.18 0.037 Q 0.064 0.06 0.026 Q 0.051 *	0.7 1.3 0.3 0.5 0.6 0.1
MW-21T	04/11/2000 03/27/2001 06/05/2002 05/15/2003 02/25/2004 05/24/2004 05/18/2005 05/30/2006 05/16/2007	 0.058 Q 0.037 Q 0.032 Q 0.018 0.030 Q <0.026 0.010 Q	<1.0 <5.0 <0.028 0.027 Q 0.031 Q 0.022 <0.023 <0.029 0.013 Q	<1.0 <5.0 0.36 0.082 0.25 0.025 0.180 <0.021 0.011 Q	<1.0 <5.0 1.8 D 0.47 1.1 D 0.066 0.75 D 0.097 0.10	<1.0 <5.0 <0.020 <0.020 <0.019 0.053 <0.018 0.039 Q 0.016 Q	<1.0 <2.0 0.027 Q 0.021 Q 0.024 Q 0.37 0.049 Q 0.14 0.053	<1.0 <2.0 <u>0.10</u> <u>0.072</u> <u>0.055</u> <u><b>0.58</b> <u>0.11</u> <u><b>0.32</b></u> <u>0.13</u></u>	<1.0 <2.0 <u>0.073</u> <u>0.066</u> <u>0.053</u> <u><b>0.72</b> <u>0.12</u> <u>0.56 Z</u> <u><b>0.21 Z</b></u></u>	<1.0 <5.0 0.15 0.11 0.068 0.63 0.15 0.44 0.18	<1.0 <5.0 <0.047 0.046 Q 0.047 Q 0.59 0.11 0.35 Z 0.14 Z	<1.0 <5.0 0.020 Q 0.030 Q 0.037 Q 0.60 0.092 0.38 0.13	<1.0 <2.0 0.037 Q 0.020 Q <0.015 0.17 0.031 Q 0.078 Q 0.027 Q	<1.0 <5.0 0.031 Q 0.046 0.059 1.0 0.15 0.51	<1.0 <5.0 0.18 0.037 Q 0.081 0.026 0.068 Q <0.023 0.012 Q	<1.0 <2.0 0.12 0.081 0.052 Q 0.54 0.11 0.34 0.16	<1.0 <5.0 0.042 Q 0.18 0.76 D 0.038 0.049 Q <0.032 0.013 Q	<1.0 <5.0 0.035 Q 0.022 Q 0.034 Q 0.35 0.059 Q 0.14 0.054	<5.0 <5.0 0.034 Q 0.042 Q 0.050 Q 0.82 0.11 0.41 0.15	nd nd 3.1 1.4 2.7 6.6 2.2 3.8 1.6

[JTB/GRL-08/02][JTB/PAR-07/03][JKL-6/04][HMS/JAH -7/05][HMS/RJG 6/06][HMS/RJG 06/07]



Page 6 of 7

Table 2 - Groundwater Monitoring Well Analytical Results - PAHs Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

									POLYN	UCLEAR AR	OMATIC HYD	ROCARBON	IS (µg/L)							
Sample Location	Sample Date	1-Methyl-naphthalene	2-Methyl-naphthalene	Acenaphthene	Acenaphthylene	Anthracene	Benz(a) anthracene	Benzo(a)pyrene	Benzo(b) fluoranthene	Benzo(g,h,i) perylene	Benzo(k) fluoranthene	Chrysene	Dibenz(a,h) anthracene	Fluoranthene	Fluorene	Indeno(1,2,3-cd) pyrene	Naphthalene	Phenanthrene	Pyrene	Total PAHs
	Wisconsin Groundwater Quality Standards (NR 140)																			
Preventive Actio	on Limit (PAL)	ns	ns	ns	ns	<u>600</u>	ns	<u>0.02</u>	<u>0.02</u>	ns	ns	<u>0.02</u>	ns	<u>80</u>	<u>80</u>	ns	<u>8</u>	ns	<u>50</u>	ns
Enforcement Sta	andard (ES)	ns	ns	ns	ns	3,000	ns	<u>0.2</u>	<u>0.2</u>	ns	ns	<u>0.2</u>	ns	<u>400</u>	<u>400</u>	ns	<u>40</u>	ns	<u>250</u>	ns

### Notes:

- 1) Pre-2002 data from Horizon Environmental reports.
- 2) Concentrations that attain or exceed an NR 140 PAL are italicized/underlined.
- 3) Concentrations that attain or exceed an NR 140 ES are underlined/bold.
- **4)** The 4/11/00 MW-13 sampling also contained: (22 μg/L 2,4-Dimethylphenol)(7.4 μg/L 2-methylphenol).
- 5) Wells PW-1 and MW-12 were buried by asphalt and well MW-1 was dry during the 5/15/03 sampling event.
- PAHs: Polynuclear aromatic hydrocarbons.
  - ns: No standard for this analyte.
- Dup (QC-1): Field duplicate sample (field identity shown in parentheses).
  - μg/L: Micrograms per liter.
  - --: Analysis was not performed.
  - nd: Not detected.

### **Laboratory Notes:**

- Q: The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ).
- C: Analyte value from diluted analysis, or surrogate result not applicable due to sample dilution.
- I: Naphthalene present in blank at 0.030 μg/L.
- \*: Duplicate analysis not within control limits.
- **D:** Analyte value from diluted analysis
- &: Laboratory Control Spike recovery not within control limit.
- **Z**: This compound was separated in the check standard but it did not meet the resolution criteria as set forth in SW846.
- **B:** Analyte is present in the method blank.



1530 SSWP Tables 1234 revised 070604-Tbl 2 GW PAH

Page 7 of 7

Table 3 - Groundwater Elevations Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

Well Name	V-1	
Well Depth from TOC (	feet)	23.71
Screen Length (feet)		3
Surface Elevation (MSL	_)	na
Top of Casing Elevation	n (MSL)	601.06
Top of Screen Elevation	n (MSL)	580.35
Bottom of Screen Eleva	ation (MSL)	577.35
	Depth to Water from	Water Elevation
Date	TOC (feet)	(MSL)
03/22/1999	19.53	581.53 *
04/10/2000	Dry	< 577.35
03/26/2001	20.65	580.41 *
10/25/2001	19.89	581.17 *
01/31/2002 A	inaccessible	due to snow/ice
03/03/2002	19.45	581.61 *
06/05/2002	19.32	581.74 *
05/15/2003	dry	dry
08/26/2003	dry	dry
11/19/2003	20.62	580.44 *
02/25/2004	20.67	580.39 *
05/24/2004	~23.7	~577.4
11/10/2004	19.29	581.77 *
5/18/2005 G	19.32	581.74 *
11/28/2005	20.04	581.02 *
05/30/2006	19.68	581.38 *
05/16/2007	19.42	TBS *

Well Depth from TOC (f	23.75		
Screen Length (feet)	3		
Surface Elevation (MSL	na		
Top of Casing Elevation	(MSL)	597.18	
Top of Screen Elevation	(MSL)	576.43	
Bottom of Screen Eleva	tion (MSL)	573.43	
	Depth to Water from	Water Elevation	
Date	TOC (feet)	(MSL)	
03/22/1999	15.57	581.61	*
04/10/2000	16.61	580.57	*
03/26/2001	16.56	580.62	*
10/25/2001	15.95	581.23	*
01/31/2002 A	16.23	580.95	*
03/03/2002	inaccessible	due to snow/ice	
06/05/2002	15.39	581.79	*
05/15/2003	16.35	580.83	*
08/26/2003	16.34	580.84	*
11/19/2003	16.74	580.44	*
02/25/2004	16.81	580.37	*
05/24/2004	15.64	581.54	*
11/10/2004	15.36	581.82	*
05/18/2005	15.43	581.75	*
11/28/2005	581.05	*	
05/30/2006	581.43	*	
05/16/2007	15.59	581.59	*

MW-2

Well Name

Well Name	V-5	٦	
Well Depth from TOC (f	29.20		
Screen Length (feet)		3	
Surface Elevation (MSL	.)	na	
Top of Casing Elevation	n (MSL)	605.24	
Top of Screen Elevation	n (MSL)	579.04	
Bottom of Screen Eleva	ition (MSL)	576.04	
	Depth to Water from	Water Elevation	
Date	TOC (feet)	(MSL)	
03/22/1999	23.48	581.76	*
04/10/2000	24.51	580.73	*
03/26/2001	24.63	580.61	*
10/25/2001	23.86	581.38	*
01/31/2002 A	24.15	581.09	*
03/03/2002	inaccessible	due to snow/ice	
06/05/2002	23.33	581.91	*
05/15/2003	24.31	580.93	*
08/26/2003	24.29	580.95	*
11/19/2003	24.86	580.38	*
02/25/2004	24.76	580.48	*
05/24/2004	23.70	581.54	*
11/10/2004	23.31	581.93	*
5/18/2005 G	22.98	582.26	*
11/28/2005	24.12	581.12	*
05/30/2006	23.75	581.49	*
05/16/2007	23.62	581.62	*

Well Name	MV	V-6		
Well Depth from TOC (	feet)	30.55		
Screen Length (feet)		10		
Surface Elevation (MSI	_)	na		
Top of Casing Elevation	n (MSL)	601.85		
Top of Screen Elevatio	n (MSL)	581.30		
Bottom of Screen Eleva	ation (MSL)	571.30		
	Depth to Water from	Water Elevation		
Date	TOC (feet)	(MSL)		
03/22/1999	20.18	581.67 *		
04/10/2000	21.23	580.62		
03/26/2001	21.34	580.51		
10/25/2001	20.56	581.29		
01/31/2002 A	inaccessible	due to snow/ice		
03/03/2002	inaccessible	due to snow/ice		
06/05/2002	20.03	581.82 *		
05/15/2003	20.91	580.94		
08/26/2003	20.98	580.87		
11/19/2003	21.39	580.46		
02/25/2004	21.43	580.42		
05/24/2004	20.25	581.60 *		
11/10/2004	19.9	581.95 *		
05/18/2005	20.06	581.79 *		
11/28/2005	20.83	581.02		
05/30/2006	20.33	581.52 *		
05/16/2007	20.22	581.63 *		



Table 3 - Groundwater Elevations Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

Well Name	I-7			
Well Depth from TOC (f	10.63			
Screen Length (feet)		5		
Surface Elevation (MSL		na		
Top of Casing Elevation	(MSL)	588.93		
Top of Screen Elevation	(MSL)	583.30		
Bottom of Screen Eleva	tion (MSL)	578.30		
	Depth to Water from	Water Elevation		
Date	TOC (feet)	(MSL)		
03/22/1999	7.30	581.63		
04/10/2000	8.32	580.61		
03/26/2001	8.43	580.50		
10/25/2001	7.66	581.27		
01/31/2003	nm	nm		
03/03/2002	7.94	580.99		
06/05/2002	7.14	581.79		
05/15/2003	8.10	580.83		
08/26/2003	8.07	580.86		
11/19/2003	8.18	580.75		
02/25/2004	8.52	580.41		
05/24/2004	7.36	581.57		
11/10/2004	581.85			
05/18/2005	05/18/2005 7.19			
11/28/2005	581.05			
05/30/2006	7.47	581.46		
05/16/2007	7.36	581.57		

Well Name	MV	V-8		
Well Depth from TOC (f	eet)	10.53		
Screen Length (feet)		5		
Surface Elevation (MSL	.)	na		
Top of Casing Elevation	(MSL)	588.13		
Top of Screen Elevation	n (MSL)	582.60		
Bottom of Screen Eleva	tion (MSL)	577.60		
	Depth to Water from	Water Elevation		
Date	TOC (feet)	(MSL)		
03/22/1999	6.58	581.55		
04/10/2000	7.59	580.54		
03/26/2001	7.70	580.43		
10/25/2001	6.94	581.19		
01/31/2003	nm	nm		
03/03/2002	inaccessible	due to snow/ice		
06/05/2002	6.75	581.38		
05/15/2003	7.35	580.78		
08/26/2003	7.32	580.81		
11/19/2003	7.70	580.43		
02/25/2004	inaccessible d	ue to snow/ice		
05/24/2004	6.72	581.41		
11/10/2004	5.16	582.97 *		
05/18/2005	6.46	581.67		
11/28/2005	7.03	581.10		
05/30/2006	7.72	580.41		
05/16/2007	7.10	581.03		

Well Name	Well Name MW				
Well Depth from TOC (f	10.60				
Screen Length (feet)	coty	5			
Surface Elevation (MSL	)	na			
Top of Casing Elevation		588.60			
Top of Screen Elevation	(MSL)	583.00			
Bottom of Screen Eleva		578.00			
Bottom of Coroon Elova	Depth to Water from	Water Elevation			
Date	TOC (feet)	(MSL)			
03/22/1999	6.99	581.61			
04/10/2000	8.04	580.56			
03/26/2001	8.14	580.46			
10/25/2001	7.36	581.24			
01/31/2002 A	7.65	580.95			
02/15/2002 E	nm	nm			
02/15/2002 B	nm	nm			
02/15/2002 C	nm	nm			
03/03/2002	7.66	580.94			
06/05/2002	6.91	581.69			
05/15/2003	7.83	580.77			
08/26/2003	7.84	580.76			
11/19/2003	8.46	580.14			
02/25/2004	8.22	580.38			
05/24/2004	7.10	581.50			
11/10/2004	6.87	581.73			
05/18/2005	6.92	581.68			
11/28/2005	7.61	580.99			
05/30/2006	7.25	581.35			
05/16/2007	7.08	581.52			

Well Name	MW	-10
Well Depth from TOC (f	feet)	14.51
Screen Length (feet)	5	
Surface Elevation (MSL	.)	na
Top of Casing Elevation	n (MSL)	588.81
Top of Screen Elevation	n (MSL)	579.30
Bottom of Screen Eleva	ition (MSL)	574.30
	Depth to Water from	Water Elevation
Date	TOC (feet)	(MSL)
03/22/1999	7.22	581.59 *
04/10/2000	8.27	580.54 *
03/26/2001	8.39	580.42 *
10/25/2001	7.66	581.15 *
01/31/2002 A	7.87	580.94 *
02/15/2002 E	7.94	580.87 *
02/15/2002 B	7.97	580.84 *
02/15/2002 C	7.97	580.84 *
03/03/2002	7.89	580.92 *
06/05/2002	7.09	581.72 *
05/15/2003	7.95	580.86 *
08/26/2003	7.96	580.85 *
11/19/2003	8.37	580.44 *
02/25/2004	8.50	580.31 *
05/24/2004	7.31	581.50 *
11/10/2004	6.95	581.86 *
05/18/2005	7.07	581.74 *
11/28/2005	7.68	581.13 *
05/30/2006	7.31	581.5 *
05/16/2007	7.19	581.62 *



Table 3 - Groundwater Elevations Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

Well Name	MW	-11	
Well Depth from TOC (for	eet)	14.64	
Screen Length (feet)	,	5	
Surface Elevation (MSL		na	
Top of Casing Elevation	(MSL)	588.94	
Top of Screen Elevation	(MSL)	579.30	
Bottom of Screen Eleva	tion (MSL)	574.30	
	Depth to Water from	Water Elevation	
Date	TOC (feet)	(MSL)	
03/22/1999	7.34	581.6	*
04/10/2000	8.38	580.56	*
03/26/2001	8.48	580.46	*
10/25/2001	7.70	581.24	*
01/31/2002 A	7.96	580.98	*
02/15/2002 E	nm	nm	
02/15/2002 B	nm	nm	
02/15/2002 C	nm	nm	
03/03/2002	7.94	581.00	*
06/05/2002	8.03	580.91	*
05/15/2003	8.11	580.83	*
08/26/2003	8.08	580.86	*
11/19/2003	8.48	580.46	*
02/25/2004	8.48	580.46	*
05/24/2004	7.39	581.55	*
11/10/2004	7.30	581.64	*
05/18/2005	7.27	581.67	*
11/28/2005	8.34	580.60	*
05/30/2006	Abandoned		

Well Name	Well Name MW-			
Well Depth from TOC (f	eet)	13.60		
Screen Length (feet)	5			
Surface Elevation (MSL	)	na		
Top of Casing Elevation	(MSL)	590.40		
Top of Screen Elevation	(MSL)	581.80		
Bottom of Screen Eleva	tion (MSL)	576.80		
	Depth to Water from	Water Elevation		
Date	TOC (feet)	(MSL)		
03/22/1999	10.35	580.05		
04/10/2000	11.43	578.97		
03/26/2001	11.72	578.68		
10/25/2001	10.63	579.77		
01/31/2002 A	10.51	579.89		
02/15/2002 E	9.87	580.53		
02/15/2002 B	11.25	579.15		
02/15/2002 C	10.91	579.49		
03/03/2002	10.20	580.20		
06/05/2002	8.80	581.60		
05/15/2003	inaccessible (co	overed with asphalt)		
08/26/2003	10.10	580.30		
11/19/2003	11.31	579.09		
02/25/2004	11.51	578.89		
05/24/2004	9.42	580.98		
11/10/2004	9.00	581.4		
05/18/2005	10.39	580.01		
11/28/2005	10.1	580.3		
05/30/2006	nm	nm		
06/20/2006	9.85	580.55		
05/16/2007	10.28	580.12		

Well Name MW-		12D	
Well Depth from TOC (feet)		35.02	
Screen Length (feet)		15	
Surface Elevation (MSL)		na	
Top of Casing Elevation (MSL)		590.62	
Top of Screen Elevation (MSL)		570.60	
Bottom of Screen Elevation (MSL)		555.60	
	Depth to Water from	Water Elevation	
Date	TOC (feet)	(MSL)	ŀ
03/22/1999	10.81	579.81	*
04/10/2000	11.82	578.80	*
03/26/2001	12.10	578.52	*
10/25/2001	10.94	579.68	*
01/31/2002 A	10.79	579.83	*
02/15/2002 E	10.10	580.52	*
02/15/2002 B	11.89	578.73	*
02/15/2002 C	11.40	579.22	*
03/03/2002	10.43	580.19	*
06/05/2002	9.06	581.56	*
05/15/2003	11.26	579.36	*
08/26/2003	10.38	580.24	*
11/19/2003	11.66	578.96	*
02/25/2004	inaccessible, well under melt water		
05/24/2004	9.81	580.81	*
11/10/2004	9.35	581.27	*
05/18/2005	10.74	579.88	*
11/28/2005	10.55	580.07	*
05/30/2006	9.23	581.39	*
05/16/2007	11.60	579.02	*

Well Name MW-13		
Well Depth from TOC (feet)		12.53
Screen Length (feet)		5
Surface Elevation (MSL)		na
Top of Casing Elevation (MSL)		590.93
Top of Screen Elevation (MSL)		583.40
Bottom of Screen Elevation (MSL)		578.40
	Depth to Water from	Water Elevation
Date	TOC (feet)	(MSL)
03/22/1999	10.48	580.45
04/10/2000	11.60	579.33
03/26/2001	11.84	579.09
10/25/2001	10.85	580.08
01/31/2002 A	10.85	580.08
02/15/2002 E	10.33	580.60
02/15/2002 B	10.99	579.94
02/15/2002 C	10.93	580.00
03/03/2002	10.70	580.23
06/05/2002	9.39	581.54
05/15/2003	10.96	579.97
08/26/2003	10.66	580.27
11/19/2003	> 8.53	na
02/25/2004	>8.53	na
05/24/2004	9.74	581.19
11/10/2004	9.60	581.33
05/18/2005	10.51	580.42
11/28/2005	10.46	580.47
05/30/2006	9.53	581.40
05/16/2007	11.45	579.48



Table 3 - Groundwater Elevations Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

USEPA ID# WIN000509949

Well Name	-14					
Well Depth from TOC (fe	eet)	17.57				
Screen Length (feet)	,	5				
Surface Elevation (MSL)	` ,					
Top of Casing Elevation	594.87					
Top of Screen Elevation	(MSL)	582.30				
Bottom of Screen Eleva	tion (MSL)	577.30				
	Depth to Water from	Water Elevation				
Date	TOC (feet)	(MSL)				
03/22/1999	13.69	581.18				
04/10/2000	14.74	580.13				
03/26/2001	14.87	580.00				
10/25/2001	14.06	580.81				
01/31/2002 A,P	14.26	580.61				
02/15/2002 E,P	14.08	580.79				
02/15/2002 B,P	14.26	580.61				
02/15/2002 C,P	14.29	580.58				
03/03/2002 P	14.19	580.68				
06/05/2002 P	nm	nm				
05/15/2003 P	14.50	580.37				
08/26/2003 P	nm	nm				
11/19/2003 P	15.32	579.55				
2/25/2004 P	14.83	580.04				
5/24/2004 P	13.10	581.77				
11/10/2004	nm	nm				
5/18/2005 P	nm	nm				
11/28/2005 P	14.04	580.83				
5/30/2006 P	13.45	581.42				
5/16/2007 P	13.80	581.07				

Well Name	MW-	15T			
Well Depth from TOC (for	eet)	20.0			
Screen Length (feet)		15			
Surface Elevation (MSL)	)	na			
Top of Casing Elevation	(MSL)	586.75			
Top of Screen Elevation	(MSL)	581.75			
Bottom of Screen Eleva	tion (MSL)	566.75			
	Depth to Water from	Water Elevation			
Date	TOC (feet)	(MSL)			
11/19/2003	nm	nm			
02/25/2004	nm	nm			
05/24/2004	nm	nm			
11/10/2004	nm	nm			
05/18/2005	6.73	580.02			
11/28/2005	7.02	579.73			
05/30/2006	6.17	580.58			
5/16/2007	6.57	580.18			

Well Name	-16T					
Well Depth from TOC (for	eet)	17.5				
Screen Length (feet)	15					
Surface Elevation (MSL)	na					
Top of Casing Elevation	(MSL)	586.74				
Top of Screen Elevation	(MSL)	584.24				
Bottom of Screen Eleva	tion (MSL)	569.24				
	Depth to Water from					
Date	TOC (feet)	(MSL)				
11/19/2003	6.89	579.85				
02/25/2004	7.48	579.26				
05/24/2004	4.26	582.48				
11/10/2004	5.93	580.81				
05/18/2005	6.16	580.58				
11/28/2005	11/28/2005 6.08					
05/30/2006	nm	nm				
5/16/2007	5.88	580.86				

Vell Depth from TOC (feet) Screen Length (feet)							
_	15						
_)	na						
Top of Casing Elevation (MSL)							
Top of Screen Elevation (MSL)							
ation (MSL)	570.85						
Depth to Water from							
Date TOC (feet)							
14.09	580.72						
15.24	579.57						
na	na						
10/25/2001 14.54							
14.65	580.16						
14.29	580.52						
14.91	579.90						
14.81	580.00						
inaccessible	due to snow/ice						
13.14	581.67						
14.74	580.07						
14.54	580.27						
15.27	579.54						
15.40	579.41						
13.48	581.33						
13.49	581.32						
14.23	580.58						
14.35	580.46						
13.54	581.27						
14.20	580.61						
	Color						

MW-17T



Well Name

Table 3 - Groundwater Elevations Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

USEPA ID# WIN000509949

Well Name	MW-	18T				
Well Depth from TOC (f	eet)	26.56				
Screen Length (feet)	,	15				
Surface Elevation (MSL	)	na				
Top of Casing Elevation	597.85					
Top of Screen Elevation	(MSL)	586.29				
Bottom of Screen Eleva	tion (MSL)	571.29				
	Depth to Water from	Water Elevation				
Date	TOC (feet)	(MSL)				
03/22/1999	16.28	581.57				
04/10/2000	17.30	580.55				
03/26/2001	17.44	580.41				
10/25/2001	16.66	581.19				
01/31/2002 A	nm	nm				
02/15/2002 E	nm	nm				
02/15/2002 B	nm	nm				
02/15/2002 C	nm	nm				
03/03/2002	16.92	580.93				
06/05/2002	16.08	581.77				
05/15/2003	16.96	580.89				
08/26/2003	17.05	580.80				
11/19/2003	17.47	580.38				
02/25/2004	17.98	579.87				
05/24/2004	16.34	581.51				
11/10/2004	16.13	581.72				
05/18/2005	16.20	581.65				
11/28/2005	16.88	580.97				
05/30/2006	16.50	581.35				
05/16/2007	16.36	581.49				

Well Name	19T					
Well Depth from TOC (f	eet)	40.00				
Screen Length (feet)	,	15				
Surface Elevation (MSL	na					
Top of Casing Elevation	(MSL)	594.50				
Top of Screen Elevation	(MSL)	569.50				
Bottom of Screen Eleva	tion (MSL)	554.50				
	Depth to Water from	Water Elevation				
Date	TOC (feet)	(MSL)				
03/22/1999	13.90	580.60	*			
04/10/2000	15.03	579.47	*			
03/26/2001	15.22	579.28	*			
10/25/2001	14.28	580.22	*			
01/31/2002 A	inaccessible	due to snow/ice				
02/15/2002 E	13.91	580.59	*			
02/15/2002 B	14.74	579.76				
02/15/2002 C	14.58	579.92				
03/03/2002	14.14	580.36				
06/05/2002	12.79	581.71	*			
05/15/2003	14.46	580.04	*			
08/26/2003	14.11	580.39	*			
11/19/2003	14.95	579.55	*			
02/25/2004	14.98	579.52	*			
05/24/2004	12.23	582.27	*			
11/10/2004	nm	nm				
05/18/2005	13.90	580.60	*			
11/28/2005	14.35	580.15	*			
05/30/2006	13.06	581.44	*			
05/16/2007	13.83	580.67	*			

Well Name	20T	٦				
Well Depth from TOC (for	eet)	39.72				
Screen Length (feet)		15				
Surface Elevation (MSL	)	na				
Top of Casing Elevation	596.13					
Top of Screen Elevation	571.41					
Bottom of Screen Eleva	556.41					
	Depth to Water from	Water Elevation				
Date	TOC (feet)	(MSL)				
03/22/1999	14.73	581.40	*			
04/10/2000	15.74	580.39	*			
03/26/2001	15.95	580.18	*			
10/25/2001	15.10	581.03	*			
01/31/2002	nm	nm				
01/31/2002 A	nm	nm				
02/15/2002 E	nm	nm				
02/15/2002 B	nm	nm				
02/15/2002 C	nm	nm				
03/03/2002	15.32	580.81	*			
06/05/2002	14.39	581.74	*			
05/15/2003	15.47	580.66	*			
08/26/2003	15.49	580.64	*			
11/19/2003	15.84	580.29	*			
02/25/2004	15.95	580.18	*			
05/24/2004	14.63	581.50	*			
11/10/2004	14.48	581.65	*			
05/18/2005	14.58	581.55	*			
11/28/2005	15.20	580.93	*			
05/30/2006	20.73	575.4	*			
05/16/2007	14.68	581.45	*			

Well Name	21T	
Well Depth from TOC (f	eet)	40.00
Screen Length (feet)		15
Surface Elevation (MSL	)	na
Top of Casing Elevation	596.99	
Top of Screen Elevation	571.99	
Bottom of Screen Eleva	556.99	
	Depth to Water from	Water Elevation
Date	TOC (feet)	(MSL)
03/22/1999	15.44	581.55 *
04/10/2000	16.48	580.51 *
03/26/2001	16.57	580.42 *
10/25/2001	15.84	581.15 *
01/31/2002	nm	nm
01/31/2002 A	16.10	580.89 *
02/15/2002 E	nm	nm
02/15/2002 B	nm	nm
02/15/2002 C	nm	nm
03/03/2002	16.08	580.91 *
06/05/2002	15.25	581.74 *
05/15/2003	16.22	580.77 *
08/26/2003	16.26	580.73 *
11/19/2003	16.57	580.42 *
02/25/2004	16.68	580.31 *
05/24/2004	15.50	581.49 *
11/10/2004	15.21	581.78 *
05/18/2005	15.31	581.68 *
11/28/2005	13.93	583.06 *
05/30/2006	15.6	581.39 *
05/16/2007	15.33	581.66 *



Table 3 - Groundwater Elevations Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

USEPA ID# WIN000509949

River Staff Gauge										
Top of Gauge (4/13/98)	Elevation (MSL)	585.88								
Top of Gauge (5/24/05)	585.33									
	Depth to Water from	Water Elevation								
Date	TOC (feet)	(MSL)								
04/13/1998	4.70	581.18								
03/22/1999	7.28	578.60								
04/10/2000	8.41	577.47								
03/26/2001 D	8.35	577.53								
10/25/2001	nm	nm								
01/31/2002 E	nm	nm								
01/31/2002 A	nm	nm								
02/15/2002 E	nm	nm								
02/15/2002 B	nm	nm								
02/15/2002 C	nm	nm								
03/03/2002	nm	nm								
06/05/2002	nm	nm								
05/15/2003	nm	nm								
08/26/2003	nm	nm								
11/19/2003	nm	nm								
02/25/2004	nm	nm								
05/24/2004	nm	nm								
11/10/2004	nm	nm								
05/24/2005	6.72	578.61								
11/28/2005	7.34	577.99								
05/30/2006	6.83	578.50								
06/20/2006	7.19	578.14								
05/16/2007	7.05	578.28								

Well Name	PW	V-1			
Well Depth from TOC (f	eet)	35.00			
Screen Length (feet)	,	15			
Surface Elevation (MSL	na				
Top of Casing Elevation	590.40				
Top of Screen Elevation	570.40				
Bottom of Screen Eleva	tion (MSL)	555.40			
	Depth to Water from	Water Elevation			
Date	TOC (feet)	(MSL)			
04/13/1998	15.05	575.35	*		
03/22/1999	15.00	575.40	*		
04/10/2000	16.76	573.64	*		
03/26/2001	19.38	571.02	*		
10/25/2001	16.41	573.99	*		
01/31/2002 E	10.21	580.19	*		
01/31/2002 A	14.05	576.35	*		
02/15/2002 E	9.90	580.50	*		
02/15/2002 B	26.93	563.47			
02/15/2002 C	19.52	570.88	*		
03/03/2002 E	10.19	580.21	*		
06/05/2002	18.52	571.88	*		
05/15/2003	inaccessible (co	overed with asphalt)			
08/26/2003	inaccessible (co	overed with asphalt)			
11/19/2003 F	18.25	572.15	*		
02/25/2004	20.81	569.59			
05/24/2004	16.25	574.15	*		
11/10/2004	nm	nm			
05/18/2005	nm	nm			
11/28/2005	13.54	576.86	*		
5/30/2006 E	9.04	581.36	*		
05/16/2007	16.32	574.08	*		

[JTB/AAS 06/25/02][U-JTB/C-PAR 7/03][U-JKY/C-JTB-5/04][U-HMS/JAH 050711][HMS/RJG 6/06][HMS/RJG 6/07]

#### Notes:

1) Well construction and pre-2002 water level data collected from Horizon Environmental reports.

A: Pump operating at 5 GPM

**B:** Pump operating at 27.5 GPM

C: Pump operating at 15.5 GPM

**D**: River was covered with 6-12 inches of ice.

E: Pump off or suspected to be off

F: Pump operating at 11 GPM

G: Bailer had to be removed to obtain water level

P: Product (DNAPL) present in well

TOC: top of well casing TOG: top of staff gauge

\*: Water elevation above top of screen.

MSL: mean sea level na: not available nm: not measured

TBS: To be surveyed in June 2007 bases on new top of casing elevation



### Table 4 - Sampling and Analysis Plan Summary Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 North Tenth Street, Manitowoc, Wisconsin

USEPA WIN000509949 / BRRTS # 02-36-000219

Sample Type/Location	Proposed Number of Sampling Locations	Matrix / Laboratory	Parameter	Method	Estimated Sample Quantity	Field Duplicates <sup>2</sup>	Equipment Blanks <sup>3</sup>	MS/MSD <sup>4</sup>	TOTAL	Container Type	Minimum Volume	Preservation (Cool to 4° ≥ 2°C All Samples)	Holding Time from Sample Date
			·		UPLAN	ID .			·				
Surface Soil	14	soil	PVOCs	8021or 8260B	14	1	0	1	16	glass vial	2 oz.	methanol	7/28 days
(Human health risk	(1 sample per	fixed or	PAHs	8270C or 8270-SIM	14	1	0	1	16	amber glass	4 oz.		14/40 days
assessment - 0 to 2 ft bgs	location)	mobile	Lead	6020A	14	1	0	1	16	plastic	5 oz.		6 mo.
and Feasibility Study)		ſ	Vanadium	6020A	14	1	0	1	16	plastic	5 oz.		6 mo.
		fixed	Total Cyanide	9012A	14	1	0	1	16	plastic	5 oz.		14 days
Subsurface Soil	26	soil	PVOCs	8021or 8260B	up to 78	up to 4	0	up to 4	up to 86	glass vial	2 oz.	methanol	7/28 days
(Human health risk	(up to 3	fixed or	PAHs	8270C or 8270-SIM	up to 78	up to 4	0	up to 4	up to 86	amber glass	4 oz.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	14/40 days
assessment and	samples	mobile	Lead	6020A	up to 78	up to 4	0	up to 4	up to 86	plastic	5 oz.		6 mo.
Feasibility Study)	per location)		Vanadium	6020A	up to 78	up to 4	0	up to 4	up to 86	plastic	5 oz.		6 mo.
		fixed	Total Cyanide	9012A	up to 78	up to 4	0	up to 4	up to 86	plastic	5 oz.		14 days
Subsurface Soil	2	soil	Grain Size Distribution	ASTM D421/D422	2	0	0	0	2	5 gal bucket	5 gal		
(Soil Vapor Assessment,	(1 location near	fixed	Moisture Content	ASTM D2216	2	Ö	0	0	2	from 5 gal bucket			
exterior building samples)	each building)		Bulk Density	ASTM D2937	2	0	0	0	2	Undisturbed Sample	Shelby		
			Specific Gravity of Soil Solids	ASTM D854	2	0	0	0	2	from Shelby			
Soil		soil	Protocol B	various	1 Composite	0	0	0	1	glass	26 oz.		varies
(Waste Characterization)		fixed											
Soil Vapor	TBD	soil vapor	BTEX + Naphthalene	TO-15	TBD	TBD	0	0	TBD	≤1-L Summa canister			30 days
(Human health risk	(2 samples per	fixed	Oxygen	ASTM D1946 or EPA 3C	TBD	TBD	0	0	TBD	≤1-L Summa canister			30 days
assessment - Indoor Air	location)		Carbon Dioxide	ASTM D1946 or EPA 3C	TBD	TBD	0	0	TBD	≤1-L Summa canister			30 days
Pathway)	ļ		Methane	ASTM D1946 or EPA 3C	TBD	TBD	0	0	TBD	≤1-L Summa canister			30 days
Groundwater Grab Samples	3	water	PVOCs	8021or 8260B	3	1	0	0	4	glass vial	2-40 ml	HCI to pH<2, Zero Headspace	14 days
(Feasibility Study)	(1 sample per	mobile	PAHs	8270C or 8270-SIM	3	1	0	0	4	amber glass	2 liters		14 days
	location)												
Groundwater - wells 1	26	water	PVOCs	8021or 8260B	26	3	0	2	31	glass vial	2-40 ml	HCI to pH<2, Zero Headspace	14 days
(Risk Assessment, Feasibility		fixed	PAHs	8270C or 8270-SIM	26	3	0	2	31	amber glass	2 liters		14 days
Study, On-going monitoring)	[		Metals <sup>15</sup> (Min. One Round)	6020A	26	3	0	2	31	glass	1 liter	H2SO4 to pH<2	
			Avail. Cyanide (Min. One Round)	OIA-1677	26	3	0	2	31	amber glass	500 ml	PbCO3; NaOH to pH>12	14 days
			Field Parameters <sup>8</sup>	Field	26	0	0	0	26	field measured			
Influent - Treatment System	1	water	VOCs	8260B	2/year	0	0	0	2/year	glass vial	2-40 ml	HCI to pH<2, Zero Headspace	14 days
		fixed	PAHs	8270C or 8270-SIM	2/уеаг	0	0	0	2/year	amber glass	2 liters		14 days
Intermediate (Between Carbon)	1	water	BTEX	8021or 8260B	Bimonthly	0	0	0	Bimonthly	glass vial	2-40 ml	HCl to pH<2, Zero Headspace	14 days
		fixed											
Effluent - Treatment System	1	water	VOCs	8260B	2/уеаг	0	0	0	2/уеаг	glass vial	2-40 ml	HCI to pH<2, Zero Headspace	14 days
		fixed	SVOCs	8270C or 8270-SIM	2/year	0	0	0	2/year	amber glass	2 liters		14 days
			Hq	150.1	2/year	0	0	0	2/year	plastic	250 ml		immediate

### Table 4 - Sampling and Analysis Plan Summary Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site 402 North Tenth Street, Manitowoc, Wisconsin USEPA WIN000509949 / BRRTS # 02-36-000219

Sample	Proposed Number of	Matrix /			Estimated	Field	Equipment			Container	Minimum	Droconyction	Holding Time
Type/Location	Sampling	Laboratory	Parameter	Method	Sample Quantity	Duplicates 2	Blanks 3	MS/MSD ⁴	TOTAL	Container Type	Volume	Preservation (Cool to 4° ≥ 2°C All Samples)	from Sample Date
	Locations				-								Date
						LING STEP I	·						
River Surface Water	9	water	PVOCs	8021or 8260B	9	1	0	1	11	glass vial	2-40 ml	HCI to pH<2, Zero Headspace	14 days
(Human Health and	(1 sample per	fixed	PAHs	8270C or 8270-SIM	9	11	0	11	11	amber glass	2 liters		14 days
Ecological Risk	location)	i  -	Metals <sup>10</sup>	6020A	9		0	1	11	plastic	500 ml	HNO3 to pH <2	28 days
Assessment)		]	Cyanide	OIA-1677	9	11	0	1 1	11	amber glass	500 ml	PbCO3; NaOH to pH>12	14 days
		-	Phenois <sup>12</sup>	8270C	9	1 1	0	1	11	amber glass	1 L		14 days
		-	Total Suspended Solids	160.2	9	11	0	1	11	plastic	250 ml		7 days
DiO-dit			Field Parameters <sup>8</sup>	Field	9	0	0	0	9	field measured			7601
River Sediment (Ecological Risk	TBD	sediment	PVOCs	8021or 8260B	TBD	TBD	TBD	TBD	TBD	glass	2 oz.	methanol	7/28 days
Assessment)	(min. 23)	mobile	34 PAHs <sup>5</sup>	8270C or 8270-SIM	TBD	TBD	TBD	TBD	TBD	amber glass	4 oz.		14/40 days
Assessment)		<b> </b>	Metals <sup>9</sup>	6020A	TBD	TBD	TBD	TBD	TBD	plastic	125 mL		6 months
			Phenols <sup>12</sup>	8270C	TBD	TBD	TBD	TBD	TBD	amber glass	8 oz.		14/40 days
			Percent Solids	Various	TBD	TBD	TBD	TBD	TBD	glass	4 oz.	keep in dark	28 days
		fixed	Cyanide	9012A	23	2	0	0	25	plastic	125 mL		14 days
		ļ <b>L</b>	Black Carbon <sup>6</sup>	Refer to Note 6	23	2	0	0	25	plastic	500 g	keep in dark	28 days
		<u> </u>	TOC	Various	23	22	0	0	25	plastic	100 g	keep in dark	28 days
			Toxicity Testing <sup>1</sup>	Refer to Note 7	23	2	0	0	25	plastic	2L	keep in dark	
			Ammonia	350.1	23	2	0	0	25	plastic	10 g		28 days
			Total Sulfide	9030	23	2	0	0	25	amber glass	25g min	Zero Headspace	7 days
River Sediment	3 cores	sediment	PVOCs	8021or 8260B	3	1	0	0	4	glass	2 oz.	methanol	7/28 days
(Human Health Risk	(1 sample per	mobile L	PAHs	8270C or 8270-SIM	3	111	0	0	4	amber glass	4 oz.		14/40 days
Assessment)	location)		Percent Solids	Various	3	1	0	0	4	glass	4 oz.	keep in dark	28 days
		fixed	TOC	Various	3	11	0	0	4	plastic	100 g	keep in dark	28 days
						LING STEP II							
River Surface Water (if needed)		water	PVOCs	8021or 8260B	TBD	TBD	TBD	TBD	TBD	glass vial	2-40 ml	HCI to pH<2, Zero Headspace	<del></del>
(Human Health and	and	fixed	PAHs	8270C or 8270-SIM	TBD	TBD	TBD	TBD	TBD	amber glass	2 liters		14 days
Ecological Risk	parameters		Metais <sup>10</sup>	6020A	TBD	TBD	TBD	TBD	TBD	plastic	500 ml	HNO3 to pH <2	28 days
Assessment)	as needed		Cyanide	OIA-1677	TBD	TBD	TBD	TBD	TBD	amber glass	500 ml	PbCO3; NaOH to pH>12	14 days
			Phenols <sup>12</sup>	8270C	TBD	TBD	TBD	TBD	TBD	amber glass	1 L		14 days
			Total Suspended Solids	EPA 160.2	TBD	TBD	TBD	TBD	TBD	plastic	250 ml		7 days
			Field Parameters <sup>8</sup>	Field	TBD	TBD	TBD	TBD	TBD	field measured			
River Sediment	32 cores	sediment	COCs <sup>13</sup>	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
(Characterization)		TBD/fixed	TOC	Various	TBD	TBD	TBD	TBD	TBD	plastic	100 g	keep in dark	28 days
			Black Carbon <sup>6</sup>	Refer to Note 6	TBD	TBD	TBD	TBD	TBD	plastic	500 g	keep in dark	28 days
River Sediment	4 cores	sediment	Protocol B	Various	1 Composite	9 0	0	0	TBD	glass	26 oz.		varies
(Waste and Geotechnical	(included in	fixed	Grain Size Distribution	ASTM D421, 422	TBD	0	0	0	TBD	5 gal bucket	5 gal.		
Characterization)	above 32	<u> </u>	Atterberg Limits	ASTM D4318	TBD	0	0	0	TBD	Glass or Plastic	8 oz.		
	cores)		Organic Content	ASTM D2974	TBD	0	0	0	TBD	plastic	100 g	keep in dark	28 days
		L	Specific Gravity	ASTM D854	TBD	0	0	0	TBD	plastic	200 g		
		<u> </u>	Moisture Content	ASTM D2216	TBD	0	0	0	TBD	Glass or Plastic	8 oz.		
			Shear Strength	pocket penetrometer/torvane	TBD	0	0	0	TBD	field measured			
River Sediment	3 cores	sediment	PCB (total)	8082	TBD	0	0	0	TBD	amber glass	250 g		14 days
(NR 347 Parameters)	(included in	fixed	Pesticides <sup>14</sup>	8081A	TBD	0	0	0	TBD	amber glass	250 g		14 days
	above 32		Metals <sup>11</sup>	6020A	TBD	0	0	0	TBD	plastic	100 g		6 months
,	cores)		Oil & Grease	9070	TBD	0	0	0	TBD	amber glass	30 g		28 days
		[	Nitrate+Nitrite	LACHAT 12-107-04-1-B (0.25)	TBD	0	0	0	TBD	plastic	30 g		28 days
		[	Ammonia-Nitrogen	LACHAT 12-107-06-1-A (0.16)	TBD	0	0	0	TBD	plastic	3 g		28 days
	1	{ <b>[</b>	Total Kjeldahl Nitrogen	LACHAT 10-107-06-2-E	TBD	0	0	0	TBD	plastic	3 g		28 days
			Total Phosphorus	365.2 or 365.3	TBD	0	0	0	TBD	plastic	3 g		28 days
		[	Percent Solids	Various	TBD	0	0	0	TBD	glass	4 oz	keep in dark	28 days
	1	i	TOC	Various	TBD	0	0	0	TBD	plastic	100 g	keep in dark	28 days

Table 4 - Sampling and Analysis Plan Summary
Wisconsin Public Service - Former Manitowoc Manufactured Gas Plant Site
402 North Tenth Street, Manitowoc, Wisconsin
USEPA WIN000509949 / BRRTS # 02-36-000219

Sample Proposed Number of Matrix / Type/Location Sampling Laboratory Locations	Parameter Method	Estimated Field Sample Quantity Duplicates <sup>2</sup>	Equipment Blanks <sup>3</sup> MS/MSD <sup>4</sup> TOTAL	Container Minim Type Volum		Holding Time from Sample Date
--	------------------	---	---	-------------------------------	--	-------------------------------------

#### Notes:

- 1. Groundwater monitoring will be quarterly for one year following new well installation including 19 existing wells and up to 7 anticipated new wells.
- 2. Field duplicates will be collected at a frequency of one per group of ten or fewer investigative water samples and one per group of twenty or fewer investigative soil/soil vapor samples.
- 3. Equipment blanks will be collected at a frequency of one per sampling day with non-dedicated sampling equipment.
- 4. Matrix Spike/Matrix Spike Duplicate (MS/MSD) samples will be collected at a frequency of one per group of twenty or fewer investigative samples. Additional volume will be determined per laboratory requirements.
- 5. Includes a list of 34 PAHs, including chain parameters as provided in USEPA Guidance Procedures for the Derivation of Equilibrium Partitioning Sediment Benchmarks (ESBs) for the Protection of Benthic Organisms: PAH Mixtures, 2002 by SW-846 Method 8270C with gas chromatograph/mass spectrometry in selected ion mode of operation.
- 6. Black Carbon ("Soot" Carbon) is the remaining carbon after muffle furnace drying and acid treatment of sediments to remove other forms of carbon. Used to estimate the bioavailable concentration of PAHs in sediment from the "freely-dissolved" chemical in the interstitial water based on USEPA Bioavailability Procedure, 2000, Gustafsson, et al. 1997, and Accardi-Day and Gschwend, 2003.
- 7. The Hyalella (amphipod) 28-day test will be used to evaluate the toxicity of whole sediments. This test will be performed in accordance with USEPA.
- 8. Field parameters include temperature, pH, specific conductivity, oxidation-reduction potential, and dissolved oxygen. Also includes turbidity for surface water samples.
- 9. Metals analyses for Step I sediment sampling include: aluminum, antimony, barium, copper, iron, lead, manganese, nickel, selenium, silver, vanadium, and zinc.
- 10. Metals analyses for Surface Water risk assessment include: aluminum, antimony, arsenic, barium, cadmium, chromium, copper, iron, lead, manganese, mercury, nickel, selenium, silver, vanadium, and zinc.
- 11. Metals analyses for NR 347 include: arsenic, cadmium, chromium, copper, lead, mercury, nickel, selenium and zinc.
- 12. Phenois include 2,4-dimethylphenol, 2-methylphenol, 4-methylphenol and phenol.
- 13. COCs will be determined after interpretation of the results of the Step I risk assessment
- 14. Pesticides for NR 347 include: chlordane, DDT, and DDD & DDE.
- 15. Metals analyses for groundwater monitoring include: aluminum, iron, manganese, and vanadium. If results of first round indicate concentrations below screening values, then parameters will be discontinued.

Acronyms:

PCB = Polychlorinated Biphenyl
TBD = To be determined based on field encountered conditions

BTEX = Benzene, toluene, ethylbenzene, and xylenes

PVOC = Petroleum Volatile Organic Compounds
TOC = Total Organic Carbon
VOC = Volatile Organic Compounds

PAHs = Polynuclear Aromatic Hydrocarbons SVOCs = Semí-volatile organic compounds COCs = Contaminants of concern

# APPENDIX A HISTORICAL STRUCTURES MAPS

# APPENDIX A1 SANBORN MAPS



"Linking Technology with Tradition"®

#### Sanborn® Map Report

Ship To: Brian Hennings Order Date: 1/9/2007 Completion Date: 1/10/2007

Natural Resource Inquiry #: 1831689.3s

23713 W. Paul Road **P.O. #:** NA

Pewaukee, WI 53072 Site Name: Former Wisconsin Fuel and Light

Address: North 11th Street/Chicago Street

Customer Project: 1530 City/State: Manitowoc, WI 54220

1017571CAR 262-523-9000 **Cross Streets:** 

Based on client-supplied information, fire insurance maps for the following years were identified

1883 - 2 Maps 1946 - 3 Maps 1887 - 2 Maps 1956 - 3 Maps 1894 - 2 Maps 1964 - 3 Maps 1900 - 3 Maps 1966 - 3 Maps

1906 - 2 Maps 1912 - 2 Maps 1919 - 3 Maps 1927 - 3 Maps

Limited Permission to Photocopy

Total Maps: 31

Natural Resource Technology (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the imited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon acquest.

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONSEQUENTIAL THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Ste Assessment performed by an environmental professional can provide nformation regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

#### **USER'S GUIDE**

This User's Guide provides guidelines for accessing Sanborn Map® images and for transferring them to your Word Processor.

#### Reading Sanborn Maps

Sanborn Maps document historical property use by displaying property information through words, abbreviations, and map symbols. The Sanborn Map Key provides information to help interpret the symbols and abbreviations used on Sanborn Maps. The Key is available from EDR's Web Site at: http://www.edrnet.com/reports/samples/key.pdf

#### Organization of Electronic Sanborn Image File

- Sanborn Map Report, listing years of coverage
- User's Guide
- Oldest Sanborn Map Image
- Most recent Sanborn Map Image

#### Navigating the Electronic Sanborn Image File

- 1. Open file on screen.
- 2. Identify TP (Target Property) on the most recent map.
- 3. Find TP on older printed images.
- 4. Using Acrobat® Reader®, zoom to 250% in order to view more clearly. (200-250% is the approximate equivalent scale of hardcopy Sanborn Maps.)
  - A. On the menu bar, click "View" and then "Zoom to..."
  - B. Or, use the magnifying tool and drag a box around the TP

#### Printing a Sanborn Map From the Electonic File

- EDR recommends printing images at 300 dpi (300 dpi prints faster than 600 dpi)
- To print only the TP area, cut and paste from Acrobat to your word processor application.

#### Acrobat Versions 6 and 7


- 1. Go to the menu bar
- 2. Click the "Select Tool"
- 3. Draw a box around the area selected
- 4. "Right click" on your mouse
- 5. Select "Copy Image to Clipboard"
- 6. Go to Word Processor such as Microsoft Word, paste and print.

#### **Acrobat Version 5**

- 1. Go to the menu bar
- 2. Click the "Graphics Select Tool"
- 3. Draw a box around the area selected
- 4. Go to "Menu"
- 5. Highlight "Edit"
- 6. Highlight "Copy"
- 7. Go to Word Processor such as Microsoft Word, paste and print.


#### Important Information about Email Delivery of Electronic Sanborn Map Images


- Images are grouped intro one file, up to 2MB.
- In cases where in excess of 6-7 map years are available, the file size typically exceeds 2MB. In these cases, you will receive multiple files, labeled as "1 of 3", "2 of 3", etc. including all available map years.
- Due to file size limitations, certain ISPs, including AOL, may occasionally delay or decline to deliver files. Please contact your ISP to identify their specific file size limitations.





















































The Sanborn Library, LLC

Reproduction in whole or in part of any map of The Sanborn Library, LLC may be prohibited without prior written permission from The Sanborn Library, LLC.











The Sanborn Library, LLC

Year EDR Research Associate
Reproduction in whole on in past of any map of The Sanborn Library, U.C. may be profiled without prior written permaken from The Sanborn Library, U.C.












The Sanborn Library, LLC


Copyrightio 1946 The Sanborn Library, LLC HNS


COR PASSACTION IN THE SANDON LIBRARY, LLC OR PROSECULATION OF THE SANDON LIBRARY LLC OR PROSECULATION OF THE SANDON LIBR













The Sanborn Library, LLC





Copyrightio\_1964 The Sunborn Library, LLC MNS


EDR Research Associate

Flagoridation in which or in part of any map of the Sunborn Library, LLC may be prohibited without prior written









The Sanborn Library, LLC

Copyright 1966


Year

The Sanborn Library, LLC


HNS

COR Research Associate

Reproduction in whole or in good of any road of The Sanborn Library, LLC may be prohibbled without prior written



# APPENDIX A2 HISTORICAL PLANT DRAWINGS



## **APPENDIX B**

# EDR INFORMATION AND OTHER SITE VICINITY INFORMATION

# APPENDIX B1 EDR RADIUS MAP AND REPORT



# The EDR Radius Map with GeoCheck®

Former Wisconsin Fuel and Light North 11th Street/Chicago Street Manitowoc, WI 54220

Inquiry Number: 1831689.2s

**January 10, 2007** 


# The Standard in Environmental Risk Management Information

440 Wheelers Farms Road Milford, Connecticut 06461

#### **Nationwide Customer Service**

Telephone: 1-800-352-0050 Fax: 1-800-231-6802 Internet: www.edrnet.com

## **DETAIL MAP - 1831689.2s**



SITE NAME: Former Wisconsin Fuel and Light ADDRESS: North 11th Street/Chicago Street Manitowoc WI 54220 44.0957 / 87.6613

CLIENT: Natural Resource Technology CONTACT: Brian Hennings

default map view.

INQUIRY #: 1831689.2s DATE: January 10, 2007 11:43 am

Copyright © 2007 EDR, Inc. © 2007 Tele Atlas Rei. 07/2006

#### **TABLE OF CONTENTS**

SECTION	PAGE
Executive Summary	. ES1
Overview Map.	. 2
Detail Map	. 3
Map Findings Summary	_ 4
Map Findings	_ 6
Orphan Summary	. 264
EPA Waste Codes	EPA-1
Government Records Searched/Data Currency Tracking	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum.	<b>A-1</b>
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	. <b>A-</b> 5
Physical Setting Source Map.	_ <b>A-11</b>
Physical Setting Source Map Findings	A-12
Physical Setting Source Records Searched	<b>A</b> -44

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

#### **Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2007 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

#### TARGET PROPERTY INFORMATION

#### **ADDRESS**

NORTH 11TH STREET/CHICAGO STREET MANITOWOC, WI 54220

#### **COORDINATES**

Latitude (North):

44.095700 - 44° 5' 44.5"

Longitude (West):

87.661300 - 87° 39' 40.7"

Universal Tranverse Mercator: Zone 16 UTM X (Meters):

447064.6 4882498.5

UTM Y (Meters): Elevation:

597 ft. above sea level

#### USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:

44087-A6 MANITOWOC, WI

Most Recent Revision: 1973

#### TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 6 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
WISCONSIN FUEL AND LIGHT CO (WPCS 402 N. TENTH ST. MANITOWOC, WI 54220	Manufactured Gas Plants	N/A
WPSC MANITOWOC MGP 402 N 10TH ST. MANITOWOC, WI 54220	CERCLIS	WIN000509949
WIFUEL AND LIGHT 10TH ST / CHICAGO MANITOWOC, WI	WI WRRSER	N/A
WISCONSIN FUEL AND LIGHT CO 402 N 10TH ST MANITOWOC, WI 54220	RCRA-SQG FINDS WI Spills WI ERP BROWNFIELDS BRRTS SHWIMS	WID007946510

#### **DATABASES WITH NO MAPPED SITES**

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

#### **FEDERAL RECORDS**

NPL...... National Priority List

ERNS..... Emergency Response Notification System

HMIRS..... Hazardous Materials Information Reporting System

CONSENT...... Superfund (CERCLA) Consent Decrees

TRIS..... Toxic Chemical Release Inventory System

TSCA...... Toxic Substances Control Act

FTTS\_\_\_\_\_\_FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, &

Rodenticide Act)/TSCA (Toxic Substances Control Act)

SSTS..... Section 7 Tracking Systems

ICIS\_\_\_\_\_Integrated Compliance Information System

PADS PCB Activity Database System

MLTS Material Licensing Tracking System

MINES..... Mines Master Index File

RAATS...... RCRA Administrative Action Tracking System

#### STATE AND LOCAL RECORDS

DRYCLEANERS\_\_\_\_\_ Five Star Recognition Program Sites

BEAP..... Brownfields Environmental Assessment Program

AIRS\_\_\_\_\_\_\_ Air Permit Program Listing
TIER 2\_\_\_\_\_\_ Tier 2 Facility Listing
LEAD\_\_\_\_\_\_ Lead Inspection Data

TRIBAL RECORDS

INDIAN RESERV..... Indian Reservations

INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land INDIAN UST..... Underground Storage Tanks on Indian Land

#### SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property. Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in **bold italics** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

#### **FEDERAL RECORDS**

**CERCLIS-NFRAP:** Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

A review of the CERC-NFRAP list, as provided by EDR, and dated 10/10/2006 has revealed that there is 1 CERC-NFRAP site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
RED ARROW PRODUCTS CO LLC	1226 SO WATER STREET	1/4 - 1/2SSW	′ <i>54</i>	118

RCRAInfo: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act ( RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System(RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month Large quantity generators generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/13/2006 has revealed that there are 13 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
JAEGER BAKERY	308 N 10TH ST	0 - 1/8 SSE	B9	26
MANITOWOC PLUMBING SUPPLY	924 YORK ST	1/8 - 1/4SE	E25	68
KWIK TRIP INC 637	401 N 8TH ST	1/8 - 1/4 E	F28	<i>79</i>

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
JACKSON WALTER L ESTATE	821 BUFFALO ST	1/8 - 1/4 ESE	G30	80
WISCONSIN BELL INC PN0506	820 BUFFALO ST	1/8 - 1/4 ESE	G33	84
DRAMM CORP	200 N 19TH ST	1/8 - 1/4SE	34	84
FIRST LUTHERAN CHURCH	521 N 8TH ST	1/8 - 1/4 NE	146	102
MOBIL ONE STOP	620 N WATER ST	1/8 - 1/4N	K52	111
Lower Elevation	Address	Dist / Dir	Map ID	Page
HOLMES OIL	1110 BUFFALO ST	0 - 1/8 SSW	C13	<i>37</i>
COLORCRAFT GRAPHIC ARTS INC	211 N 10TH ST	1/8 - 1/4SSE	D17	<i>57</i>
QUICK LUBE	204 N 10TH ST	1/8 - 1/4SSE	D21	63
RBA INC	300 S 16TH ST	1/8 - 1/4 NNW	44	101
WISCONSIN MARITIME MUSEUM INC	75 MARITIME DR	1/8 - 1/4SSE	49	106

#### STATE AND LOCAL RECORDS

**WI ERP:** Emergency Repair Program Database. Non - LUST Sites with Contaminated Soil and/or GW. Often these are historic releases to the environment.

A review of the WI ERP list, as provided by EDR, and dated 09/30/2006 has revealed that there are 12 WI ERP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
WCL	SW CORNER 11TH ST / B	0 - 1/8 SE	B6	18
FIRST PRESBYTERIAN CHURCH	502 N 8TH ST	1/8 - 1/4 ENE	141	98
MOBIL ONE-STOP	620 N WATER ST	1/4 - 1/2N	<i>53</i>	111
PROFESSIONAL ARTS BLDG	605 YORK ST	1/4 - 1/2 ESE	L57	135
THOR AUTO BODY	603 YORK ST	1/4 - 1/2 ESE	L59	144
RUZEKS STANDARD SERVICE	732 N 11TH ST	1/4 - 1/2 N	<i>62</i>	169
MIRRO CO PLT 1	1616 WOLLMER, P O BOX 1	1/4 - 1/2 WSV	/ 67	206
FIRESTONE BLDG (FORMER)	1011 WASHINGTON ST	1/4 - 1/28	72	242
Lower Elevation	Address	Dist / Dir	Map ID	Page
WCL	200 N 10TH ST	1/8 - 1/4SSE	D22	64
RIDGE MOTOR SUPPLY CO	1011 FRANKLIN ST	1/4 - 1/2S	61	163
MANITOWOC ENGINEERING CO	500 S 16TH ST	1/4 - 1/2 W	<i>63</i>	181
WCI COMMERCIAL REFRIGERATION	621 QUAY ST	1/4 - 1/2SE	69	223

**WI WDS:** The Registry was created by the DNR to serve as a comprehensive listing of all sites where solid or hazardous wastes have been or may have been deposited.

A review of the WI WDS list, as provided by EDR, and dated 11/01/2000 has revealed that there is 1 WI WDS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
WIS ALUMINUM FOUNDRY	838 S 16TH ST	1/4 - 1/2SW	O74	246

**LUST:** The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Natural Resource's LUST Database.

A review of the LUST list, as provided by EDR, and dated 09/30/2006 has revealed that there are 26 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
JAEGER BAKERY Facility Status: CLOSED	308 N 10TH ST	0 - 1/8 SSE	B9	26
Not reported Facility Status: CLOSED	401 N 8TH ST	1/8 - 1/4E	F27	71
DICK BROTHERS BAKERY Facility Status: CLOSED	306 N 8TH ST	1/8 - 1/4ESE	G38	91
ASSOCIATED BANK (FORMER) Facility Status: CLOSED	204 N 8TH ST	1/8 - 1/4SE	J47	104
MOBIL ONE-STOP Facility Status: CLOSED	620 N WATER ST	1/4 - 1/2 <b>N</b>	53	111
VALLESKEY MARITAL TRUST Facility Status: CLOSED	1310 CLARK ST	1/4 - 1/2SW	M58	140
SCHLEIS AUTO ELECTRIC Facility Status: CLOSED Facility Status: CLOSED	803 S 14TH ST	1/4 - 1/2SW	M60	152
RUZEKS STANDARD SERVICE Facility Status: CLOSED	732 N 11TH ST	1/4 - 1/2 <b>N</b>	62	169
STEFFEN'S CITY SALES & SERVICE Facility Status: CLOSED	1317 FRANKLIN ST	1/4 - 1/2SSW	66	204
TOM'S STANDARD SERVICE Facility Status: CLOSED	734 N 8TH ST	1/4 - 1/2 <b>NN</b> E	68	219
SWETLIK SHELL Facility Status: CLOSED	802 N 11TH	1/4 - 1/2N	71	241
BOELTER'S JEWELERS Facility Status: CLOSED	1106 WASHINGTON ST	1/4 - 1/2S	73	244
WISCONSIN ALUMINUM FOUNDRY Facility Status: CLOSED	838 S 16TH ST	1/4 - 1/2SW	<i>075</i>	247
LLOYDS PHOTO & VIDEO Facility Status: CLOSED	1201 WASHINGTON ST	1/4 - 1/2SSW	76	<i>252</i>
QUALITY Q-MART Facility Status: CLOSED	802 HURON AVE	1/4 - 1/2NNE	77	259
Lower Elevation	Address	Dist / Dir	Map ID	Page
HOLMES OIL CORP Facility Status: CLOSED	1110 BUFFALO ST	0 - 1/8 SSW	C12	31
COLOR CRAFT GRAPHIC ARTS INC Facility Status: CLOSED	211 N 10TH ST	1/8 - 1/4SSE	D19	<i>58</i>
BADGER CYCLE Facility Status: CLOSED	109 N 10TH ST	1/8 - 1/4SSE	H36	85
Not reported Facility Status: CLOSED	17 MARITIME DR	1/8 - 1/4 SSE	H39	93

Lower Elevation	Address	Dist / Dir	Map ID	Page
WATERFORD PLACE Facility Status: CLOSED	N SIDE MARITIME DR BETW	1/4 - 1/2SE	55	127
PIETROSKE BODY SHOP Facility Status: CLOSED	901 QUAY	1/4 - 1/2SSE	56	128
RIDGE MOTOR SUPPLY CO Facility Status: CLOSED	1011 FRANKLIN ST	1/4 - 1/2S	61	163
MANITOWOC ENGINEERING CO Facility Status: CLOSED	500 S 16TH ST	1/4 - 1/2 W	63	181
PIETROSKE PROPERTY Facility Status: CLOSED	822 FRANKLIN ST	1/4 - 1/2 SSE	N64	196
MANITOWOC SAFETY BLDG Facility Status: CLOSED Facility Status: CLOSED	817 FRANKLIN ST	1/4 - 1/2SSE	N65	198
MANITOWOC MARINA SAILBOATS INC Facility Status: CLOSED	425 MARITIME DR	1/4 - 1/2 E	70	232

**UST:** The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Commerces' List: All Underground Storage Tanks Except for Fuel Oil.

A review of the UST list, as provided by EDR, and dated 10/06/2006 has revealed that there are 23 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
Not reported	402 N 10TH ST	0 - 1/8 ESE	5	17
Not reported	950 CHICAGO ST	0 - 1/8 ESE	7	23
Not reported	315 N 10TH ST	0 - 1/8 SSE	B8	24
Not reported	306 N 10TH ST	0 - 1/8 SSE	10	29
Not reported	533 N 10TH ST	1/8 - 1/4 NNE	23	66
Not reported	924 YORK ST	1/8 - 1/4SE	E26	70
Not reported	401 N 8TH ST	1/8 - 1/4 E	F27	71
Not reported	821 BUFFALO ST	1/8 - 1/4 ESE	G29	80
Not reported	820 BUFFALO ST	1/8 - 1/4 ESE	G32	83
Not reported	306 N 8TH ST	1/8 - 1/4 ESE	G37	90
Not reported	822 YORK	1/8 - 1/4SE	J42	99
Not reported	521 N 8TH ST	1/8 - 1/4NE	145	101
Not reported	205 N 8TH ST	1/8 - 1/4SE	J48	106
Not reported	612 N WATER ST	1/8 - 1/4N	K50	107
Not reported	620 N WATER ST	1/8 - 1/4N	K51	109
Lower Elevation	Address	Dist / Dir	Map ID	Page
Not reported	1110 BUFFALO ST	0 - 1/8 SSW	C11	30
Not reported	1114 BUFFALO ST	0 - 1/8 SW	C15	49
Not reported	211 N 10TH ST	1/8 - 1/4SSE	D18	58
Not reported	204 N 10TH ST	1/8 - 1/4SSE	D20	60
Not reported	204 N 10TH ST	1/8 - 1/4SSE	D24	68
Not reported	109 N 10TH	1/8 - 1/4SSE	H35	85
Not reported	17 MARITIME DR	1/8 - 1/4SSE	H39	93
Not reported	50 MARITIME DR	1/8 - 1/4SSE	43	100

LAST: A listing of leaking aboveground storage tank sites.

A review of the LAST list, as provided by EDR, and dated 10/02/2006 has revealed that there is 1 LAST site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
HOLMES OIL CORP	1110 BUFFALO ST	0 - 1/8 SSV	/ C12	31

AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Industry, Labor & Human Resources' List: All Aboveground Storage Tanks Except for Fuel Oil.

A review of the AST list, as provided by EDR, and dated 10/06/2006 has revealed that there are 4 AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir Map I	D Page
Not reported	820 BUFFALO ST	1/8 - 1/4 ESE G31	81
Lower Elevation	Address	Dist / Dir Map I	D Page
Not reported Not reported Not reported	1114 BUFFALO ST 1115 BUFFALO ST 17 MARITIME DR	0 - 1/8 SW C14 0 - 1/8 SW C16 1/8 - 1/4SSE H40	38 51 97

**AUL:** Date a deed restriction is recorded at the Register of Deeds office for a property. Extent of soil contamination is known but impracticable to remove now or an engineering control is required to be maintained or NR720 industrial stds are applied. Restricts property use or requires future actions.

A review of the AUL list, as provided by EDR, and dated 09/30/2006 has revealed that there are 16 AUL sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
WCL	SW CORNER 11TH ST / B	0 - 1/8 SE	B6	18
MOBIL ONE-STOP	620 N WATER ST	1/4 - 1/2N	53	111
PROFESSIONAL ARTS BLDG	605 YORK ST	1/4 - 1/2ESE	L57	135
VALLESKEY MARITAL TRUST	1310 CLARK ST	1/4 - 1/2SW	M58	140
THOR AUTO BODY	603 YORK ST	1/4 - 1/2ESE	L59	144
SCHLEIS AUTO ELECTRIC	803 S 14TH ST	1/4 - 1/2SW	M60	152
RUZEKS STANDARD SERVICE	732 N 11TH ST	1/4 - 1/2N	62	169
MIRRO CO PLT 1	1616 WOLLMER, P O BOX 1	1/4 - 1/2 WSW	67	206
LLOYDS PHOTO & VIDEO	1201 WASHINGTON ST	1/4 - 1/2SSW	<i>76</i>	252
QUALITY Q-MART	802 HURON AVE	1/4 - 1/2NNE	77	259
Lower Elevation	Address	Dist / Dir	Map ID	Page
HOLMES OIL CORP	1110 BUFFALO ST	0 - 1/8 SSW	C12	31
BADGER CYCLE	109 N 10TH ST	1/8 - 1/4SSE	H36	85
Not reported	17 MARITIME DR	1/8 - 1/4SSE	H39	93
PIETROSKE BODY SHOP	901 QUAY	1/4 - 1/2SSE	<i>56</i>	128
MANITOWOC SAFETY BLDG	817 FRANKLIN ST	1/4 - 1/2SSE	N65	198
WCI COMMERCIAL REFRIGERATION	621 QUAY ST	1/4 - 1/2SE	69	223

**VCP:** The Voluntary Party Liability Exemption is an elective environmental cleanup program. Interested persons who meet the definition of "voluntary party" are eligib le to apply. A "voluntary party" is any person who submits an application and pays all the necessary fees.

A review of the VCP list, as provided by EDR, and dated 09/30/2006 has revealed that there are 2 VCP sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
RIDGE MOTOR SUPPLY CO	1011 FRANKLIN ST	1/4 - 1/2 S	61	163
MANITOWOC ENGINEERING CO	500 S 16TH ST	1/4 - 1/2 W	63	181

**BROWNFIELDS:** A listing of brownfields sites included in the BRRTS database. Brownfields are abandoned, idle or underused commercial or industrial properties, where the expansion or redevelopment is hindered by real or perceived contamination. Brownfields vary in size, location, age, and past use -- they can be anything from a five-hundred acre automobile assembly plant to a small, abandoned corner gas station.

A review of the BROWNFIELDS list, as provided by EDR, and dated 09/30/2006 has revealed that there is 1 BROWNFIELDS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
MANITOWOC ENGINEERING CO	500 S 16TH ST	1/4 - 1/2 W	63	181

Due to poor or inadequate address information, the following sites were not mapped:

Site Name

Database(s)

MANITOWOC PUBLIC UTILITIES

CITY OF MANITOWOC (OLD BOAT RAMP) MANITOWOC BOAT RAMP MANITOWOC RAPIDS TN SPRINGER PROPERTY

TUNE UP SHOP

DEAN BRENNAN TRANSPORT INC

1500 HWY 310

7416 COUNTY HWY CR

1500 HWY 310

CANADIAN NATIONAL RR

WI MARITIME MUSEUM (FORMER SMALLEY MFG)

WANEK BROTHERS CONST CO

LAKEVIEW PROPERTY

MANITOWOC B GROUNDWATER

MANITOWOC CTY LF (OLD BOAT RAMP)\*

SHWS SHWS

CERC-NFRAP SWF/LF, SHWIMS

LUST

RCRA-SQG, FINDS, LUST,

SHWIMS

LUST, SHWIMS

UST UST AST

WI Spills, WI ERP

WI ERP, BROWNFIELDS,

BRRTS, SHWIMS WI ERP, SHWIMS

WI ERP

WI ERP, SHWIMS

## **MAP FINDINGS SUMMARY**

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FEDERAL RECORDS								
NPL Proposed NPL Delisted NPL NPL RECOVERY CERCLIS CERC-NFRAP CORRACTS RCRA TSD RCRA Lg. Quan. Gen. RCRA Sm. Quan. Gen. ERNS HMIRS US ENG CONTROLS US INST CONTROL DOD FUDS US BROWNFIELDS CONSENT ROD UMTRA ODI TRIS TSCA FTTS SSTS ICIS PADS	x x	1.000 1.000 1.000 TP 0.500 0.500 1.000 0.500 0.250 TP TP 0.500 0.500 1.000 1.000 1.000 0.500 1.000 TP TP TP TP TP TP	0 0 0 R 0 0 0 0 0 2 R R 0 0 0 0 0 0 0 0	000R00001RR000000000RRRRRRRRR	000R0100RRRR000000000RRRRRRRR	000000000000000000000000000000000000000	N N N N N N N N N N N N N N N N N N N	0 0 0 0 0 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0
MLTS MINES FINDS RAATS	х	TP 0.250 TP TP	NR 0 NR NR	NR 0 NR NR	NR NR NR NR	NR NR NR NR	NR NR NR NR	0 0 0 0
STATE AND LOCAL RECO	RDS							
State Haz. Waste BRRTS WI ERP State Landfill WI WDS LUST UST LAST AST MANIFEST WI Spills AGSPILLS CRS AUL	X X	1.000 TP 0.500 0.500 0.500 0.500 0.250 0.250 0.250 TP TP TP TP 0.500	0 NR 1 0 2 6 1 2 0 NR NR NR 2	0 NR 2 0 0 6 17 0 2 0 NR NR NR NR 2	0 NR 9 0 1 18 NR 0 NR NR NR NR NR	O NR NR NR NR NR NR NR NR NR NR NR	NR NR NR NR NR NR NR NR NR NR	0 0 12 0 1 26 23 1 4 0 0 0

# MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
VCP DRYCLEANERS WI WRRSER BEAP BROWNFIELDS AIRS TIER 2 LEAD SHWIMS	x x	0.500 0.250 TP 0.500 0.500 TP TP TP TP	0 NR 0 0 NR NR NR	O O NR O O NR NR NR NR	2 NR NR 0 1 NR NR NR	NR NR NR NR NR NR NR NR	NR NR NR NR NR NR NR NR	2 0 0 1 0 0 0
TRIBAL RECORDS								
INDIAN RESERV INDIAN LUST INDIAN UST		1.000 0.500 0.250	0 0 0	0 0 0	0 0 NR	0 NR NR	NR NR NR	0 0 0
EDR PROPRIETARY RECORD	<u>s</u>							
Manufactured Gas Plants	X	1.000	0	0	0	0	NR	0

#### NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

# APPENDIX B2 EDR REPORT EXCERPTS FOR SITES B6, B9 AND C12

MAP FINDINGS Map ID

Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number** 

#### 1000180010 (Continued)

Tank Market: No Federally Regulated: Yes Facility ID: 146559 Facility county code: 36 Site Municipality С Municipality Name: MANITOWO Fire Dept ID: Manitowoo 382987

Town Cust ID: Land Owner Type: Owner Name:

Private WISCONSIN FUEL & LIGHT CO 402 N 10TH ST

Owner Address Owner PO Box:

Not reported MANITOWOC, WI 54220

Building Address: Building City, St, Zip:

402 N 10TH ST MANITOWOC 54220

**B6** SE < 1/8

381 ft.

SW CORNER 11TH ST / BUFFALO ST

MANITOWOC, WI 0

Site 1 of 3 in cluster B

Relative: Higher

WI ERP:

Actual: 601 ft.

6638000 Site Id: Detail Seq No: 176478 Activity Type: **ERP** 

**Activity Name:** W C L - TURNTABLE FORMER ROUNDHOUSE

**Activity Number:** 0236176478 Activity Display Number: 02-36-176478 Activity Detail Address: NONE **NORTHEAST** Region Name: Faclity ID: NONE Start Date: 11/10/1997 End Date: 00/00/0000 07/27/2006 Last Action: Status Cd: CC

Status: CONDITIONALLY CLOSED

DNR-RR Jurisdiction: Act Code: 330 Owner Name: Not reported

Owner Addr: Not reported Owner City, St, Zip: Not reported Dept Of Commerce Number: NONE Comm Occurrence Id: NONE EPA Cerclis Id: NONE Risk Code: N/A Acres: .5 Acres 100: Ν EPA NPL Site?: No Dept Of Commerce Tracking: No No No

PECFA Funds Eligible ?: Above Ground Storage Tank?: Drycleaner?: No Co-contamination?: No

Public Land Survey System Desc: NE 1/4 of the NE 1/4 of Sec 30, T19N, R24E

Geo Located: NE DNR GIS Registry View Map Layers: N

TC1831689.2s Page 18

WCL

Owner Qity,St,Zip: Building Name:

WISCONSIN FUEL & LIGHT CO

WI ERP AUL

S105164673 N/A

Map ID MAP FINDINGS
Direction

Distance
Distance (ft.)
Elevation Site
Database(s)

WCL (Continued) S105164673

L (Continued)						
GIS Area Point F	flag: P					
Action Date:	11/10/97	Action Code:	1			
Action Name:	Notification					
Action Date:	11/21/97	Action Code:	2			
Action Name:	RP Letter Sent					
Action Date:	04/27/04	Action Code:	99			
Action Name:	Miscellaneous/3					
Action Date:	06/07/05	Action Code:	50			
Action Name:	GIS Registry Required					
Action Date:	07/07/04	Action Code:	43			
Action Name:	Status Report Received/4					
Action Date:	05/24/04	Action Code:	43			
Action Name:	Status Report Received/3					
Action Date:	02/24/03	Action Code:	99			
Action Name:	Miscellaneous/2					
Action Date:	10/19/04	Action Code:	43			
Action Name:	Status Report Received/6					
Action Date:	09/27/04	Action Code:	43			
Action Name:	Status Report Received/5					
Action Date:	06/02/03	Action Code:	37			
Action Name:	SI Report Received (w/out Fee)					
Action Date:	06/19/03	Action Code:	30			
Action Name:	Site Investigation Workplan Go Ahea					
Action Date:	03/10/03	Action Code:	43			
Action Name:	Status Report Received/2					
Action Date:	05/29/02	Action Code:	99			
Action Name:	Miscellaneous					
Action Date:	06/18/02	Action Code:	43			
Action Name:	Status Report Received					
Action Date:	07/28/05	Action Code:	80			
Action Name:	Closure Not Approved					
Action Date:	09/26/05	Action Code:	43			
Action Name: Action Date:	Status Report Received/7	Askar O. d.	70			
Action Date:	06/07/05	Action Code:	79			
Action Name: Action Date:	Closure Review Request Received v 06/07/05		740			
Action Date:		Action Code:	710			
Action Date:	Date Soil Registry Fee Paid 06/07/05	Astion Code	700			
Action Date:	Date Groundwater Registry Fee Rec	Action Code:	700			
Action Name:	05/15/06	Action Code:	99			
Action Name:	Miscellaneous/4	Action Code.	99			
Action Date:	10/18/99	Action Code:	35			
Action Name:	Site Investigation Workplan Received		33			
Action Desc:	Date Fee received for Closed Remed		o PonietryData Eco			
71011011 2000.	received for Closed Remediation Soi	il Sita RegistryDate clos	e negistrybate ree			
	received for Closed Remediation Soil Site RegistryDate closure not approved letter is sent.Date of letter to RP notifying of legal responsibilities					
	associated with the discovery of contamination. Date the DNR allows the RP to					
	proceed without approval of the SIWP. Either written or by phone call.Date					
	the DNR is notified of the discovery of the contamination.Date the DNR receives					
	the Site Investigation Report. Provid					
	performed to determine degree & ex					
	choosing the appropriate remedial ac					
	Investigation Workplan. States the ol					

proceed without approval of the SIWP. Either written or by phone call.Date the DNR is notified of the discovery of the contamination.Date the DNR receives the Site Investigation Report. Provides information regarding activities performed to determine degree & extent of contamination and forming a basis for choosing the appropriate remedial action.Date the DNR receives the Site Investigation Workplan. States the objectives of the investigation to determine the degree and extent of contamination.Date the closure review request is received and a fee paid for DNR review.Date updates on progress are received. Can be 30, 60, 90 days or other interval.Miscellaneous action. Please see action comments.Upon completing final closure conditions, this case will be

EDR ID Number

EPA ID Number

Map ID MAP FINDINGS
Direction

Distance
Distance (ft.)
Elevation Site

Datahaaa/a

EDR ID Number Database(s) EPA ID Number

WCL (Continued) S105164673

placed on the GIS Registry with groundwater contamination exceeding the NR140

Enforcement Standard and/or soil contamination above the NR720 RCL.

Active Comment: STATUS UPDATE REQUESTEDTRC HIRED AS CONSULTANT, WILL CONTINUE

INVESTIGATIONSTATUS UPDATED REC'D, SENT RFPS SEEKING NEW CONSULTANTWDNR REQUESTS STATUS UPDATESTATUS UPDATE RECEIVED VIA E-MAILTELEPHONE CONVERSATION WITH CONSULTANTSIR - CONSULTANT RECOMMENDS MORE OFF-SITE INVESTIGATIONWILL HAVE

REPORT BY MID- MARCHWDNR REQUEST FOR STATUS UPDATE & CHANGE RPQUARTERLY SAMPLING CONDUCTED IN 5 WELLS-2 MORE WELLS INSTALLED VOC'SAWAITING DEED RESTRICTION RECORDINGCN WORKING ON FUNDING CONTINUED WORK FOR CLOSURE

DETERMINATIONSTATUS UPDATE REQUESTED (TEL CALL)

Active Desc: Not reported Incident Date: Not reported Report Date: Not reported Spill Source: Not reported DNR Investigate: Not reported Spill Cause: Not reported Spill Comments: Not reported Spill Action Code: Not reported Spill Action Desc: Not reported Not reported Spill Action Cmmnts: Substance Desc: Metals Amount Released: Not reported Release Code: Not reported

Substance Desc: Polynuclear Aromatic Hydrocarbons

Amount Released: Not reported Release Code: Not reported

Substance Desc: Volatile Organic Compounds

Amount Released: Not reported Release Code: Not reported Spill Comments: Not reported Impact Number: 176481 Impact Code: 5

Impact Comments: Soil Contamination
Impact Potential: Not reported
Impact Number: 176480
Impact Code: 4

Impact Comments: Groundwater Contamination

Impact Potential: Not reported

Org. Flag: Y

Contact name: SOO LINE RAILROAD

Contact Address: Not reported Contact Addr2: Not reported

Contact City,St,Zip: MINNEAPOLIS, MN 55440

Contact Country: UNITED STATES

Comany Address: MINNEAPOLIS, MN 55440

Role Desc: Responsible Party

Org. Flag: Y

Contact name: CANADIAN NATIONAL RAILWAY PROPERTIES INC

Contact Address: 17641 S ASHLAND AVE

Contact Addr2: Not reported

Contact City,St,Zip: HOMEWOOD, IL 604301345

Contact Country: UNITED STATES
Comany Address: HOMEWOOD, IL 60430
Role Desc: Responsible Party

Org. Flag: N

Contact name: ANNETTE WEISSBACH
Contact Address: 2984 SHAWANO AVE

Map ID MAP FINDINGS

Direction Distance Distance (ft.) Elevation Site

Database(s)

W C L - TURNTABLE FORMER ROUNDHOUSE

6638000

NORTHEAST

02-36-176478

00/00/0000

**DNR-RR** 

CC

No

ΝE

1

2

99

50

43

43

99

43

43

37

Ν

GIS Registry Required

EDR ID Number EPA ID Number

WCL (Continued) S105164673

Site Id:

Region Name:

Activity Name:

Act Name:

End Date:

Status Cd:

Jurisdiction:

Acres 100:

Geo Located:

Action Code:

EPA NPL Site?:

Display Number:

Contact Addr2:

Not reported

Contact City, St, Zip: Contact Country:

GREEN BAY, WI 543070448 **UNITED STATES** 

Comany Address:

GREEN BAY, WI 54307

Role Desc:

Project Manager

AUL:

Facid: Detail Seq No: NONE

176478 50

07/27/2006

Action Code: Action Comments:Not reported

Action Date: 06/07/2005

Activity Type: **ERP** Activity Number: 0236176478

Act Code: 330

Detail Address: NONE Start Date: 11/10/1997

Status: CONDITIONALLY CLOSED Risk Code: N/A Acres: Ν

Drycleaner: No

Last Action:

Owner Name: Owner Addr: Owner City.St.Zip: Dept Of Commerce Number:

NONE Comm Occurrence Id: NONE EPA Cerclis Id: NONE Dept Of Commerce Tracking: Nο PECFA Funds Eligible ?: No Above Ground Storage Tank?: No

Co-contamination?: No Public Land Survey System Desc:

NE 1/4 of the NE 1/4 of Sec 30, T19N, R24E

Not reported

Not reported

Not reported

DNR GIS Registry View Map Layers: N GIS Area Point Flag: Action Date: 11/10/97

Action Name: Notification Action Date: 11/21/97 Action Name: RP Letter Sent Action Date: 04/27/04 Action Name: Miscellaneous/3 Action Date: 06/07/05 Action Name: GIS Registry Required

Action Date: 07/07/04

Action Name: Status Report Received/4 Action Date: 05/24/04

Action Name: Status Report Received/3 Action Date: 02/24/03

Miscellaneous/2 Action Name: Action Date: 10/19/04

Status Report Received/6 Action Name:

Action Date: 09/27/04 Action Name:

Status Report Received/5 Action Date: 06/02/03

Action Name: SI Report Received (w/out Fee)

Action Date: 06/19/03 Action Name: Site Investigation Workplan Go Ahead (notice to proceed)

Action Date: 03/10/03 Action Code:

Action Code:

Action Code:

30

43

Map ID Direction Distance Distance (ft.) Site Elevation

#### MAP FINDINGS

Database(s)

EDR ID Number **EPA ID Number** 

WCL (Continued) S105164673

Action Name: Status Report Received/2 05/29/02 Action Code: Action Date: 99 Action Name: Miscellaneous 06/18/02 Action Code: Action Date: 43 Status Report Received Action Name: Action Date: 07/28/05 Action Code: 80 Action Name: Closure Not Approved Action Date: 09/26/05 Action Code: 43 Action Name: Status Report Received/7 Action Date: 06/07/05 Action Code: 79 Closure Review Request Received with Fee Action Name: Action Date: 06/07/05 Action Code: 710 Action Name: Date Soil Registry Fee Paid 06/07/05 700 Action Date: Action Code: Action Name: Date Groundwater Registry Fee Received 05/15/06 Action Code: 99 Action Date:

Miscellaneous/4 Action Name:

Action Date: 10/18/99 Action Code: 35

Site Investigation Workplan Received (w/out Fee) Action Name:

Action Desc: Date Fee received for Closed Remediation Groundwater Site RegistryDate Fee

received for Closed Remediation Soil Site RegistryDate closure not approved

letter is sent. Date of letter to RP notifying of legal responsibilities

associated with the discovery of contamination. Date the DNR allows the RP to proceed without approval of the SIWP. Either written or by phone call.Date the DNR is notified of the discovery of the contamination. Date the DNR receives

the Site Investigation Report. Provides information regarding activities

performed to determine degree & extent of contamination and forming a basis for choosing the appropriate remedial action. Date the DNR receives the Site Investigation Workplan. States the objectives of the investigation to determine the degree and extent of contamination. Date the closure review request is received and a fee paid for DNR review. Date updates on progress are received. Can be 30, 60, 90 days or other interval. Miscellaneous action. Please see action comments. Upon completing final closure conditions, this case will be placed on the GIS Registry with groundwater contamination exceeding the NR140

Enforcement Standard and/or soil contamination above the NR720 RCL.

Active Comment: STATUS UPDATE REQUESTEDTRC HIRED AS CONSULTANT, WILL CONTINUE

INVESTIGATIONSTATUS UPDATED REC'D, SENT RFPS SEEKING NEW CONSULTANTWONR REQUESTS STATUS UPDATESTATUS UPDATE RECEIVED VIA E-MAILTELEPHONE CONVERSATION WITH CONSULTANTSIR - CONSULTANT RECOMMENDS MORE OFF-SITE INVESTIGATIONWILL HAVE REPORT BY MID- MARCHWDNR REQUEST FOR STATUS UPDATE & CHANGE RPQUARTERLY SAMPLING CONDUCTED IN 5 WELLS-2 MORE WELLS INSTALLED VOC'SAWAITING DEED

RESTRICTION RECORDINGCN WORKING ON FUNDING CONTINUED WORK FOR CLOSURE

DETERMINATIONSTATUS UPDATE REQUESTED (TEL CALL) Active Desc: Not reported

Not reported Incident Date: Report Date: Not reported Spill Source: Not reported DNR Investigate: Not reported Spill Cause: Not reported Spill Comments: Not reported Spill Action Code: Not reported Spill Action Desc: Not reported Spill Action Cmmnts: Not reported Substance Desc: Metals Amount Released: Not reported Release Code: Not reported

Substance Desc: Polynuclear Aromatic Hydrocarbons Map ID MAP FINDINGS

Direction
Distance
Distance (ft.)
Elevation Site

Database(s)

EDR ID Number EPA ID Number

WCL (Continued) S105164673

Amount Released: Not reported Release Code: Not reported

Substance Desc: Volatile Organic Compounds

Amount Released: Not reported Release Code: Not reported Spill Comments: Not reported Impact Number: 176481

Impact Code: 5
Impact Comments: Soi

Impact Comments: Soil Contamination
Impact Potential: Not reported
Impact Number: 176480

Impact Code: 4
Impact Comments: Groundwater Contamination

Impact Potential: Not reported

Org. Flag: Y

Contact name: SOO LINE RAILROAD

Contact Address: Not reported Contact Addr2: Not reported

Contact City, St, Zip: MINNEAPOLIS, MN 55440 UNITED STATES

Comany Address: MINNEAPOLIS, MN 55440

Role Desc: Responsible Party

Org. Flag: Y

Contact name: CANADIAN NATIONAL RAILWAY PROPERTIES INC

Contact Address: 17641 S ASHLAND AVE

Contact Addr2: Not reported

Contact City, St, Zip: HOMEWOOD, IL 604301345

Contact Country: UNITED STATES
Comany Address: HOMEWOOD, IL 60430
Role Desc: Responsible Party

Org. Flag:

Contact name: ANNETTE WEISSBACH
Contact Address: 2984 SHAWANO AVE

Contact Addr2: Not reported

Contact City,St,Zip: GREEN BAY, WI 543070448

Contact Country: UNITED STATES
Comany Address: GREEN BAY, WI 54307
Role Desc: Project Manager

ESÈ 950 CHICAGO ST < 1/8 MANITOWOC, WI 54220 404 ft. บริร Relative: Object ID: 414821 Higher Object Type: UST Actual: Tank Wang Object ID: 360700556 605 ft. Tank Status: Abandoned without Product Wall Size: Single Tank Status Date: Not reported Tank Size (gal): 800 Tank Contents: Waste/Used Motor Oil Mercantile/Commercial Tank Occupancy: Tank Market: No Federally Regulated: Yes Facility ID: 64335 Facility county code:

UST U002140612 N/A Map ID MAP FINDINGS

Direction
Distance
Distance (ft.)
Elevation Site

Database(s)

EDR ID Number EPA ID Number

(Continued) U002149254

Land Owner Type: Private
Owner Names RODNEY AJULA
Owner Address: 315 M 10TH ST
Owner PO Box: Not reported

Owner City,St,Zip: MANTOWOC, WI 54220
Building Name: REDS UNION 76
Building Address: 315 N 10TH ST
Building City,St,Zip: MANITOWOC 54220

B9 SSE < 1/8 431 ft. JAEGER BAKERY 308 N 10TH ST MANITOWOC, WI 54220 RCRA-SQG 1000879438 FINDS WI0000072157 LUST

**SHWIMS** 

Site 3 of 3 in cluster B

Relative: Higher

RCRAInfo: Owner:

EPA ID:

METZ BAKING CO WI0000072157

Actual: 600 ft.

Contact: CHRISTOPHER RANTS

Classification: Small Quantity Generator

TSDF Activities: Not reported
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LUST:

 Site Id:
 2734100

 Detail Seq No:
 26076

 Activity Type:
 LUST

**Activity Name:** JAEGER BAKERY Activity Number: 0336001210 Activity Display Number: 03-36-001210 **Activity Detail Address:** NONE Region Name: **NORTHEAST** Faclity ID: 436104460 Start Date: 06/22/1992 End Date: 08/30/1996 Last Action: 08/30/1996 Status Cd: С

Status: CLOSED
Jurisdiction: DNR-RR
Act Code: 340

Owner Name: METZ BAKING CO
Owner Addr: 1014 NEBRASKA ST
Owner City, St, Zip: SOUIX CITY, IA 51005

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

Database(s)

EDR ID Number EPA ID Number

#### JAEGER BAKERY (Continued)

1000879438

CCC DARLIN (C	zonimueu)			
Dept Of Commer	rce Number:	54220401806		
Comm Occurren		8446		
EPA Cerclis Id:		NONE		
Risk Code:		HIGH		
Acres:		UNKNOWN		
Acres 100:		N		
EPA NPL Site?:		No		
Dept Of Commer	rce Tracking:	Yes		
PECFA Funds E	ligible ?:	Yes		
Above Ground S	torage Tank?:	No		
Drycleaner?:		No		
Co-contamination	n?:	No		
Public Land Surv	ey System Desc:	NE 1/4 of the NE 1/	4 of Sec 30, T19N, R2	24E
Geo Located:		NE		
DNR GIS Regist	ry View Map Layer:	s:N		
GIS Area Point F	•	P		
Action Date:	07/06/94		Action Code:	3
Action Name:	Notice of Noncon	npliance (NON)/2		
Action Date:	01/09/95		Action Code:	37
Action Name:	SI Report Receiv	ed (w/out Fee)		
Action Date:	06/06/92		Action Code:	2
Action Name:	RP Letter Sent			
Action Date:	12/05/94		Action Code:	43
Action Name:	Status Report Re	eceived/2		
Action Date:	06/28/95		Action Code:	43
Action Name:	Status Report Re	eceived/5	_	
Action Date:	01/17/95		Action Code:	30
Action Name:		Workplan Go Ahead	, , ,	
Action Date:	08/30/96		Action Code:	11
Action Name:	Activity Closed		4.11 0. 1.	E0.
Action Date:	01/09/95	I/Datuma ta Camadiana	Action Code:	59
Action Name:		I/Return to Compliand		4.4
Action Date: Action Name:	11/15/94 Notice of Violatio	n (NOM	Action Code:	14
Action Date:	04/28/95	ii (IVOV)	Action Code:	43
Action Name:	Status Report Re	aceived//	Action Code.	40
Action Date:	07/19/96	2001VC0/-F	Action Code:	43
Action Name:	Status Report Re	eceived/6	Action Code.	<del>-10</del>
Action Date:	06/22/92	,00170070	Action Code:	1
Action Name:	Notification			•
Action Date:	04/26/96		Action Code:	37
Action Name:	SI Report Receiv	red (w/out Fee)/2		
Action Date:	07/06/92	, ,	Action Code:	2
Action Name:	RP Letter Sent/2			
Action Date:	06/02/93		Action Code:	3
Action Name:	Notice of Noncon	npliance (NON)		
Action Date:	01/13/95		Action Code:	43
Action Name:	Status Report Re	eceived/3		
Action Date:	11/30/94		Action Code:	43
Action Name:	Status Report Re	eceived		
Action Date:	04/26/96		Action Code:	39
Action Name:		Options Report receive		
Action Desc:			iance (NON) as a resu	
			c violation and require	
			r to RP notifying of leg	
	•		covery of contamination	
	Giosure Letter or	No Further Action let	ter is sent. NOTE: Th	is is the ONLY

Map ID Direction Distance Distance (ft.) Elevation Site

#### MAP FINDINGS

Database(s)

**EDR ID Number EPA ID Number** 

#### **JAEGER BAKERY (Continued)**

1000879438

action code that will close an activity. Date the DNR allows the RP to proceed without approval of the SIWP. Either written or by phone call. Date the DNR is notified of the discovery of the contamination. Date the DNR receives the Remedial Action Options Report (workplan). Includes actions to prevent, minimize, stabilize, eliminate threat of discharged hazardous substances, restore the environment to the extent practicable. Identify and evaluate opDate the DNR receives the Site Investigation Report. Provides information regarding activities performed to determine degree & extent of contamination and forming a basis for choosing the appropriate remedial action. Date the DNR sends letter indicating no further enforcement action will be taken at this time.Date the RP is sent a Notice of Violation (NOV) stating that a violation exists & the violator is responsible. Advises of possible prosecution & forfeitures. Requires written response within a specified time. More specific than NON.Date updates on progress are received. Can be 30, 60, 90 days or other interval.tions consistent with DNR standards.

Active Comment: SI WORKPLAN DUE 10/6/92LAB RESULTSRI UPDATEQUARTERLY REPORT; GW RESULTSSI

WORKPLAN DUE 8/5/93ENF. CONF. CANCELLEDMORE INFO HAD TO BE REQUESTED

Active Desc: Not reported Not reported Incident Date: Report Date: Not reported Spill Source: Not reported **DNR** Investigate: Not reported Spill Cause: Not reported Spill Comments: Not reported Spill Action Code: Not reported Spill Action Desc: Not reported Spill Action Cmmnts: Not reported Substance Desc: Not reported Amount Released: Not reported Release Code: Not reported Spill Comments: Not reported Impact Number: 69273

Impact Comments: Soil Contamination Impact Potential: Not reported

Impact Number: 99944 Impact Code:

Impact Comments: **Groundwater Contamination** Impact Potential: Not reported

Org. Flag:

Impact Code:

METZ BAKING CO Contact name:

Contact Address: Not reported Not reported Contact Addr2:

Contact City, St, Zip: SIOUX CITY, IA 51102 Contact Country: **UNITED STATES** Comany Address: SIOUX CITY, IA 51102 Role Desc: Responsible Party

Org. Flag:

Contact name: KELD LAURIDSEN Contact Address: 2984 SHAWANO AVE

Contact Addr2: Not reported

Contact City.St.Zip: GREEN BAY, WI 543070448

Contact Country: **UNITED STATES** Comany Address: GREEN BAY, WI 54307 Role Desc: Project Manager

Intentionally

Left

Blank

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

Database(s)

LUST

LAST

**CRS** 

**AUL** 

**SHWIMS** 

S102322070

N/A

EDR ID Number EPA ID Number

#### (Continued) U002205204

Object ID: 415121
Object Type: UST
Tank Wang Object ID: 360700933
Tank Status: Closed/Removed
Wall Size: Single

Tank Status Date: 1996-07-15 00:00:00.0

Tank Size (gal): 1500
Tank Contents: Unleaded Gasoline
Tank Occupancy: Rulk Storage
Tank Market: Yes

Federally Regulated: Yes
Facility ID: 72466
Facility county code: 36
Site Municipality: C

Municipality Name: MANITOWOC
Fire Dept ID: Manitowoc
Town Cust ID: 389736
Land Owner Type: Private

Owner Name: HOLMES OIL CO
Owner Address: 702 PARK
Owner PO Box: Not reported

Wwner City,St,Zip: MANITOWOC, WI 54220
Building Name: HOLMES OIL CO
Building Address: H110 BUFFALO ST
Building City,St,Zip: MANITOWOC 54220

SSW 1110 BUFFALO ST < 1/8 MANITOWOC, WI 54220 464 ft.

Site 2 of 6 in cluster C

**HOLMES OIL CORP** 

Relative: Lower

C12

LUST:

Actual: 593 ft.

 Site Id:
 3858800

 Detail Seq No:
 28607

 Antitit Time:
 11007

Activity Type: LUST
Activity Name: HOLMES OIL CORP
Activity Number: 0336001962
Activity Display Number: 03-36-001962

Activity Detail Address: NONE
Region Name: NORTHEAST
Faclity ID: NONE
Start Date: 11/11/1994
End Date: 10/17/2005
Last Action: 11/18/2005
Status Cd: C

Status: CLOSED
Jurisdiction: COMMERCE

Act Code: 340

Owner Name: WILLIAM HOLMES
Owner Addr: 702 PARK ST

Owner City,St,Zip: MANITOWOC, WI 54220

Dept Of Commerce Number: 54220462114
Comm Occurrence Id: 12848
EPA Cerclis Id: NONE
Risk Code: MEDIUM
Acres: UNKNOWN

Acres 100: N

Map ID MAP FINDINGS
Direction

Direction
Distance
Distance (ft.)

Database(s)

EDR ID Number EPA ID Number

### **HOLMES OIL CORP (Continued)**

Action Date:

Action Name:

Action Desc:

11/11/94

Notification

Elevation

Site

S102322070

EPA NPL Site?:		No		
Dept Of Commerc	ce Tracking:	Yes		
PECFA Funds Eli	gible ?:	Yes		
Above Ground St	orage Tank?:	Yes		
Drycleaner?:	_	No		
Co-contamination	?:	No		
Public Land Surve	ey System Desc:	NE 1/4 of the NE 1/4 o	f Sec 30, T19N, R24	ŧΕ
Geo Located:		NE		
DNR GIS Registry	y View Map Layers	: N		
GIS Area Point FI	ag:	P		
Action Date:	05/30/95		Action Code:	35
Action Name:	Site Investigation	Workplan Received (w/e	out Fee)	
Action Date:	11/16/94		Action Code:	2
Action Name:	RP Letter Sent			
Action Date:	04/19/99		Action Code:	43
Action Name:	Status Report Red	ceived		
Action Date:	10/17/05		Action Code:	11
Action Name:	Activity Closed			
Action Date:	09/15/05		Action Code:	84
Action Name:	Conditional Closu	re		
Action Date:	05/19/98		Action Code:	37
Action Name:	SI Report Receive	ed (w/out Fee)		
Action Date:	08/22/05		Action Code:	710
Action Name:	Date Soil Registry	Fee Paid		
Action Date:	08/22/05		Action Code:	700
Action Name:	Date Groundwate	r Registry Fee Received	i	
Action Date:	12/03/99		Action Code:	76
Action Name:	Activity Transferre	ed to Dept. of Commerce	Э	
Action Date:	08/22/05		Action Code:	50
Action Name:	GIS Registry Requ	uired		
Action Date:	11/18/05		Action Code:	100
Action Name:	GIS Registry QAC	QC Completed		
Action Date:	06/05/95		Action Code:	30
Action Name:	Site Investigation	Workplan Go Ahead (no	otice to proceed)	
A sties Date	44/44/04			_

Date Fee received for Closed Remediation Groundwater Site RegistryDate Fee received for Closed Remediation Soil Site RegistryDate and status that this site had QAQC completed for GIS registryDate of letter to RP notifying of legal responsibilities associated with the discovery of contamination. Date the Closure Letter or No Further Action letter is sent. NOTE: This is the ONLY action code that will close an activity. Date the DNR allows the RP to proceed without approval of the SIWP. Either written or by phone call.Date the DNR is notified of the discovery of the contamination. Date the DNR receives the Site Investigation Report. Provides information regarding activities performed to determine degree & extent of contamination and forming a basis for choosing the appropriate remedial action. Date the DNR receives the Site Investigation Workplan. States the objectives of the investigation to determine the degree and extent of contamination. Date the site closure was approved, but the site will not be formally closed until receipt of documentation of abandonment of wells, disposal of soil, recording of deed instruments, etc.Date updates on progress are received. Can be 30, 60, 90 days or other interval. Oversight of medium or low risk petroleum cleanup has been transferred to the Wisconsin Department of Commerce. Upon completing final closure conditions, this case will be placed on the GIS Registry with groundwater contamination exceeding the NR140 Enforcement Standard and/or soil contamination above the NR720 RCL.

Action Code:

1

Active Comment: SIWP DUE 1/20/95\*\*\* NR726 Closure from Commerce Data Interchange \*\*\*\*\*\*

MAP FINDINGS Map ID Direction

Distance (ft.)

EDR iD Number Elevation Database(s) **EPA ID Number** Site

### **HOLMES OIL CORP (Continued)**

Distance

S102322070

Conditional Closure from Commerce Data Interchange \*\*\*\*\*\* SIR Received by

Commerce - Updated from Commerce Data Interchange \*\*\*NOT HIGH RISK; CLOSURE REQUEST RECEIVEDAUTOPOPULATED FROM 700/710 ACTION ENTRY ON 20-OCT-05

Active Desc: Not reported Incident Date: Not reported Not reported Report Date: Spill Source: Not reported DNR Investigate: Not reported Not reported Spill Cause: Spill Comments: Not reported Spill Action Code: Not reported Spill Action Desc: Not reported Spill Action Cmmnts: Not reported Not reported Substance Desc: Amount Released: Not reported Release Code: Not reported Spill Comments: Not reported Impact Number: 72031 Impact Code:

Soil Contamination Impact Comments: Impact Potential: Not reported 187676 Impact Number:

Impact Code:

Impact Comments: **Groundwater Contamination** 

Not reported Impact Potential:

Org. Flag:

WISCONSIN CENTRAL LTD Contact name:

Contact Address: Not reported Contact Addr2: Not reported

Contact City, St, Zip: ROSEMONT, IL 600175062 Contact Country: **UNITED STATES** Comany Address: ROSEMONT, IL 60017

Role Desc: Responsible Party

Org. Flag:

Contact name: WI DEPT OF COMMERCE (DCOM) Contact Address: 201 WEST WASHINGTON AVE

Contact Addr2: Not reported Contact City, St, Zip: MADISON, WI 53703 Contact Country: **UNITED STATES** Comany Address: MADISON, WI 53703 Role Desc: **Project Manager** 

LAST:

Jurisdiction: COMMERCE Region: NORTHEAST Facility ID: NONE Site ID: 3858800 Seq No: 28607 AST Flag: Yes Start Date: 11/11/1994 10/17/2005 End Date:

Last Action: 11/18/2005 LUST Activity Type:

Action Date: 05/30/95 Action Code: 35

Site Investigation Workplan Received (w/out Fee) Action Name:

Action Code: 2 Action Date: 11/16/94

Action Name: RP Letter Sent

Action Date: 04/19/99 Action Code: 43 Map ID MAP FINDINGS

Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number** 

### **HOLMES OIL CORP (Continued)**

S102322070

Action Name:	Status Report Received		
Action Date:	10/17/05	Action Code:	11
Action Name:	Activity Closed		
Action Date:	09/15/05	Action Code:	84
Action Name:	Conditional Closure		
Action Date:	05/19/98	Action Code:	37
Action Name:	SI Report Received (w/out Fee)		
Action Date:	08/22/05	Action Code:	710
Action Name:	Date Soil Registry Fee Paid		
Action Date:	08/22/05	Action Code:	700
Action Name:	Date Groundwater Registry Fee Received	d	
Action Date:	12/03/99	Action Code:	76
Action Name:	Activity Transferred to Dept. of Commerc	е	
Action Date:	08/22/05	Action Code:	50
Action Name:	GIS Registry Required		
Action Date:	11/18/05	Action Code:	100
Action Name:	GIS Registry QAQC Completed		
Action Date:	06/05/95	Action Code:	30
Action Name:	Site Investigation Workplan Go Ahead (no	otice to proceed)	
Action Date:	11/11/94	Action Code:	1
Action Name:	Notification		

Date Fee received for Closed Remediation Groundwater Site RegistryDate Fee received for Closed Remediation Soil Site RegistryDate and status that this site had QAQC completed for GIS registryDate of letter to RP notifying of legal responsibilities associated with the discovery of contamination. Date the Closure Letter or No Further Action letter is sent. NOTE: This is the ONLY action code that will close an activity. Date the DNR allows the RP to proceed without approval of the SIWP. Either written or by phone call. Date the DNR is notified of the discovery of the contamination. Date the DNR receives the Site Investigation Report. Provides information regarding activities performed to determine degree & extent of contamination and forming a basis for choosing the appropriate remedial action. Date the DNR receives the Site Investigation Workplan. States the objectives of the investigation to determine the degree and extent of contamination. Date the site closure was approved, but the site will not be formally closed until receipt of documentation of abandonment of wells, disposal of soil, recording of deed instruments, etc. Date updates on progress are received. Can be 30, 60, 90 days or other interval. Oversight of medium or low risk petroleum cleanup has been transferred to the Wisconsin Department of Commerce. Upon completing final closure conditions, this case will be placed on the GIS Registry with groundwater contamination exceeding the NR140 Enforcement Standard and/or soil contamination above the NR720 RCL.

Action Desc:

Active Comment: SIWP DUE 1/20/95\*\*\* NR726 Closure from Commerce Data Interchange \*\*\*\*\*\*\* Conditional Closure from Commerce Data Interchange \*\*\*\*\*\* SIR Received by

Commerce - Updated from Commerce Data Interchange \*\*\*NOT HIGH RISK; CLOSURE REQUEST RECEIVEDAUTOPOPULATED FROM 700/710 ACTION ENTRY ON 20-OCT-05

Active Desc: Not reported Incident Date: Not reported Report Date: Not reported Spill Source: Not reported DNR Investigate: Not reported Spill Cause: Not reported Spill Comments: Not reported Spill Action Code: Not reported Spill Action Desc: Not reported Spill Action Cmmnts: Not reported Substance Desc: Not reported Amount Released: Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

### MAP FINDINGS

Database(s)

**EDR ID Number EPA ID Number** 

S102322070

### **HOLMES OIL CORP (Continued)**

Release Code: Spill Comments: Not reported Not reported 72031

Impact Number: Impact Code:

5

Impact Comments: Impact Potential:

Soil Contamination Not reported

Impact Number: Impact Code:

187676

Impact Comments:

Groundwater Contamination

Impact Potential:

Not reported

Org. Flag:

Contact name:

WISCONSIN CENTRAL LTD

Contact Address: Contact Addr2:

Not reported Not reported

Contact City, St, Zip:

**ROSEMONT, IL 600175062** 

Contact Country:

**UNITED STATES** 

Comany Address: Role Desc:

ROSEMONT, IL 60017 Responsible Party

Org. Flag:

Contact name:

WI DEPT OF COMMERCE (DCOM)

Contact Address:

201 WEST WASHINGTON AVE

Contact Addr2: Contact City, St, Zip: Not reported

Project Manager

Contact Country:

MADISON, WI 53703 **UNITED STATES** MADISON, WI 53703

Comany Address: Role Desc:

CRS:

Object ID: 20903539

DNR Activity Number: 0336001962 Site ID:

3858800

Facility ID: Activity Detail Name:

Not reported HOLMES OIL CORP

Start Date:

11/11/94 10/17/05

Fnd Date:

Soil or Groundwater: Groundwater and Soil

AUL:

Facid: Detail Seq No: NONE

28607

Site Id: Region Name: 3858800 **NORTHEAST** 

Action Code:

50

Action Comments:AUTOPOPULATED FROM 700/710 ACTION ENTRY ON 20-OCT-05

Action Date:

08/22/2005

Activity Type: Activity Number: 0336001962

LUST

**Activity Name:** Display Number: HOLMES OIL CORP 03-36-001962

Act Code: Detail Address:

340 NONE Act Name:

GIS Registry Required

Start Date:

11/11/1994

End Date: Status Cd: 10/17/2005 С

Last Action: Status:

11/18/2005 **CLOSED** 

Jurisdiction:

COMMERCE

Risk Code:

**MEDIUM** 

EPA NPL Site?: Acres 100:

No

Acres: Drycleaner: No

Ν

Geo Located:

Ν NE

Owner Name:

WILLIAM HOLMES 702 PARK ST

Owner Addr: Owner City, St, Zip:

MANITOWOC, WI 54220

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

Database(s)

EDR ID Number EPA ID Number

S102322070

### **HOLMES OIL CORP (Continued)**

Comm Occurrence Id:

Dept Of Commerce Number:

54220462114 12848 NONE

Action Code:

35

37

710

76

EPA Cerclis Id:

Dept Of Commerce Tracking:

PECFA Funds Eligible ?:

Above Ground Storage Tank?:

Co-contamination?:

No

Public Land Survey System Desc: NE 1/4 of the NE 1/4 of Sec 30, T19N, R24E

DNR GIS Registry View Map Layers: N GIS Area Point Flag: P Action Date: 05/30/95

Action Name: Site Investigation Workplan Received (w/out Fee) Action Date: 11/16/94 Action Code: 2 RP Letter Sent Action Name: Action Date: 04/19/99 Action Code: 43 Action Name: Status Report Received 10/17/05 Action Code: Action Date: 11 Action Name: Activity Closed Action Date: 09/15/05 Action Code: 84 Action Name: Conditional Closure

Action Date: 05/19/98 Action Code:
Action Name: SI Report Received (w/out Fee)
Action Date: 08/22/05 Action Code:

Action Name: Date Soil Registry Fee Paid
Action Date: 08/22/05 Action Code: 700

Action Name: Date Groundwater Registry Fee Received
Action Date: 12/03/99 Action Code:

Action Name: Activity Transferred to Dept. of Commerce
Action Date: 08/22/05 Action Code: 50

Action Name: GIS Registry Required
Action Date: 11/18/05 Action Code: 100
Action Name: GIS Registry QAQC Completed

Action Name: GIS Registry QAQC Completed

Action Date: 06/05/95 Action Code: 30

Action Name: Site Investigation Workplan Go Ahead (notice to proceed)

Action Date: 11/11/94 Action Code: 1

Action Name: Notification

Action Desc: Date Fee received for Closed Remediation Groundwater Site RegistryDate Fee

received for Closed Remediation Soil Site RegistryDate and status that this site had QAQC completed for GIS registryDate of letter to RP notifying of legal responsibilities associated with the discovery of contamination. Date the Closure Letter or No Further Action letter is sent. NOTE: This is the ONLY action code that will close an activity. Date the DNR allows the RP to proceed without approval of the SIWP. Either written or by phone call. Date the DNR is notified of the discovery of the contamination. Date the DNR receives the Site Investigation Report. Provides information regarding activities performed to determine degree & extent of contamination and forming a basis for choosing the appropriate remedial action. Date the DNR receives the Site Investigation Workplan. States the objectives of the investigation to determine the degree and extent of contamination. Date the site closure was approved, but the site will not be formally closed until receipt of documentation of abandonment of wells, disposal of soil, recording of deed instruments, etc. Date updates on progress are received. Can be 30, 60, 90 days or other interval. Oversight of medium or low risk petroleum cleanup has been transferred to the Wisconsin Department of Commerce. Upon completing final closure conditions, this case will be placed on the GIS Registry with groundwater contamination exceeding the

NR140 Enforcement Standard and/or soil contamination above the NR720 RCL.

Active Comment: SIWP DUE 1/20/95\*\*\* NR726 Closure from Commerce Data Interchange \*\*\*\*\*\*\*

Map ID Direction Distance Distance (ft.) Elevation Site

### MAP FINDINGS

Database(s)

**EDR ID Number EPA ID Number** 

### **HOLMES OIL CORP (Continued)**

S102322070

Conditional Closure from Commerce Data Interchange \*\*\*\*\*\* SIR Received by Commerce - Updated from Commerce Data Interchange \*\*\*NOT HIGH RISK; CLOSURE REQUEST RECEIVEDAUTOPOPULATED FROM 700/710 ACTION ENTRY ON 20-OCT-05

Active Desc: Not reported Not reported Incident Date: Report Date: Not reported Spill Source: Not reported DNR Investigate: Not reported Spill Cause: Not reported Spill Comments: Not reported Spill Action Code: Not reported Spill Action Desc: Not reported Spill Action Cmmnts: Not reported Not reported Substance Desc: Amount Released: Not reported Release Code: Not reported Spill Comments: Not reported

72031 Impact Number: Impact Code:

Impact Comments: Soil Contamination Impact Potential: Not reported Impact Number: 187676

Impact Code:

Impact Comments: **Groundwater Contamination** 

Impact Potential: Not reported

Org. Flag:

Contact name: WISCONSIN CENTRAL LTD

Contact Address: Not reported Contact Addr2: Not reported

Contact City,St,Zip: ROSEMONT, IL 600175062 Contact Country: **UNITED STATES** Comany Address: ROSEMONT, IL 60017

Role Desc:

Responsible Party Org. Flag:

Contact name: WI DEPT OF COMMERCE (DCOM) Contact Address: 201 WEST WASHINGTON AVE Not reported

Contact Addr2: Contact City, St, Zip:

MADISON, WI 53703 **UNITED STATES** Contact Country: Comany Address: MADISON, WI 53703 Role Desc: Project Manager

1004799834 C13 **HOLMES OIL** RCRA-SQG SSW 1110 BUFFALO ST WIR000016501 FINDS < 1/8 MANITOWOC, WI 54220 464 ft. Site 3 of 6 in cluster C Relative: Lower Actual 593 ft.

### **APPENDIX B3**

## FORMER HOLMES OIL INFORMATION FROM WDNR BRRTS AND GIS REGISTRY SITES

Home	About	A-Z Index	Contact	

### WDNR BRRTS on the Web

### HOLMES OIL CORP Remediation Activity Details

	PR	INT   HELP   F	<u>EEDBACK</u>		
Activity Number and Name			Activity Type		Status
03-36-001962 HOLMES OIL	CORP		LUST		CLOSED
Facility ID	Start Date	Location Name	View other activit	ies at this Location	
NONE	11/11/1994	HOLMES OIL	CORP		
Commerce Number	End Date	Address <u>View</u>	v on Google Maps <sup>™</sup>	M [Exit DNR]	Municipality
54220462114 [Exit DNR]	10/17/2005	1110 BUFFAL	O ST	NAME OF THE OWNER	MANITOWOC
EPA CERCLIS ID	Date of Last Action	County		DNR Region	
NONE	11/18/2005	MANITOWOC		NORTHEAST	
Agency Jurisdiction	Petroleum Risk	Other Location	Info	7-10-10-10-10-10-10-10-10-10-10-10-10-10-	Plot Size (Acres)
COMMERCE	MEDIUM	NONE			UNKNOWN
Public Land Survey System De	escription			DNR RR Sites Ma	<u>ap</u>
NE 1/4 of the NE 1/4 of Sec	30, T19N, R24E			View Activity on N	<b>Л</b> ар
Comments				******	
*** TRANSFERRED TO CO ARE 0 REMEDIATION AND TO VIEW LOCATION DETA	NO WASTE ACTIV	ITIES AT THIS	LOCATION. CL	JCK ON THE LO	** THERE CATION NAME LINK
		Characteris	tics		
EPA NPL Site?	Commerce Tracked?	Eligible for PECFA Funds?	Above Ground Storage Tank?	Drydleaner?	Co-Contamination?
No	Yes	Yes	Yes	No	No


		Actions Place Cursor Over Code to View D	Description
Date	Code	Name	Comment
11/11/1994	1	Notification	-
11/16/1994	2	RP Letter Sent	SIWP DUE 1/20/95
05/30/1995	35	Site Investigation Workplan Received (w/out Fee)	
06/05/1995	30	Site Investigation Workplan Go Ahead (notice to proceed)	-
05/19/1998	37	SI Report Received (w/out Fee)	*** SIR Received by Commerce - Updated from Commerce Data Interchange ***
04/19/1999	43	Status Report Received	
12/03/1999	76	Activity Transferred to Dept. of Commerce	NOT HIGH RISK; CLOSURE REQUEST RECEIVED
08/22/2005	50	GIS Registry Site	AUTOPOPULATED FROM 700/710 ACTION ENTRY ON 20-OCT-05
08/22/2005	700	Date Groundwater Registry Fee Received	

08/22/2005	710	Date Soil Registry Fee Paid	-
09/15/2005	84	Conditional Closure	*** Conditional Closure from Commerce Data Interchange ***
10/17/2005	11	Activity Closed	*** NR726 Closure from Commerce Data Interchange ***
11/18/2005	100	GIS Registry QAQC Completed	-

	Impacts
Туре	Comment
Groundwater Contamination	
Soil Contamination	

	 ***************************************
	Who
<del></del>	
Project Manager: WI DE	201 WEST WASHINGTON AVE MADISON, WI 53703

BRRTS data comes from various sources, both internal and external to DNR. There may be omissions and errors in the data and delays in updating new information. Please see the <u>BOTW disclaimers page</u> for more information.



dnr.wi.gov

Release 2.6.1 | 11/28/2007

The Official Internet site for the Wisconsin Department of Natural Resources

101 S. Webster Street . PO Box 7921 . Madison, Wisconsin 53707-7921 . 608.266.2621

Legal Notices and Disclaimers | Accessibility Notice | PDF Download Information Employment | Feedback | Sitemap

### GIS REGISTRY INFORMATION

SITE NAME:	Holmes Oil C	огр									······································	
BRRTS #:	03-36-001962	2					FID :	#				
							(if ap	prop	oriate)	:		
COMMERCE #	<b>542</b> 20-4621-1	14										
(if appropriate): CLOSURE DATE:	10/17/05		• .									
STREET ADDRESS:	1114 Buffalo	St				•						
CITY:	Manitowoc											.
SOURCE PROPERTY		DINA'	TES	X =	707083	3			<b>Y</b> = 4	0508	39	
(meters in WTM91 pro	jection):											
CONTAMINATED ME	DIA:	Gro	oundwater			Soil			Both		х	
OFF-SOURCE GW C	ONTAMINATIO	ON >	ES:		Yes				No		x	
<ul> <li>IF YES, STREET A</li> </ul>												
<ul> <li>GPS COORDINAT</li> </ul>	l l	K =					Y =					
(meters in WTM91 pro					<u> </u>	<u> </u>	<u> </u>					
OFF-SOURCE SOIL				Yes	<b>3</b>		No	X				•
>Generic or Site-Spe		RCL	) <del>:</del>	L	<u> </u>	· · · · · · · · · · · · · · · · · · ·	<u> L</u> ,	<u> </u>	2.5 % % 			
• IF YES, STREET A	<del></del>	V _		•	34 1 T 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Y =	1				
GPS COORDINAT	-	X =					T =					·
(meters in WTM91 pro	<del></del>	AV.	Yes				No	x				
CONTAMINATION IN	KIGHT OF W		DOCUMEN.	rs a	IEEDE	<u>,                                     </u>	NO				<del></del>	
Closure Letter, and any con	iditional closure b			101	<u> </u>		<u></u>	<del>- 1</del>		<del>- 1, 1</del>	<u> </u>	
<u> </u>						<del>, , , , , , , , , , , , , , , , , , , </del>		·				×
Copy of most recent deed,										·		×
Certified survey map or rele	evant portion of th	18 1800	orded plat map	(if rei	erenced in	the legal o	descript 	ion) f	or all af	ected	properties	х
County Parcel ID number, it	f used for county,	for all	affected prope	rties	(See ma	(p)						х
Location Map which outlines a parcels to be located easily (8.5) potable wells within 1200' of the s	(14" if paper copy). I	ontamir If ground	nated site boundar dwater standards	ries or are e	n USGS top xceeded, th	ographic m e map mus	iap or pl st also in	at maj clude	in suffic the locati	ient de ion of a	tail to permit the all municipal and	×
Detailed Site Map(s) for all	affected propert	ies, sh	owing buildings,	roads	, property I	oundaries,	contam	inant	sources,	utility I	ines, monitoring	×
wells and potable wells. (8.5x14 way in relation to the source pro- exceeding ch. NR 720 generic or	", if paper copy) This perty and in relation	s map s	hall also show the	locat	ion of all co	ontaminated	public:	streets	s, highway	y and ra	ailroad rights-of-	- "
Tables of Latest Groundwa		ults (n	o shading or c	ross.	hatching	)						x
Tables of Latest Soil Analyl	tical Results (no s	hading	g or cross-hatc	hing	)		• •					x
Isoconcentration map(s), if	required for site	invest	igation (SI) (8.5	x14"	if paper co	y). The is	oconcen	tration	map sho	ould ha	ve flow direction	X
and extent of groundwater contar	mination defined. If n	ot avail	able, include the	lates	t extent of	contamina	int plum	e maj	<b>9.</b>			
GW: Table of water level el												×
GW: Latest groundwater fl is greater than 20 degrees)	ow direction/mon	itoring	well location	map	(should b	e 2 maps	if max	imun	ı variati	on in	flow direction	' X
SOIL: Latest horizontal ext	ent of contamina	tion ex	ceeding gener	ic or	SSRCLs,	with one	contou	ır				х
Geologic cross-sections, if	required for SI. (	8.5x14	if paper copy)		49	· . · ·						х
RP certified statement that	legal descriptions	s are c	omplete and a	ccura	ite.		•					х
Copies of off-source notific	ation letters (if a	plicab	ole)						*.			na
Letter informing ROW own				<u> </u>						eded '	to railroad)	na
Copy of (soil or land use) d	eed restriction (s	) or de	ed notice if any	y req	ulred as a	conditio	n of clo	sure				na
Copy of any maintenance p	olan referenced in	the de	ed restriction				,					na

BUREAU OF PECFA 2129 Jackson Street

Oshkosh, Wisconsin 54901-1805 TDD #: (608) 264-8777

> Fax #: (920) 424-0217 Jim Doyle, Governor Mary P. Burke, Secretary



October 17, 2005

Ms. Nina Sayyat
Canadian National Railway
Macmillan Administration Building
1 Administration Road
Concord Ontario L4K 1B9, CN

**RE: Final Closure** 

Commerce # 54220-4621-14 WDNR BRRTS # 03-36-001962 Holmes Oil Corp., 1114 Buffalo Street, Manitowoc

Dear Ms. Sayyat:

The Wisconsin Department of Commerce (Commerce) has received the items required as the condition for closure of the site referenced above. This case is now listed as "closed" on the Commerce database and will be included on the Wisconsin Department of Natural Resources (WDNR) Geographic Information System (GIS) Registry of Closed Remediation Sites to address residual soil and groundwater contamination. It is in your best interest to keep all documentation related to the environmental activities that were conducted.

If residual contamination is encountered in the future, it must be managed in accordance with all applicable state and federal regulations. If it is determined that any remaining contamination poses a threat, the case may be reopened and further investigation or remediation may be required.

Thank you for your efforts to bring this case to closure. If you have any questions, please contact me in writing at the letterhead address or by telephone at (920) 424-0046.

Sincerely,

Robert H. Klauk Hydrogeologist Site Review Section

cc: Lynelle P. Caine - Northern Environmental Technologies, Inc.

Case File

W. War

Oshkosh, Wisconsin 54901-1805

TDD #: (608) 264-8777 Fax #: (920) 424-0217 Jim Doyle, Governor Mary P. Burke, Secretary



September 15, 2005

Ms. Nina Sayyat
Canadian National Railway
Macmillan Administration Building
1 Administration Road
Concord Ontario L4K 1B9, CN

RE: Conditional Case Closure

Commerce # 54220-4621-14

WDNR BRRTS # 03-36-001962

Holmes Oil Corp, 1114 Buffalo Street, Manitowoc

Dear Ms. Sayyat:

The Wisconsin Department of Commerce (Commerce) has reviewed the request for case closure, prepared by Northern Environmental Technologies, Inc., for the site referenced above. It is understood that residual soil and groundwater contamination remain on-site. Commerce has determined that this site does not pose a significant threat to the environment and human health. No further investigation or remedial action is necessary.

The following condition must be satisfied to obtain final closure:

 Documentation of the abandonment (WDNR Abandonment Form 3300-5B) groundwater monitoring wells MW-1 through MW-13.

This letter serves as your written notice of "no further action." Timely filing of your final PECFA claim is encouraged. If your claim is not received within 120 days of the date of this letter, interest costs incurred after 60 days of the date of this letter will not be eligible for PECFA reimbursement.

Thank you for your efforts to protect Wisconsin's environment. If you have any questions, please contact me in writing at the letterhead address or by telephone at (920) 424-0046.


Sincerely,


Robert H. Klauk Hydrogeologist


Site Review Section


cc: Lynelle P. Caine - Northern Environmental Technologies, Inc.

Case File












TABLE 1

SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS

SITE INVESTIGATION REPORT

FORMER HOLMES OIL - SITE C 308 North 11th Street Manitowoc, Wisconsin

	5	C2	63	2	CS	92	C2	C8	క్ర	C10	C-11	C12	C13	C14	C15	C18
DATE	6/17/97	6/17/97	6/17/97	6/17/97	6/11/97	6/17/97	6/17/87	8/17/97	6/17/97	6/17/97	6/17/97	6/17/97	6/17/87	6/17/97	6/17/97	B/21/97
DEPTH (feet)	4-6	0-2	4-8	2.4	4-8	0-2	9-4	2-4	<del>1</del>	2-4	4-6	4-6	4-6	2-4	3	2
PID (i.u.)	1.478	42	799	3	18	-	£	3	386	130	3	3	3	3	187	7
GRO (mg/kg)	2.240	238	3,000	<2.3	95	<2.0	<2.1	<2.2	1,680	69	<2.1	<2.1	3	<2.1	345	<1.5
DRO (mg/kg)	1,350	189	3,950	27	51	233	73	12	7,690	207	43	24	400	52	809	12
LEAD (ma/kg)	=	48	<2.7	7.7	3.5	191	13	9.7	6.3	13	8.4	7.2	8	8.2	6.4	12
(Benzene (ug/kg)	<347	×2.7	6,420	<18	417	416	99	418	646	3,010	<b>212</b>	110	<18	<17	<18	<19
Toluene (ua/ka)	2,050	63	1,830	۸10 د 10	<b>69.3</b>	82	218	6.6>	980	9,600	89	545	34	7.1	<9.8	<10
Ethylbenzene (ua/ka)	30.400	1,720	30,800	1.44	495	7.5	25	64.0	2,840	1,640	<13.8	110	1.42	<3.8	<4.0	64.3
Xvlenes (ug/kg)	102,500	4.160	68,070	21.7	417	158	4114	42	19,240	9,120	51	938	82	91	38	<21.9
TMBs (va/kg)	88 300	10.440	84,600	<14.8	2,814	7.2	163	×14.4	48,200	3,363	13.8	277	<14.8	<143	<14.3	<14.3
MTBE (ug/kg)	<233	<25	<b>187</b>	<12	110	-11	<12	<12	<115	<45	-11>	<12	<12	<12	<12	<13
Naphthalene (Ug/kg)	14,000	1,020	7,070	<13	\$0.00	170	318	42	16,800	1,750	7.5	570	47	74	157	÷4/8≥
Isopropylbenzene (ug/kg)	3,260	409	3,430	- 1.7>	219	€8,9	<7.2	<7.5	1,090	<28	<7.1	<7.2	<7.5	<7.3	<7.4	€7.9

Notes:
DRO - diesel range organics
GRO - gasoline range organics
i.u. - instrument units
mg/kg - milligrams per kilogram
ATBE - mshryl tein buryl either
PID - phodonization detector
TMBs - trimethytbenzenes
ug/kg - micrograms per kilogram

0411010/TABLES.XLS

Table 4 Groundwater Analytical Resulta, Former Bolines Oil, Manitowoc, Wisconsin

		Relevant an	d Significan	t VOC Anal	Relevant and Significant VOC Analytical Results (µg/t)	(h/h)								;				
Well ID	Date Sampled	рво	СВО	bas-J	Henzene.	a-Butylbenzene	tert-Buttylbenzene	anstitaeotolici-L, L	Ethylbenzene	Isopropylbenzene	p-Isopropyttoluene	aetm	Naphthalene	u-Bropylbenzene	Johnson	Trimethylbenzene	Vlayl Chloride	χγίετες
NR 140 Preventive Action Limit (µg/l)	տ ենամ (աջ/)	Z	뀢	5.1	0.5	빞	문	0.5	140	发	묏	12		SE E	, 002	 %	0.02	000
NR 140 Enforcement Standard (µg/1)	ndard (µg/l)	Ä	뜅	15	. 5	Ä	÷ E	5	700	吳	岩	8	40	N.	000	88	0.2	10,000
MWI	16/12/80	320	9 V	<1.5	-	× 0.50	< 0.50	05'0>	0.52	<0.50	< 0.50	3.7	· 8.8 >	< 0.50	< 0.50	< 2.0	<0.17	0.53
Pre-Excavation	01/14/98	930	8	< 1.7	<0.50	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	9	× 8.0	< 0.50	< 0.50	< 2.0	<0.17	< 0.50
Post-Excuration	06/26/03	ı	ŧ	ľ,	<0.30	1	ŀ	1	< 0.60	i	1	< 0.58	< 0.58	1	< 0.58	< 1.18	}	×1.84
	09/11/63	1	ļ	ŀ	<0.30	!	ļ.	ţ	< 0.60	i	ŧ.	0.68 J	1	I	< 0.58	< 1.18	l	× 1.84
	01/07/04	1	]	ı	< 0.30	J	1	1	09.0 >	1	1	< 0.58	Į	ļ.	< 0.58	< 1.18		×1.84
	04/08/04	ı	ł	ı	<0.14	I.	1	ŀ	< 0.40	. !	ı	<0.36	ı	ļ	× 0.36	6.0×	i	× 1.10
MWZ	76/17/80	350	10,000	\$15	259	1	<25	<25	270	×25	<25	ι	× 400	32	<25	429	<8.5	90g*
Pro-Excavation	.86/>1/10	3,700	12,000	38	88	120	8	< 0.50	830	8	8	R	< 800	98	05.0 >	1,850	<17	2,800
Post-Exerution	06/26/03	ı	:	1	906	i	ł	<u> </u>	1,000	1	1	121	550	ŀ	4	1,820	ì	3,082
	09/1/63	ì	i	ı	910	ŀ	1	; i	850		1	24.1	280	I	21.5	2,060	ŀ	2,463
	01/07/04	1.	1 -	l	1,100	·	ı		830	1	1	.92	460	ı.	×	1,900	1	2,457
	04/08/04	1	-	1	Š				1,400	;	1	<7.2	Ę	1	ŝ	2,850	ļ	43.0
CWM	08/27/97	2,700	3	×1.5	< 0.50	< 0.50	0.0>	05.0 >	0.55	< 0.50	< 0.50	<0.20	< 8.0	0.52	0.50 >	<2.0	<0.17	1.7
Pre-Excavation	01/14/98	38	<del></del>	1.5	< 0.50	4.0	< 0.50	< 0.50	< 0.50	9.1	< 0.50	< 0.20	× 8.0	0.77	< 0.50	<20	<0.17	0.59
Post-Excevation	06/26/03	1	ì	1	< 0.30	i	ŀ	ŀ	< 0.60	i	1	< 0.58	×0.58	ļ	< 0.58	<1.18	i	× 1.84
	01/07/04	1	i	1	<0.30	1	I	;	< 0.60	1	1	< 0.58	1	ľ	< 0.58	< 1.18	1	< 1.84
MW4	08/27/97	001 >	95.	<1.5	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	0.1	=	< 8.0	< 0.50	99.0	<2.0	< 0.17	3.0
Pro-Excevation	01/14/98	8	\$ V	1.5	< 0.50	05.0 ×	< 0.50	< 0.50	× 0.50	< 0.50	1.5	1.7	< 8.0	< 0.50	< 0.50	<2.0	< 0.17	96.0
Post-Excavation	06/26/03	1	ţ	Į.	< 0.30	ì	ł	ì	< 0.60	į	ŀ	< 0.58	< 0.58	i	< 0.58	× 1.18	1	× 1.84
-	60/17/60	1	1	Į.	<0.30	i	ı	ı	< 0.60	ı	ı	2.6	< 0.58	ţ	< 0.58	<1.18	i	48 <u>.</u> 1
	40/02/10	ı	ŀ	1	< 0.30	1	ì	ì	< 0.60	1	1.	3.7	< 0.58	1	< 0.58	<1.18	1.	× 28.
	04/08/04	1	ì	1	<0.14	1	ı	ı	< 0.40	4	1	< 0.36	< 0.47		< 0.36	< 0.79	Þ	×1.10

s/proj/Wcl/22001351/tables/wla.xls

Table 4 Groundwater Analytical Resalts, Former Holmes Oll, Manitowoc, Wisconsin

		Relevant and Significant VOC A	d Significan		nalytical Results (ug/l)	λ (με/λ) ε				~;								
well ₪	Date Sampled	рво	СКО	bss.i	реплене	ansznsciyind-n	suszusdylug-hat	snadssovoldsid-2,1	Ethylbenzene	Yzobiobkipenzene	р-Ізоргоруісої цепе	MTBE	Марасрајске	a-Propylbeazene	Toluene	Trimethylbenzene	Vinyi Chloride	χλιευεε
NR 140 Preventive Action Limit (µg/1)	n Limit (µg/l)	Ä	NE	1.5	0.5	NE	NE	0.5	04-	ZE.	Ë	12	8	22	82	8	0.02	0001
NR 140 Enforcement Standard (µg/l)	urdard (µg/l)	EN.	띶	15	S	发	S.	\$	00/	吳	g	8	ş	뛽	900	<del>\$</del>	0.2	10,000
MW5	16/17/80	220	8 >	۸ کا ۲	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	05.0 >	< 0.50	< 0.20	< 8.0	< 0.50	< 0.50	<2.0	<0.17	0.92
Pre-Excavation	01/14/98	8	× 50	9]	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	< 0.20	< 8.0	< 0.50	< 0.50	< 2.0	<0.17	< 0.50
Post-Excavation	06/26/03	!		1	< 0.30	1	1	ï	09:0 ×	i		< 0.58	< 0.58	ı	< 0.58	< 1.18	ı	× 1.84
	09/17/03	1	.1	I	0.00	ı		ţ	< 0.60	. 1	ı	< 0.58	< 0.58	1	<b>R</b> 5:0 >	< 1.18	į.	× 1.84
-	01/07/04	1	ı	1	< 0.30	-	1	ı	> 0.60	į	1	< 0.58	< 0.58	ł	< 0.58	< 1.18	į	2.1.2 22.1.2
MW6	72/15/20	110	os >	< 1.5	05.0 >	< 0.50	< 0.50	05.0 >	× 0.50	02.05	2,0 ×	< 0.20	< 8.0	< 0.50	< 0.50	< 2.0	< 0.17	0.95
Pre-Excavation	01/14/98	v 100	o	1.7	< 0.50	< 0.50	< 0.50	< 0.50	> 0.50	05.0 >	< 0.50	< 0.50	0.8	< 0.50	< 0.50 >	< 2.0	<0.17	< 0.50
Post-Excevation	06/26/03	I č	j.	. 1	< 0.30	.]	ı	ì	09'0 >	1	1	< 0.58	< 0.58	ı	< 0.58	× 1.18	ı	48.1.84
	01/07/04	!	1	1	0°0>	1	1	1	< 0.60		1	< 0.58	1	ı	< 0.58	< 1.18		- 1.84 1.84
MW7	76/17/80	<u>5</u>	8	د اع	< 0.50	< 0.50	< 0.50	< 0.50	05'0>	< 0.50	1.3	< 0.20	0.8 >	< 0.50	< 0.50	<2.0	<0.17	1.4
Pro-Euchvation	01/14/98	8 V	v 30	۸ اے	< 0.50	< 0.50	< 0.50	0.50	< 0.50	< 0.50	7.8	< 0.20	0.8 ×	< 0.50	< 0.50	< 20	< 0.17	< 0.50
Post-Excavation	06/26/03		-	ı	< 0.30		***	ŀ	09'0>	ı	ì	< 0.58	<0.58		< 0.58	× 1.18	1:	18.
MUV8	16172/80	016	400	۸ ا.۵	190	< 0.50	< 0.50	×25	12	7	05.0 >	< 0.20	< 8.0	6.2	3.2	<b>8.4</b>	<0.17	¥
Fre-Excevation	01/14/98	370	180	۸ ک	15	5.6	< 0.50	< 0.50	2.2	9.1	< 0.50	< 0.20	< 8.0	97	× 0.50	< 20	< 0.17	£.
Post-Excevation	092903	ì	i	1	190	ì	ļ	i	6		ļ	3.9	9.4	ŀ	7.5	63.7	i	182
	00/11/60	!	i	i	280	ı	1	1	87	i	i	6.3	6.7	ı	93	42.8	1	173.2
	01/07/04	1	I	1	170	ı	ļ	ï	· <u>*</u>	1	Į.	T 87	5	ł	<b>4</b> 0	44.7	. 1	82.2 3
	04/08/04	ļ	ı	_	8.2	1	į.	1	1.7	1	1	0.40 J	0.87 J	1	< 0.36	12.53.1	1	7.3
6МЖ	16/LZ/80	901	8,5	۸ اج	< 0.50	< 0.50	< 0.50	< 0,50	< 0.50	< 0.50	<0.50	< 0.20	< 8.0	< 0.50	< 0.50	3	<0.17	6.1
Pro-Excernations	01/14/98	V 100	< 50	< 1.5	05.0 >	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	< 0.20	98 V	< 0.50	< 0.50	<20	< 0.17	< 0.50
Post-Excavation	06/26/03	ı		1	× 0.30	1	ı	1	09 0>	i,	i	< 0.58	< 0.58	ł	\$5'0 ×	< 1.18	į	< 1.84
	01/07/04	ı	1	Í,	< 0.30	1	Ļ	Ì	< 0.60	1	1	× 0.58	I	1	< 0.58	< 1.18	1	×1.84

s/proj/Wcl/22001351/tables/wla.xts

Table 4 Graundwater Analytical Results, Former Holmes Oil, Manitowoc, Wisconsin

Xylenes

< 0.43 <0.17 Vinyl Chloride × 5.5 112 0.70 ×1.18 .i. 25 75 1067 5 0.79 46.2 29.6 Trimethylbenzene 25. 4. 4. 88.05 <0.58 < 0.58
< 0.58
< 0.56
</pre> < 0.58 < 0.58 1.7 Toluene 2 2 1 թեւահ**ի**լրբաշար **≅** \$ 1 | 1 | 1 2 1 1 1 2 2 2 2 1 1 1 8 8 V V 05.0 × 05 < 0.58 < 0.58 < 0.36 0.20 × ۸.0 کی 1.9 2 8 MLBE 6.1.3 # # 1 1 1 1 焸띬 2 2 2 2 2 240 × 1.4 2.0 A 08.0 A 08.0 A 08.0 A 08.0 A 08.0 A 08.0 A < 0.60 < 0.60 < 0.60 ₹ 8 97.6 ggplpeuseue 6.13 0.00 0.00 0.00 3 3nadtsoroldsiG-2,1 < 1.3 < 0.50 五五 1111 221111 թաշաթգինյո<del>ց-յ</del>ոթյ Relevant and Significant VOC Analytical Results (1281) 焸焸 n-Bucylbenzene < 0.30 < 0.30 × 0.30 < 0.30 < 0.30 < 0.14 วขอวขอด 1 1 1 1 ско ORG Date Sampled 09/17/03 01/07/04 04/08/04 7672780 01/14/98 09/17/03 01/14/98 09/17/03 06/26/03 04/08/04 76/17/97 06/26/03 NR 140 Preventive Action Limit (µg/1) NR 140 Enforcement Standard (µg/1) Pre-Euchyntion Pro-Excernion Pre-Excavation Well TD **8**€ MW12 MW.

270 170 1.84

35.4 J 01'19 s/proj/Wct/22001351/tables/wla.xls

Table 4 Groundwater Analytical Results, Former Holmes Oil, Maultowoc, Wisconsin

		Refevant a	Retevant and Significant VOC.	If VOC Ana	Analytical Results (µg/l)	3 (µZrl)												
Well ID	Date Sampled	Ояа	ояо	bas-J	Вепзепе	u-grtAlpeuzene	tert-Butyibenzene	ənaritəotoldəld-2,1	Ethylbenzene	[sobtobλ peuxeue	. b-tzobrobyłtołucne	MTBE	Naphtbalene	и-Ргоруйсевгеве	Тоічеле	Trimethylbenzene	Vinyl Chiorlde	Xylenes
NR 140 Preventive Action Limit (µg/l)	on Limit (µg/l)	RE	Z	(.5	5.0	£	말	0.5	<del>5</del>	윗	N.E.	12	8	NE	200	%	0.02	1,000
NR 140 Enforcement Standard (µg/l)	andard (µg/l)	翌	Z.	23	S	Ħ	핃	5	200	R	Æ	S	0\$	NE	1,000	480	0.2	10,000
MW13	06/26/03	-	ı	1	< 0.30	.1	ļ	1	09:0 >	. 1	i	2.6	< 0.58	}	< 0.58	< 1.18	ı	× 1.84
	09/17/03	1	ļ	l	< 0.30	ı	- 1	1	> 0.60	i		< 0.58	i	ì	< 0.58	< 1.18	ı	<u>*</u>
	01/07/04	1	ı	1	< 0.30	i	ı.	i	09:0 >	ı	1	5.0	ì	1	0.90 J	<1.18	1	× 18
	04/08/04	1	1	1	<0.14	1		1	× 0.40	ŧ	i	<0.36	ì		< 0.36	< 0.79	i	< 1.10
								-			-							

. <b>BE</b> _		DRO • Diesel Range Organics	GRO = Gasoline Range Organics	VOC - Volatile Organic Compounds	~ Not Analyzed	32 = Excepts NR 140 Preventive Action Limit	32 = Excepts NR 140 Enforcement Standard	
MTBE ms/l ms/l fbg vs		<ul> <li>Methyl-Tertiary-Butyl-Ether</li> </ul>	" micrograms per liter	# Mesa Sea Lovel	<ul> <li>Analyte detected between Limit of Detection</li> </ul>	and Limit of Quantitation	- Feet Below Grade	<ul> <li>Not Established by Wis. Adm. Code</li> </ul>
	Key	MTBE	1/811	ms I	5		gqj	Ä

### **APPENDIX C**

WWES IN-SITU STABILIZATION OF COAL IMPACTED SOILS DRAWINGS (SHEETS C1 THROUGH C4, S1 AND S2)

# ONSIN FUEL & LIGHT COMPANY MANITOWOC, WISCONSIN

N SITU STABILIZATION/SOLIDIFICATION OF COAL TAR IMPACTED SOILS

CONTRACT NO. 2

JUNE, 1993

22574/63595 PROJECT NO.


C2 C3 C4


REFERENCE DRAWII


SITE PLAN
SECTION & DETAILS SYSTEM RETAINING WALL ANCHOR RETAINING WALL ANCHOR S2 S2 S3


REMEDIATION AREA – SITE PLAN CROSS SECTION LOCATION MAP – SITE REMEDIATION AREA CROSS SECTIONS – REMEDIATION AREA CROSS SECTIONS –


WW Engineering & Science















# APPENDIX D ISS VERIFICATION SAMPLE LOCATIONS



### **APPENDIX E**

# SITE RECONNAISSANCE FIELD NOTES, OBSERVATIONS AND PHOTO LOG (JANUARY 5, 2007)

### CHECKLIST FOR ECOLOGICAL ASSESSMENT/SAMPLING

ΛΛ. 1	
County: Mantaeex Ci	·
arinde: T19W, ROLE, Sedi	Longitude:
What is the approximate area of the site?	all Longitude:  upland portion area estimated to  acres hive portion renkmin
EXPOURA:	S QUEST (N.D). If no, attach trip report of previous site visit(s), if available.
Please attach to the checklist USGS topo	graphic map(s) of the site, if available.
Are aerial or other site photographs available (s) to the site map at the conclusion	nilable? yes no. If yes, please attach any available of this section.
The land use on the site is:	The area surrounding the site is: mile radius
The land use on the site is: % Urban	The area surrounding the site is: mile radius % Urban,
	mile radius
% Urban % Rural	% Urban, % Rural
% Urban	mile radius  "We Urban,  "Rural  "Residential
	mile radius  "W Urban,  "Rural  "Residential
W Urban  Rural  Residential  Nesidential  Nesidential	## Mile radius  ## Urban  ## Rural  ## Residential  ## Neavy)  ## Agricultural
W Urban  Rural  Residential  Italian  Industrial  Agricultural	## Mile radius  ## Urban  ## Rural  ## Residential  ## Neavy)  ## Agricultural
% Urban % Rural % Residential % Industrial	## Mile radius  ## Urban  ## Rural  ## Residential  ## Neavy)  ## Agricultural  ## (Crops:

10872

V5/07

8.	Has any movement of soil likely cause of this disturba	taken place at the site?	yes no. If yes	s, please identify the	e most
	Agricultural Us	е Неаvy	Equipment	Mining	,
	Natural Events	Erosic		Other	
	Please describe: None	observed during	Side Dist.	The upland	poillon
	of the site is co	wered with paw	ement and	buldwap.	Omby
	a Small amout	t garany e	ma in Ir	ord & H	<u>.</u>
	bulding -	0	·		
9.	Federal and State parks, N plains and wetlands are no	ve environmental areas exisational and State monument talways obvious; do not ans	s, wetlands, prairie po wer "no" without con	otholes? Remember, afirming information	flood
	Property but	constrained with	in sheet pil	e healts as	ship Course
	Please provide the source general location on the site	V ,	dentify these sensitive	e areas, and indicate	e their
10.	What type of facility is loc	ated at the site?			
	☐ Chemical 🔀	Manufacturing	Mixing	Waste disposa	I
estin	•	mercial, food s			
01010		Storang Vould			
11.	concentration levels?	ontaminants of concern at 145, PWCo, Cyci	nis metals	Menols.	amum Coo
10	compression ruges	- you make new	- CARCILITA	tings "	
12.		of off-site migration of cont	_		
	Swales	Depressions		Drainage ditches	
	Runoff	Windblown particulate	^ ^	Vehicular traffic	£.,
	<i>*</i>	en soem on i		· / ()	102
13.		eximate depth to the water ta		A. Carre	

2 4 (2

V5/07

14.	Is the direction of surface runoff apparent from site observations? yes no. If yes, to which of the following does the surface runoff discharge: Indicate all that apply.
	Surface water Groundwater Sewer Collection impoundment
	47 Rear putting lot drainto River & Front of Drukhing drains to Sever
15.	Is there a navigable waterbody or tributary to a navigable waterbody? yes no.
	Manitouoc River
16.	Is there a waterbody anywhere on or in the vicinity of the site? If yes, also complete Section III: Aquatic Habitat Checklist - Non-Flowing Systems and/or Section IV: Aquatic Habitat Checklist - Flowing Systems.
	yes (approx. distance dited sedjacad) no
17.	Is there evidence of flooding?  yes  ino. Wetlands and flood plains are not always obvious; do not answer "no" without confirming information. If yes, complete Section V: Wetland Habitat
FERA Flood	Checklist. The reater body is constrained within Iboduals, but the
18.	If a field guide was used to aid any of the identifications, please provide a reference. Also, estimate
	the time spent identifying fauna. (Use a blank sheet if additional space is needed for text.)
	Spent copproximately I he picking investebrates you said grave materi
Collected	you River trees along edges of River look primarily like
Cottonua	Do other early succession species, some dogwood tos.
19.	Are any threatened and/or endangered species (plant or animal) known to inhabit the area of the site?  Yes □no. If yes, you are required to verify this information with the U.S. Fish and Wildlife
	Service. If species' identities are known, please list them next.  White Level Report from WPSC based on information
	from the WOW indicates that an endangered fish
	Show the conversion and an entrangent of
20.	Record weather conditions at the time this checklist was prepared:
20.	
	-11-0
	Temperature (°¢/°F)  Normal daily high temperature
•	Wind (direction/speed) 1000 Precipitation (rain, snow)
•	
	Note this will be early in
	Wha Rollan up request to
	ELITALIA SO COLOTOS
	William Comments

36/12

V5(0<del>)</del>

IA. SUMMARY OF OBSERVATIONS AND SITE SETTING
Walker theiste from = 9:15 Am. & 10:30, then collected benthic
invertebrates with a D-met from = 10:30-11:30. Note see
cottadred map for location of video, pitimes, and benthus
This site does not afford any upland terrestriso Nathal
In will ge. The upland portion of the site is covered with
buildings and aparting tot. Banks arong the river are with a steel sheet pile wall. Brenks along the river are area from the sheet pile wall is lined with was pilings.
aren from the sheet pile wall is lined with not
marrow area of theeo opposits is a have madeing real
Acros the river from the property is a heavy moderation
complex. The remainder of the area surrounding the property
is either light undustrial / commercial or rusidential,
Benthic most shales were collected from a shallow are mean the end of the sheet pile well. The sides of the weal piles were probed with a D-mit and on avel / let into was collected from bottom and picted
with a D-met and gravel / det rith was collected from bottom and picted
humaraw zebra moussalo shello i Garmarus, agordio sonbrap vostry
Completed by Milhard Kienske Affiliation Exported
Additional Preparers
Site Manager
Date 1/5/07
Pudomiast 150 Singerling 10
were which were present un
Date 1/5/07  Pulomiant 1000 Singerling J'bl  were chiefed which were preserved in  Methanol. Splint super with NRT.
4 Of to 15/167

# II. TERRESTRIAL HABITAT CHECKLIST

IIA.	WOODED
1.	Are there any wooded areas at the site?  yes ino. If no. go to Section IIB: Shrub/Scrub.
2.	What percentage or area of the site is wooded? ( % acres). Indicate the wooded area on the site map which is attached to a copy of this checklist. Please identify what information was used to determine the wooded area of the site.
3.	What is the dominant type of vegetation in the wooded area? (Circle one Evergreen/Deciduous/Mixed) Provide a photograph, if available.
	Dominant plant, if known:
4.	What is the predominant size of the trees at the site? Use diameter at breast height.
	□ 0-6 in. □ 6-12 in. □ >12 in.
5.	Specify type of understory present, if known. Provide a photograph, if available.
IIB.	SHRUB/SCRUB
1.	Is shrub/scrub vegetation present at the site?  yes no. If no, go to Section IIC: Open Field.
2.	What percentage of the site is covered by scrub/shrub vegetation? (
3.	What is the dominant type of scrub/shrub vegetation, if known? Provide a photograph, if available.
4.	What is the approximate average height of the scrub/shrub vegetation?
	□ 0-2 ft. □ 2-5 ft. □ >5 ft.
5.	Based on site observations, how dense is the scrub/shrub vegetation?
	Dense Patchy Sparse

5 812

V5/07

1.	Are there open (bare, barren) field areas present at the site?  yes no. If yes, please indicate the type below:
	Prairie/plains Savannah Old field Other (specify)
2.	What percentage of the site is open field? ( % acres). Indicate the open field on the site map.
3.	What is/are the dominant plant(s)? Provide a photograph, if available.
4.	What is the approximate average height of the dominant plant?
5.	Describe the vegetation cover: Dense Sparse Patchy
IID.	MISCELLANEOUS
1.	Are other types of terrestrial habitats present at the site. other than woods, scrub/shrub, and open field?  yes kino. If yes, identify and describe them below.  upland portioned 5th is append with buildings parker  area , with only small area of armamental grass for
2.	Describe the terrestrial miscellaneous habitat(s) and identify these area(s) on the site map.
3.	What observations, if any, were made at the site regarding the presence and/or absence of insects, fish, birds, mammals, etc.?
4.	Review the questions in Section I to determine if any additional habitat checklists should be completed

IIC. OPEN FIELD

6 812

1/05/07

# III. AQUATIC HABITAT CHECKLIST – NON-FLOWING SYSTEMS

Note:	Aquatic systems are oft Habitat Checklist.	en associated with wetland .	habitats. Please refer to Section V, Wetland
1.	What type of open-water, i	non-flowing system is present	at the site? Whe
	Natural (pond, lake)		
	Artificially created (lag	oon, reservoir, canal, impound	dment)
2.	If known, what is the name	e(s) of the waterbody(ies) on c	or adjacent to the site?
3.	If a waterbody is present, v	vhat are its known uses (e.g.:	recreation, navigation, etc.)?
4.	What is the approximate si	ze of the waterbody(ies)?	acre(s).
5.	Is any aquatic vegetation p is known.	resent? yes no. If yes	s, please identify the type of vegetation present
	Emergent Sub	omergent	
6.	If known, what is the dept	of the water?	
7.	What is the general compo	sition of the substrate? Checl	c all that apply.
	Bedrock	Sand (coarse)	Muck (fine/black)
	☐ Boulder (> 10 in.)	Silt (fine)	Debris
	Cobble (2.5-10 in.)	Marl (shells)	Detritus
	Gravel (0.1-2.5 in.)	Clay (slick)	Concrete
	Other (specify)	·	\
8.	What is the source of water	in the waterbody?	
	River/Stream/Creek	Groundwater	Other (specify)
	Industrial discharge	Surface runoff	
9.	Is there a discharge from discharge and its path.	the site to the waterbody?	yes no. If yes, please describe this

70812

V05/07

10.	Is there a discharge from identify from the list below	the waterbody? v the environmen	yes no. it into which the wa	If yes, and the information is available, sterbody discharges.
	☐ River/Steam/Creek	On-site	Off-site	Distance
	Groundwater	On-site	Off-site	
	☐ Wetlands	On-site	Off-site	Distance
	Impoundment	On-site	Off-site	
11.	Identify any field measu parameters for which data	rements and ob- were collected pr	servations of water rovide the measurer	er quality that were made. For those ment and the units of measure below:
	Depth (ave	erace)		
			untag at unbigh the	4'
		re (depinyor the v	vaier at which the r	eading was taken)
	рН			
	Dissolved	oxygen \	NA	
	Salinity		1011	
	Turbidity (	clear, slightly tur	bid. turbid. opaque	) (Secchi disk depth, visual)
	Other (spec	cify)		
12.	Describe observed color and	nd area of colorat	ion.	
13.	Mark the open-water, non-	flowing system o	on the site map attac	ched to his checklist.
14.	What observations, if any benthic macroinvertebrates	, were made at s, fish, birds, mar	the waterbody reg nmals, etc.?	garding the presence and/or absence of

8 0 17

Y05 107

# IV. AQUATIC HABITAT CHECKLIST - FLOWING SYSTEMS

Note:

	Habitat Checklists.		y a contract of the contract o
l.	What type(s) of flowin	g water system(s) is (are) present	at the site?
	River	Stream	Creek
	Dry wash	Arroyo	Brook
	Artificially	Intermittent Stream	☐ Channeling
	created (ditch, etc.)	Other (specify)	
2.	If known, what is the n	name of the waterbody? <u>M</u> &	nitoux River
3.	For natural systems, ar	e there any indicators of physical	alteration (e.g., channeling, debris, etc.)?
4.	Dyes no. If yes, Area in a time What is the general con	please describe indicators that we want Dapin Construction Stocks? Check the substrate? Check the construction of the substrate?	ere observed, Le within sheet foil walls and k all that apply.
	Bedrock	Sand (coarse)	Muck (fine/black)
	Boulder (> 10 in.)	Silt (fine)	☐ Debris
	Cobble (2.5-10 in.)	Marl (shells)	Detritus
	Gravel (0.1-2.5 in.)	Clay (slick)	Concrete
Sc. 5. eed ve 5.	What is the condition of pile wall on to	of the bank (e.g., height, slope, ex propals, fock by -propals, 5horehi	oulder valls at wood giving
7.		t? 🗌 yes 🔀 no. If yes, please	e note the information that was used in making

Aquatic systems are often associated with wetland habitats. Please refer to Section 4, Wetland

, 分亿

15/07

8.	Is there a discharge from the site to the waterbody?  yes no. If yes, please describe the discharge and its path.
P	Is there a discharge from the site to the waterbody? I yes X no. If yes, please describe the discharge and its path. Work Motices, sail adjacent to Riverture remarks solicities (see completion report).
9.	Is there a discharge from the waterbody? Yes no. If yes, and the information is available, please identify what the waterbody discharges to and whether the discharge is on-site or off-site.
10.	Identify any field measurement sand observations of water quality that were made. For those parameters for which data were collected, provide the measurement and the units of measure in the appropriate space below:
	Width (ft) <b>\(\frac{1}{2}\)</b>
	Depth (ft)
	Velocity (specify units):
	Temperature (depth of the water at which the reading was taken)
	рН
	Dissolved oxygen
	Salinity
	Turbidity (clear, slightly turbid, turbid, opaque) (Secchi disk depth)
	Other (specify)
11.	Describe observed color and area of coloration. Stightly terbiol bracen water
12.	Is any aquatic vegetation present?  yes  no. If yes, please identify the type of vegetation present, if known.
	☐ Emergent ☐ Submergent ☐ Floating
13.	Mark the flowing water system on the attached site map.  See attached may
14.	What observations were made at the waterbody regarding the presence and/or absence of benthic
e Aco	e of bookwell. Obsered some Som Musing and
) ت الما الأ	He live wear propert during the west song birds
T (C	macroinvertebrates. fish, birds, mammals, etc.? offected benthic invertebrates at one location acceptible along of of flood well. Observed space, seaguily using and etterine mean property during sole walk, smooth song bird already manopolal, but I ittle habital un area for bird
ave '	10 0 12
	1/05/07

l.	Based on observations ar present at the site?	d/or available informati	on, are designated or known wetlands definitely
	☐ yes <b>∑</b> no		
	Please note the sources of Wetland Inventory, Federa Rield Observation	l or State Agency, etc.) to	tion used (e.g., USGS Topographic Maps, National make this determination.
2.	<ul> <li>standing water, dark, wet s</li> </ul>	oils: mud cracks; debris	terbody, in a floodplain) and site conditions (e.g line; water marks), are wetland habitats suspected of the wetland habitat identification checklist.
3.	What type(s) of vegetation	are present in the wetlan	d?
	Submergent	☐ Emergent	
	Scrub/Shrub	Wooded	
	Other (specify)		
		NA	
4.	Provide a general descripti Provide a photograph of th	on of the vegetation present the known or suspected we	sent in and around the wetland (height, color, etc.) tlands, if available.
5.	Is standing water present? approximate area of the wain Checklist III – Aquatic I	ter (sq. ft.)	is this water: fresh brackish. What is the Please complete questions 4, 11, 1 ystems.
5.	To these evidence of flooding	No. of the end of William I are	No.
J.	Is there evidence of flooding	ig at the site? what obse	rvations were noted?
	Buttressing	Water marks	Mud cracks
	Debris line	Other (describe below)	ow)
7.	If known, what is the source	e of the water in the wetl	and?
	Steam/River/Creek/Lak	e/Pond	Groundwater
	Flooding		Surface Runoff
3.	Is there a discharge from describe.	the site to a known or su	ispected wetland?  yes no. If yes, pleas

V. WETLAND HABITAT CHECKLIST


1.8/2

9.	Is there a discharge from the wetland?  yes  no. If yes, to what waterbody is discharge released?
	Surface Stream/River Groundwater Lake/Pond Marine
10.	If a soil sample was collected, describe the appearance of the soil in the wetland area. Circle or write in the best response.
	Color (blue/gray, brown, black, mottled)  Water content (dry, wet, saturated/unsaturated)
11.	Mark the observed wetland area(s) ion the attached site map.

End of Form

N:\Jobs\forms\wprocess\48\_Master checklist eco assess.doc

12 8/12







 ${Photo}\ 1$  Looking northeast from the west end of the sheet pile wall near the termination of North  $11^{th}\ Street$  and the Manitowoc River.



Looking north-northeast from the west end of the sheet pile wall near the termination of North 11<sup>th</sup> Street in the upstream direction of the Manitowoc River.



Photo 3

Looking north from the west end of the sheet pile wall near the termination of North 11<sup>th</sup> Street across the Manitowoc River to the industrial complex on the opposite side of the river.



Looking north-northwest from the west end of the sheet pile wall near the termination of North 11<sup>th</sup> Street across the Manitowoc River to the far end of the industrial complex on the opposite side of the river.



Photo 5

Looking west from the west end of the sheet pile wall near the termination of North 11<sup>th</sup> Street downstream along the Manitowoc River; the south shore of the river adjacent to the Wisconsin Central Property is shown.



Example of Notice signs posted on the rail of the sheet pile wall on the property.



Looking east up the steep slope on the property showing the east edge of the parking lot and the north end of the WPSC building.



Looking to the west-southwest across the parking lot from atop the step slope on the east end of the property. North side of the WPSC building is shown.



Photo 9

Looking at the southwest corner of the WPSC building from near the corner of North 11<sup>th</sup> Street and Chicago Street. NRT employee is standing in the approximate location of monitoring well MW14, which is located approximately 30 feet from the building.



Photo 10

Looking north from the corner of North 11<sup>th</sup> Street and Chicago Street. Note how the road and adjacent parking lot slope toward the river.



Looking approximately west toward the Wisconsin Central Railroad and Braun Building properties from the corner of North 11<sup>th</sup> Street and Chicago Street.



Photo 12
Looking south toward the garage building (Kitzerow Enterprises) from the corner of North 11<sup>th</sup>
Street and Chicago Street.



Photo 13

Looking east along Chicago Street from the corner of North 11<sup>th</sup> Street and Chicago Street. Note the lawn area located on the south side of the WPSC building (left) and the WPSC-owned storage building and Winter building (right).



Photo 14

Looking east from the southeast corner of the WPSC Building across North 10<sup>th</sup> Street toward the commercial development on the opposite side of the street.




Photo 15
Looking south from the corner of North 10<sup>th</sup> Street and Chicago Street toward the Winter building (middle) and WPSC storage building (right).



Photo 16 Looking north from the corner of North  $10^{\rm th}$  Street and Chicago Street which shows the residential development further down North  $10^{\rm th}$  Street.

### **DETAIL MAP - 1831689.2s**




SITE NAME: Former Wisconsin Fuel and Light ADDRESS: North 11th Street/Chicago Street

Manitowoc WI 54220 LAT/LONG: 44.0957 / 87.6613 CLIENT: Natural Resource Technology


CONTACT: Brian Hennings INQUIRY #: 1831689.2s

DATE: January 10, 2007 11:43 am



# WISCONSIN WETLANDS' INVENTORY

# LEGEND



#### Class and subclass

- A Aquatic bed
  - 1 Submergent
  - 2 Floating
  - Rooted floating
  - Free floating
- M Moss
- E Emergent/wet meadow
  - 1 Persistent
  - Narrow-leaved persistent
  - Broad-leaved persistent
  - 4 Nonpersistent
  - Narrow-leaved nonpersistent
  - Broad-leaved nonpersistent
- S Scrub/shrub
  - 1 Deciduous
  - 2 Needle-leaved deciduous
  - Broad-leaved deciduous
  - 4 Evergreen
  - Needle-leaved evergreen
  - Broad-leaved evergreen
  - 7 Dead
  - 8 Needle-leaved
  - 9 Broad-leaved
- T Forested
  - 1 Deciduous
  - 2 Needle-leaved deciduous
  - Broad-leaved deciduous
  - 5 Needle-leaved evergreen
  - 7 Dead
  - 8 Needle-leaved
- F Flats/unvegetated wet soil

  - 1 Cobble/gravel
  - 2 Sand
  - 3 Mud
  - 4 Organic
  - 5 Vegetated pioneer
- W Open water

  - 1 Cobble/gravel
  - 2 Sand
  - 3 Mud 4 Organic

# Hydrologic modifier

- Standing water, Lake
- Flowing water, River R
- Standing water, Palustrine H
- Wet soil, Palustrine


# Special modifiers

- Abandoned cropland
- Man-made cranberry bog С
- Exposed flats complex Farmed in dry years
- Grazed g Central sands complex j
- Floating vegetated mats m
- Ridge and swale complex S
- Vegetation recently removed Floodplain complex W
- Excavated Х
- Red clay complex

## Map symbols

Upland surrounded by wetland Wetland — upland boundary

Wetland - deep water lake



# APPENDIX F

# SITE-SPECIFIC MODIFICATIONS TO MULTI-SITE DOCUMENTS

# APPENDIX F1 SITE-SPECIFIC QUALITY ASSURANCE PROJECT PLAN

# F1 QUALITY ASSURANCE PROJECT PLAN

This appendix provides site-specific elements as identified in the Multi-Site Quality Assurance Project Plan (QAPP). Unless specifically noted otherwise, the Multi-Site QAPP will be followed while implementing the Site-Specific Work Plan (SSWP) at the Manitowoc Former MGP. This appendix references the Multi-Site QAPP sections which may require site-specific elements.

#### Section 1.1 - Introduction

The Multi-Site QAPP addresses all of the activities to be performed at the Manitowoc Former MGP.

#### Section 1.3 – Problem Definition/Background Information (A5)

Soil vapor, related to vapor intrusion into buildings, may be considered a media of potential concern for buildings on the Site. Recommendations on whether soil vapor sampling is warranted is discussed in Section 6.5.

#### Section 1.4 – Project/Task Description and Schedule (A6)

Refinement of the Data Quality Objectives (DQOs) presented in the Multi-Site QAPP are presented in Section 5.4 of the SSWP. Geophysical investigations to assess limits of waste, etc. are not proposed in the SSWP. The other activities described in Section 1.4 of the Final QAPP will be performed.

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1

04/10/08

Appendix F1 – Quality Assurance Project Plan

Page 2 of 3

Site-specific tasks to be performed and the sampling rationale are presented in Section 6 of the SSWP.

The project quantitation limits (PQLs) presented in the Multi-Site QAPP will be used for the Manitowoc SSWP. There are no additional analytical sampling parameters required. The laboratories (mobile and fixed) to be used for soil, soil vapor, sediment, and water analyses will be identified prior to initiating RI field work. A site-specific sampling and analysis summary is presented on Table 4 of the SSWP and details the media to be sampled and the constituents to be analyzed.

A site-specific schedule for implementing the remedial investigation/feasibility study (RI/FS) activities is presented in Figure 16 and discussed in Section 9 of the SSWP.

Modifications to the Generalized Conceptual Site Model (CSM) and the Multi-Site Risk Assessment Framework (RAF) are discussed in Appendix F3.

Section 1.5.3 – Step 3 Decision Inputs

As mentioned above, Table 4 summarizes the media to be sampled and the constituents to be analyzed. The PQLs presented in the Multi-Site QAPP will be used for the Manitowoc SSWP. The PQLs will be sufficiently low to compare with the screening levels presented in the Multi-Site RAF. In some instances, the PQL may be above the screening level because commercially available techniques cannot achieve detection levels below the screening levels. Section 6 of the SSWP describes the sampling devices to be used in accordance with the Multi-Site Field Sampling Plan (FSP). Modifications to the FSP are included in Appendix F4.

Section 1.5.3.1 – Screening Level Ecological Risk Assessment (SLERA)

Guidance documents to be used to evaluate ecological risk are described in the Multi-Site RAF.

Section 1.5.3.2 – Human Health Risk Assessment (HHRA)

Guidance documents to be used to evaluate human health risks are described in the Multi-Site RAF.

Section 1.5.4 – Step 4 Investigation Boundaries

1530 Appx F1 QAPP 080410

NATURAL RESOURCE TECHNOLOGY

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1

evision 1 04/10/08

Appendix F1 – Quality Assurance Project Plan

Page 3 of 3

Figure 3 of the SSWP depicts the site boundaries, zoning and ownership. Figure 13 presents the proposed soil sampling locations, Figure 14 presents the proposed soil vapor sampling locations, and Figure 15 presents the proposed groundwater monitoring well and piezometer locations. Sheets 2 and 3 provide proposed surface water and sediment sampling locations.

Sample volumes required for laboratory and toxicity testing are provided on Table 4 of the SSWP.

As mentioned above, the sampling rationale is presented in Section 6 of the SSWP.

#### Section 1.5.8 Measurement Performance Criteria

As discussed in Section 6 of the SSWP, the laboratories selected to perform the analysis will be provided to USEPA for review and approval in accordance with the AOC/SOW.

#### Section 2.1.1 Schedule

A site-specific schedule for implementing the remedial investigation/feasibility study (RI/FS) activities is presented in Figure 16 and discussed in Section 9 of the SSWP.

#### **Section 2.1.2 Sampling Design Rationale**

Table 4 summarizes the media to be sampled and the constituents to be analyzed.

#### Section 2.3.1.3 Sample Container, Volume, Preservation and Holding Time

Table 4 summarizes the sample containers, volume, preservation and holding times for the media to be sampled and the constituents to be analyzed.

#### Section 2.4 Analytical Methods Requirements (B4)

Table 4 summarizes the parameters to be analyzed.

# APPENDIX F2 SITE-SPECIFIC HEALTH AND SAFETY PLAN

# **DRAFT**

### **HEALTH AND SAFETY PLAN**

# WISCONSIN PUBLIC SERVICE CORPORATION FORMER MANUFACTURED GAS PLANT SITE MANITOWOC, WISCONSIN

# Prepared for:

Wisconsin Public Service Corporation 700 North Adams Street Green Bay, Wisconsin 54307

# Prepared by:

Natural Resource Technology, Inc. 23713 W. Paul Road, Suite D Pewaukee, WI 53072

April 10, 2008

Project No: 1530

#### NATURAL RESOURCE TECHNOLOGY MULTI-SITE HEALTH AND SAFETY PLAN SUMMARY

Prior to initiating site-specific field activities, the following information will be provided to USEPA and to each field staff member within the Site-Specific Work Plan. A copy of this Health and Safety Plan (HASP) will be maintained on site during field activities and updated as determined necessary by the Project Manager.

Site Address: 402 N. 10<sup>th</sup> Street, Manitowoc, WI

Major Cross Roads: Chicago Street and 10th Street

Hospital Address: 2300 Western Avenue

### Direction to Hospital from Site (see map below):

1: Start out going SOUTH on N 10TH ST / US-10 E / CR-B S toward CHICAGO ST.. 0.2 miles

2: 2: Turn RIGHT. 0.1 miles


3: Turn RIGHT onto S WATER ST. 0.1 miles

4: S WATER ST becomes CLARK ST. 0.2 miles

5: Turn SLIGHT RIGHT onto WESTERN AVE. 0.3 miles

6: End at Holy Family Memorial Med Ctr: 2300 Western Ave, Manitowoc, WI 54220, US

Total Est. Time: 4 minutes Total Est. Distance: 1.16 miles



## Activity(s) and Dates of Work: Sediment assessment and sampling, groundwater and surface

water sampling, groundwater monitoring well and soil boring installation, and soil and soil vapor sampling. Schedule presented in Figure 16 of the Site-Specific Work Plan.

# Description of Site (See map Figure 2 in Work Plan): Approximately 2.5 acres, currently

owned by WPSC, City of Manitowoc (property and street right-of-ways), Wisconsin Central Railroad, and Winter.

### Potential Health/Safety Hazards on Site:

Chemical	Concentration Concentration (Water) (Soil)		Concentration	Maximum Concentration (Sediment)	Routes of Exposure
Volatile Organic Compounds	Water, Soil, Sediment	330 µg/L benzene	32 mg/kg benzene (17'bgs)	112,000 mg/kg total BTEX (0- 2')	Inhalation, ingestion, skin or eye contact
Semi-Volatile Organic Compounds	Water, Soil, Sediment	783 µg/L total PAHs	3,200 mg/kg naphthalene (13' bgs)	10,890 mg/kg total PAHs (0-2')	Inhalation, ingestion, skin or eye contact
Metals	Water, Soil, Sediment	0.005 mg/L arsenic (1992)	3.0 mg/kg arsenic (7' bgs), 490 mg/kg lead (7')	516 mg/kg lead (4-6')	Inhalation, ingestion, skin or eye contact
Cyanide	Water, Soil, Sediment	0.02 mg/L (2004)	15 mg/kg (15' bgs)	23 mg/kg (0-2')	Inhalation, ingestion, skin or eye contact
Others based on Site- Specific conditions	n/a	n/a	n/a	n/a	n/a

The safety coordinator/emergency coordinator will be the NRT staff personnel supervising the field investigation/work.

### **Protective Equipment/Instruments:**

In general, personal protective equipment (PPE) will be used as specified on Table 1 for the anticipated project tasks. The project manager may require additional PPE based on field conditions or additional data collection. A list of the PPE required for the various site activities is listed on Table 1.

#### Air Monitoring:

In general, a PID (and possibly a CGM) will be used to monitor air quality in the work zone and breathing zone during subsurface site investigation activities. Tasks requiring use of either the PID or CGM are listed in Table 1. Use of the PID will be continuous during test pit excavation and sampling, and sporadically during soil boring sampling.

Actions levels for the PID are listed below and discussed in more detail in Section 7.3 of the Multi-Site HASP. The VOC action levels include the following:

- Occurs when a reading of 50 ppm is sustained on PID when it is held at a constant height either in the excavation or the breathing zone. (Sustained readings last more than 30 seconds and the meter either continues to climb or remains relatively stable. Wildly fluctuating readings require a calibration check).
- Sustained readings of 50 ppm require use of either full-face or half-face respirators utilizing Organic Vapor cartridge filters.
- Air quality monitoring continues to ensure that PID readings do not exceed sustained readings of 500 ppm.
- If the 500-ppm action level is achieved, all activities on the site will immediately stop. The NRT PM will be contacted prior to taking any further action on the site.

# Safety Equipment: Fire extinguisher and first aid kit in NRT field vehicles

# **EMERGENCY CONTACT LIST**

Emergency contact phone numbers will be provided in the Site-Specific Work Plan. The emergency numbers will be confirmed prior to initiating field activities.

Client Contact:	Brian Bartoszek	920-433-2643
Fire Dept:	Manitowoc Fire Department	920-683-4520
Police:	Manitowoc Police Department	920-683-4500
Sheriff:	Manitowoc County Sheriff	920-683-4200
Local Utility	Manitowoc Public Utilities	920-683-4600
Local Water Co.	Manitowoc Public Utilities	920-683-4600
NRT:	Julie Zimdars	262-523-9000
Ambulance or	911	911
Emerge. Med.		
Contractors:		
Hospital:	Holy Family Memorial Med Center	920-320-2011
Field Staff Emerge	ency Contact	

Table 1. Summary of PPE By Sampling Activities

Subsurface structure sampling (from surface)	Av	×	×	×	Av		×					×	×	
Sediment Sampling (water craft)	Av	×	X	×	×	×	×	×	۸۷					
Sediment Sampling (shallow wading)	Av	Av		×	×	×	×	×	A۸					
Surface Water Sampling (water craft)	Av	×		×	×	X	×	×						
Surface Water Sampling (from land or shallow wading)	Av	×		×	×	×	×	×						
Soil Sampling (hand augers or shovels)	Av	×		×	×	×	×		Av	Ą	×	۸v		
Soil Sampling (heavy equipment or drill rig)	Av	×	×	×	×	×	×		۸۷	A	×	Av		
Groundwater Levels and Sampling	Av	×		×	×	×	×							
Monitoring Well Development and Conductivity Testing	Av	×		×	×	×	×							
Drilling (monitoring wells/bore holes)	Av	×	×	×	×	X	×		۸۷			۸v		
Site Reconnaissance/Field Mobilization		×		×	Av		×							
PPE Required	Steel-Toed Boots (Rubber)	Steel-Toed Boots (Leather)	Hard Hat	Safety Glasses/Goggles	Gloves-Inner (Nitrile)	Gloves-Outer (Nitrile)	Orange Vest	Life Vest	Tyvek Coverall	Half-Face Respirator	Respirator Cartridge (Hepa or Org. Vapor)	Photoionization Detector (PID)	Combustible Gas Meter (CGM)	Other

X = PPE Required Key:

Av = Have available at work site Glove types may be altered based on field conditions to include Vinyl, Neoprene, and/or Latex "Other" required or to be available PPE will be identified for each task in the Site-Specific Work Plan.

# FIELD HEALTH & SAFETY BRIEFING

NRT Project #	1530	NRT Task #	
		CERTIFY THAT I HAVE READ AND UNDERSTOOD ALL H AND SAFETY PROCEDURES AS STATED HEREIN:	
Name and Affiliat (printed)	tion	Signature	Date
	eceived from	n subcontracting company. NO □ Not Applicable	
		n was received from subcontracting company NO   Not Applicable	
This page should	be copied af	ter it has been signed and put into the project file.	

NATURAL RESOURCE TECHNOLOGY

# **APPENDIX F3**

# SITE-SPECIFIC CONCEPTUAL SITE MODEL AND RISK ASSESSMENT FRAMEWORK

# F3 SITE-SPECIFIC CONCEPTUAL SITE MODEL AND RISK ASSESSMENT FRAMEWORK

This appendix provides a summary of supplemental methods, approaches, media, receptors (human or ecological) and/or exposure pathways that may be necessary to evaluate the Manitowoc Former MGP Site and were not included in the Final Generalized Conceptual Site Model (CSM) and Final Multi-Site Risk Assessment Framework (RAF). A general Baseline Risk Assessment Report outline is presented in the RAF.

# 1.1 Additional Potential Receptors and Media Identified in Site Reconnaissance

Soil vapor, related to vapor intrusion into buildings, may be considered a media of potential concern for buildings on the Site. The human health risk assessment methods for this potential exposure pathway are described below.

# 1.2 Supplemental Human Health Risk Assessment Methods

#### 1.2.1 Data Evaluation Process for Vapor Intrusion Assessments

#### 1.2.1.1 Introduction

The purpose of this document is to provide a general framework for evaluating the data obtained during vapor intrusion assessments. Vapor intrusion assessments will generally include the evaluation of data from multiple media, potentially including soil, groundwater, soil gas, sub-slab soil gas, and/or indoor air. Data from each medium will be evaluated individually for validity and usability, as well as in combination with data from other media in order to consider multiple lines of evidence in determining whether vapor intrusion poses potential human health risks. The evaluation process conceptually follows the tiered approach presented in *United States Environmental Protection Agency (USEPA) Office of Solid Waste and Emergency Response (OSWER) Draft Subsurface Vapor Intrusion Guidance (November 2002)* by proceeding from a

NATURAL RESOURCE TECHNOLOGY generic screening assessment to a site-specific pathway assessment if necessary. The most updated published attenuation factors contained USEPA's Vapor Intrusion Database: Preliminary Evaluation of Attenuation Factors (2008) will be used for generic screening level calculations.

#### 1.2.1.2 Medium-Specific Evaluation of Analytical Data

Data from different media are appropriate to use for different purposes. For example, most regulatory agencies consider soil data to be inappropriate for evaluating potential exposure due to vapor intrusion; however, soil data can be very useful to identify locations for groundwater and/or soil gas sampling. Each environmental medium also has similar benefits and limitations. The following paragraphs discuss the appropriate uses of data from each medium and provide a general description of how the data will be evaluated.

#### Soil

Limited empirical data are available establishing attenuation factors from soil to indoor air, and modeling vapor intrusion from soil can be unreliable due to the heterogeneous nature of the medium. As a result of these data limitations, evaluating vapor intrusion from soil may be less reliable than evaluating vapor intrusion from other media, such as soil gas and sub-slab soil gas. In consideration of these limitations, analytical data from soil will primarily be used as means of identifying locations for collecting soil gas samples. Soil gas samples will be collected from areas where soil sampling has indicated the potential for residual source material to be present.

#### Groundwater

Groundwater data will primarily be used as a means of identifying soil gas and/or sub-slab soil gas sample locations. Additionally, groundwater data will also be used as one line of evidence to establish whether or not vapor intrusion poses potential risk at a site.

The United States Environmental Protection Agency (USEPA) has compiled empirical data on attenuation factors from groundwater to indoor air (USEPA, 2008), and these data can be used to calculate generic screening levels for groundwater. Generic screening levels for groundwater are defined as risk-based screening levels protective of indoor air exposures that are calculated using published attenuation factors from groundwater to indoor air. These screening levels are intended to be used in comparison to analytical data from groundwater as a conservative initial evaluation tool. Since generic attenuation factors are available for groundwater, generic screening levels can be calculated (See Section 1.2.1.3). Groundwater data from a site will be compared to generic screening levels to identify areas where soil gas sampling is warranted. These areas may overlap those where residual source material was identified during soil sampling; however, depending on the hydrogeology at a specific site, evaluation of groundwater data in comparison to generic groundwater screening levels for the vapor intrusion pathway may indicate additional locations where soil gas sampling would be prudent.

Groundwater data will also be used in conjunction with soil gas and/or sub-slab data to provide evidence of the presence or absence of a migration pathway from the subsurface to indoor air. Evaluating analytical data from groundwater along with soil gas data from multiple depth intervals provides a means of tracking the upward vertical migration of vapor-phase chemicals.

#### Soil Gas and Sub-Slab Soil Gas

Soil gas and sub-slab soil gas will be the primary media used to evaluate whether the vapor intrusion pathway is complete and has the potential to pose unacceptable risk to human health. Collecting exterior soil gas samples is less intrusive to building occupants, and exterior soil gas is less likely to be influence by the building pressure variations that can cause sub-slab soil gas data to be highly variable. For these reasons, exterior soil gas sampling is the preferred method of vapor intrusion investigation. However, the ultimate decision of whether to collect exterior or sub-slab soil gas samples will be influenced by the location of residual source materials. The location of residual source material, the presence or areas of elevated chemical concentrations in groundwater, and building construction information will be factored into the decision of whether soil gas samples will be collected externally to the building or sub-slab within the building.

The USEPA has compiled empirical data on attenuation factors from soil gas and sub-slab soil gas to indoor air, and these data can be used to calculate generic soil gas and sub-slab soil gas screening levels. Generic screening levels for soil gas and sub-slab soil gas are defined as risk-based screening levels protective of indoor air exposures that are calculated using published

attenuation factors from soil gas or sub-slab soil gas to indoor air. These screening levels are intended to be used in comparison to analytical data from soil gas or sub-slab soil gas as a conservative initial evaluation tool. Soil gas and/or sub-slab soil gas data will be compared to generic screening levels to determine whether additional evaluation or mitigation is warranted. If exterior soil gas data exceed generic screening levels, consideration will be given to either calculating site-specific soil gas screening levels or collecting sub-slab soil gas samples. Site-specific soil gas screening levels can be calculated by replacing the published attenuation factor used in the generic calculation with a site-specific attenuation factor derived from vertical soil gas concentration profiles. If sub-slab soil gas data exceed generic sub-slab soil gas screening levels, site-specific sub-slab soil gas screening levels will be calculated using site-specific attenuation factors. If sub-slab soil gas data also exceed site-specific screening levels, consideration will be given to either collecting indoor air samples or taking mitigation measures.

#### **Indoor Air**

This vapor intrusion program is designed with the intent of not performing indoor air sampling to the extent feasible. The contaminants of interest at former manufactured gas plant (MGP) sites are also commonly present in household and commercial products, and the likely presence of indoor sources of site-related compounds confounds interpretation of the resulting analytical data. However, should indoor air sampling be warranted, the resulting data will be used in conjunction with soil gas, sub-slab, outdoor (ambient) air, and/or groundwater data to establish the presence or absence of a completed vapor intrusion pathway. If it is concluded that constituents in indoor air are likely present as a result of vapor intrusion, the indoor air data will be used to evaluate potential risks to human health. Risks to human health will either be evaluated by comparing the analytical data to risk-based screening levels for indoor air or through completing a site-specific risk assessment.

#### 1.2.1.3 Risk-Based Screening Levels for Evaluating Vapor Intrusion

There are two types of screening levels that may be used to judge the potential for health risk – levels based on direct exposure to air, and levels that are derived to represent a source medium such as groundwater and soil gas. The first category includes concentration-based values (ug/m<sup>3</sup>)

of air) that are applicable to indoor air. These values are derived based on the following sitespecific considerations:

- Use of the building (residence, school, office space, storage area, etc.)
- Age and behaviors of people associated with the use of the building
- Distinctions in use, as appropriate, between basements, ground floors and upper floors
- Applicable lifetime cancer and sub-chronic or chronic health target levels
- Published values on toxic potency (e.g., reference doses, reference concentrations, and unit risk values)

The second category represents values that may be developed to correspond with measurements of soil gas, soils, or groundwater. This set of values are considered source terms that may lead to a particular indoor air concentration. The second set of values is derived from the applicable indoor air target levels by applying appropriate attenuation factors to represent how concentrations attenuate as vapors move through the vadose zone and pass into the building structure. It is anticipated that standard models and attenuation factors representative of particular soils and building types will be used to calculate soil gas values that could result in the indoor air risk-based levels. Because there are several types of soil gas measurement that might be developed for a site-specific investigation, attenuation factors can vary. For example, the attenuation factor applied to a soil gas measurement taken beneath the slab or a building would differ from that made just above the soil/groundwater interface several feet below the ground surface. Because of the site-specific variables associated with deriving appropriate attenuation factors, each case must be considered separately. However, these types of considerations are the same across sites and can draw from common databases (e.g., USEPA, 2008; ASTM, 2008) and models. When collecting soil gas and sub-slab soil gas samples, fixed gases (i.e., oxygen, carbon dioxide, and methane) will be included in the analytical suite. Data on fixed gases can be used to evaluate the potential for bioattenuation, which can then be used to support site-specific attenuation factors and site-specific screening levels.

#### 1.2.1.4 References

- ASTM International, 2008. ASTM E2600-08 Standard Practice for Assessment of Vapor Intrusion into Structures on Property Involved in Real Estate Transactions.
- USEPA, 2002, United States Environmental Protection Agency (USEPA) Office of Solid Waste and Emergency Response (OSWER) Draft Subsurface Vapor Intrusion Guidance, EPA 530-D-02-004.
- USEPA, 2008. U.S. EPA's Vapor Intrusion Database: Preliminary Evaluation of Attenuation Factors. Office of Solid Waste, U.S. Environmental Protection Agency, Washington, DC 20460.

## 1.3 Supplemental Ecological Risk Assessment Methods

There are no additional risk assessment methods (beyond those presented in the CSM and RAF) necessary to evaluate ecological receptors and media to be considered at the Manitowoc Former MGP Site.

# APPENDIX F4 SITE-SPECIFIC FIELD SAMPLING PLAN

## F4 FIELD SAMPLING PLAN

This appendix provides site-specific elements as identified in the Multi-Site Field Sampling Plan (FSP). Unless specifically noted otherwise, the Multi-Site FSP will be followed while implementing the Site-Specific Work Plan (SSWP) at the Manitowoc Former MGP. This appendix references the Multi-Site FSP sections which may require site-specific elements.

#### 1.1.3 Technical Approach

The approach to determine sample locations, types, frequencies, collection methods, and field analysis is discussed in Section 4 and 6 of the SWPP.

Section 6 of the SSWP describes the process for decision making using site knowledge on a real-time basis to determine additional sample type, location, frequency, and analytes.

Table 4 provides the site-specific Sampling and Analysis Plan, summarizing the media and constituents to be analyzed. Figure 13 presents proposed soil exploration and sampling locations, Figure 14 presents proposed soil vapor sampling locations, and Figure 15 presents proposed groundwater monitoring well and piezometer locations. Sheets 2 and 3 provide proposed surface water and sediment sampling locations. Previously performed sampling locations are provided on Figure 6 (upland) and Sheet 1 (sediment).

#### 1.3.2.1 Project Team

The attached Figure 1 presents the Technical Team Strategy. Subcontracted services will be provided to USEPA for review and approval prior to initiating field work, in accordance with the AOC/SOW.

#### 1.3.3 Communication Strategy

Technical Team titles and flow of communication is presented on Figure 1. Resumes of key team members are provided in Attachment 1.

1530 Appx F4 FSP 080410

NATURAL RESOURCE TECHNOLOGY

WPSC Manitowoc Former MGP Site Site-Specific Work Plan Revision 1 04/10/08 Appendix F4 – Field Sampling Plan Page 2 of 3

#### 1.3.4 Decision-Making Processes

The decision-making process for field activities is provided in Section 6 of the SSWP.

#### 1.3.5 Data Exchange

Section 6 describes the data required to make field decisions. As data are generated, analytical data will be provided to USEPA in an electronic format in accordance with the AOC/SOW. Data will provided in the monthly progress reports, submitted on the 15<sup>th</sup> of each month. As appropriate, data may also be provided in figures and tables for submittal with the progress report or stand alone. The RI Report will be submitted in accordance with the Project Schedule, Figure 16 and Section 9 of the SSWP.

# **Additional Standard Operating Procedures (SOP)**

As described in Section 6.6.2.1, an additional standard operating procedure is included below for field logging of the bedrock for rock quality designation (RQD).

## 1.1 Rock Quality Designation (RQD)

Rock Quality Designation (RQD) is a means of indicating rock mass properties. RQD is based on a modified core recovery procedure which, in turn, is based indirectly on the number of fractures and the amount of softening or alternation in the rock mass as observed in the rock cores from the borehole. Core recovery is the ratio of the length of core recovered to the length drilled (e.g., no recovery = 0 and full recovery = 100). This procedure is an indicator of the general quality of rock for engineering purposes and provides a numerical value which is more sensitive and consistent than gross percentage core recovery.

#### 1.1.1 Procedure

Sum the total length of core recovered by counting only those pieces of hard and sound core which are 4 inches (10 cm) or greater in length. Divide that sum by the total length that the core barrel was advanced. RQD is presented as a percentage.

1530 Appx F4 FSP 080410

NATURAL RESOURCE TECHNOLOGY Although this procedure is less applicable where core recovery is poor, the results are indicative of poor quality rock. However, it should be noted that poor drilling techniques and equipment can also cause poor recovery. It is for this reason that proper equipment and procedure along with competent supervision of the drilling procedure are imperative.

Rock Quality Designation (RQD)	Description of Rock Quality
0 - 25	very poor
25 - 50	poor
50 - 75	fair
75 - 90	good
90 - 100	excellent


#### 1.1.2 Limitations

- 1) RQD should not be applied to core less than 2 inches (5.4 cm) in diameter as a false RQD may be obtained because smaller cores can be frequently broken during the coring operation;
- 2) Care must be taken when removing the core from the core barrel. If a core is broken by handling or during drilling, the fresh broken pieces should be fitted together and counted as one piece; and
- 3) Some judgment is necessary in the case of thinly bedded sedimentary rock and foliated metamorphic rocks. The method is most suitable for igneous rock, thick-bedded limestone, sandstone, etc. However, this procedure can be applied to shale; although it is necessary to log the cores immediately upon removal from the core barrel before air slaking and cracking can occur.

#### 1.2 References

ASTM International, 2003, D5434-03 Guide for Field Logging of Subsurface Explorations of Soil and Rock.

# FIGURE 1 TECHNICAL TEAM STRATEGY



TBD - To Be Determined

# **MANITOWOC MGP CONTACT LIST**

Mary Logan Project Coordinator United States Protection Agency, Region V 77 W. Jackson Boulevard, SR-6J Chicago, Illinois 60604-3590 312.886.4699

Charlie A. Menzie, Ph.D. Principal Exponent 1800 Diagonal Road, Suite 300 Alexandria, VA 22314 571.214.3648

Julie A. Zimdars, PE
Technical Team Leader
Natural Resource Technology, Inc.
23713 W. Paul Road, Suite D
Pewaukee, WI 53072
262.522.1204 (262.523.9000 – general)

Clark Crosby
QA/QC Officer
Natural Resource Technology, Inc.
23713 W. Paul Road, Suite D
Pewaukee, WI 53072
262.522.1197 (262.523.9000 – general)

Brian Bartoszek, PE Project Coordinator Wisconsin Public Service Corporation 700 North Adams Street Green Bay, Wisconsin 54307-9002 920.433.2643

Richard H. Weber, PE Project Manager Natural Resource Technology, Inc. 23713 W. Paul Road, Suite D Pewaukee, WI 53072 262.522.1237 (262.523.9000 – general)

Rebecca Caudill, PG
Health and Safety Officer
Natural Resource Technology, Inc.
23713 W. Paul Road, Suite D
Pewaukee, WI 53072
262.522.1215 (262.523.9000 – general)

Jody Barbeau
Project Data Leader
Natural Resource Technology, Inc.
23713 W. Paul Road, Suite D
Pewaukee, WI 53072
262.522.1206 (262.523.9000 – general)

# ATTACHMENT 1 KEY TEAM MEMBER RESUMES

# Natural Resource Technology

# **Professional Profile**

#### Areas of Expertise

- Contaminated sediment remedial investigation/ feasibility study and remedial design/remedial action
- Project management
- Construction management
- Construction quality assurance/ quality control
- Geotechnical engineering
- Slope stability analysis
- Landfill investigation, design and construction
- Peer review
- Probabilistic cost analysis

#### Education

- M.S., Civil/Geotechnical Engineering, Northwestern University, Illinois, 1981
- B.S., Civil Engineering, UW-Platteville, Wisconsin, 1979

#### **Professional Registrations**

- Professional Engineer -#E22938 - WI
- Professional Engineer -#062-047154 - IL
- Professional Engineer -#PE19700348 - IN
- Professional Engineer -#71678 - OH

### Richard H. Weber, PE

#### **Managing Engineer**

#### Summary of Qualifications

Twenty-seven years experience in environmental consulting and geotechnical engineering in the United States and abroad, specializing in client service and management of large projects. Technical expertise includes contaminated sediments, construction management, geotechnical analysis, and solid waste.

#### Representative Project Experience

#### Contaminated Sediments and Construction Management

Project Manager of multi-disciplined team to work with Wisconsin Department of Natural Resources (WDNR) and the Fox River Group in site characterization, design, permitting, and implementation of the Sediment Management Unit (SMU) 56/57 Demonstration Project in Green Bay, Wisconsin. About 31,000 cubic yard (cy) of soft sediment, contaminated with upwards of 700 mg/kg of polychlorinated biphenyls were hydraulically dredged and disposed for the \$12.4 million project budget.

Project Manager for remedial investigations and development of remedial scopes of work to address polychlorinated biphenyl contamination in Pine Creek sediments and overbank soils for the Hayton Area Remediation Project, New Holstein, Wisconsin.

#### Former Manufactured Gas Plant Sites

Project Manager for remedial investigations/feasibility studies (RI/FS) of sediments affected by former manufactured gas plant (MGP) sites adjacent to the Sheboygan River and Manitowoc River, Wisconsin. Work is being done cooperatively with USEPA Region 5 under CERCLA and Superfund Alternative Site programs. The Triad approach is being used for flexibility and to save time and money, where appropriate. The scope includes risk assessments to evaluate risk to ecological and human receptors, and to facilitate cleanup decisions.

Technical Lead responsible for assessment of environmental remediation cost liability associated with residual contamination in river sediments adjacent to seven former MGP sites in Wisconsin. The assessment required site-by-site review of preliminary investigation results, and an extensive knowledge of regulations, pertinent sediment remedial technologies, and environmental cost estimating principles found in ASTM.

#### **Professional Affiliations**

- American Society of Civil Engineers (ASCE)
- Federation of Environmental Technologists (FET),
   Sediment Subcommittee
   Chair
- Western Dredging Association (WEDA), Current Board Member

#### **Professional History**

- Natural Resource Technology, Inc., (2003-Present), Managing Engineer
- MWH (Predecessor companies of Montgomery Watson and Warzyn Engineering), (1989-2003), Principal Engineer/ Vice President
- Warzyn Engineering, Inc., (1983-1989), Geotechnical Section Manager
- Dames & Moore, (1981-1983), Geotechnical Engineer

#### **Regulatory Committees**

- WDNR Bureau of Solid Waste Management
   Technical Advisory
   Committee, Revision of
   Chapter NR 500 per Federal
   Subtitle D (1990-1994)
- WDNR Contaminated Sediment Advisory Committee (2000-2001)
- WDNR Bureau of Remediation and Redevelopment Brownfields Study Group (2003-2004)
- WDNR Waste Management Program Redesign, Consultant Group (2004)

#### Remedial Design, Site Closure and Construction Management

Project Manager for demolition/deconstruction of 8-acre brownfield property of former battery manufacturer/packager in Madison, Wisconsin, for redevelopment into commercial and residential uses. 87% of demolition materials were recycled/reused.

Project Manager with complete technical/construction responsibility for \$23 million closure of three un-engineered landfills at the former Chanute Air Force Base in Rantoul, Illinois. Closure work at landfills, varying from 12 to 22 acres, included waste consolidation followed by confirmation sampling and analyses, installation of passive gas vent systems and perimeter leachate collection systems, and construction of 5-foot thick composite geosynthetic/soil covers.

#### Landfill/Solid Waste Facilities

Project Manager for design and permitting of an impoundment for disposal of approximately 700,000 cy of contaminated sediments to be hydraulically dredged from the Grand Calumet River in Gary, Indiana. An approximately 33-acre impoundment was designed to contain the dredged sediments using Resource Conservation Recovery Act (RCRA) Subtitle C liner technology. Liner design consisted of a primary and secondary high density polyethylene (HDPE) geomembrane with granular and geonet drainage layers, overlying a geosynthetic clay liner. A gradient control system was designed below the liner for site dewatering during construction. Design included a soil-bentonite slurry wall around the impoundment to minimize construction dewatering, and to provide tertiary containment of the dredged materials.

Managed numerous construction quality assurance projects for phased development and closure at the Kestrel Hawk Landfill (formerly Land Reclamation Company) in Racine, Wisconsin. Construction projects included clay liners and leachate collection systems, manholes interior to the landfill, compacted clay barrier walls separating the hazardous waste unit from the non-hazardous portion, both clay and RCRA composite (40-mil very low density polyethylene over compacted clay) final covers, dual vertical extraction systems for landfill gas and leachate, and storm water control systems. Managed preparation of contract documents, specifications, and construction drawings.

#### Geotechnical Analysis

Project Manager for forensic geotechnical analysis following a sudden mass waste movement event at active solid waste landfill in southeastern Wisconsin. Worked with facility owner, WDNR, and subconsultant university professors to investigate probable cause(s), and to develop plan for repair and restoration. Extensive analyses performed to evaluate global and veneer stability of waste mass and liner components. Assessment determined primary factors for waste movement were insufficient interface strength and waste mass geometry (height/width ratio). Restoration relocated about 400,000 cy municipal waste and replacement of geosynthetic liner.

# **Professional Profile**



#### Areas of Expertise

- Remedial Scope of Work planning for sediment removal
- Design and construction of remedial measures for gas and electric utility residuals
- Design of geosynthetic and soil covers and leachate handling facilities
- Soil and groundwater investigation and remediation involving a wide variety of contaminant types
- Feasibility studies for conventional and innovative technologies/approaches
- Pumping system hydraulics and operation, maintenance and optimization of pumping systems
- HELP modeling, contaminant transport modeling
- Site specific soil cleanup standard development
- Regulatory agency liaison support and regulatory compliance
- Brownfields site redevelopment
- Water resource engineering

#### Education

- M.S., Civil Engineering, UW-Milwaukee, 1994
- B.S., Civil Engineering, UW-Milwaukee, 1991

#### **Professional Registrations**

Professional Engineer #31452 - WI

# Julie A. Zimdars, PE Senior Engineer

#### **Summary of Qualifications**

Sixteen years of experience in environmental consulting engineering involving the remedial planning, design, construction, and operation and monitoring of various environmental management sites. Experience includes sediment and soil removal remedial planning, and design of landfill cover and leachate collection systems at fly ash disposal facilities. Other experience includes development and implementation of remedial strategies for manufactured gas plant (MGP) coal tar-impacted soil, groundwater and river sediments, and wastewater and storm water permitting. Other projects include brownfields redevelopment, Resource Conservation and Recovery Act (RCRA) corrective actions, and remediation of underground storage tank releases.

#### Representative Project Experience

#### Sediment Remediation

Senior Project Engineer responsible for development of the Remedial Scope of Work (SOW) document for polychlorinated biphenyl (PCB) contamination along a 6-mile stretch of creek in Wisconsin. Major components of the SOW included site preparation and erosion controls, creek diversion and monitoring, dewatering system design, identification of removal areas designating Toxic Substance Control Act (TSCA) and non-TSCA materials, identification of post-remedial verification sampling locations, planning for sediment solidification necessary for disposal, and site restoration needs. The SOW identified an estimated 9,000 cubic yards (cy) of creek sediment and 27,300 cy of over bank soils that require removal; about 3,500 cy of soil require disposal as TSCA material.

Senior Project Engineer for the Remedial Investigation/Feasibility Study (RI/FS) and Remedial Design for PCB-contaminated sediment on a portion of the Milwaukee River in Wisconsin. Remedial action includes removal and landfilling of 4,000 cubic yards of TSCA and non-TSCA material.

Project Manager and Lead Engineer for the design and construction management of solidification/stabilization of 6,500 cy of leadcontaminated sediment in the reservoir basin at a former major industrial manufacturing facility in southeastern Wisconsin.



#### **Professional Affiliations**

- American Society of Civil Engineers (ASCE)
- National Ground Water Association (NGWA)
- University of Wisconsin -Milwaukee Industrial Advisory Counsel/Curriculum Advisory Civil Engineering Department

#### **Professional History**

- Natural Resource Technology, Inc. (1995 to Present), Senior Engineer
- Montgomery Watson/Warzyn Engineering, Inc. (1992 to 1995), Environmental Engineer
- WDNR Southeast, Wastewater
   Unit (1991), Industrial Pretreatment
   Assistant

#### **Publications/Presentations**

- FET Environment '05 Allis-Chalmers Trust Brownfield Redevelopment: City of West Allis Stormwater Retention Basin Project, Co-author
- Field Evaluation of the Comanagement of Utility Low-Volume Wastes with High-Volume Coal Combustion By-Products: OK Site, EPRI Final Report 2004, Co-author
- Field Evaluation of the Comanagement of Utility Low-Volume Wastes with High-Volume Coal Combustion By-Products: CY Site, EPRI Final Report 2005, Co-author
- Field Evaluation of the Comanagement of Utility Low-Volume Wastes with High-Volume Coal Combustion By-Products: PA Site, EPRI Final Report 2006, Co-author

#### Landfill

Project Manager and Design Engineer for implementation of remediation measures at four closed ash landfills located in southeastern Wisconsin. Major components of the projects included design and construction oversight of either geomembrane or clay/soil covers, drainage systems, ash excavation and relocation, and quality assurance documentation. Design Engineer for two landfill groundwater remediation systems, one at an operating electric power generation facility in Michigan and one at a city landfill in southeastern Wisconsin.

Other projects included ash stabilization and treatability studies, feasibility and cost studies, remedy selection, waste consolidation, and beneficial use of coal combustion products. Performed research on co-management disposal practices of high-volume by-products (fly ash, etc.) and low-volume wastes generated at coal-fired electric generating plants for the Electric Power Research Institute (EPRI).

#### Former Manufactured Gas Plant/Brownfields

Project Manager/Engineer for two major utility clients in Wisconsin for all aspects of their former manufactured gas plant sites at locations in central and eastern Wisconsin and Upper Michigan. Experience includes engineering and management for the excavation and thermal treatment/landfill disposal of over 100,000 tons of coal tar-impacted soil at various sites. One site involves review and additional evaluation of performance of in-situ stabilization/solidification (ISS) of 14,000 cy of coal tar-impacted soil. Project requirements have included development of site management strategies, cost planning, site histories and subsurface/sediment assessments, feasibility studies, remedy selections, construction, regulatory liaison, public communications, and interfacing with redevelopment interests.

Senior Engineer/Project Manager for the ISS of approximately 8,000 cy of coal tar-impacted material at a former MGP site in southeastern Wisconsin. Extensive coordination was required with the community due to the difficult site access conditions. Project elements included bench scale testing, removal of former MGP infrastructure and restoration for reuse by current property owner.

Project Manager for the redevelopment of a brownfields site at a former major industrial manufacturing facility in southeastern Wisconsin. Project included obtaining a state-funded grant for converting a former cooling water reservoir into a city wet detention basin to serve the community for water quality improvements and integrating environmental remediation into the site-wide redevelopment plan. Project also involved demolition of former pump buildings containing asbestos and management of a PCB-oil remediation system at the site for the past 10 years.

# APPENDIX G ADDITIONAL ANALYTICAL DATA

# **APPENDIX G1**

# MAY 2005 GROUNDWATER LABORATORY ANALYTICAL REPORT



1241 Bellevue Street, Suite 9 Green Bay, WI 54302 920-469-2436, Fax: 920-469-8827

## **Analytical Report Number: 859580**

Client: NATURAL RESOURCE TECHNOLOGY

Lab Contact: Tom Trainor

Project Name: WPSC - MANITOWOC

Project Number: 1530

Lab Sample Number	Field ID	Matrix	Collection Date
859580-001	MW-1	GW	05/18/05
859580-002	MW-2	GW	05/18/05
859580-003	MW-5	GW	05/18/05
859580-004	MW-8	GW	05/18/05
859580-005	MW-9	GW	05/18/05
859580-006	MW-10	GW	05/18/05
859580-007	MW-12	GW	05/18/05
859580-008	MW-12D	GW	05/18/05
859580-009	MW-13	GW	05/18/05
859580-010	MW-17T	GW	05/18/05
859580-011	MW-18T	GW	05/18/05
859580-012	MW-19T	GW	05/18/05
859580-013	MW-20T	GW	05/18/05
859580-014	MW-21T	GW	05/18/05
859580-015	QC-1	GW	05/18/05
859580-016	QC-2	GW	05/18/05
859580-017	ТВ	WATER	05/18/05

I certify that the data contained in this Final Report has been generated and reviewed in accordance with approved methods and Laboratory Standard Operating Procedure. Exceptions, if any, are discussed in the accompanying sample comments. Release of this final report is authorized by Laboratory management, as is verified by the following signature. This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc. The sample results relate only to the analytes of interest tested.

Approval Signature

Date

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY Matrix Type: GROUNDWATER

 Project Name :
 WPSC - MANITOWOC
 Collection Date :
 05/18/05

 Project Number :
 1530
 Report Date :
 05/31/05

 Field ID :
 MW-1
 Lab Sample Number :
 859580-001

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene	<	0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform	<	0.94	0.94	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane	<	0.91	0.91	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride	<	0.49	0.49	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform		0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane	<	0.24	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane	<	0.60	0.60	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether	<	0.76	0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene		0.74	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane	<	0.79	0.79	2.6		1			05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene	<	0.73	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	
		0.59	0.59	2.0		1	ug/L				SW846 8260B
Isopropylbenzene Methylene Chleride	<						ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride	<	0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

## **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-1 Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05

Lab Sample Number: 859580-001

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	0.89	0.89	3.0		. 1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene		11	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		85				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B

PAH/ PNA										Prep Da	te: 05/23/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1-Methylnaphthalene	<	0.80	0.80	2.7		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.91	0.91	3.0		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Acenaphthene	<	0.78	0.78	2.6		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Acenaphthylene	<	0.77	0.77	2.6		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Anthracene		0.75	0.71	2.4		40	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene		4.4	0.78	2.6		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		10	0.72	2.4		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		11	0.72	2.4		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		9.8	0.83	2.8		40	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene		10	0.77	2.6		40	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Chrysene		8.9	0.66	2.2		40	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene		2.1	0.88	2.9		40	ug/L	Q&	05/25/05	SW846 3510C	8270C-SIM
Fluoranthene		13	0.66	2.2		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Fluorene	<	0.87	0.87	2.9		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene		7.8	0.68	2.3		40	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Naphthalene	<	0.89	0.89	3.0		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Phenanthrene		4.7	0.82	2.7		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Pyrene		9.5	0.65	2.2		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5		0				40	%Recov	D	05/25/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl		0				40	%Recov	D	05/25/05	SW846 3510C	8270C-SIM
Terphenyl-d14		0				40	%Recov	D	05/25/05	SW846 3510C	8270C-SIM

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-2 Matrix Type: GROUNDWATER

Collection Date: 05/18/05
Report Date: 05/31/05
Lab Sample Number: 859580-002

VOLATILES							* *****		·	Prep Da	ite: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0	•	1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846.8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene		4.4	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene		0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene		0.83	0.83	2.8		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene		0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane		0.61	0.61	2.0		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene		0.95	0.95	3.2		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene		0.74	0.74	2.5		1	ug/L ug/L		05/24/05	SW846 5030B	
Benzene		0.41	0.41	1.4		1	ug/L ug/L		05/24/05		SW846 8260B
Bromobenzene		0.41	0.82	2.7		1	ug/L ug/L		05/24/05	SW846 5030B SW846 5030B	SW846 8260B
Bromochloromethane		0.02	0.02	3.2		1	-				SW846 8260B
Bromodichloromethane		0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform		0.94	0.94	3.1			ug/L		05/24/05	SW846 5030B	SW846 8260B
				3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane		0.91	0.91			1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride		0.49	0.49	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene		0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane		0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane		0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform	<	0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane	<	0.24	0.24	0.80		1	ug/L.	_	05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene		0.91	0.83	2.8		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene		0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane	<	0.60	0.60	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane		0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether	<	0.76	0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene		38	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane	<	0.79	0.79	2.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sopropylbenzene		4.1	0.59	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride	<	0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene	<	0.74	0.74	2.5		1			05/24/05	SW846 5030B	SW846 8260B
Tup I I I I I I I I I I I I I I I I I I I		0.7 .	U., .	2.0			ug/L		03/24/03	344040 30300	3VV040 0Z0UD

Terphenyl-d14

## **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-2 Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05 Lab Sample Number: 859580-002

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Ani Date	Prep Method	Anl Method
n-Propylbenzene		2.0	0.81	2.7		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene		0.94	0.67	2.2		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene		50	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o		2.6	0.83	2.8		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
PAH/ PNA									-	Prep Dat	te: 05/23/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1-Methylnaphthalene		11	0.80	2.7		40	ug/L	D	05/25/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.45	0.45	1.5		20	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthene		4.2	0.39	1.3		20	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthylene		2.7	0.39	1.3		20	ug/L		05/24/05	SW846 3510C	8270C-SIM
Anthracene	<	0.35	0.35	1.2		20	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene		1.1	0.39	1.3	,	20	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		1.2	0.36	1.2		20	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		1.1	0.36	1.2		20	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		0.94	0.41	1.4		20	ug/L	Q&	05/24/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene		1.1	0.39	1.3		20	ug/L	Q&	05/24/05	SW846 3510C	8270C-SIM
Chrysene		1.1	0.33	1.1		20	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene	<	0.44	0.44	1.5		20	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Fluoranthene		2.3	0.33	1.1		20	ug/L		05/24/05	SW846 3510C	8270C-SIM
Fluorene		0.52	0.44	1.5		20	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene		0.77	0.34	1.1		20	ug/L	Q&	05/24/05	SW846 3510C	8270C-SIM
Naphthalene		0.71	0.45	1.5		20	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Phenanthrene		0.74	0.41	1.4		20	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Pyrene		2.0	0.33	1.1		20	ug/L		05/24/05		8270C-SIM
Nitrobenzene-d5		0				20	%Recov	D	05/24/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl		0				20	%Recov	D	05/24/05	SW846 3510C	8270C-SIM
						•		-			

20

%Recov

D

05/24/05 SW846 3510C 8270C-SIM

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-5 Matrix Type: GROUNDWATER

Collection Date: 05/18/05

Report Date: 05/31/05 Lab Sample Number: 859580-003

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L ug/L		05/24/05	SW846 5030B	
Benzene	<	0.41	0.41	1.4		1	ug/L		05/24/05		SW846 8260B
Bromobenzene	<	0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	0.97	0.97	3.2		1				SW846 5030B	SW846 8260B
Bromodichloromethane	<	0.56	0.56	1.9		1	ug/L		05/24/05 05/24/05	SW846 5030B	SW846 8260B
Bromoform	<	0.94	0.94	3.1		1	ug/L			SW846 5030B	SW846 8260B
Bromomethane	<	0.91	0.91	3.0		1	ug/L		05/24/05	SW846 5030B	SW846.8260B
Carbon Tetrachloride		0.49	0.49	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene		0.49	0.49	1.6		•	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane						1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
		0.37	0.37	1.2		1	ug/L		05/24/05		SW846 8260B
Chloromethane	<	0.24	0.24	0.80		1	ug/L		05/24/05		SW846 8260B
cis-1,2-Dichloroethene		0.83	0.83	2.8		1	ug/L		05/24/05		SW846 8260B
cis-1,3-Dichloropropene		0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane		0.60	0.60	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane		0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether		0.76	0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene		0.54	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane	<	0.79	0.79	2.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene		0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Isopropylbenzene	<	0.59	0.59	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride	<	0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene	<	0.74	0.74	2.5		1	ug/L		05/24/05		SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05		SW846 8260B

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-5 Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05

Lab Sample Number: 859580-003

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene	<	0.48	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		88				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B

PAH/ PNA										Prep Da	te: 05/23/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Ani Date	Prep Method	Anl Method
1-Methylnaphthalene	<	8.5	8.5	28	•	200	ug/L		05/25/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	9.6	9.6	32		200	ug/L		05/25/05	SW846 3510C	8270C-SIM
Acenaphthene	<	8.2	8.2	27		200	ug/L		05/25/05	SW846 3510C	8270C-SIM
Acenaphthylene	<	8.2	8.2	27		200	ug/L		05/25/05	SW846 3510C	8270C-SIM
Anthracene	<	7.5	7.5	25		200	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene		25	8.3	28		200	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		58	7.7	26		200	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		110	7.6	25		200	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		75	8.7	29		200	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene		98	8.2	27		200	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Chrysene		110	6.9	23		200	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene		18	9.3	31		200	ug/L	Q&	05/25/05	SW846 3510C	8270C-SIM
Fluoranthene		190	7.0	23		200	ug/L		05/25/05	SW846 3510C	8270C-SIM
Fluorene	<	9.2	9.2	31		200	ug/L		05/25/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene		60	7.2	24		200	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Naphthalene	<	9.5	9.5	32		200	ug/L		05/25/05	SW846 3510C	8270C-SIM
Phenanthrene		48	8.6	29		200	ug/L		05/25/05	SW846 3510C	8270C-SIM
⊃yrene		120	6.9	23		200	ug/L		05/25/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5		0				200	%Recov	D	05/25/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl		0				200	%Recov	D	05/25/05	SW846 3510C	8270C-SIM
Terphenyl-d14		0				200	%Recov	D	05/25/05	SW846 3510C	8270C-SIM

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-8 Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05 Lab Sample Number: 859580-004

VOLATILES										Prep Da	ate: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<		0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane		0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene	<	0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform	<	0.94	0.94	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane	<	0.91	0.91	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride	<	0.49	0.49	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	
Chlorodibromomethane		0.81	0.81	2.7		1	ug/L		05/24/05		SW846 8260B
Chloroethane		0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform		0.37	0.37	1.2		1	ug/L ug/L		05/24/05	SW846 5030B SW846 5030B	SW846 8260B
Chloromethane		0.24	0.24	0.80		1	ug/L		05/24/05		SW846 8260B
cis-1,2-Dichloroethene		0.83	0.83	2.8		1	•			SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene		0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane		0.60	0.60	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane		0.99	0.99	3.3			ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether		0.76				1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene			0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane		0.54 0.79	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene			0.79	2.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
		0.67	0.67	2.2		1	ug/L		05/24/05		SW846 8260B
Isopropylbenzene		0.59	0.59	2.0		1	ug/L		05/24/05		SW846 8260B
Methylene Chloride		0.43	0.43	1.4		1	ug/L		05/24/05		SW846 8260B
Methyl-tert-butyl-ether		0.61	0.61	2.0		1	ug/L		05/24/05		SW846 8260B
Naphthalene		0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-8 Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05 Lab Sample Number: 859580-004

Tetrachloroethene	VOLATILES								-		Prep Da	ite: 05/24/05
p-Isopropyltoluene	Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
Sec_Butylbenzene	n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tell-Butylbenzene	sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trans-1,3-Dichloropropene	Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene	trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichlorethene	trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	Trichloroethene		2.5	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	
Xylene, o         <         0.83         0.83         2.8         1         ug/L         05/24/05         SW846 5030B         SW846 8260B           Xylenes, m + p         <         1.8         1.0         1         ug/L         05/24/05         SW846 5030B         SW846 8260B           Herromofluorobenzene         85         .         1         %Recov         05/24/05         SW846 5030B         SW846 8260B           Toluene-d8         86         .         .         1         %Recov         05/24/05         SW846 5030B         SW846 8260B           PAH/ PNA           Result         LOD         LOQ         EQL         Dil.         Units         Code         Anl Date         Prep Method         Anl Method           1-Methylnaphthalene         <	Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	
Xylenes, m + p	Xylene, o	<	0.83	0.83	2.8		1			05/24/05	SW846 5030B	SW846 8260B
Toluene-d8 86	Xylenes, m + p	<	1.8	1.8	6.0		1			05/24/05	SW846 5030B	SW846 8260B
Toluene-d8	4-Bromofluorobenzene		85				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
PAH/ PNA   Prep   Date   Prep   Date   Prep   Date   District	Toluene-d8		86				1	%Recov		05/24/05	SW846 5030B	
Analyte Result LOD LOQ EQL Dil. Units Code Anl Date Prep Method Anl Method 1-Methylnaphthalene	Dibromofluoromethane		84				1	%Recov		05/24/05	SW846 5030B	
1-Methylnaphthalene	PAH/ PNA										Prep Dat	te: 05/23/05
2-Methylnaphthalene	Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
Acenaphthene	1-Methylnaphthalene	<	0.80	0.80	2.7		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Acenaphthylene 2.0 0.77 2.6 40 ug/L Q 05/25/05 SW846 3510C 8270C-SIM Anthracene 1.8 0.71 2.4 40 ug/L Q 05/25/05 SW846 3510C 8270C-SIM Benzo(a)anthracene 5.5 0.78 2.6 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a)pyrene 7.8 0.72 2.4 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a)pyrene 6.2 0.72 2.4 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 5.6 0.83 2.8 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.6 0.77 2.6 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.88 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.88 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.88 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.88 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.88 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.88 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.88 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.88 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.88 2.3 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.68 2.3 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)anthracene 1.2 0.65 2.2	2-Methylnaphthalene	<	0.91	0.91	3.0		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Anthracene 1.8 0.71 2.4 40 ug/L Q 05/25/05 SW846 3510C 8270C-SIM Benzo(a)anthracene 5.5 0.78 2.6 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a)pyrene 7.8 0.72 2.4 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(b)fluoranthene 6.2 0.72 2.4 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 5.6 0.83 2.8 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.6 0.77 2.6 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L Q& 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.87 0.87 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.89 0.89 3.0 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.89 0.89 3.0 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.6 0.77 2.6 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.5 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.5 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.6 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.5 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.5 0.66 2.2 40 ug/	Acenaphthene	<	0.78	0.78	2.6		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(a) anthracene	Acenaphthylene		2.0	0.77	2.6		40	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene 7.8 0.72 2.4 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(b)fluoranthene 6.2 0.72 2.4 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 5.6 0.83 2.8 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 6.6 0.77 2.6 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Benzo(k)fluoranthene 6.3 0.66 2.2 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Benzo(k)fluoranthene 6.3 0.66 2.2 40 ug/L Q& 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.2 0.88 2.9 40 ug/L Q& 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM	Anthracene		1.8	0.71	2.4		40	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene 6.2 0.72 2.4 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 5.6 0.83 2.8 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Benzo(k)fluoranthene 6.6 0.77 2.6 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Benzo(k)fluoranthene 6.3 0.66 2.2 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Dibenz(a,h)anthracene 1.2 0.88 2.9 40 ug/L Q& 05/25/05 SW846 3510C 8270C-SIM Dibenz(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Benzo(1,2,3-cd)pyrene 4.5 0.68 2.3 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 4.5 0.68 2.3 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 4.5 0.68 2.3 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 4.5 0.68 2.3 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(1,2,3-cd)pyrene 12 0.65 2.2 40 ug/L	Benzo(a)anthracene		5.5	0.78	2.6		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene 5.6 0.83 2.8 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Benzo(k)fluoranthene 6.6 0.77 2.6 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Chrysene 6.3 0.66 2.2 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Dibenz(a,h)anthracene 1.2 0.88 2.9 40 ug/L Q& 05/25/05 SW846 3510C 8270C-SIM Dibenz(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenz(a,h)anthracene 1.3 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenzene 4.5 0.68 2.3 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenzene 4.5 0.68 2.3 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenzene 4.5 0.89 0.89 3.0 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenzene 4.5 0.89 0.89 3.0 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenzene 4.5 0.89 0.89 3.0 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenzene 4.5 0.89 0.89 3.0 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Dibenzene 4.5 0.65 2.2 40 ug/L 05/25/05	Benzo(a)pyrene		7.8	0.72	2.4		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Senzo(ghi)perylene   5.6   0.83   2.8   40   ug/L   & 05/25/05   SW846 3510C   8270C-SIM	Benzo(b)fluoranthene		6.2	0.72	2.4		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Chrysene 6.3 0.66 2.2 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Dibenz(a,h)anthracene 1.2 0.88 2.9 40 ug/L Q& 05/25/05 SW846 3510C 8270C-SIM Pluoranthene 13 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene < 0.87 0.87 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene < 0.87 0.87 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene < 0.89 0.89 3.0 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene < 0.89 0.89 3.0 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 3.7 0.82 2.7 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pleonanthrene 12 0	Benzo(ghi)perylene		5.6	0.83	2.8		40	ug/L	&	05/25/05	SW846 3510C	
Chrysene 6.3 0.66 2.2 40 ug/L & 05/25/05 SW846 3510C 8270C-SIM Dibenz(a,h)anthracene 1.2 0.88 2.9 40 ug/L Q& 05/25/05 SW846 3510C 8270C-SIM Pluoranthene 13 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene < 0.87 0.87 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene < 0.87 0.87 2.9 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene 4.5 0.68 2.3 40 ug/L 8 05/25/05 SW846 3510C 8270C-SIM Pluorene < 0.89 0.89 3.0 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene 3.7 0.82 2.7 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene 3.7 0.82 2.7 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pluorene 14 0 %Recov D 05/25/05	Benzo(k)fluoranthene		6.6	0.77	2.6		40	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene	Chrysene		6.3	0.66	2.2		40	-	&	05/25/05	SW846 3510C	
Fluoranthene 13 0.66 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM 95/25/05 SW846 3510C 8270C-SI	Dibenz(a,h)anthracene		1.2	0.88	2.9		40	ug/L	Q&	05/25/05	SW846 3510C	
Fluorene	Fluoranthene		13	0.66	2.2		40			05/25/05		
Indeno(1,2,3-cd)pyrene       4.5       0.68       2.3       40       ug/L       &       05/25/05       SW846 3510C       8270C-SIM         Naphthalene       < 0.89	Fluorene	<	0.87	0.87	2.9		40	ug/L		05/25/05		
Naphthalene       < 0.89	Indeno(1,2,3-cd)pyrene		4.5	0.68	2.3		40	-	&			
Phenanthrene 3.7 0.82 2.7 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Nitrobenzene-d5 0 40 %Recov D 05/25/05 SW846 3510C 8270C-SIM P-Fluorobiphenyl 0 40 %Recov D 05/25/05 SW846 3510C 8270C-SIM	Naphthalene	<	0.89	0.89	3.0		40	-				
Pyrene 12 0.65 2.2 40 ug/L 05/25/05 SW846 3510C 8270C-SIM Nitrobenzene-d5 0 40 %Recov D 05/25/05 SW846 3510C 8270C-SIM 2-Fluorobiphenyl 0 40 %Recov D 05/25/05 SW846 3510C 8270C-SIM	Phenanthrene		3.7	0.82	2.7			=				
Nitrobenzene-d5 0 40 %Recov D 05/25/05 SW846 3510C 8270C-SIM 0 40 %Recov D 05/25/05 SW846 3510C 8270C-SIM 0 40 %Recov D 05/25/05 SW846 3510C 8270C-SIM	Pyrene		12	0.65	2.2			_				
2-Fluorobiphenyl 0 40 %Recov D 05/25/05 SW846 3510C 8270C-SIM	Nitrobenzene-d5		0				-	•	D			
Family 1. 144	2-Fluorobiphenyl											
TU /01\CCV D U0/Z0/U0 5\WXAD 3510C 82/0C.SIM	Terphenyl-d14		0				40	%Recov	D	05/25/05		8270C-SIM

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-9 Matrix Type: GROUNDWATER

Collection Date : 05/18/05

Report Date : 05/31/05

Lab Sample Number : 859580-005

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene	<	0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform	<	0.94	0.94	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane	<	0.91	0.91	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride	<	0.49	0.49	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform		0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane	_	0.24	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene		0.83	0.83	2.8		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene		0.19	0.03	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane		0.60	0.60	2.0		1			05/24/05	SW846 5030B	
Dichlorodifluoromethane	<	0.99	0.99	3.3		1	ug/L			SW846 5030B	SW846 8260B
	<	0.76	0.76	3.3 2.5			ug/L		05/24/05		SW846 8260B
Diisopropyl Ether		0.76	0.76	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene	<					1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane	<	0.79	0.79	2.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Isopropylbenzene	<	0.59	0.59	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride	<	0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Matrix Type: GROUNDWATER

Project Name: WPSC - MANITOWOC

Collection Date: 05/18/05

Project Number: 1530

Report Date: 05/31/05

Field ID: MW-9

Field ID: MW-9	W-9 Lab Sample Number: 859580-005										
VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Ani Date	Prep Method	Ani Method
n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene	<	0.48	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		87				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
PAH/ PNA										Prep Dat	te: 05/23/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Ani Date	Prep Method	Anl Method
1-Methylnaphthalene	<	0.16	0.16	0.53		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.18	0.18	0.60		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthene	<	0.16	0.16	0.52		8	ug/L		05/24/05	SW846 3510C	8270C-SIM

AH/ PNA							Prep Da	te: 05/23/05			
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Ani Date	Prep Method	Anl Method
1-Methylnaphthalene	<	0.16	0.16	0.53		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.18	0.18	0.60		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthene	<	0.16	0.16	0.52		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthylene		0.19	0.15	0.52		8	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Anthracene		0.29	0.14	0.47		8	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene		0.94	0.16	0.52		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		1.9	0.14	0.48		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		2.5	0.14	0.48		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		2.2	0.17	0.55		8	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene		2.0	0.15	0.51		8	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Chrysene		1.9	0.13	0.44		8	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene		0.45	0.18	0.59		8	ug/L	Q&	05/24/05	SW846 3510C	8270C-SIM
Fluoranthene		3.1	0.13	0.44		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
Fluorene	<	0.17	0.17	0.58		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene		1.7	0.14	0.46		8	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Naphthalene	<	0.18	0.18	0.60		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
Phenanthrene		0.58	0.16	0.54		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
<sup>D</sup> yrene		2.4	0.13	0.43		8	ug/L		05/24/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5		106				8	%Recov		05/24/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl		80				8	%Recov		05/24/05	SW846 3510C	8270C-SIM
Terphenyl-d14		98				8	%Recov		05/24/05	SW846 3510C	8270C-SIM
•											

## **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-10 Matrix Type: GROUNDWATER

Collection Date: 05/18/05
Report Date: 05/31/05
Lab Sample Number: 859580-006

VOLATILES										Prep Da	ite: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0	•	1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene		7.5	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	. <	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane		0.62	0.62	2.1		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene		0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene		0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene		0.82	0.82	2.7		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane		0.97	0.97	3.2		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane		0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform		0.94	0.94	3.1		, 1	ug/L ug/L		05/24/05	SW846 5030B	
Bromomethane		0.91	0.91	3.0		1			05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride		0.49	0.49	1.6		1	ug/L		05/24/05		SW846 8260B
Chlorobenzene		0.49	0.49	1.4		1	ug/L			SW846 5030B	SW846 8260B
Chlorodibromomethane		0.41	0.41	2.7			ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane		0.97	0.81	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform		0.37		ა.∠ 1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
	<		0.37			1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane		0.24	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane	<	0.60	0.60	2.0		1	ug/L 		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether		8.7	0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene		0.54	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane		0.79	0.79	2.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene		0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Isopropylbenzene		0.59	0.59	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride	<	0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether		1.3	0.61	2.0		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
Naphthalene		0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

## **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-10 Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05

Lab Sample Number: 859580-006

VOLATILES										Prep Da	ite: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene	<	0.48	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		85				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		86	-			1_	%Recov		05/24/05	SW846 5030B	SW846 8260B
PAH/ PNA										Prep Dat	te: 05/23/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Ani Date	Prep Method	Anl Method
1-Methylnaphthalene		0.45	0.20	0.66		10	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.23	0.23	0.76		10	ug/L		05/25/05	SW846 3510C	8270C-SIM
Acenaphthene		0.66	0.19	0.65		10	ug/L		05/25/05	SW846 3510C	8270C-SIM
Acenaphthylene		0.70	0.19	0.64		10	ug/L		05/25/05	SW846 3510C	8270C-SIM
Anthracene		0.49	0.18	0.59		10	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene		1.2	0.20	0.65		10	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		2.0	0.18	0.60		10	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		2.3	0.18	0.60		10	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		2.1	0.21	0.69		10	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene		2.0	0.19	0.64		10	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Chrysene		2.1	0.16	0.55		10	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene		0.39	0.22	0.73		10	ug/L	Q&	05/25/05	SW846 3510C	8270C-SIM
Fluoranthene		3.8	0.16	0.55		10	ug/L		05/25/05		8270C-SIM
Fluorene		0.31	0.22	0.73		10	ug/L	Q	05/25/05		8270C-SIM
Indeno(1,2,3-cd)pyrene		1.6	0.17	0.57		10	ug/L	&	05/25/05		8270C-SIM
Naphthalene		0.25	0.22	0.75		10	ug/L	Q	05/25/05		8270C-SIM
Phenanthrene		0.84	0.20	0.68		10	ug/L		05/25/05		8270C-SIM
Pyrene		3.2	0.16	0.54		10	ug/L		05/25/05		8270C-SIM
Nitrobenzene-d5		0.0				10	%Recov	D	05/25/05		8270C-SIM
2-Fluorobiphenyl		0.0				10	%Recov	D	05/25/05		8270C-SIM
Terphenyl-d14		0.0				10	%Recov	D	05/25/05		8270C-SIM

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-12 Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05 Lab Sample Number: 859580-007

VOLATILES							•			Prep Da	ate: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L	<del></del>	05/24/05	SW846 5030B	
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	
1,2-Dibromoethane		0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene		0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane		_	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L ug/L		05/24/05		SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene	<	0.41	0.41	1.4		1				SW846 5030B	SW846 8260B
Bromobenzene	<	0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	0.97	0.97	3.2		1	ug/L		05/24/05 05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane	<	0.56	0.56	1.9		1	ug/L			SW846 5030B	SW846 8260B
Bromoform	· <	0.94	0.94	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane	<	0.91	0.91	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride	<	0.49	0.49	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene		0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane		0.41	0.41	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane		0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform		0.37	0.37	1.2		•	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane						1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene		0.24 0.83	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene		0.03	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane			0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane		0.60	0.60	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
		0.99	0.99	3.3		1	ug/L 		05/24/05	SW846 5030B	SW846 8260B
Diisopropyi Ether		0.76	0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene Fluorotrichloromethane		0.54	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
		0.79	0.79	2.6		1	ug/L		05/24/05		SW846 8260B
Hexachlorobutadiene		0.67	0.67	2.2		1	ug/L		05/24/05		SW846 8260B
Isopropylbenzene Mothylone Chloride		0.59	0.59	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride		0.43	0.43	1.4		1	ug/L		05/24/05		SW846 8260B
Methyl-tert-butyl-ether		0.61	0.61	2.0		1	ug/L				SW846 8260B
Naphthalene		0.74	0.74	2.5		1	ug/L			SW846 5030B	SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L	(	05/24/05	SW846 5030B	SW846 8260B

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-12 Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05

Lab Sample Number: 859580-007

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L	· · · · · · · · · · · · · · · · · · ·	05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene		0.92	0.48	1.6		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8	,	85				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
PAH/ PNA										Prep Dat	te: 05/23/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1-Methylnaphthalene	<	0.80	0.80	2.7	_	40	ug/L	-	05/25/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.91	0.91	3.0		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Acenaphthene	<	0.78	0.78	2.6		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Acenaphthylene	<	0.77	0.77	2.6		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Anthracene	<	0.71	0.71	2.4		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene		4.5	0.78	2.6		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		9.5	0.72	2.4		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		11	0.72	2.4		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		11	0.83	2.8		40	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene		10	0.77	2.6		40	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Chrysene		8.9	0.66	2.2		40	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene		2.2	0.88	2.9		40	ug/L	Q&	05/25/05	SW846 3510C	8270C-SIM
Fluoranthene		13	0.66	2.2		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Fluorene	<	0.87	0.87	2.9		40	ug/L		05/25/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene		8.3	0.68	2.3		40	ug/L	&	05/25/05		8270C-SIM
Naphthalene	<	0.89	0.89	3.0		40	ug/L		05/25/05		8270C-SIM
Phenanthrene		2.5	0.82	2.7		40	ug/L	Q	05/25/05		8270C-SIM
Pyrene		10	0.65	2.2		40	ug/L	-	05/25/05		8270C-SIM
Nitrobenzene-d5		0				40	%Recov	D	05/25/05		8270C-SIM
2-Fluorobiphenyl		0				40	%Recov	D	05/25/05		8270C-SIM
Terphenyl-d14		0				40	%Recov	D	05/25/05		8270C-SIM
• •								_	55/25/05	511040 00 10C	OZ I OO-OHVI

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-12D Matrix Type: GROUNDWATER

Collection Date: 05/18/05
Report Date: 05/31/05
Lab Sample Number: 859580-008

VOLATILES										Prep Da	ate: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L ug/L		05/24/05	SW846 5030B	
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene		2.3	0.41	1.4		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene	<	0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	0.97	0.97	3.2		1	ug/L ug/L		05/24/05		SW846 8260B
Bromodichloromethane		0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform		0.94	0.94	3.1		1	ug/L ug/L		05/24/05	SW846 5030B SW846 5030B	SW846 8260B
Bromomethane		0.91	0.91	3.0		1	ug/L		05/24/05		SW846 8260B
Carbon Tetrachloride	<	0.49	0.49	1.6		1	_			SW846 5030B	SW846 8260B
Chlorobenzene		0.43	0.43	1.4		1	ug/L		05/24/05 05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane		0.81	0.81	2.7		1	ug/L			SW846 5030B	SW846 8260B
Chloroethane		0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform		0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane	<					-	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene		0.24 0.83	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene			0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane		0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane		0.60	0.60	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
		0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether		0.76	0.76	2.5		1	ug/L		05/24/05		SW846 8260B
Ethylbenzene		0.54	0.54	1.8		1	ug/L		05/24/05		SW846 8260B
Fluorotrichloromethane		0.79	0.79	2.6		1	ug/L		05/24/05		SW846 8260B
Hexachlorobutadiene		0.67	0.67	2.2		1	ug/L		05/24/05		SW846 8260B
Isopropylbenzene		0.59	0.59	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride		0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether		0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene		0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

## **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-12D Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05

Lab Sample Number: 859580-008

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene		1.3	0.89	3.0		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene		1.7	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		85				1	%Recov		05/24/05	SW846 5030B	SW846 8260B

PAH/ PNA										Prep Da	te: 05/23/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1-Methylnaphthalene		0.10	0.080	0.27		4	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.091	0.091	0.30		4	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthene	<	0.078	0.078	0.26		4	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthylene		0.11	0.077	0.26		4	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Anthracene	<	0.071	0.071	0.24		4	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene		0.45	0.078	0.26		4	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		0.84	0.072	0.24		4	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		1.2	0.072	0.24		4	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		1.0	0.083	0.28		4	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene		0.88	0.077	0.26		4	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Chrysene		0.80	0.066	0.22		4	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene		0.22	0.088	0.29		4	ug/L	Q&	05/24/05	SW846 3510C	8270C-SIM
Fluoranthene		1.1	0.066	0.22		4	ug/L		05/24/05	SW846 3510C	8270C-SIM
Fluorene	<	0.087	0.087	0.29		4	ug/L		05/24/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene		0.80	0.068	0.23		4	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Naphthalene		0.50	0.089	0.30		4	ug/L		05/24/05	SW846 3510C	8270C-SIM
Phenanthrene		0.21	0.082	0.27		4	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Pyrene		0.80	0.065	0.22		4	ug/L	-	05/24/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5		121				4	%Recov		05/24/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl		94				4	%Recov		05/24/05	SW846 3510C	8270C-SIM
Terphenyl-d14		89				4	%Recov		05/24/05	SW846 3510C	8270C-SIM

# **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-13 Matrix Type: GROUNDWATER

Collection Date: 05/18/05
Report Date: 05/31/05
Lab Sample Number: 859580-009

VOLATILES										Prep Da	nte: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
1,1,1,2-Tetrachloroethane	<	18	18	61		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	18	18	60		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	4.0	4.0	13		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	8.4	8.4	28		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	15	15	50		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	11	11	38		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	15	15	50		20	ug/L		05/24/05	SW846 5030B	
1,2,3-Trichlorobenzene	<	15	15	49		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	20	20	66		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	19	19	65		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene		110	19	65		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	17	17	58		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	11	11	37		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	17	17	55		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	7.2	7.2	24		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	9.2	9.2	31		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene		28	17	55		20	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	17	17	58		20	ug/L	~	05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	12	12	41		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	19	19	63		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	12	12	41		20	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	17	17	57		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	15	15	49		20	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene		270	8.2	27		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene	<	16	16	55		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	19	19	65		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane	<	11	11	37		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform	<	19	19	63		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane	<	18	18	61		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride	<	9.8	9.8	33		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene	<	8.2	8.2	27		20	ug/L		05/24/05	SW846 5030B	
Chlorodibromomethane	<	16	16	54		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane	<	19	19	65		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform		7.4	7.4	25		20	ug/L ug/L		05/24/05		SW846 8260B
Chloromethane	<	4.8	4.8	16		20	-			SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene	<	17	17	55		20	ug/L ug/L		05/24/05 05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene	<	3.8	3.8	13		20	ug/L		05/24/05	SW846 5030B SW846 5030B	SW846 8260B
Dibromomethane	<	12	12	40		20			05/24/05		SW846 8260B
Dichlorodifluoromethane		20	20	66			ug/L			SW846 5030B	SW846 8260B
Diisopropyl Ether		15	15	51		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene	`	670	11	36		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane	<	16	16	53		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene	<	13				20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Isopropylbenzene	`	37	13	45 20		20	ug/L	•	05/24/05		SW846 8260B
• • •			12	39		20	ug/L	Q	05/24/05		SW846 8260B
Methylene Chloride		8.6	8.6	29		20	ug/L		05/24/05		SW846 8260B
Methyl-tert-butyl-ether	<	12	12	41		20	ug/L 		05/24/05		SW846 8260B
Naphthalene	_	1800	15	49		20	ug/L		05/24/05		SW846 8260B
N-Butylbenzene	<	19	19	62		20	ug/L		05/24/05	SW846 5030B	SW846 8260B

### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530

Field ID: MW-13

Matrix Type: GROUNDWATER

Collection Date: 05/18/05

Report Date: 05/31/05

Lab Sample Number: 859580-009

VOLATILES										Prep Da	ite: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
n-Propylbenzene	<	16	16	54		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	13	13	45		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	18	18	59		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	17	17	57		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	19	19	65		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	9.0	9.0	30		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene		17	13	45		20	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	18	18	59		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	3.8	3.8	13		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene	<	9.6	9.6	32		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	3.6	3.6	12		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o		310	17	55		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p		220	36	120		20	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		85				20	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		85				20	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		86				20	%Recov		05/24/05	SW846 5030B	SW846 8260B
PAH/ PNA							-			Prep Dat	te: 05/23/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
1-Methylnaphthalene		190	50	170		2500	ug/L	D	05/25/05	SW846 3510C	8270C-SIM
O 8 8 11 1 1 1 1 1 1								_			

PAH/ PNA										Prep Da	te: 05/23/05
Analyte		Result	LOD	LOQ	EQL	ĐiI.	Units	Code	Anl Date	Prep Method	Ani Method
1-Methylnaphthalene		190	50	170		2500	ug/L	D	05/25/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene		66	57	190		2500	ug/L	QD	05/25/05	SW846 3510C	8270C-SIM
Acenaphthene		51	48	160		2500	ug/L	QD	05/25/05	SW846 3510C	8270C-SIM
Acenaphthylene		4.5	1.9	6.4		100	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM
Anthracene	<	1.8	1.8	5.9		100	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene	<	2.0	2.0	6.5		100	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene	<	1.8	1.8	6.0		100	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene	<	1.8	1.8	6.0		100	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene	<	2.1	2.1	6.9		100	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene	<	1.9	1.9	6.4		100	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Chrysene	<	1.6	1.6	5.5		100	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene	<	2.2	2.2	7.3		100	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Fluoranthene		2.0	1.6	5.5		100	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM
Fluorene		3.5	2.2	7.3		100	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene	<	1.7	1.7	5.7		100	ug/L	&	05/25/05	SW846 3510C	8270C-SIM
Naphthalene		920	56	190		2500	ug/L	D	05/25/05	SW846 3510C	8270C-SIM
Phenanthrene	<	2.0	2.0	6.8		100	ug/L		05/25/05	SW846 3510C	8270C-SIM
Pyrene	<	1.6	1.6	5.4		100	ug/L		05/25/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5		0				100	%Recov	D	05/25/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl		0				100	%Recov	D	05/25/05	SW846 3510C	8270C-SIM
Terphenyl-d14		0				100	%Recov	D	05/25/05	SW846 3510C	8270C-SIM

### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

**Client: NATURAL RESOURCE TECHNOLOGY** 

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-17T Matrix Type: GROUNDWATER

VOLATILES										Prep Da	ite: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene	<	0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	-
Bromodichloromethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform		0.94	0.94	3.1		1	ug/L		05/24/05		SW846 8260B
Bromomethane		0.91	0.91	3.0		1				SW846 5030B	SW846 8260B
Carbon Tetrachloride		0.49	0.49	1.6			ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene	`	0.49	0.49	1.4		1 1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane							ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
		0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform		0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane		0.24	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	
cis-1,2-Dichloroethene		0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene		0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane		0.60	0.60	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane		0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether		0.76	0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene		0.54	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane		0.79	0.79	2.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene		0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Isopropylbenzene	<	0.59	0.59	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride		0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

Dibromofluoromethane

#### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

84

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-17T Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05

Lab Sample Number: 859580-010

**VOLATILES** Prep Date: 05/24/05 **Analyte** Result LOD LOQ **EQL** Dil. Units **Anl Date Ani Method** Code Prep Method 0.81 2.7 1 n-Propvlbenzene 0.81 ua/L 05/24/05 SW846 5030B SW846 8260B p-Isopropyitoluene < 0.67 0.67 2.2 1 ug/L 05/24/05 SW846 5030B SW846 8260B sec-Butylbenzene < 0.89 0.89 3.0 1 ug/L 05/24/05 SW846 5030B SW846 8260B 0.86 2.9 Styrene < 0.86 1 ug/L 05/24/05 SW846 5030B SW846 8260B tert-Butvlbenzene 0.97 0.97 < 3.2 1 ug/L 05/24/05 SW846 5030B SW846 8260B Tetrachloroethene 0.45 0.45 1.5 ug/L 05/24/05 < 1 SW846 5030B SW846 8260B Toluene 0.67 0.67 2.2 1 ug/L 05/24/05 SW846 5030B SW846 8260B trans-1,2-Dichloroethene < 0.89 0.89 3.0 1 ug/L 05/24/05 SW846 5030B SW846 8260B trans-1,3-Dichloropropene 0.19 0.19 0.63 ug/L 05/24/05 1 SW846 5030B SW846 8260B Trichloroethene 89 0.48 1.6 1 ug/L 05/24/05 SW846 5030B SW846 8260B Vinyl Chloride 0.60 1 < 0.18 0.18 ug/L 05/24/05 SW846 5030B SW846 8260B Xylene, o 0.83 0.83 2.8 1 ug/L 05/24/05 SW846 5030B SW846 8260B Xylenes, m + p 1.8 1.8 6.0 1 ug/L 05/24/05 SW846 5030B SW846 8260B 4-Bromofluorobenzene 83 1 %Recov 05/24/05 SW846 5030B SW846 8260B Toluene-d8 1 SW846 8260B 86 %Recov 05/24/05 SW846 5030B

1

%Recov

05/24/05

SW846 5030B

SW846 8260B

PAH/ PNA										Prep Da	te: 05/23/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
1-Methylnaphthalene	<	0.020	0.020	0.066		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.023	0.023	0.076		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthene	<	0.019	0.019	0.065		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthylene	<	0.019	0.019	0.064		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Anthracene	<	0.018	0.018	0.059		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene	<	0.020	0.020	0.065		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		0.030	0.018	0.060		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		0.032	0.018	0.060		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		0.031	0.021	0.069		1	ug/L	Q&	05/24/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene		0.030	0.019	0.064		1	ug/L	Q&	05/24/05	SW846 3510C	8270C-SIM
Chrysene		0.026	0.016	0.055		1	ug/L	Q&	05/24/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene	<	0.022	0.022	0.073		1	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Fluoranthene		0.037	0.016	0.055		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Fluorene	<	0.022	0.022	0.073		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene		0.024	0.017	0.057		1	ug/L	Q&	05/24/05	SW846 3510C	8270C-SIM
Naphthalene		0.046	0.022	0.075		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Phenanthrene	<	0.020	0.020	0.068		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Pyrene		0.033	0.016	0.054		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5		111				1	%Recov		05/24/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl		84				1	%Recov		05/24/05	SW846 3510C	8270C-SIM
Ferphenyl-d14		96				1	%Recov		05/24/05	SW846 3510C	8270C-SIM

### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-18T Matrix Type: GROUNDWATER

VOLATILES	•								-	Prep Da	ite: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Ani Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1	<del></del> -	1	ug/L	<del></del>	05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	
1,3-Dichloropropane		0.61	0.61	2.0		1	_		05/24/05		SW846 8260B
1,4-Dichlorobenzene		0.95	0.95	3.2		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane		0.62	0.62	2.1		1			05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene		0.85	0.85	2.1		1	ug/L			SW846 5030B	SW846 8260B
4-Chlorotoluene		0.74	0.83	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene		0.74	0.74	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene		0.82	0.41	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane		0.82	0.82	3.2		-	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane		0.56	0.56	3.2 1.9		1 1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform		0.94	0.94	3.1		-	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane		0.94				1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride			0.91	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
	<	0.49	0.49	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane	<	0.81	0.81	2.7		1	ug/L 		05/24/05	SW846 5030B	SW846 8260B
Chloroethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform		0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane	<	0.24	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene	<	0.83	0.83	2.8		1	ug/L	•	05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene		0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane		0.60	0.60	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane		0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether		0.76	0.76	2.5		1	ug/L		05/24/05		SW846 8260B
Ethylbenzene		0.54	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane		0.79	0.79	2.6		1	ug/L		05/24/05		SW846 8260B
Hexachlorobutadiene		0.67	0.67	2.2		1	ug/L		05/24/05		SW846 8260B
Isopropylbenzene		0.59	0.59	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride		0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether		0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-18T Matrix Type: GROUNDWATER

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
p-Isopropyitoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene		56	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		85				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B

PAH/ PNA						Prep Dat			te: 05/23/05		
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1-Methylnaphthalene	<	0.020	0.020	0.066		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.023	0.023	0.076		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthene	<	0.019	0.019	0.065		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthylene	<	0.019	0.019	0.064		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Anthracene	<	0.018	0.018	0.059		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene	<	0.020	0.020	0.065		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		0.019	0.018	0.060		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		0.022	0.018	0.060		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene	<	0.021	0.021	0.069		1	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene	<	0.019	0.019	0.064		1	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Chrysene		0.019	0.016	0.055		1	ug/L	Q&	05/24/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene	<	0.022	0.022	0.073		1	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Fluoranthene		0.030	0.016	0.055		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Fluorene	<	0.022	0.022	0.073		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene	<	0.017	0.017	0.057		1	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Naphthalene	<	0.022	0.022	0.075		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Phenanthrene	<	0.020	0.020	0.068		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Pyrene		0.025	0.016	0.054		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5		108				1	%Recov		05/24/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl		85				1	%Recov		05/24/05	SW846 3510C	8270C-SIM
Terphenyl-d14		89				1	%Recov		05/24/05	SW846 3510C	8270C-SIM

### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-19T Matrix Type: GROUNDWATER

VOLATILES								_		Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene		0.95	0.95	3.2		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene		0.85	0.85	2.8		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene	<	0.74	0.74	1.4		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene		0.82	0.82	2.7		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane		0.97	0.02	3.2		1			05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane		0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform		0.94	0.94	3.1		1	ug/L				
Bromomethane			0.94	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
	<	0.91	0.49	1.6			ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride		0.49				1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene	<	0.41	0.41	1.4 2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane	<	0.81	0.81			1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorosophana		0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane	<	0.24	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	
cis-1,2-Dichloroethene		3.6	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene		0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane	<	0.60	0.60	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether	<	0.76	0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene	<	0.54	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane	<	0.79	0.79	2.6		1	ug/L		05/24/05		SW846 8260B
Hexachlorobutadiene	<	0.67	0.67	2.2		1	ug/L		05/24/05		SW846 8260B
Isopropylbenzene	<	0.59	0.59	2.0		1	ug/L		05/24/05		SW846 8260B
Methylene Chloride	<	0.43	0.43	1.4		1	ug/L		05/24/05		SW846 8260B
Methyl-tert-butyl-ether	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene	<	0.74	0.74	2.5		1	ug/L		05/24/05		SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

**VOLATILES** 

#### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Prep Date: 05/24/05

Matrix Type: GROUNDWATER

Collection Date: 05/18/05

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530

Report Date: 05/31/05 Field ID: MW-19T Lab Sample Number: 859580-012

trans-1,3-Dichloropropene	Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
Sec-Butylbenzene	n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
terl-Butylbenzene	sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene         85         0.48         1.6         1         ug/L         05/24/05         SW846 5030B         SW846 8260B           Vinyl Chloride         < 0.18         0.18         0.60         1         ug/L         05/24/05         SW846 5030B         SW846 8260B           Xylene, o         < 0.83         0.83         2.8         1         ug/L         05/24/05         SW846 5030B         SW846 8260B           Xylenes, m + p         < 1.8         1.8         6.0         1         ug/L         05/24/05         SW846 5030B         SW846 8260B           4-Bromofluorobenzene         88         1         6.0         1         %Recov         05/24/05         SW846 5030B         SW846 8260B           Dibromofluoromethane         86         1         %Recov         05/24/05         SW846 5030B         SW846 8260B           PAH/ PNA         ************************************	trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride         < 0.18         0.18         0.60         1         ug/L         05/24/05         SW846 5030B         SW846 8260B           Xylene, o         < 0.83         0.83         2.8         1         ug/L         05/24/05         SW846 5030B         SW846 8260B           Xylenes, m + p         < 1.8         1.8         6.0         1         ug/L         05/24/05         SW846 5030B         SW846 8260B           4-Bromofluorobenzene         88         .         1         %Recov         05/24/05         SW846 5030B         SW846 8260B           Toluene-d8         86         .         1         %Recov         05/24/05         SW846 5030B         SW846 8260B           Dibromofluoromethane         84         .         1         %Recov         05/24/05         SW846 5030B         SW846 8260B           PAH/ PNA         ***********************************	trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o         < 0.83         0.83         2.8         1         ug/L         05/24/05         SW846 5030B         SW846 8260B           Xylenes, m + p         < 1.8         1.8         6.0         1         ug/L         05/24/05         SW846 5030B         SW846 8260B           A-Bromoffluorobenzene         88         1         %Recov         05/24/05         SW846 5030B         SW846 8260B           Dibromoffluoromethane         86         1         %Recov         05/24/05         SW846 5030B         SW846 8260B           PAH/ PNA         Frep Date: 05/23/05           Analyte         Result         LOD         LOQ         EQL         DII.         Units         Code         AnI Date         Prep Method         AnI Method           1-Methylnaphthalene         < 0.020	Trichloroethene		85	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene 88	Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8 86	Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
PAH/ PNA   Prop   Patro   Prop	4-Bromofluorobenzene		88				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
PAH/ PNA         Result         LOD         LOQ         EQL         Dil.         Units         Code         AnI Date         Prep Date:         05/23/05           Analyte         Result         LOD         LOQ         EQL         Dil.         Units         Code         AnI Date         Prep Method         Ani Method           1-Methylnaphthalene         < 0.020	Toluene-d8		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Analyte         Result         LOD         LOQ         EQL         Dil.         Units         Code         Anl Date         Prep Method         Anl Method           1-Methylnaphthalene         < 0.020	Dibromofluoromethane		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
1-Methylnaphthalene	PAH/ PNA										Prep Dat	te: 05/23/05
2-Methylnaphthalene	Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
Acenaphthene          0.019         0.019         0.065         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Acenaphthylene         0.040         0.019         0.064         1         ug/L         Q         05/24/05         SW846 3510C         8270C-SIM           Anthracene         0.026         0.018         0.059         1         ug/L         Q         05/24/05         SW846 3510C         8270C-SIM           Benzo(a)anthracene         0.10         0.020         0.065         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Benzo(a)pyrene         0.17         0.018         0.060         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Benzo(b)fluoranthene         0.21         0.018         0.060         1         ug/L         &         05/24/05         SW846 3510C         8270C-SIM           Benzo(k)fluoranthene         0.16         0.019         0.064         1         ug/L         &         05/24/05         SW846 3510C         8270C-SIM           Chrysene         0.14         0.016         0.055         1         ug/L         &         05/24/05         SW846 3510C         8270C-SIM <td>1-Methylnaphthalene</td> <td>&lt;</td> <td>0.020</td> <td>0.020</td> <td>0.066</td> <td></td> <td>1</td> <td>ug/L</td> <td></td> <td>05/24/05</td> <td>SW846 3510C</td> <td>8270C-SIM</td>	1-Methylnaphthalene	<	0.020	0.020	0.066		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthylene 0.040 0.019 0.064 1 ug/L Q 05/24/05 SW846 3510C 8270C-SIM Anthracene 0.026 0.018 0.059 1 ug/L Q 05/24/05 SW846 3510C 8270C-SIM Benzo(a)anthracene 0.10 0.020 0.065 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Benzo(a)pyrene 0.17 0.018 0.060 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Benzo(b)fluoranthene 0.21 0.018 0.060 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 0.20 0.021 0.069 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 0.20 0.021 0.069 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM Benzo(k)fluoranthene 0.16 0.019 0.064 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM Benzo(k)fluoranthene 0.14 0.016 0.055 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM Dibenz(a,h)anthracene 0.041 0.022 0.073 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM Fluoranthene 0.24 0.016 0.055 1 ug/L 0.05/24/05 SW846 3510C 8270C-SIM Benzo(1,2,3-cd)pyrene 0.16 0.017 0.057 1 ug/L 0.05/24/05 SW846 3510C 8270C-SIM Indeno(1,2,3-cd)pyrene 0.16 0.017 0.057 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM Phenanthrene 0.069 0.022 0.075 1 ug/L 0.05/24/05 SW846 3510C 8270C-SIM Phenanthrene 0.075 0.020 0.068 1 ug/L 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 ug/L 0.05/24/05 SW846 3510C 8270C-SIM Nitrobenzene-d5 107 1 wg/L 0.05/24/05 SW846 3510C 8270C-SIM	2-Methylnaphthalene	<	0.023	0.023	0.076		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Anthracene 0.026 0.018 0.059 1 ug/L Q 05/24/05 SW846 3510C 8270C-SIM Benzo(a)anthracene 0.10 0.020 0.065 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Benzo(a)pyrene 0.17 0.018 0.060 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Benzo(b)fluoranthene 0.21 0.018 0.060 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Benzo(ghi)perylene 0.20 0.021 0.069 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM Benzo(k)fluoranthene 0.16 0.019 0.064 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM Benzo(k)fluoranthene 0.16 0.019 0.064 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM Benzo(k)fluoranthene 0.14 0.016 0.055 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM Dibenz(a,h)anthracene 0.041 0.022 0.073 1 ug/L Q8 05/24/05 SW846 3510C 8270C-SIM Fluoranthene 0.24 0.016 0.055 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Benzo(1,2,3-cd)pyrene 0.16 0.017 0.057 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM Phenanthrene 0.069 0.022 0.075 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM Phenanthrene 0.075 0.020 0.068 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Nitrobenzene-d5 107 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Nitrobenzene-d5 107 1 wg/L 05/24/05 SW846 3510C 8270C-SIM PRecov 05/24/05 SW846 3510C 8270C-SIM 8270C-SIM Precov 05/24/05 SW846 3510C 8270C-SIM 827	Acenaphthene	<	0.019	0.019	0.065		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene         0.10         0.020         0.065         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Benzo(a)pyrene         0.17         0.018         0.060         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Benzo(ghi)perylene         0.21         0.018         0.060         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Benzo(ghi)perylene         0.20         0.021         0.069         1         ug/L         & 05/24/05         SW846 3510C         8270C-SIM           Benzo(ghi)perylene         0.16         0.019         0.064         1         ug/L         & 05/24/05         SW846 3510C         8270C-SIM           Benzo(k)fluoranthene         0.16         0.019         0.064         1         ug/L         & 05/24/05         SW846 3510C         8270C-SIM           Chrysene         0.14         0.016         0.055         1         ug/L         & 05/24/05         SW846 3510C         8270C-SIM           Dibenz(a,h)anthracene         0.041         0.022         0.073         1         ug/L         Q\$         05/24/05         SW846 3510C         8270C-SIM           Fluoranthene         0.041	Acenaphthylene		0.040	0.019	0.064		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene         0.17         0.018         0.060         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Benzo(b)fluoranthene         0.21         0.018         0.060         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Benzo(ghi)perylene         0.20         0.021         0.069         1         ug/L         & 05/24/05         SW846 3510C         8270C-SIM           Benzo(k)fluoranthene         0.16         0.019         0.064         1         ug/L         & 05/24/05         SW846 3510C         8270C-SIM           Chrysene         0.14         0.016         0.055         1         ug/L         & 05/24/05         SW846 3510C         8270C-SIM           Dibenz(a,h)anthracene         0.041         0.022         0.073         1         ug/L         Q& 05/24/05         SW846 3510C         8270C-SIM           Fluoranthene         0.24         0.016         0.055         1         ug/L         Q         05/24/05         SW846 3510C         8270C-SIM           Fluorene         < 0.022	Anthracene		0.026	0.018	0.059		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene         0.21         0.018         0.060         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Benzo(ghi)perylene         0.20         0.021         0.069         1         ug/L         &         05/24/05         SW846 3510C         8270C-SIM           Benzo(k)fluoranthene         0.16         0.019         0.064         1         ug/L         &         05/24/05         SW846 3510C         8270C-SIM           Chrysene         0.14         0.016         0.055         1         ug/L         &         05/24/05         SW846 3510C         8270C-SIM           Dibenz(a,h)anthracene         0.041         0.022         0.073         1         ug/L         Q&         05/24/05         SW846 3510C         8270C-SIM           Fluoranthene         0.24         0.016         0.055         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Fluorene         < 0.022	Benzo(a)anthracene		0.10	0.020	0.065		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene         0.20         0.021         0.069         1         ug/L         & 05/24/05         SW846 3510C         8270C-SIM           Benzo(k)fluoranthene         0.16         0.019         0.064         1         ug/L         & 05/24/05         SW846 3510C         8270C-SIM           Chrysene         0.14         0.016         0.055         1         ug/L         & 05/24/05         SW846 3510C         8270C-SIM           Dibenz(a,h)anthracene         0.041         0.022         0.073         1         ug/L         Q& 05/24/05         SW846 3510C         8270C-SIM           Fluoranthene         0.24         0.016         0.055         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Fluorene         < 0.022	Benzo(a)pyrene		0.17	0.018	0.060		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene         0.16         0.019         0.064         1         ug/L         &         05/24/05         SW846 3510C         8270C-SIM           Chrysene         0.14         0.016         0.055         1         ug/L         &         05/24/05         SW846 3510C         8270C-SIM           Dibenz(a,h)anthracene         0.041         0.022         0.073         1         ug/L         Q&         05/24/05         SW846 3510C         8270C-SIM           Fluoranthene         0.24         0.016         0.055         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Fluorene          0.022         0.073         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Indeno(1,2,3-cd)pyrene         0.16         0.017         0.057         1         ug/L         &         05/24/05         SW846 3510C         8270C-SIM           Naphthalene         0.069         0.022         0.075         1         ug/L         Q         05/24/05         SW846 3510C         8270C-SIM           Phenanthrene         0.075         0.020         0.068         1         ug/L         05/24/05         SW846 3510C         8270C-SIM	Benzo(b)fluoranthene		0.21	0.018	0.060		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Chrysene         0.14         0.016         0.055         1         ug/L         &         05/24/05         SW846 3510C         8270C-SIM           Dibenz(a,h)anthracene         0.041         0.022         0.073         1         ug/L         Q&         05/24/05         SW846 3510C         8270C-SIM           Fluoranthene         0.24         0.016         0.055         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Fluorene         < 0.022	Benzo(ghi)perylene		0.20	0.021	0.069		1	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene         0.041         0.022         0.073         1         ug/L         Q&         05/24/05         SW846 3510C         8270C-SIM           Fluoranthene         0.24         0.016         0.055         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Fluorene         < 0.022	Benzo(k)fluoranthene		0.16	0.019	0.064		1	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Fluoranthene 0.24 0.016 0.055 1 ug/L 05/24/05 SW846 3510C 8270C-SIM 1 ug/L 05/24/05 SW846 3510C 8270C-SIM 0.022 0.022 0.073 1 ug/L 05/24/05 SW846 3510C 8270C-SIM 0.024 0.016 0.017 0.057 1 ug/L 8 05/24/05 SW846 3510C 8270C-SIM 0.00000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.00000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.00000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.000	Chrysene		0.14	0.016	0.055		1	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Fluorene < 0.022 0.022 0.073 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Indeno(1,2,3-cd)pyrene 0.16 0.017 0.057 1 ug/L & 05/24/05 SW846 3510C 8270C-SIM Naphthalene 0.069 0.022 0.075 1 ug/L Q 05/24/05 SW846 3510C 8270C-SIM Phenanthrene 0.075 0.020 0.068 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Nitrobenzene-d5 107 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 ug/L 05/24/05 SW846 3510C 8270C-SIM Nitrobenzene-d5 107 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Nitrobenzene-d5 107 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.20 0.016 0.054 1 wg/L 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.05/24/05 SW846 3510C 8270C-SIM Pyrene 0.05/24/05 SW846 3510C 8270C-SI	Dibenz(a,h)anthracene		0.041	0.022	0.073		1	ug/L	Q&	05/24/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene         0.16         0.017         0.057         1         ug/L         &         05/24/05         SW846 3510C         8270C-SIM           Naphthalene         0.069         0.022         0.075         1         ug/L         Q         05/24/05         SW846 3510C         8270C-SIM           Phenanthrene         0.075         0.020         0.068         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Pyrene         0.20         0.016         0.054         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Nitrobenzene-d5         107         1         %Recov         05/24/05         SW846 3510C         8270C-SIM           2-Fluorobiphenyl         79         1         %Recov         05/24/05         SW846 3510C         8270C-SIM	Fluoranthene		0.24	0.016	0.055		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Naphthalene         0.069         0.022         0.075         1         ug/L         Q         05/24/05         SW846 3510C         8270C-SIM           Phenanthrene         0.075         0.020         0.068         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Pyrene         0.20         0.016         0.054         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Nitrobenzene-d5         107         1         %Recov         05/24/05         SW846 3510C         8270C-SIM           2-Fluorobiphenyl         79         1         %Recov         05/24/05         SW846 3510C         8270C-SIM	Fluorene	<	0.022	0.022	0.073		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Phenanthrene         0.075         0.020         0.068         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Pyrene         0.20         0.016         0.054         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Nitrobenzene-d5         107         1         %Recov         05/24/05         SW846 3510C         8270C-SIM           2-Fluorobiphenyl         79         1         %Recov         05/24/05         SW846 3510C         8270C-SIM	Indeno(1,2,3-cd)pyrene		0.16	0.017	0.057		1	ug/L	&	05/24/05	SW846 3510C	8270C-SIM
Phenanthrene         0.075         0.020         0.068         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Pyrene         0.20         0.016         0.054         1         ug/L         05/24/05         SW846 3510C         8270C-SIM           Nitrobenzene-d5         107         1         %Recov         05/24/05         SW846 3510C         8270C-SIM           2-Fluorobiphenyl         79         1         %Recov         05/24/05         SW846 3510C         8270C-SIM	Naphthalene		0.069	0.022	0.075		1			05/24/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5       107       1       %Recov       05/24/05       SW846 3510C       8270C-SIM         2-Fluorobiphenyl       79       1       %Recov       05/24/05       SW846 3510C       8270C-SIM	Phenanthrene		0.075	0.020	0.068		1			05/24/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5       107       1       %Recov       05/24/05       SW846 3510C       8270C-SIM         2-Fluorobiphenyl       79       1       %Recov       05/24/05       SW846 3510C       8270C-SIM	Pyrene		0.20	0.016	0.054		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl 79 1 %Recov 05/24/05 SW846 3510C 8270C-SIM	Nitrobenzene-d5		107				1			05/24/05		
	2-Fluorobiphenyl		79				1	%Recov		05/24/05		
	Terphenyl-d14		76				1	%Recov		05/24/05	SW846 3510C	

### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-20T Matrix Type: GROUNDWATER

VOLATILES										Prep Da	nte: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1	-	1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene		0.85	0.85	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene		0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene		0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene		0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform	<	0.94	0.94	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane	<	0.91	0.91	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride	<	0.49	0.49	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform	<	0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane		0.24	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene		30	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane		0.60	0.60	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane		0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether		0.76	0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene		0.54	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane		0.79	0.79	2.6		1	ug/L		05/24/05		SW846 8260B
Hexachlorobutadiene		0.67	0.67	2.2		1	ug/L		05/24/05		SW846 8260B
Isopropylbenzene		0.59	0.59	2.0		1	ug/L ug/L		05/24/05		
Methylene Chloride		0.43	0.43	1.4		1	ug/L ug/L		05/24/05		SW846 8260B
Methyl-tert-butyl-ether		0.43	0.43	2.0		1			05/24/05 05/24/05		SW846 8260B
Naphthalene		0.74	0.74	2.5		1	ug/L		05/24/05 05/24/05		SW846 8260B
N-Butylbenzene		0.74	0.74	3.1		1	ug/L				SW846 8260B
A Datylochizerie	`	0.53	0.53	J. I		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

**Client: NATURAL RESOURCE TECHNOLOGY** 

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-20T Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05

Lab Sample Number: 859580-013

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene		90	0.48	1.6		1	ug/L	4	05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		85				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B

PAH/ PNA										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Ani Date	Prep Method	Anl Method
1-Methylnaphthalene	<	0.020	0.020	0.066		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.023	0.023	0.076		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthene	<	0.019	0.019	0.065		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthylene	<	0.019	0.019	0.064		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Anthracene	<	0.018	0.018	0.059		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene	<	0.020	0.020	0.065		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		0.027	0.018	0.060		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		0.035	0.018	0.060		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		0.029	0.021	0.069		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene		0.027	0.019	0.064		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Chrysene		0.029	0.016	0.055		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene	<	0.022	0.022	0.073		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Fluoranthene		0.046	0.016	0.055		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Fluorene	<	0.022	0.022	0.073		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene		0.022	0.017	0.057		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Naphthalene		0.039	0.022	0.075		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Phenanthrene		0.023	0.020	0.068		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Pyrene		0.037	0.016	0.054		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5		112				1	%Recov		05/24/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl		85				1	%Recov		05/24/05	SW846 3510C	8270C-SIM
Terphenyl-d14		94				1	%Recov		05/24/05	SW846 3510C	8270C-SIM

### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY Matrix Type: GROUNDWATER

Project Name: WPSC - MANITOWOC

Project Number: 1530

Field ID: MW-21T

Collection Date: 05/18/05

Report Date: 05/31/05

Lab Sample Number: 859580-014

VOLATILES										Prep Da	te: 05/24/05
Analyte	< 0.92		LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene	<	0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform	<	0.94	0.94	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane	<	0.91	0.91	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride	<	0.49	0.49	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform	<	0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane	<	0.24	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene		38	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane	<	0.60	0.60	2.0		1 .	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether	<	0.76	0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene	<	0.54	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane	<	0.79	0.79	2.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Isopropylbenzene	<	0.59	0.59	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride	<	0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
N-Butylbenzene		0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
,						•					

### Analytical Report Number: 859580

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: MW-21T Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05

Lab Sample Number: 859580-014

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene		54	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		85				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		86				1	%Recov	<del></del>	05/24/05	SW846 5030B	SW846 8260B

PAH/ PNA										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
1-Methylnaphthalene		0.030	0.020	0.066		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.023	0.023	0.076		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthene		0.18	0.019	0.065		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Acenaphthylene		0.75	0.048	0.16		2.5	ug/L	Ð	05/25/05	SW846 3510C	8270C-SIM
Anthracene	<	0.018	0.018	0.059		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene		0.049	0.020	0.065		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		0.11	0.018	0.060		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		0.12	0.018	0.060		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		0.15	0.021	0.069		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene		0.11	0.019	0.064		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Chrysene		0.092	0.016	0.055		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene		0.031	0.022	0.073		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Fluoranthene		0.15	0.016	0.055		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Fluorene		0.068	0.022	0.073		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene		0.11	0.017	0.057		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Naphthalene		0.049	0.022	0.075		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Phenanthrene		0.059	0.020	0.068		1	ug/L	Q	05/24/05	SW846 3510C	8270C-SIM
Pyrene		0.11	0.016	0.054		1	ug/L		05/24/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5		108				1	%Recov		05/24/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl		78				1	%Recov		05/24/05	SW846 3510C	8270C-SIM
Terphenyl-d14		86				1	%Recov		05/24/05	SW846 3510C	8270C-SIM

### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: QC-1 Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05

Lab Sample Number: 859580-015

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene		5.3	0.41	1.4		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene	<	0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane		0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane		0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform		0.94	0.94	3.1		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane		0.91	0.91	3.0		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride		0.49	0.49	1.6		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene		0.49	0.43	1.4		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
		0.41	0.41	2.7		1	_		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane				3.2			ug/L				
Chloroethane	<	0.97	0.97			1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform		0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane	< .	0.24	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L 		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane	<	0.60	0.60	2.0		1	ug/L 		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether	<	0.76	0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene	<	0.54	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane	<	0.79	0.79	2.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Isopropylbenzene		1.2	0.59	2.0		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride	<	0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

Terphenyl-d14

99

### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530

Field ID: QC-1

Matrix Type: GROUNDWATER

Collection Date: 05/18/05 Report Date: 05/31/05

Lab Sample Number: 859580-015

05/26/05 SW846 3510C 8270C-SIM

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene		1.5	0.89	3.0		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene		1.6	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		82				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
PAH/ PNA										Prep Dat	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1-Methylnaphthalene	<	0.10	0.10	0.33		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.11	0.11	0.38		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Acenaphthene	<	0.097	0.097	0.32		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Acenaphthylene		0.12	0.097	0.32		5	ug/L	Q	05/26/05	SW846 3510C	8270C-SIM
Anthracene	<	0.088	0.088	0.29		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene		0.51	0.098	0.33		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		0.94	0.091	0.30		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		1.2	0.089	0.30		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		1.0	0.10	0.34		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Benzo(k)fluoranthene		1.1	0.097	0.32		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Chrysene		0.93	0.082	0.27		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Dibenz(a,h)anthracene		0.21	0.11	0.37		5	ug/L	Q	05/26/05	SW846 3510C	8270C-SIM
Fluoranthene		1.1	0.082	0.27		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Fluorene	<	0.11	0.11	0.36		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Indeno(1,2,3-cd)pyrene		0.81	0.085	0.28		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Naphthalene	<	0.11	0.11	0.37		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Phenanthrene		0.25	0.10	0.34		5	ug/L	Q	05/26/05	SW846 3510C	8270C-SIM
Pyrene		0.97	0.081	0.27		5	ug/L		05/26/05	SW846 3510C	8270C-SIM
Nitrobenzene-d5		96				5	%Recov		05/26/05	SW846 3510C	8270C-SIM
2-Fluorobiphenyl		80				5	%Recov		05/26/05	SW846 3510C	8270C-SIM
						_					

%Recov

Analytical Report Number: 859580

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Matrix Type: GROUNDWATER

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: QC-2 **Report Date**: 05/31/05 **Lab Sample Number**: 859580-016

Collection Date: 05/18/05

VOLATILES							•			Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Ani Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene		4.3	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene	<	0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform	<	0.94	0.94	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane	<	0.91	0.91	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride	<	0.49	0.49	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform		0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane	<	0.24	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene	<	0.83	0.83	2.8		1	ug/L ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane		0.60	0.60	2.0		1			05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane		0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
		0.76	0.76	2.5		1	ug/L				
Diisopropyl Ether	`	37	0.76	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene	<	0.79	0.79	2.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane							ug/L		05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Isopropylbenzene	_	4.0	0.59	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride		0.43	0.43	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether		0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene		0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

Benzo(k)fluoranthene

Dibenz(a,h)anthracene

Indeno(1,2,3-cd)pyrene

Chrysene

Fluorene

Pyrene

Fluoranthene

Naphthalene

Phenanthrene

Nitrobenzene-d5

2-Fluorobiphenyl

Terphenyl-d14

#### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY Matrix Type: GROUNDWATER

Project Name: WPSC - MANITOWOC

Project Number: 1530

Field ID: QC-2

Collection Date: 05/18/05

Report Date: 05/31/05

Lab Sample Number: 859580-016

Fleid ID: QC-2							Li	ab Sample	Number: 85958	0-016	
VOLATILES		•								Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
n-Propylbenzene		2.0	0.81	2.7		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
p-lsopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene		0.94	0.67	2.2		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene		47	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o		2.4	0.83	2.8		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		85				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		85				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
PAH/ PNA										Prep Dat	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Ani Method
1-Methylnaphthalene		7.2	0.42	1.4		20	ug/L		05/25/05	SW846 3510C	8270C-SIM
2-Methylnaphthalene	<	0.48	0.48	1.6		20	ug/L		05/25/05	SW846 3510C	8270C-SIM
Acenaphthene		2.9	0.41	1.4		20	ug/L		05/25/05	SW846 3510C	8270C-SIM
Acenaphthylene		2.0	0.41	1.4		20	ug/L		05/25/05	SW846 3510C	8270C-SIM
Anthracene		0.39	0.38	1.3		20	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM
Benzo(a)anthracene		1.5	0.42	1.4		20	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(a)pyrene		1.5	0.39	1.3		20	ug/L		05/25/05	SW846 3510C	8270C-SIM
Benzo(b)fluoranthene		1.2	0.38	1.3		20	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM
Benzo(ghi)perylene		0.88	0.44	1.5		20	ug/L	Q	05/25/05	SW846 3510C	8270C-SIM

20

20

20

20

20

20

20

20

20

20

20

20

ug/L

ug/L

ug/L

ug/L

ug/L

ug/L

ug/L

ug/L

ug/L

%Recov

%Recov

%Recov

05/25/05

05/25/05

05/25/05

05/25/05

05/25/05

05/25/05

05/25/05

05/25/05

05/25/05

05/25/05

05/25/05

05/25/05

Q

Q

Q

Q

D

D

D

SW846 3510C 8270C-SIM

1.4

1.9

3.4

0.47

0.68

0.54

1.2

3.7

0

0

0

< 0.47

0.41

0.35

0.47

0.35

0.46

0.36

0.48

0.43

0.35

1.4

1.2

1.6

1.2

1.5

1.2

1.6

1.4

1.2

#### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Matrix Type: WATER

Collection Date: 05/18/05

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530 Field ID: TB Report Date: 05/31/05
Lab Sample Number: 859580-017

VOLATILES					· · ·	_				Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
1,1,1,2-Tetrachloroethane	<	0.92	0.92	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,1-Trichloroethane	<	0.90	0.90	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2,2-Tetrachloroethane	<	0.20	0.20	0.67		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1,2-Trichloroethane	<	0.42	0.42	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethane	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloroethene	<	0.57	0.57	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,1-Dichloropropene	<	0.75	0.75	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichlorobenzene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,3-Trichloropropane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trichlorobenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2,4-Trimethylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromo-3-chloropropane	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dibromoethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichlorobenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloroethane	<	0.36	0.36	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,2-Dichloropropane	<	0.46	0.46	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3,5-Trimethylbenzene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichlorobenzene	<	0.87	0.87	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,3-Dichloropropane	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
1,4-Dichlorobenzene	<	0.95	0.95	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2,2-Dichloropropane	<	0.62	0.62	2.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
2-Chlorotoluene	<	0.85	0.85	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Chlorotoluene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Benzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromobenzene	<	0.82	0.82	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromochloromethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromodichloromethane	<	0.56	0.56	1.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromoform	<	0.94	0.94	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Bromomethane	<	0.91	0.91	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Carbon Tetrachloride	<	0.49	0.49	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorobenzene	<	0.41	0.41	1.4		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chlorodibromomethane	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroethane	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloroform	<	0.37	0.37	1.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Chloromethane	<	0.24	0.24	0.80		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,2-Dichloroethene	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
cis-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dibromomethane	<	0.60	0.60	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Dichlorodifluoromethane	<	0.99	0.99	3.3		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Diisopropyl Ether	<	0.76	0.76	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Ethylbenzene	<	0.54	0.54	1.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Fluorotrichloromethane	<	0.79	0.79	2.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Hexachlorobutadiene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Isopropylbenzene	<	0.59	0.59	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Methylene Chloride		0.58	0.43	1.4		1	ug/L	Q	05/24/05	SW846 5030B	SW846 8260B
Methyl-tert-butyl-ether	<	0.61	0.61	2.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Naphthalene	<	0.74	0.74	2.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
N-Butylbenzene	<	0.93	0.93	3.1		1	ug/L		05/24/05	SW846 5030B	SW846 8260B

#### **Analytical Report Number: 859580**

1241 Bellevue Street Green Bay, WI 54302 920-469-2436

Client: NATURAL RESOURCE TECHNOLOGY

Project Name: WPSC - MANITOWOC

Project Number: 1530

Field ID: TB

Matrix Type: WATER

Collection Date: 05/18/05

Report Date: 05/31/05

Lab Sample Number: 859580-017

VOLATILES										Prep Da	te: 05/24/05
Analyte		Result	LOD	LOQ	EQL	Dil.	Units	Code	Anl Date	Prep Method	Anl Method
n-Propylbenzene	<	0.81	0.81	2.7		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
p-Isopropyltoluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
sec-Butylbenzene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Styrene	<	0.86	0.86	2.9		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
tert-Butylbenzene	<	0.97	0.97	3.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Tetrachloroethene	<	0.45	0.45	1.5		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Toluene	<	0.67	0.67	2.2		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,2-Dichloroethene	<	0.89	0.89	3.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
trans-1,3-Dichloropropene	<	0.19	0.19	0.63		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Trichloroethene	<	0.48	0.48	1.6		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Vinyl Chloride	<	0.18	0.18	0.60		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylene, o	<	0.83	0.83	2.8		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
Xylenes, m + p	<	1.8	1.8	6.0		1	ug/L		05/24/05	SW846 5030B	SW846 8260B
4-Bromofluorobenzene		84				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Toluene-d8		86				1	%Recov		05/24/05	SW846 5030B	SW846 8260B
Dibromofluoromethane		85				1	%Recov		05/24/05	SW846 5030B	SW846 8260B

#### **Qualifier Codes**

are evaluated on a sample basis.  B Inorganic  The analyte has been detected between the method detection limit and the reporting limit.  Crganic  Crganic  Analyte is present in the method blank. Method blank criteria is evaluated to the laboratory method detection limit. Additions method blank acceptance may be based on project specific oriteria or determined from analyte concentrations in the sample are evaluated on a sample by sample basis.  Elevated detection limit.  Analyte value from diluted analysis or surrogate result not applicable due to sample dilution.  Estimated concentration due to matrix interferences. During the metals analysis the serial dilution failed to meet the establish of the control limits of 10°10%. The sample concentration is greater than 50 times the IDL for analysis done on the ICP-MS. The result was flagged with the E qualifier to indicate that a physical interference can be considered.  Analyte concentration exceeds calibration range.  Forganic  Forganic  Granic  Granic Analysis done on the ICP-MS. The result was flagged with the E qualifier to indicate that a physical interference for this analysis by fluductively Coupled Plasma techniques (SW-846 Method 6010), this analysis been confirmed by and reported from an alternate method.  Forganic Due to potential interferences for this analysis by fluductively Coupled Plasma techniques (SW-846 Method 6010), this analysis been confirmed by and reported from an alternate method.  Forganic The result is estimated because the concentration is less than the lowest calibration standard concentration utilized in the interior detection of the project.  Free results is estimated because the concentration is less than the proporting limit specified for this project.  All Concentration detected equal to or greater than the method detection limit is less than the reporting limit specified for this project.  All Concentration detected a field parameter, and the recommended holding time.  Free results is unconditional to the sample variety of the pre			Explanation
Analyte is present in the method blank. Method bank criteria is evaluated to the laboratory method detection limit. Additiona method blank acceptance may be based on project specific criteria or determined from analyte concentrations in the sample are evaluated on a sample by sample basis.  All Elevated detection limit.  Analyte value from diluted analysis or surrogate result not applicable due to sample dilution.  Estimated concentration due to matrix interferences. During the metals analysis the serial dilution failed to meet the establist control limits of 0-10%. The sample concentration is greater than 50 times the IDL for analysis done on the ICP-0r 100 times in IDL for analysis done on the ICP-0r 100 times i	1	Inorganic	method blank acceptance may be based on project specific criteria or determined from analyte concentrations in the sample and
method blank acceptance may be based on project specific criteria or determined from analyte concentrations in the sample are evaluated on a sample by aspire basing the sample hasis.  All Elevated detection limit.  Estimated concentration due to matrix interferences. During the metals analysis the serial dilution failed to meet the establist control limits of 0-10%. The sample concentration is greater than 50 times the IDL for analysis done on the ICP or 100 times in 10. For analysis done on the ICP or 100 times observed.  Organic Analyte concentration exceeds calibration range.  Organic Due to potential interferences for this analysis by Inductively Coupled Plasma techniques (SW-846 Method 6010), this analytic bean confirmed by and reported from an alternate method.  Surrogate results outside control criteria.  All The result is estimated because the concentration is less than the lowest calibration standard concentration utilized in the initicalibration. The method detection limit is less than the reporting limit specified for this project.  All Preservation, extraction or analysis performed past holding time.  Inorganic Inorganic Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.  Concentration detected equal to or greater than the method detection limit but less than the reporting limit.  Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.  Detection limit may be elevated due to the presence of an unrequested analyte.  Elevated detection limit due to low sample volume.  All Spiked sample recovery not within control limits.  Sample received overweight.  The relative percent difference between the timit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  Organic The relative percent difference between the limit of detection columns exceeds internal quality control criteria.  All Inadequate	В	Inorganic	The analyte has been detected between the method detection limit and the reporting limit.
Analyte value from diluted analysis or surrogate result not applicable due to sample dilution.  Inorganic Estimated concentration due to matrix interferences. During the metals analysis the serial dilution failed to meet the establist control limits of 10%. The sample concentration is greater than 50 times the IDL for analysis done on the ICP or 100 times IDL for analysis done on the ICP	В	Organic	Analyte is present in the method blank. Method blank criteria is evaluated to the laboratory method detection limit. Additionally, method blank acceptance may be based on project specific criteria or determined from analyte concentrations in the sample and are evaluated on a sample by sample basis.
Estimated concentration due to matrix inforferences. During the metals analysis the serial dilution failed to meet the establish control limits of 0-10%. The sample concentration is greater than 50 times the IDL for analysis done on the ICP-MS. The result was flagged with the E qualifier to indicate that a physical interference was observed.  Progranic Analyte concentration exceeds calibration range.  Due to potential interferences for this analysis by Inductively Coupled Plasma techniques (SW-946 Method 6010), this analytic been confirmed by and reported from an alternate method.  Gall The result is estimated because the concentration is less than the lowest calibration standard concentration utilized in the initicalibration. The method detection limit is less than the reporting limit specified for this project.  Hall Preservation, extraction or analysis performed past holding time.  J All Preservation, extraction or analysis performed past holding time.  J All Concentration detected equal to or greater than the method detection limit but less than the reporting limit.  Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.  Detection limit may be elevated due to the presence of an unrequested analyte.  Elevated detection limit due to low sample volume.  All Spiked sample received overweight.  Porganic Sample private prevent difference between the two columns for detected concentrations was greater than 40%.  The analyte has been detected between the him of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  All The reality percent difference between the work of the range.  All The reality percent difference between the firm of detected concentrations was greater than 40%.  The analyte was not detected at or above the reporting limit.  All The analyte was not detected at or above the reporting limit.  All The analyte was not detected at or above the reporting li	С	All	Elevated detection limit.
control limits of 0-10%. The sample concentration is greater than 50 times the IDL for analysis done on the ICP or 100 times observed.  Forganic Dict or analysis done on the ICP D-MS. The result was flagged with the E qualifier to indicate that a physical interference was observed.  Forganic Due to potential interferences for this analysis by Inductively Coupled Plasma techniques (SW-846 Method 6010), this analyte been confirmed by and reported from an alternate method.  Forganic Surrogate results outside control criteria.  G All The result is estimated because the concentration is less than the lowest calibration standard concentration utilized in the initialization. The method detection limit is less than the reporting limit specified for this project.  H All Preservation, extraction or analysis performed past holding time.  This test is considered a field parameter, and the recommended holding time is 15 minutes from collection. The analysis was performed in the laboratory beyond the recommended holding time.  K Inorganic All Concentration detected equal to or greater than the method detection limit but less than the reporting limit.  Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.  Detection limit may be elevated due to the presence of an unrequested analyte.  Elevated detection limit due to low sample volume.  Sample pH was greater than 2  Spiked sample received overweight.  The relative percent difference between the two columns for detected concentrations was greater than 40%.  The analyte has been detected between the limit of detected concentrations was greater than 40%.  The analyte has been detected between the limit of detected concentration columns exceeds internal quality control criteria. Becauther result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  The analyte was not detected at or above the reporting limit.  All The analyte was not detected at or above the reporting limit.  All Prec	D	Ail	Analyte value from diluted analysis or surrogate result not applicable due to sample dilution.
Findings and the potential interferences for this analysis by Inductively Coupled Plasma techniques (SW-846 Method 6010), this analysis been confirmed by and reported from an alternate method.  Findings and reported from an alternate method.  Graph Corganic  Graph Corganic  Graph Corganic  All The result is estimated because the concentration is less than the lowest calibration standard concentration utilized in the initicalibration. The method detection limit is less than the reporting limit specified for this project.  He All Preservation, extraction or analysis performed past holding time.  Her Inorganic  This test is considered a field parameter, and the recommended holding time is 15 minutes from collection. The analysis was performed in the laboratory beyond the recommended holding time.  All Concentration detected equal to or greater than the method detection limit but less than the reporting limit.  Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.  Detection limit may be elevated due to the presence of an unrequested analyte.  Elevated detection limit due to low sample volume.  Sample preceived volume received unpreserved. Sample was either presence of an unrequested analyte.  Elevated detection limit due to low sample volume.  Sample ph was greater than 2  All Spiked sample recovery not within control limits.  Sample received overweight.  Presalve percent difference between the two columns for detected concentrations was greater than 40%.  The nalyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauther result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  Indigentation of the result is unconfirmed, it has been reported as a non-detect with an	E	Inorganic	,
been confirmed by and reported from an alternate method.  For Organic Surrogate results outside control criteria.  All The result is estimated because the concentration is less than the lowest calibration standard concentration utilized in the init calibration. The method detection limit is less than the reporting limit specified for this project.  Here and the preservation, extraction or analysis performed past holding time.  This test is considered a field parameter, and the recommended holding time is 15 minutes from collection. The analysis was performed in the laboratory beyond the recommended holding time.  J All Concentration detected equal to or greater than the method detection limit but less than the reporting limit.  K Inorganic Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.  Detection limit may be elevated due to the presence of an unrequested analyte.  Elevated detection limit due to low sample volume.  M Organic Sample PH was greater than 2  N All Spiked sample recovery not within control limits.  Sample received overweight.  The relative percent difference between the two columns for detected concentrations was greater than 40%.  The relative percent difference between the limit of detection (LOD) and limit of quantitation (LOD). The results are qualified to the uncertainty of analyte concentrations within this range.  S Organic The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauth the result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  Inadequate sample volume received to perform the method required MS/MSD.  All Inadequate sample volume received to perform the method required MS/MSD.  All Sample received with headspace.  All Ascond aliquot of sample was analyzed from a container with headspace.  All Fersion not within control limits.  All Precision not within control limits.  Inorganic Dissolved analyte or fil	E	Organic	Analyte concentration exceeds calibration range.
The result is estimated because the concentration is less than the lowest calibration standard concentration utilized in the initial calibration. The method detection limit is less than the reporting limit specified for this project.  H All Preservation, extraction or analysis performed past holding time.  Inorganic This test is considered a field parameter, and the recommended holding time is 15 minutes from collection. The analysis was performed in the laboratory beyond the recommended holding time.  J All Concentration detected equal to or greater than the method detection limit but less than the reporting limit.  K Inorganic Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.  Detection limit may be elevated due to the presence of an unrequested analyte.  Elevated detection limit due to low sample volume.  M Organic Sample PH was greater than 2  N All Spiked sample recovery not within control limits.  Sample received overweight.  The relative percent difference between the two columns for detected concentrations was greater than 40%.  The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  S Organic The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauther essult is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  T All Inadequate sample volume received to perform the method required MS/MSD.  All Sample received with headspace.  All The analyte was not detected at or above the reporting limit.  Sample received with headspace.  All See Sample Narrative.  All Precision not within control limits.  Precision not within control limits.  Precision not within control limits.  Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  BOD Desult is estimat	F	Inorganic	Due to potential interferences for this analysis by Inductively Coupled Plasma techniques (SW-846 Method 6010), this analyte habeen confirmed by and reported from an alternate method.
calibration. The method detection limit is less than the reporting limit specified for this project.  Preservation, extraction or analysis performed past holding time.  This test is considered a field parameter, and the recommended holding time is 15 minutes from collection. The analysis was performed in the laboratory beyond the recommended holding time.  Concentration detected equal to or greater than the method detection limit but less than the reporting limit.  Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.  Detection limit may be elevated due to the presence of an unrequested analyte.  L All Elevated detection limit due to low sample volume.  Sample ph was greater than 2  Spiked sample recoevery not within control limits.  Organic Sample received overweight.  P Organic Sample received overweight.  The relative percent difference between the two columns for detected concentrations was greater than 40%.  The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  Organic The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauther result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  Inadequate sample volume received to perform the method required MS/MSD.  All The analyte was not detected at or above the reporting limit.  Sample received with headspace.  All As econd aliquot of sample was analyzed from a container with headspace.  All As econd aliquot of sample was analyzed from a container with headspace.  All Laboratory Control Spike recovery not within control limits.  Precision not within control limits.  The analyte was not detected at or above the reporting limit.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  BOD Dre	F	Organic	Surrogate results outside control criteria.
HF Inorganic This test is considered a field parameter, and the recommended holding time is 15 minutes from collection. The analysis was performed in the laboratory beyond the recommended holding time.  J All Concentration detected equal to or greater than the method detection limit but less than the reporting limit.  K Inorganic Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.  K Organic Detection limit may be elevated due to the presence of an unrequested analyte.  Elevated detection limit due to low sample volume.  Sample pH was greater than 2  N All Spiked sample received overweight.  Organic Sample peceived overweight.  Organic Sample received overweight.  The relative percent difference between the two columns for detected concentrations was greater than 40%.  The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  Organic The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauther result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  Inadequate sample volume received to perform the method required MS/MSD.  All Inequality and the headspace.  All Ascond aliquot of sample was analyzed from a container with headspace.  All Ascond aliquot of sample was analyzed from a container with headspace.  All Precision not within control limits.  All Precision not within control limits.  The analyte was not detected at or above the reporting limit.  Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and ty to correct the	G	All	The result is estimated because the concentration is less than the lowest calibration standard concentration utilized in the initial calibration. The method detection limit is less than the reporting limit specified for this project.
performed in the laboratory beyond the recommended holding time.  Concentration detected equal to or greater than the method detection limit but less than the reporting limit.  Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.  Detection limit may be elevated due to the presence of an unrequested analyte.  Elevated detection limit due to low sample volume.  Sample PH was greater than 2  Spiked sample received overweight.  Organic Sample received overweight.  Porganic The relative percent difference between the two columns for detected concentrations was greater than 40%.  The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  Organic The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becaute result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  Inadequate sample volume received to perform the method required MS/MSD.  The analyte was not detected at or above the reporting limit.  All Sample received with headspace.  All A second aliquot of sample was analyzed from a container with headspace.  All Laboratory Control Spike recovery not within control limits.  All Precision not within control limits.  All Precision not within control limits.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to correct percent oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to	Н	All	Preservation, extraction or analysis performed past holding time.
K Inorganic Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.  K Organic Detection limit may be elevated due to the presence of an unrequested analyte.  Elevated detection limit due to low sample volume.  Sample preparation.  Sample precived within control limits.  Precision of detected between the two columns for detected concentrations within this range.  Sample preparation presults are qualified to the uncertainty of detected on function (LOO) and limit of quantitation (LOO).  The relative precent difference between the	HF	Inorganic	This test is considered a field parameter, and the recommended holding time is 15 minutes from collection. The analysis was performed in the laboratory beyond the recommended holding time.
K Organic Detection limit may be elevated due to the presence of an unrequested analyte.  L All Elevated detection limit due to low sample volume.  Sample pH was greater than 2  Spiked sample recovery not within control limits.  Organic Sample received overweight.  P Organic The relative percent difference between the two columns for detected concentrations was greater than 40%.  All The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  S Organic The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauther result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  Inadequate sample volume received to perform the method required MS/MSD.  All Ineanlyte was not detected at or above the reporting limit.  All Sample received with headspace.  W All A second aliquot of sample was analyzed from a container with headspace.  See Sample Narrative.  All Laboratory Control Spike recovery not within control limits.  All Precision not within control limits.  All The analyte was not detected at or above the reporting limit.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  ROD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanal	J	All	Concentration detected equal to or greater than the method detection limit but less than the reporting limit.
L All Elevated detection limit due to low sample volume.  M Organic Sample pH was greater than 2  N All Spiked sample recovery not within control limits.  O Organic Sample received overweight.  P Organic The relative percent difference between the two columns for detected concentrations was greater than 40%.  Q All The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  S Organic The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauther result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  I All Inadequate sample volume received to perform the method required MS/MSD.  I The analyte was not detected at or above the reporting limit.  Sample received with headspace.  W All Sample received with headspace.  W All See Sample Narrative.  All Laboratory Control Spike recovery not within control limits.  All Precision not within control limits.  All Precision not within control limits.  I Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen	K	Inorganic	Sample received unpreserved. Sample was either preserved at the time of receipt or at the time of sample preparation.
M Organic Sample pH was greater than 2 N All Spiked sample recovery not within control limits. O Organic Sample received overweight. P Organic The relative percent difference between the two columns for detected concentrations was greater than 40%. All The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range. S Organic The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauther result is unconfirmed, it has been reported as a non-detect with an elevated detection limit. I Inadequate sample volume received to perform the method required MS/MSD. U All Inadequate sample volume received to perform the method required MS/MSD. W All Sample received with headspace. W All Sample received with headspace. W All Asecond aliquot of sample was analyzed from a container with headspace. W All See Sample Narrative. All Precision not within control limits. All Precision not within control limits. All Precision not within control limits. Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria. Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria. BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion. BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency. BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency. BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency. BOD result is estimated due to complete oxygen depletion. Due to the 48 hour ho	K	Organic	Detection limit may be elevated due to the presence of an unrequested analyte.
N All Spiked sample recovery not within control limits. O Organic Sample received overweight. P Organic The relative percent difference between the two columns for detected concentrations was greater than 40%. The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range. S Organic The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauther result is unconfirmed, it has been reported as a non-detect with an elevated detection limit. Inadequate sample volume received to perform the method required MS/MSD. U All Inadequate sample volume received to perform the method required MS/MSD. W All Sample received with headspace. W All Sample received with headspace. W All See Sample Narrative. W All A second aliquot of sample was analyzed from a container with headspace. W All Laboratory Control Spike recovery not within control limits. W All Precision not within control limits. W All Precision not within control limits. W All Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria. Unorganic Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria. Unorganic BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion. Unorganic BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency. W BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency. W BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency. W BOD result is estimated due to complete oxygen depleti	L	All	Elevated detection limit due to low sample volume.
O Organic Sample received overweight.  P Organic The relative percent difference between the two columns for detected concentrations was greater than 40%.  The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauther result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  Inadequate sample volume received to perform the method required MS/MSD.  The analyte was not detected at or above the reporting limit.  Sample received with headspace.  All Sample received with headspace.  All A second aliquot of sample was analyzed from a container with headspace.  All Laboratory Control Spike recovery not within control limits.  All Precision not within control limits.  All Precision not within control limits.  All Precision not within control limits.  Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test	M	Organic	Sample pH was greater than 2
The relative percent difference between the two columns for detected concentrations was greater than 40%.  The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauther result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  Inadequate sample volume received to perform the method required MS/MSD.  All Inadequate sample volume received to perform the method required MS/MSD.  All Sample received with headspace.  All Sample received with headspace.  All A second aliquot of sample was analyzed from a container with headspace.  All Laboratory Control Spike recovery not within control limits.  All Precision not within control limits.  All Precision not within control limits.  All The analyte was not detected at or above the reporting limit.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the	N	All	Spiked sample recovery not within control limits.
The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified to the uncertainty of analyte concentrations within this range.  The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauthe result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  Inadequate sample volume received to perform the method required MS/MSD.  The analyte was not detected at or above the reporting limit.  Sample received with headspace.  All Sample received with headspace.  All See Sample Narrative.  All Laboratory Control Spike recovery not within control limits.  All Precision not within control limits.  All Precision not within control limits.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  Inorganic BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.	0	Organic	Sample received overweight.
to the uncertainty of analyte concentrations within this range.  Organic The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Becauther result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  Inadequate sample volume received to perform the method required MS/MSD.  Inadequate sample volume received to perform the method required MS/MSD.  Inadequate sample volume received to perform the method required MS/MSD.  Inadequate sample volume received to perform the method required MS/MSD.  Inadequate sample volume received to perform the method required MS/MSD.  Inadequate sample volume received to perform the method required MS/MSD.  Inadequate sample volume received to perform the method required MS/MSD.  Inadequate sample volume received with headspace.  Inadequate sample volume received to perform the method required MS/MSD.  Inadequate sample volume received to perform the method required MS/MSD.  Inadequate sample volume received to perform the method required MS/MSD.  Inadequate sample volume received with an elevated detected MS/MSD.  Inadequate sample volume received with an elevated desease on percision criteria.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  Inorganic BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  Inorganic BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  Inorganic BOD result is estimated due to oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  Inorganic BOD result is estimated due to complete o	Р	Organic	The relative percent difference between the two columns for detected concentrations was greater than 40%.
the result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.  Inadequate sample volume received to perform the method required MS/MSD.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  In analyte received with headspace.  In a second aliquot of sample was analyzed from a container with headspace.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  In analyte was not detected at or above the reporting limit.  Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze at try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.	Q	All	The analyte has been detected between the limit of detection (LOD) and limit of quantitation (LOQ). The results are qualified due to the uncertainty of analyte concentrations within this range.
The analyte was not detected at or above the reporting limit.  All Sample received with headspace.  All A second aliquot of sample was analyzed from a container with headspace.  All Laboratory Control Spike recovery not within control limits.  All Precision not within control limits.  All Precision not within control limits.  All The analyte was not detected at or above the reporting limit.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  Inorganic BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanal dry to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanal dry to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanal dry to correct the deficiency.	S	Organic	The relative percent difference between quantitation and confirmation columns exceeds internal quality control criteria. Because the result is unconfirmed, it has been reported as a non-detect with an elevated detection limit.
Sample received with headspace.  All A second aliquot of sample was analyzed from a container with headspace.  All See Sample Narrative.  All Laboratory Control Spike recovery not within control limits.  All Precision not within control limits.  All The analyte was not detected at or above the reporting limit.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.	Т	All	Inadequate sample volume received to perform the method required MS/MSD.
All A second aliquot of sample was analyzed from a container with headspace.  See Sample Narrative.  All Laboratory Control Spike recovery not within control limits.  All Precision not within control limits.  All The analyte was not detected at or above the reporting limit.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze at try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to	U	All	The analyte was not detected at or above the reporting limit.
All Laboratory Control Spike recovery not within control limits.  * All Precision not within control limits.  * All Precision not within control limits.  * All Dissolved analyte was not detected at or above the reporting limit.  1 Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  2 Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.  3 Inorganic BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  4 Inorganic BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze at try to correct the deficiency.  5 Inorganic BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  6 Inorganic BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  7 Inorganic BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.	V	All	Sample received with headspace.
Laboratory Control Spike recovery not within control limits.  All Precision not within control limits.  All The analyte was not detected at or above the reporting limit.  Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  Inorganic BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze at try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.	W	All	A second aliquot of sample was analyzed from a container with headspace.
Precision not within control limits.  All The analyte was not detected at or above the reporting limit.  Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze at try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanal dry to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanal and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to	X	Ali	See Sample Narrative.
The analyte was not detected at or above the reporting limit.  Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze at try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.	&	All	Laboratory Control Spike recovery not within control limits.
Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.  Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze at try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to	*	All	Precision not within control limits.
Inorganic Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.  BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze at try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to	<	All	The analyte was not detected at or above the reporting limit.
BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.  BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze at try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to	1	Inorganic	Dissolved analyte or filtered analyte greater than total analyte; analyses passed QC based on precision criteria.
Inorganic BOD duplicate precision not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze at try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze at try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to	2	Inorganic	Dissolved analyte or filtered analyte greater than total analyte; analyses failed QC based on precision criteria.
try to correct the deficiency.  BOD result is estimated due to insufficient oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to	3	Inorganic	BOD result is estimated due to the BOD blank exceeding the allowable oxygen depletion.
reanalyze and try to correct the deficiency.  BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reana and try to correct the deficiency.  BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to	4	Inorganic	
and try to correct the deficiency.  7 Inorganic BOD result is estimated due to complete oxygen depletion. Due to the 48 hour holding time for this test, it is not practical to	5	Inorganic	reanalyze and try to correct the deficiency.
	5	Inorganic	BOD laboratory control sample not within control limits. Due to the 48 hour holding time for this test, it is not practical to reanalyze and try to correct the deficiency.
	7	Inorganic	

Pace Ana	lytical
Services,	Inc.

### Analysis Summary by Laboratory

1241 Bellevue Street Green Bay, WI 54302

Test Group Name	859580-001	859580-002	859580-003	859580-004	859580-005	859580-006	859580-007	859580-008	859580-009	859580-010	859580-011	859580-012	859580-013	859580-014	859580-015	859580-016	859580-017	
PAH/ PNA	В	В	В	В	В	В	В	В	В	В	В	В	В	В	В	В		
VOLATILES	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	

Code	Facility	Address	WI Certification
В	Green Bay Lab (Bellevue St)	1241 Bellevue Street, Suite 9 Green Bay, WI 54302	405132750 / DATCP: 105-444
G	Green Bay Lab (Industrial Dr)	1795 Industrial Drive Green Bay, WI 54302	405132750

### En Chem, Inc. Cooler Receipt Log

Batch No. 859580	En Chem, II	nc. Cooler Receipt	Log	
Project Name or ID_WIS		No. of Coolers:	Temps:	1201
•	er was opened: 5-20-05	By: AB	nemps.	
	ice? (Must be $\leq$ 6 C )	$\overline{}$	NO <sup>2</sup>	NA
2. Was there a Temperature E	Blank?	YES	<b>(6)</b>	
3: Were custody seals presen	t and intact on cooler? (Record on CO	C)YES	<b>(</b> €)	
4: Are COC documents present	nt?	(Es	NO <sup>2</sup>	
5: Does this Project require qu	ick turn around analysis?	YES	$\odot$	
6: Is there any sub-work?		YES	(NO)	
7: Are there any short hold time	e tests?	YES	NO	
8: Are any samples nearing ex	xpiration of hold-time? (Within 2 days)	YES <sup>1</sup>	$\bigcirc$	Contacted by/Who
9: Do any samples need to be	Filtered or Preserved in the lab?		MO)	Contacted by/Who
B. Check-in Phase: Date sam	ples were Checked-in: $6-20$	)-05 <sub>By: AB</sub>		
1: Were all sample containers	listed on the COC received and intact?	<b>(</b> È\$)	NO <sup>2</sup>	NA
2: Sign the COC as received b	y En Chem. Completed	ES	NO	
3: Do sample labels match the	COC?		NO <sup>2</sup>	
	served samples		NO	(NA)
5: Do samples have correct ch	ply to water: VOC, O&G, TOC, DRO, emical preservation?	YES	NO <sup>2</sup>	NA)
(This statement does not ap 6: Are dissolved parameters field	ply to water: VOC, O&G, TOC, DRO, eld filtered?	Total Rec. Phenolics)YES	NO <sup>2</sup>	NA
7: Are sample volumes adequa	ate for tests requested?	YES	NO <sup>2</sup>	
8: Are VOC samples free of bu	bbles >6mm	XES	$NO^2$	NA
9: Enter samples into logbook.	Completed	KES	NO	
10: Place laboratory sample nu	umber on all containers and COC. Cor	npletedE\$	NO	
11: Complete Laboratory Track	ring Sheet (LTS). Completed	YES	NO	
12: Start Nonconformance form	n	YES	NO	
13: Initiate Subcontracting prod	cedure. Completed	YES	NO	NA)
14: Check laboratory sample n	umber on all containers and COC	C(S/W YES)	NO	NA
Short Hold-time tests:		,		
24 Hours or less	48 Hours	7 days		Footnotes
Coliform Corrosivity = pH	BOD Color	Ash Adusous Extractable Ordan	ICS-ALL	1 Notify proper lab group immediately.
Dissolved Oxygen	Nitrite or Nitrate	Flashpoint		2 Complete nonconformance
Hexavalent Chromium	Ortho Phosphorus	Free Liquids		memo.
HPC	Surfactants	Sulfide		
Ferrous Iron	Turbidity En Core Preservation	TDS TSS	l	
Eh Odor	Power stop preservation	Total Solids		
Residual Chlorine	. The stab breast serior	TVS		
Sulfite		TVSS		
		Unpreserved VOC's		

Rev. 2/05/04, Attachment to 1-REC-5. Subject to QA Audit.

Reviewed by/date Ty 5/13/05

Company Name: MATURA TEXALLE TELHIDLAST (Please Print Legibly)

PENMUKEE Branch or Location: Project Contact. [KIL TINGE, Richard Weber

262. 523. 9000 Telephone:

W/96 . 74/ 1530 Project Number: Project Name:

Wisconsin Sampled By (Print): \_ Project State:

=Ground Wate Regulatory Program UST RCRA SDWA NPDES CERCLA Data Package Options - (please circle if requested EPA Level III (Subject to Surcharge) EPA Level IV (Subject to Surcharge) EPA Level II (Subject to Surcharge) Sample Results Only (no QC) PO #

DATE TIME COLLECTION FELDID LABORATORY ID (Lab Use Only)

CHEM H

A Division of Pace Analytical Services, Inc.

Fax 920-469-8827

1241 Bellevue St., Suite 9 Green Bay, WI 54302 920-469-2436

Webek FAMLRY 08 Present / More resent Cooler Custody Seal En Chem Project No **%**Б0 3 Intact / Not intact LAB COMMENTS (Lab Use Only) Mail Report To: Aich Sample Receip (Wet/Metals) Address: 237/9 W. ersion 4.0: 09/04 Personal El Quote #: 45 Company: \_\_ 5/20/05 1000 Date/Time: · 1300 Date/Time: Date/Time: Date/Time: Date/Time: 3 Invoice To: Company: G-NaOH - ILamber\* No.131472 Address: Mail Invoice To: CLIENT COMMENTS 5-30-05 INSS STILLOR SO W WILOI F=Methanol Meliterreyer J=Other E=EnCore I=Sodium Thiosulfate 1 Ì Received By: Received By: Sign Received By: Received By CHAIN OF CUSTODY \*Preservation Codes C=H2SO4 D=HN03 P 5 25 65 1200 1415 18 Date/Time: ate/Time: Date/Time: A=None B=HCL C=H H=Sodium Bisulfate Solution Date/Time: FILTERED? (YES/NO) PRESERVATION (CODE)\* OBLISTATORIUS TEXTORIUS 5-70-0E × M. C. Clemenson X  $\lambda$ B=Biota SI=Sludge WP=Wipe MATRIX Z 5.805/180 Am Relinquished By: Relinquished By: 0571 1280 1230 asi 1340 1300 Relinquished By 1410 1350 460 anthuac Rush Turnaround Time Requested (TAT) - Prelim Samples on HOLD are subject to special pricing and release of liability 17 MW-12D (Rush TAT subject to approval/surcharge) MW-12 E-mail Transmit Prelim Rush Results by (circle): 6, 2727 MW.5 MW-8 nn 001 Phone E-Mail Address: Date Needed: Phone #:

Fax #:

Present / Mot Present Cooler Custody Seal Intact / Not intact (Lab Use Only) 237/3 W. KWAUKCE Mail Report To: 1/24 Page . Quote #: Company: \_\_ Green Bay, WI 54302 920-469-2436 5/3c/os 1000 Date/Time: Address: 1300 Date/Time: Date/Time: Fax 920-469-8827 Invoice To: Company: G-NaOH -IL JAMPEN No.131473 Address: CLIENT COMMENTS Mail Invoice To: INSESSILICE TO # 50-08-5 F=Methanol Bild Mathemayer J=Other E=EnCore I=Sodium Thiosulfate Ç Received By: Received By: Received By: CHAIN OF CUSTODY \*Preservation Codes C=H2SO4 D=HN03 No NO 1200 Date/Time: A=None B=HCL C=HZ H=Sodium Bisulfate Solution Date/Time: Date/Time: A Division of Pace Analytical Services, Inc. FILTERED? (YES/NO) PRESERVATION (CODE)\* DELEGION STEEL 50.0E-5 H COLLECTION MATRIX B=Biota SI=Sludge WP=Wipe 5-18-4 1330 GAW ed By: Relinquished By: Relinquished By: DATE TIME 0181 1 ١ Company Name: NATURAL TESOURIE TECHNOLOS Regulatory Program UST RCRA SDWA NPDES CERCLA 78-45 Speritel Project Contact Fle Tachac, Tichwa Data Package Options - (please circle if requested 262-523-9000 Rush Turnaround Time Requested (TAT) - Prelim Samples on HOLD are subject to special pricing and release of liability WW- 207 FIELD 10 0 (Rush TAT subject to approval/surcharge) E-mail Transmit Prelim Rush Results by (circle): Hanor ノのハウン EPA Level III (Subject to Surcharge) EPA Level IV (Subject to Surcharge) EPA Level II (Subject to Surcharge) Sample Results Only (no QC) Project Name: Sampled By (Print): \_\_ Branch or Location: (Please Print Legibly) 2 LABORATORY ID (Lab Use Only) Phone Project Number: E-Mail Address: Project State: Date Needed: Telephone: Phone #: PO # Fax #:

Version 4.0: 09/04

Paul Ro.

leto

₽

# APPENDIX G2 TREATMENT SYSTEM ANALYTICAL SUMMARY TABLES

Table 6 - Pretreatment System Analytical Results - Influent, Intermediate, and Effluent Wisconsin Public Service - Manitowoc Former Fuel & Light Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin USEPA ID# WIN000509949

			BTEX	Compounds	(µg/L)			Additi	onal Volatil	e Organic	Compou	ınds (VOCs	s, µg/L)					SVOCs (μο	/L)	*		
Sample ID	Collect Date	Benzene	Toluene	Ethylbenzene	Xylene, Total	Total BTEX	cis-1,2-Dichloroethene	1,1-Dichloroethane	sopropyl-benzene	Methyl Tertiary Butyl Ether	n-Propylbenzene	Styrene	Trimethylbenzenes	Trichloroethene	Acenaphthylene	Anthracene	Fluorene	Phenanthrene	2,4-Dimethylphenol	1-Methylnapthalene	2-Methylnaphthalene	Naphthalene
																			,			
Influent (PW-1)	10/28/1997	420 750	260	150	290	1120				<250			71		nd			***	29		nd	420
(PVV-1)	11/12/1997 11/13/1997	750 420	420	510	550	2230				nd			nd		30	Eta 190			60		66	2200
	11/20/1997	420 190	190 98	290 140	360 170	1260				nd			nd		22 7				nd		nd	1600
	11/25/1997	140	73	93	120	598 426				nd			55.2		1 '				nd d		11	470
	12/4/1997	160	110	140	160	426 570				nd <250			33.2		nd 9				nd		nd nd	400 640
	12/9/1997	200	140	180	200	720				<50			<1.0 <1.0		9				nd nd		nd nd	640 640
	1/15/1998	170	190	120	220	700		~~		<50 <50			60								11G 1	040
	2/17/1998	110	110	74	160	454	****			<50		**	39.4									
	3/11/1998	<1.0	<1.0	<1.0	<3.0	nd				<50			<1.0									
	4/14/1998	94	100	72	170	436				<50			33.3									
	5/19/1998	31	1.8	<1.0	7.6	40.4				<50			<1.0					-~				
	6/11/1998	100	120	74	170	464				<50			38.2					<b>i</b>				
	1/12/1999	90	99	72	240	501																
	9/14/2001	47	52	47	150	296													<del></del> -			
	4/23/2002	50	65	61	121	297	0.86 Q	<0.48	4.4	<0.67	1.8 Q	42	28.6	27	7.3 Q				<5.2		10 Q	210
	10/8/2002	46	66	43	124	279	<4.0	<4.3	<3.3	<4.3	<4.8	41 &	32.8	31	<10				<10		16 Q	380
	4/16/2003	44	59	56	108	267	<4.2	<3.8	4.1 Q	<3.0	<4.0	36	29.1 Q	39	<19	<11	<19	<8.4	<12		<16	310
	10/17/2003	48	63	65 40	111	287	<4.2	<3.8	4.4 Q	<3.0	<4.0	37	30.9 Q	36	<19	<20	<17	<16		22 Q	<17	310
	5/24/2004 11/10/2004	35	38	43	75	191	<4.1	<2.8	3.5 Q	<3.0	<4.1	16	13 Q	40	5.4 Q D*	0.020 Q *	0.22	0.082		16 D	5.7 Q D*	170 D
	5/18/2005	38 33	30 47	37 58	118 98	223	2.5 Q	<1.5	6.8	<1.2	2.0 Q	<1.7	21 Q	54	4.3 Q	<1.8	<2.2	<2.0		18	4.1 Q	190 D
	11/28/2005	38	47	58 58	95	236 235	<4.1 4.1 Q	<3.8 <1.9	4.2 Q 3.4 Q	<3.0	<4.1 <2.0	27 24	27 Q 23 Q	36 40	2.6 Q	<1.8 0.021 Q	<2.2 0.29	<2.0		17 18 D	6.2 Q 6.0 QD	30 240 D
	5/30/2006	43	28	48	72	235 191	3.3	<0.75	7.4	<1.5 <0.61	2.2 Q	<0.86	<0.97	52	5.5 QD <3.2	0.021 Q <4.6	0.29 <3.6	0.17 <4.5		10 Q	6.0 QD <4.5	120
	0.00,2000	70	L &V		1 4	131	3.5	70.13	/	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	2.2 W	~0.00	70.87	JL	``J	<b>~</b> +.0	~3.0	\ <del>4</del> .0	<u> </u>	1000	74.0	120



Table 6 - Pretreatment System Analytical Results - Influent, Intermediate, and Effluent Wisconsin Public Service - Manitowoc Former Fuel & Light Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

USEPA ID# WIN000509949

			BTE	(Compounds	(µg/L)			Additi	onal Volatil	e Organio	Compo	ınds (VOCs	s, µg/L)				· · · · · · · · · · · · · · · · · · ·	SVOCs (µ	g/L)			
										•									<u> </u>			
Sample ID	Collect Date	Benzene	Toluene	Ethylbenzene	Xylene, Total	Total BTEX	cis-1,2-Dichloroethene	1,1-Dichloroethane	Isopropyl-benzene	Methyl Tertiary Butyl Ether	n-Propylbenzene	Styrene	Trimethylbenzenes	Trichloroethene	Acenaphthylene	Anthracene	Fluorene	Phenanthrene	2,4-Dimethylphenol	1-Methyinapthalene	2-Methylnaphthalene	Naphthalene
Intermediate	07/13/1998	68	16	<1.0	42	126											~~		<del>                                     </del>			
	08/24/1998	75	20	<1.0	85	180																
	09/22/1998	72	17	<1.0	120	209							uo na									1
	11/02/1998	<1.0	<1.0	<1.0	<3.0	nd						-										
	11/23/1998	6.6	<1.0	<1.0	<3.0	6.6																
	12/16/1998	14	2.6	<1.0	6	22.6		<b></b>						-							···~	
	01/12/1999 02/11/1999	38	3	<1.0	19	60		-			~~~										<b> </b>	
	03/24/1999	56 64	6.2	<1.0	32	94																
	09/14/2001	<1.0	11 <1.0	<1.0 <1.0	57	132								~~								] [
	04/23/2002	48	<0.82	4.6	<3.0 40	nd															<del></del>	
	06/24/2002	58	16	4.6 <0.82	55	93		_												~~	AL-TON	
	08/26/2002	60	14	<0.82	83	129 157			-										7			
	10/08/2002	55	16	1.8 Q	95	168											-			-		
	06/09/2003	13	2.3	<0.6	11.9	27		<del></del> 				<del>~ -</del>					-			-		-
	10/17/2003	41	11	<0.6	52	104																
	12/29/2003	44	8.7	0.79 Q	52	105										-		-		-		
	04/29/2004	<0.14	<0.36	<0.40	<0.74	nd		-														
	06/30/2004	2.3	1.2	1.4	4.3	9.2																
	08/25/2004	3.3	1.3	1.0 Q	3.9 Q	9.5						****										
	12/28/2004	21	5.7	1.3	22.9	50.9												~~				
	02/16/2005	40	29	6.8	75	150.8																
	04/14/2005	40	8.6	4.6	55	108.2																
	06/16/2005	40	3.8	<0.4	64	107.8						~										
	08/10/2005	43	14	11	83	151	mr ma															
	10/17/2005	43	9.9	4.6	84	141.5											***			***		
	12/20/2005	41	24	31	99	195																
	02/20/2006	39	17	18	75	149																
	04/26/2006	37	23	23	85	168							***							~~		
	08/08/2006	35	16	19	63	133																



Table 6 - Pretreatment System Analytical Results - Influent, Intermediate, and Effluent Wisconsin Public Service - Manitowoc Former Fuel & Light Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

USEPA ID# WIN000509949

			BTE	X Compounds	(µg/L)			Additi	onal Volati	le Organic	Compo	unds (VOCs	s, µg/L)					SVOCs (μ	g/L)			
Sample ID	Collect Date	Benzene	Toluene	Ethylbenzene	Xylene, Total	Total BTEX	cis-1,2-Dichloroethene	1,1-Dichloroethane	sopropyl-benzene	Methyl Tertiary Butyl Ether	n-Propylbenzene	Styrene	Trimethylbenzenes	Trichloroethene	Acenaphthylene	Anthracene	Fluorene	Phenanthrene	2,4-Dimethylphenol	1-Methylnapthalene	2-Methylnaphthalene	Vaphthalene
		105						С	ity of Manito	owoc Efflu	ent Water	Standards (	(µg/I)									
Effluent	10/28/1997	125	ne	ne	ne	250	ne	пе	ne	ne	ne	ne	ne	ne	nd	nd	nd	nd	ne	nd	nd	nd
Lindent	10/28/1997	<1.0 <1.0	<1.0	<1.0	<30.	nd				<50			<1.0		nd	#4			nd		nd	nd
	11/13/1997	<1.0	<1.0 <1.0	<1.0	<3.0	nd				<50			<1.0		nd				nd		nd	nd
	11/20/1997	<1.0	<1.0 <1.0	<1.0 <1.0	<3.0 <3.0	nd				<50			<1.0		nd				nd		nd	nd
	11/25/1997	<1.0	<1.0 <1.0	<1.0	<3.0	nd				<50			<1.0		nd				nd		nd	nd
	12/04/1997	<1.0	<1.0	<1.0	<3.0	nd nd				<50 <50		~=	<1.0		nd			-	nd		nd	nd
	12/09/1997	<1.0	<1.0	<1.0	<3.0	nd				<50 <50			<1.0		nd		<del></del>	-	nd		nd	nd
	01/15/1998	<1.0	<1.0	<1.0	<3.0	nd				<50 <50			<1.0		nd				nd		nd	nd
	02/17/1998	1.1	1.0	<1.0	<3.0	nd				<50			<1.0 <1.0						-			~-
	03/11/1998	<1.0	<1.0	<1.0	<3.0	nd				<50			<1.0									
	04/14/1998	<1.0	<1.0	<1.0	<3.0	nd				<50 <50			<1.0	<del>-</del>								
	05/19/1998	<1.0	<1.0	<1.0	<3.0	nd				<50			<1.0							-		
	06/11/1998	<1.0	<1.0	<1.0	<3.0	nd				<50			<1.0		 			 				
	07/13/1998	<1.0	<1.0	<1.0	<3.0	nd																
	08/24/1998	<1.0	<1.0	<1.0	<3.0	nd										~~						
	09/22/1998	2.7	<1.0	<1.0	<3.0	2.7																
	11/02/1998	<1.0	<1.0	<1.0	<3.0	nd						m-u										
	11/23/1998	<1.0	<1.0	<1.0	<3.0	nd						<u></u>										
	12/16/1998	<1.0	<1.0	<1.0	<3.0	nd																
	01/12/1999	<1.0	<1.0	<1.0	<3.0	nd																
i	02/11/1999	<1.0	<1.0	<1.0	<1.0	nd																
	03/24/1999	3.9	<1.0	<1.0	<3.0	3.9					]				500-VA							
	09/14/2001	9.7	<1.0	<1.0	<3.0	9.7																
	04/23/2002	4.4	<0.47	<0.43	<1.4	4.4	<0.73	<0.48	<0.43	0.68 Q	<0.64	<0.43	<0.60	0.94 Q	<2.6				<2.6		<2.6	<2.7
	10/8&14/02	22	<0.84	< 0.53	2.0 Q	24	0.88 Q	<0.87	<0.66	1.0 Q	<0.95	<0.62 &	<0.69	7.0	<2.6				<2.6		<2.6	<2.7
	04/16/2003	<0.41	<0.67	<0.54	<1.8	nd	<0.83	<0.75	<0.59	<0.61	<0.81	<0.86	<0.97	<0.48	<4.7	<2.8	<4.7	<2.1	<2.9		<3.9	<3.8
	10/17/2003 05/24/2004	0.92 Q <0.41	<0.67	<0.54	<1.8	0.92	<0.83	<0.75	<0.59	<0.61	<0.81	<0.86	<0.97	<0.48	<4.7	<2.8	<4.7	<2.1	<2.9		<3.9	<3.8
	03/24/2004	<b>~0.41</b>	<0.67	<0.54	<1.8	nd	<0.83	<0.75	<0.59	<0.61	<0.81	<0.86	<0.97	<0.48	<4.4	<2.6	<4.4	<2.0	<2.8		<3.7	<3.6



Table 6 - Pretreatment System Analytical Results - Influent, Intermediate, and Effluent Wisconsin Public Service - Manitowoc Former Fuel & Light Manufactured Gas Plant Site 402 N. Tenth Street, Manitowoc, Wisconsin

USEPA ID# WIN000509949

			BTEX	Compounds	(µg/L)			Additio	onal Volatil	e Organio	Compou	ınds (VOCs	s, μg/L)					SVOCs (µ	g/L)			
Sample ID	Collect Date	Benzene	Toluene	Ethylbenzene	Xylene, Total	Total BTEX	cis-1,2-Dichloroethene	1,1-Dichloroethane	Isopropyl-benzene	Methyl Tertiary Butyl Ether	n-Propylbenzene	Styrene	Trimethylbenzenes	Trichloroethene	Acenaphthylene	Anthracene	Fluorene	Phenanthrene	2,4-Dimethylphenol	1-Methylnapthalene	2-Methyinaphthalene	Naphthalene
								Ci	ty of Manito	woc Efflue	ent Water	Standards	(µg/l)									<u></u>
		125	ne	ne	ne	250	ne	ne	ne	ne	ne	ne	ne	ne	nd	nd	nd	nd	ne	nd	nd	nd
Effluent	11/10/2004	<0.41	<0.67	<0.54	<1.8	nd	<0.83	<0.75	<0.59	<0.61	<0.81	<0.86	<0.97	<0.48	<0.50	<1.6	<0.50	<0.50	<0.72		<1.9	<0.6
(cont)	02/16/2005	1.2	<0.36	<0.40	<0.74	1.2																
	05/18/2005	10	<0.67	<0.54	<1.8	10	2.4 Q	<0.75	<0.59	<0.61	<0.81	<0.86	<0.97	6.1	<0.50	<1.6	<0.50	<0.50	<0.72		<1.9	<0.60
	11/28/2005	26	<0.67	<0.54	<1.8	26	4.9	<0.75	<0.59	<0.61	<0.81	<0.86	<0.97	16	<1.1	<0.82	<0.88	<0.72	<0.65		<1.6	<1.4
	05/30/2006	29	<0.67	<0.54	<1.8	29	6.0	<0.75	<0.59	<0.61	<0.81	<0.86	<0.97	18	<1.0	<0.77	<0.83	<0.68	<0.72		<1.5	<1.3

Notes:

- 1) Pre-2002 data from Horizon Environmental reports. Possible Data missing.
- 2) Trimethylbenzenes include 1,2,4- and 1,3,5-trimethylbenzene
- 3) Only detected compounds shown. Laboratory report should be referenced for full list of analytes.
- 4) Analytes attaining or exceeding the Preventive Action Limit (PAL) are shown in italics.
- 5) Analytes attaining or exceeding the Enforcement Standard (ES) are shown in bold.
- D: Analyte value from diluted analysis or surrogate result not applicable due to sample dilution.
- Q: Analyte detected between the limit of detection (LOD) and limit of quantitation (LOQ).
- &: Laboratory Control Spike recovery not within control limits. ne: City of Manitowoc effluent water standard not established.
- nd: Analyte not detected.
- --: Not Analyzed or unknown if analyzed

[JTB/LJH - 09/03][JAZ-10/03][JKY/SAG - 7/04][JKY-10/04][EJT/HMS - 9/05][HMS/RJG 06/06]



Table 8 - Pretreatment System Analytical Summary for WWTP Wisconsin Public Service - Manitowoc Former Fuel & Light Man 402 N. Tenth Street, Manitowoc, Wisconsin USEPA ID# WIN000509949

		Apri	April 2002	October 2002	r 2002	April 2003	2003	October 2003	2003	May 2004	,004	Novemi	November 2004	May	May 2005	November 2005	ar 2005	May 2006	9008	Effluent
Parameter	Unit	influent	effluent	influent	effluent	Influent	effluent	influent	effluent	influent	effluent	influent	effluent	influent	effluent	influent	effluent	influent	effluent	Limit
Arsenic	mg/L	0.0025	0.00067 Q	0.0028 Q	<dl< th=""><th>≺0F</th><th>-O-</th><th>. 3</th><th>ì</th><th>;</th><th>:</th><th>:</th><th>1</th><th></th><th>-</th><th>-</th><th>71</th><th>:</th><th>1</th><th>ML</th></dl<>	≺0F	-O-	. 3	ì	;	:	:	1		-	-	71	:	1	ML
Barium	mg/L	680.0	0.091	0.088	<dl< th=""><th>0.093</th><th>0.094</th><th>į</th><th></th><th>;</th><th>ı</th><th>1</th><th>1</th><th>-</th><th>-</th><th>;</th><th>ı</th><th>1</th><th>1</th><th>ı,</th></dl<>	0.093	0.094	į		;	ı	1	1	-	-	;	ı	1	1	ı,
Cadmium	mg/L	-û	Ϋ́	ģ	ģ	ŝ	-OL	,	,	;	;		ı	,	ı	-		;	-	N.
Chromium	mg/L	φ	0.00056 Q	-QC	40	ζÇ	4ĐĽ	1	1	;	ı	1	1	-	-	ł	-		1	٦
Copper	mg/L	0.0032	0.0028	-OF	ď	0.0024 Q	0.0013 Q	-	;	;	ę.	:	-	1	:	-	-	ţ	1	Z
Lead	mg/L	7Q≻	-CDL	φ	√D[	.°DL	-QF	1		:	ï	i			;	-	1	:	;	NL
Mercury	mg/L	<b>~</b> DΓ	ФĽ	4D	겋	DL	ΪÇ	:	;	1	^=	:		-	:	1	:	;		ž
Molybdenum	mg/L	0.0012 Q	0.0013 Q	å	Ϋ́	^Dľ	TQ>	;	;	*,	-	-		,,	:		ž	1	ì	¥
Nickel	¬/bω	0.0073	0.012	ģ	0.025 Q	0.0036 Q	0.038	;	i	1			1	;			:	-	1	¥
Selenium	η/bω	0.0024	0.00088 Q	ģ	Ŷ	-do-	10,0	;	1		-		To de	-	-		1	:	ı	Ä
Silver	J/bw	å	ÎĢ.		ģ	ģ	ď	;	;	ı			;	ł	-	:	1	1	:	NF
Zinc	ma/L	0.031	0.01	0.076	ŝ	0.026	0.0048 Q	1	;	-	١	;	į	;	ı		š	-	-	NF
Cyanide, total	та/Г	0.046	0.049	0.059	0.052	0.042	0.041	ı	ı	3	:	:	ŀ	ŧ	:			1	-	NE
Cvanide, amen.	mg/L	0.046	0.046	0.059	0.052	0.042	0.041	;			;	;	١	ŀ	-	-	-		1	Į.
Hd	stq	7.3	7.3	7.2	7.2	6.7	6.7	;	7.5	ı	7.0	;	7.1		7.33		7.3	-	6.9	5.0 - 10.5
Oll & Grease	mg/L	ΔĠ	1.2 Q	3.4 Q	1.2 0	ó	70>		1	1	1	:	i	ı	ı	ł	<5.0		:	NL
Benzene	na/L	20	4.4	46	22	44	Ω.	48	0.92 Q	35	û	38	ď	33	10	38	56	43	29	125
Total BTEX (7)	ug/L	297	4.4	279	24	267	-Q-	287	0.92 Q	191	ĵo,	223	, OL	236	10	235	26	191	29	250
TPH (8)	ug/L	2500	.o⊳	2600	29	2400	4DF	1	1	;	ţ	:	;	1	;		-	417	-	NL
Total PAH (9)	ug/L	227.3 Q	-CDL	396 Q	^°DL	310	<dl< th=""><th>332 Q</th><th>-Dr</th><th>197 Q*D</th><th>, JÇ</th><th>216 QD</th><th>70×</th><th>56 Q</th><th>^Dľ</th><th>270 QD</th><th>JQ&gt;</th><th>130 Q</th><th><dγ< th=""><th>-OL</th></dγ<></th></dl<>	332 Q	-Dr	197 Q*D	, JÇ	216 QD	70×	56 Q	^Dľ	270 QD	JQ>	130 Q	<dγ< th=""><th>-OL</th></dγ<>	-OL
																				[EJT/PAR-8/05]

Page 1 of 1



### **SHEETS**

